

Premium Vehicle Maintenance Report

for your
2009 TOYOTA PRIUS

@ 12,234 miles

VIN: JTDKKB20U393493301







Average MPG: 46

Maintenance

11 items

If you have not completed the following items below, completing these services before they are due will help keep your car running smoothly.


This service is due at 15,000 mi

Service Item (s)	Difficulty	Cost
 Inspect Ball Joints Buy Online Now	 Repair difficulty	\$221 Cost of repair \$221 in parts \$0 in labor
 90947-02F18 トヨタ純正パーツ 交換部品 Inspect Brake Hoses & Lines Buy Online Now	 Repair difficulty	\$76 Cost of repair \$76 in parts \$0 in labor
 Inspect Brake System, Friction Material & Hydraulic System Buy Online Now	 Repair difficulty	\$109 Cost of repair \$109 in parts \$0 in labor
		\$513



Inspect Driveshaft & Related Components

[Buy Online Now](#)




Cost of repair
\$513 in parts
\$0 in labor



Inspect Engine and Inverter Fluid Levels and Condition

[Buy Online Now](#)




\$26
Cost of repair
\$26 in parts
\$0 in labor



Inspect Exhaust System

[Buy Online Now](#)




\$20
Cost of repair
\$20 in parts
\$0 in labor



Inspect Radiator and Condenser

[Buy Online Now](#)




\$296
Cost of repair
\$296 in parts
\$0 in labor



Inspect Steering Gearbox Assembly and Linkage

[Buy Online Now](#)




\$67
Cost of repair
\$67 in parts
\$0 in labor



Inspect Tie-Rod Ends, Steering Gear & Boots

[Buy Online Now](#)




\$17
Cost of repair
\$17 in parts
\$0 in labor

Change Engine Oil and Filter

N/A

\$0
Cost of repair
\$0 in parts

		\$0 in labor
Rotate Tires, Inspect Tire Wear, & Adjust Tire Pressure	 Repair difficulty	\$41 Cost of repair \$0 in parts \$41 in labor

Safety Recalls

9 items

Your vehicle has 9 Safety Recalls. These are announcements made by your vehicle's manufacturer that there is a safety-related problem that needs immediate repair and should be repaired free of charge by your vehicle's dealership.

CAMPAIGN ID NUMBER: **13V014000** DATE: 1/16/2013

Recall Number: 136681

Description Defect: SOUTHEAST TOYOTA DISTRIBUTORS, LLC (SET) IS RECALLING CERTAIN MODELS INTERSPERSED THROUGH MODEL YEARS 2009 THROUGH 2013 AS FOLLOWS: MODEL YEAR 2009-2012 TACOMA, 4RUNNER, CAMRY, CAMRY HYBRID, PRIUS, AND RAV4; MODEL YEAR 2009-2010 AVALON, FJ CRUISER, AND HIGHLANDER HYBRID; MODEL YEAR 2010-2013 MODEL YEAR COROLLA, SIENNA AND TUNDRA; MODEL YEAR 2009-2013 HIGHLANDER AND VENZA; MODEL YEAR 2012 PRIUS V; AND MODEL YEAR 2010-2012 SEQUOIA. DURING MODIFICATION BY SET TO INCLUDE ACCESSORIES SUCH AS LEATHER SEAT COVERS, SEAT HEATERS OR HEADREST DVD SYSTEMS, THESE VEHICLES MAY NOT HAVE HAD THE PASSENGER SEAT OCCUPANT SENSING SYSTEM CALIBRATION TESTED. WITHOUT PASSING THE CALIBRATION TEST, THE OCCUPANT SENSING SYSTEM MAY NOT OPERATE AS DESIGNED.

Consequence: IF THE FRONT PASSENGER SEAT OCCUPANT SENSING SYSTEM IS OUT OF CALIBRATION, THE FRONT PASSENGER AIRBAGS MAY NOT DEPLOY OR THEY MAY DEPLOY INAPPROPRIATELY FOR THE PASSENGER'S SIZE AND POSITION. THIS COULD INCREASE THE RISK OF PERSONAL INJURY DURING THE EVENT OF A VEHICLE CRASH NECESSITATING AIRBAG DEPLOYMENT.

Corrective Action: SOUTHEAST TOYOTA WILL NOTIFY OWNERS, AND DEALERS WILL TEST THE SENSITIVITY OF THE OCCUPANT DETECTION SENSORS, AND RECALIBRATE THEM AS NECESSARY. THE RECALL BEGAN ON MARCH 21, 2013. OWNERS MAY CONTACT SOUTHEAST TOYOTA AT 1-800-301-6859.

CAMPAIGN ID NUMBER: **13V014000** DATE: 1/16/2013

Recall Number: 136682

Description Defect: SOUTHEAST TOYOTA DISTRIBUTORS, LLC (SET) IS RECALLING CERTAIN MODELS INTERSPERSED THROUGH MODEL YEARS 2009 THROUGH 2013 AS FOLLOWS: MODEL YEAR 2009-2012 TACOMA, 4RUNNER, CAMRY, CAMRY HYBRID, PRIUS, AND RAV4; MODEL YEAR 2009-2010 AVALON, FJ CRUISER, AND HIGHLANDER HYBRID; MODEL YEAR 2010-2013 MODEL YEAR COROLLA, SIENNA AND TUNDRA; MODEL YEAR 2009-2013 HIGHLANDER AND VENZA; MODEL YEAR 2012 PRIUS V; AND MODEL YEAR 2010-2012 SEQUOIA. DURING MODIFICATION BY SET TO INCLUDE ACCESSORIES SUCH AS LEATHER SEAT COVERS, SEAT HEATERS OR HEADREST DVD SYSTEMS, THESE VEHICLES MAY NOT HAVE HAD THE PASSENGER SEAT OCCUPANT SENSING SYSTEM CALIBRATION TESTED. WITHOUT PASSING THE CALIBRATION TEST, THE OCCUPANT SENSING SYSTEM MAY NOT OPERATE AS DESIGNED.

Consequence: IF THE FRONT PASSENGER SEAT OCCUPANT SENSING SYSTEM IS OUT OF CALIBRATION, THE FRONT PASSENGER AIRBAGS MAY NOT DEPLOY OR THEY MAY DEPLOY INAPPROPRIATELY FOR THE PASSENGER'S SIZE AND POSITION. THIS COULD INCREASE THE RISK OF PERSONAL INJURY DURING THE EVENT OF A VEHICLE CRASH NECESSITATING AIRBAG DEPLOYMENT.

Corrective Action: SOUTHEAST TOYOTA WILL NOTIFY OWNERS, AND DEALERS WILL TEST THE SENSITIVITY OF THE OCCUPANT DETECTION SENSORS, AND RECALIBRATE THEM AS NECESSARY. THE RECALL BEGAN ON MARCH 21, 2013. OWNERS MAY CONTACT SOUTHEAST TOYOTA AT 1-800-301-6859.

CAMPAIGN ID NUMBER: **12V536000** DATE: 1/14/2012

Recall Number: 136679

Description Defect: TOYOTA IS RECALLING CERTAIN MODEL YEAR 2004-2009 PRIUS VEHICLES MANUFACTURED AUGUST 6, 2003, THROUGH MARCH 30, 2009 AND FCHV-ADV VEHICLES MANUFACTURED DECEMBER 12, 2008, THROUGH SEPTEMBER 13, 2011. DURING MANUFACTURING, A SCRATCH MAY HAVE OCCURRED INSIDE OF THE ELECTRICALLY DRIVEN WATER PUMP AT THE COIL WIRE. THE COIL WIRE MAY CORRODE AT THE SCRATCHED PORTION.

Consequence: THE CORRODED COIL WIRE MAY BREAK AND THE WATER PUMP COULD STOP. THE CORRODED COIL WIRE COULD CAUSE A SHORT CIRCUIT BETWEEN COIL WIRES AND A POSSIBLE OPEN FUSE, CREATING A STALL-LIKE CONDITION OF THE HYBRID SYSTEM WHILE THE VEHICLE IS BEING DRIVEN. THIS MAY INCREASE THE RISK OF A VEHICLE CRASH.

Corrective Action: TOYOTA WILL NOTIFY ITS OWNERS, AND DEALERS WILL REPLACE THE ELECTRIC WATER PUMP, FREE OF CHARGE. THE RECALL BEGAN ON JANUARY 17, 2013. OWNERS MAY CONTACT THEIR TOYOTA DEALER OR THE TOYOTA CUSTOMER EXPERIENCE CENTER AT 1-800-331-4331.

CAMPAIGN ID NUMBER: **12V537000** DATE: 1/14/2012

Recall Number: 136674

Description Defect: TOYOTA IS RECALLING CERTAIN MODEL YEAR 2004-2009 PRIUS VEHICLES MANUFACTURED AUGUST 5, 2003, THROUGH MARCH 30, 2009. THE AFFECTED VEHICLES HAVE A STEERING INTERMEDIATE EXTENSION SHAFT ASSEMBLY BUILT WITH METAL SPLINES THAT COMPLETE THE CONNECTION FROM THE STEERING WHEEL TO THE STEERING GEAR. THESE SPLINES MAY HAVE BEEN MANUFACTURED WITH AN INSUFFICIENT HARDNESS.

Consequence: OVER TIME, THE SPLINES MAY WEAR AND EVENTUALLY FAIL RESULTING IN A LOSS OF STEERING ABILITY, INCREASING THE RISK OF A VEHICLE CRASH.

Corrective Action: TOYOTA WILL NOTIFY OWNERS, AND DEALERS WILL INSPECT THE EXTENSION SHAFT AND REPLACE IT IF IT IS ONE WITH INSUFFICIENT HARDNESS, FREE OF CHARGE. THE RECALL BEGAN DURING DECEMBER 2012. OWNERS MAY CONTACT THEIR TOYOTA DEALER OR THE TOYOTA CUSTOMER EXPERIENCE CENTER AT 1-800-331-4331.

CAMPAIGN ID NUMBER: **12V537000** DATE: 1/14/2012

Recall Number: 136675

Description Defect: TOYOTA IS RECALLING CERTAIN MODEL YEAR 2004-2009 PRIUS VEHICLES MANUFACTURED AUGUST 5, 2003, THROUGH MARCH 30, 2009. THE AFFECTED VEHICLES HAVE A STEERING INTERMEDIATE EXTENSION SHAFT ASSEMBLY BUILT WITH METAL SPLINES THAT COMPLETE THE CONNECTION FROM THE STEERING WHEEL TO THE STEERING GEAR. THESE SPLINES MAY HAVE BEEN MANUFACTURED WITH AN INSUFFICIENT HARDNESS.

Consequence: OVER TIME, THE SPLINES MAY WEAR AND EVENTUALLY FAIL RESULTING IN A LOSS OF STEERING ABILITY, INCREASING THE RISK OF A VEHICLE CRASH.

Corrective Action: TOYOTA WILL NOTIFY OWNERS, AND DEALERS WILL INSPECT THE EXTENSION SHAFT AND REPLACE IT IF IT IS ONE WITH INSUFFICIENT HARDNESS, FREE OF CHARGE. THE RECALL BEGAN DURING DECEMBER 2012. OWNERS MAY CONTACT THEIR TOYOTA DEALER OR THE TOYOTA CUSTOMER EXPERIENCE CENTER AT 1-800-331-4331.

CAMPAIGN ID NUMBER: **12V536000** DATE: 1/14/2012

Recall Number: 136676

Description Defect: TOYOTA IS RECALLING CERTAIN MODEL YEAR 2004-2009 PRIUS VEHICLES MANUFACTURED AUGUST 6, 2003, THROUGH MARCH 30, 2009 AND FCHV-ADV VEHICLES MANUFACTURED DECEMBER 12, 2008, THROUGH SEPTEMBER 13, 2011. DURING MANUFACTURING, A SCRATCH MAY HAVE OCCURRED INSIDE OF THE ELECTRICALLY DRIVEN WATER PUMP AT THE COIL WIRE. THE COIL WIRE MAY CORRODE AT THE SCRATCHED PORTION.

Consequence: THE CORRODED COIL WIRE MAY BREAK AND THE WATER PUMP

COULD STOP. THE CORRODED COIL WIRE COULD CAUSE A SHORT CIRCUIT BETWEEN COIL WIRES AND A POSSIBLE OPEN FUSE, CREATING A STALL-LIKE CONDITION OF THE HYBRID SYSTEM WHILE THE VEHICLE IS BEING DRIVEN. THIS MAY INCREASE THE RISK OF A VEHICLE CRASH.

Corrective Action: TOYOTA WILL NOTIFY ITS OWNERS, AND DEALERS WILL REPLACE THE ELECTRIC WATER PUMP, FREE OF CHARGE. THE RECALL BEGAN ON JANUARY 17, 2013. OWNERS MAY CONTACT THEIR TOYOTA DEALER OR THE TOYOTA CUSTOMER EXPERIENCE CENTER AT 1-800-331-4331.

CAMPAIGN ID NUMBER: **10V035000** DATE: 1/3/2010

Recall Number: 136677

Description Defect: GULF STATES TOYOTA IS RECALLING CERTAIN MODEL YEAR 2005-2010 VEHICLES FOR FAILING TO COMPLY WITH THE REQUIREMENTS OF FEDERAL MOTOR VEHICLE SAFETY STANDARD NO. 110, TIRE SELECTION AND RIMS. THESE VEHICLES WERE SOLD BETWEEN SEPTEMBER 1, 2005 AND JUNE 2, 2008 WITHOUT THE REQUISITE LOAD CARRYING CAPACITY MODIFICATION LABELS.

Consequence: THIS DOES NOT MEET THE STANDARD REQUIREMENTS.

Corrective Action: DEALERS WILL MAIL TO CONSUMERS THE CORRECTED LABEL OR THE CUSTOMER WILL HAVE THE OPTION FOR DEALERS TO INSTALL THE LABEL FREE OF CHARGE. DEALERS WILL ALSO CORRECT THE OWNER'S MANUAL. THE SAFETY RECALL BEGAN ON MAY 27, 2010. OWNERS MAY CONTACT GULF STATES TOYOTA AT 713-580-3300.

CAMPAIGN ID NUMBER: **10V036000** DATE: 1/3/2010

Recall Number: 136678

Description Defect: SOUTHEAST TOYOTA IS RECALLING CERTAIN MODEL YEAR 2005-2011 PASSENGER VEHICLES FOR FAILING TO COMPLY WITH THE REQUIREMENTS OF FEDERAL MOTOR VEHICLE SAFETY STANDARD NO. 110, TIRE SELECTION AND RIMS. THESE VEHICLES WERE SOLD WITHOUT THE REQUISITE LOAD CARRYING CAPACITY MODIFICATION LABELS.

Consequence: A DRIVER MAY OVERLOAD A VEHICLE WHICH MAY INCREASE THE RISK OF A CRASH.

Corrective Action: DEALERS WILL MAIL TO CONSUMERS THE CORRECTED LABEL OR THE CUSTOMER WILL HAVE THE OPTION FOR DEALERS TO INSTALL THE LABEL FREE OF CHARGE. THE SAFETY RECALL BEGAN ON MAY 27, 2010. OWNERS MAY CONTACT SOUTHEAST TOYOTA AT 1-800-301-6859.

CAMPAIGN ID NUMBER: **09V388000** DATE: 1/5/2009

Recall Number: 136680

Description Defect: TOYOTA IS RECALLING CERTAIN MODEL YEAR 2004-2010 PASSENGER VEHICLES. THE ACCELERATOR PEDAL CAN GET STUCK IN THE WIDE OPEN POSITION DUE TO ITS BEING TRAPPED BY AN UNSECURED OR INCOMPATIBLE DRIVER'S FLOOR MAT.

Consequence: A STUCK OPEN ACCELERATOR PEDAL MAY RESULT IN VERY HIGH VEHICLE SPEEDS AND MAKE IT DIFFICULT TO STOP THE VEHICLE, WHICH COULD CAUSE A CRASH, SERIOUS INJURY OR DEATH.

Corrective Action: TOYOTA FILED AN AMENDED DEFECT REPORT ON NOVEMBER 25, 2009, STATING THAT DEALERS WILL MODIFY THE ACCELERATOR PEDAL AND, ON CERTAIN VEHICLES, ALTER THE SHAPE OF THE FLOOR SURFACE UNDER THE PEDAL. THESE CHANGES ADDRESS THE RISK OF PEDAL ENTRAPMENT DUE TO INTERFERENCE WITH THE FLOOR MAT. REDESIGNED ACCELERATOR PEDALS WILL BECOME AVAILABLE BEGINNING IN APRIL 2010 AND DEALERS WILL REPLACE ANY MODIFIED PEDAL WITH THE NEW PEDAL IF DESIRED. ALSO, DEALERS WILL REPLACE ANY GENUINE TOYOTA OR LEXUS ALL-WEATHER FLOOR MATS WITH REDESIGNED ALL-WEATHER MATS, OR REPURCHASE THE PREVIOUS MATS FROM OWNERS WHO DO NOT WANT THE NEW ONES. ADDITIONALLY, SOFTWARE MODIFICATIONS WILL BE INSTALLED ON CAMRY, AVALON AND LEXUS ES 350, IS 350 AND IS 250 MODELS THAT WILL ENSURE THAT THE BRAKE OVERRIDES THE ACCELERATOR IN THE EVENT BOTH BRAKE AND ACCELERATOR PEDALS ARE APPLIED. TOYOTA WILL BEGIN MAILING LETTERS TO OWNERS ON DECEMBER 31, 2009. OWNERS MAY CONTACT TOYOTA AT 1-800-331-4331, LEXUS AT 1-800-255-3987.

Warranty Status



This vehicle is **NOT** currently covered. All warranties have expired.

Below is your default warranty information. This excludes any additional warranty coverage you may have purchased.



Basic new car
warranty
3 years



Powertrain
warranty
5 years



Federal emissions
warranty
8 years

Extend your vehicle warranty



Customers Receive **\$100 OFF** With Purchase

Upcoming Issues

4 items

By analyzing other vehicles of the same year make model our results show you may need the following repairs in the next 12 months. It is recommended that you have these parts inspected by a trusted technician, and replace as needed.

25%

Likelihood of

Replace Coolant Flow Control

Valve

\$417

Cost of repair

\$122 in parts

\$295 in labor



15%

Likelihood of

Replace Catalytic Converter(s)

with new OE Catalytic

Converter(s)

\$2,429

Cost of repair

\$2,327 in parts

\$102 in labor



Extend your vehicle warranty

 Customers Receive **\$100 OFF** With Purchase

Technical Service Bulletins (TSBs)

66 items

A technical service bulletins (TSB) is an advisory issued by an automotive manufacture to its dealership service departments. If your vehicle is still under warranty; you can usually get the related repairs covered

ACCESSORIES AND FLUIDS (2 TOTAL)				
OEM#s	Issue Date	TSB Description	Type	View
SB-0101-11	8/17/2011	T-SB-0101-11: All '83-'12 Toyota Models: Interior Electrical Component Precautions	Accessories and Fluids	View
SB-0006-11	1/6/2011	T-SB-0006-11: 04-11 Applicable Toyota Models: World Standard Automatic Transmission Fluid	Accessories and Fluids	View

BODY (26 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
SB-0057-18	7/6/2018	Immobilizer and Smart Key Reset	Body	View
SB-0304-17	10/27/2017	Replacement Certification Labels and VIN Plates	Body	View
CP-SET013-A110-D	1/16/2015	Safety Recall SET-14A (SET013): 2005-2011 Various Toyota Models; Vehicles equipped with accessory leather seat heaters (Dealer Letter)	Body	View
SB-0185-13	12/19/2013	T-SB-0185-13: All '85-'14 Toyota Models: Wiper Blade Maintenance and Cleaning	Body	View
SB-0142-13	9/12/2013	T-SB-0142-13: '04-'14 Applicable Toyota Models: HVAC Odor Maintenance	Body	View
CP-SET012-A110-D	5/20/2013	Safety Recall 13V-123 (SET012): Certain Toyota and Scion vehicle models interspersed through model years 2008 through 2013; Load Carrying Capacity Label (Dealer Letter)	Body	View
SB-0033-13	2/19/2013	T-SB-0033-13: Applicable Toyota Vehicles: Smart Key Specifications	Body	View
SB-0012-13	1/29/2013	T-SB-0012-13: '01-'14 Applicable Toyota Models: Techstream ECU Flash Reprogramming Procedure	Body	View
SB-0229-12	11/21/2012	T-SB-0229-12: '00-'13 Toyota Models: Flood Damaged Vehicle Inspection & Handling	Body	View
SB-0087-12	6/13/2012	T-SB-0087-12: '01-'13 Applicable Toyota Models: Accelerator Pedal Sensor Assembly Service Precaution	Body	View
CP-SET011-A110-D	3/22/2012	Safety Recall 10V-036 (SET011): Certain Toyota and Scion vehicle models interspersed through model years 2005 through 2011; Load Carrying Capacity Label (Dealer Letter)	Body	View
SB-0188-11	12/7/2011	T-SB-0188-11: '07-'09 Prius: Headlamp Condensation	Body	View
SB-0142-11	9/14/2011	T-SB-0142-11: '04-'09 Prius: Vehicle Returns to Neutral	Body	View
SB-0122-11	9/6/2011	T-SB-0122-11: '98-'12 Applicable Toyota Models: Seat Cover Replacement For Side Airbag Equipped Vehicles	Body	View
SB-0101-11	8/17/2011	T-SB-0101-11: All '83-'12 Toyota Models: Interior Electrical Component Precautions	Body	View

CP-90L-E510-D	4/12/2010	Safety Recall 90L - 2004-2009 Prius: Potential Floor Mat Interference (Technical Instructions)	Body	View
DEALER STOCK VEHICLE INSPECTION GUIDE	2/8/2010	Inspection Guide - CTS Accelerator Pedal Vehicle Stop Delivery	Body	View
SB-0397-09	12/18/2009	T-SB-0397-09 Rev1: '04-'10 Applicable Toyota Models: Carpet Grommet Serviceability	Body	View
SB-0172-09	6/11/2009	T-SB-0172-09: 04-09 Prius: Combination Meter - Intermittent Display	Body	View
SB-0079-09	3/4/2009	T-SB-0079-09: '98-'10 Applicable Toyota Models: Long Term Vehicle Storage Guidelines	Body	View
CP-90L-E110-D	3/1/2009	Safety Recall 90L - 2004-2009 Prius: Potential Floor Mat Interference (Dealer Letter)	Body	View
SB-0315-08	10/16/2008	T-SB-0315-08: 09 Applicable Toyota Models: Toyota Seat Belt Extender	Body	View
SB-0288-08	9/8/2008	T-SB-0288-08 Rev1: '04-'10 Applicable Toyota Models: Front Seat Squeak Noise	Body	View
CP-90L-Z110-D	7/20/1920	Supplemental Information for Safety Recall 90L - Pedal Replacement Process	Body	View
CP-9SL-0001-D	3/12/1920	Vehicle Covered by Safety Recall 90L - PLEASE READ	Body	View
CP-SET013-A510-D	2/16/1920	Safety Recall SET-14A (SET013): 2005-2011 Various Toyota Models; Vehicles equipped with accessory leather seat heaters (Technical Instructions)	Body	View

BRAKE (6 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
CP-ZG1-A110-D	4/19/2016	WEP ZG1: 2006-2007 Highlander HV and 2004-2009 Prius; Extension of Warranty Coverage for Brake Actuator Assembly	Brake	View
SB-0032-16	4/13/2016	T-SB-0032-16: '04-'09 Prius & '06-'09 Highlander HV: ABS Brake Warning Light On	Brake	View
SB-0141-13	9/9/2013	T-SB-0141-13: '90-'14 Applicable Toyota Models: Brake Pedal Force Gauge SST for Parking Brake	Brake	View
SB-0229-12	11/21/2012	T-SB-0229-12: '00-'13 Toyota Models: Flood Damaged Vehicle Inspection & Handling	Brake	View

SB-0174-12	9/17/2012	T-SB-0174-12: '07-'11 Camry HV, '04-'09 Prius: ABS/VSC DTC C1247 - Stroke Sensor Detection Logic Update	Brake	View
SB-0285-09	8/24/2009	T-SB-0285-09: 04-10 Prius: Parking Brake Pedal Pad Feels Loose	Brake	View

COOLING (4 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
SB-0153-13	10/8/2013	T-SB-0153-13: '04-'09 Prius: MIL "ON" DTC P0A80 or P0A7F due to Dust or Debris in the HV Battery Cooling Fan	Cooling	View
SB-0098-13	8/12/2013	T-SB-0098-13: '04-'09 Prius: HV Battery Cooling Fan Maintenance for Severe Usage Vehicles	Cooling	View
CP-C0U-A510-D	1/15/2013	Safety Recall C0U: 2004-2009 Prius; Hybrid Electric Water Pump (Technical Instructions)	Cooling	View
SB-0117-11	9/1/2011	T-SB-0117-11: '01-'11 Applicable Toyota Models: Water Pump Inspection and Diagnostic Tips	Cooling	View

ELECTRICAL (21 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
SB-0057-18	7/6/2018	Immobilizer and Smart Key Reset	Electrical	View
SB-0218-17	5/19/2017	SRS Component Disposal as Hazardous Material Treatment	Electrical	View
SB-0182-17	1/6/2017	Interior Electrical Component Precautions	Electrical	View
SB-0119-15	12/2/2015	T-SB-0119-15: '01-'15 Applicable Toyota Models: High Voltage (HV) Battery Rescue Charge (HEV Workstation / GRX-5100)	Electrical	View
SB-0186-13	12/19/2013	T-SB-0186-13: '04-'09 Prius: HV Inverter Repair Components Available	Electrical	View
SB-0153-13	10/8/2013	T-SB-0153-13: '04-'09 Prius: MIL "ON" DTC P0A80 or P0A7F due to Dust or Debris in the HV Battery Cooling Fan	Electrical	View
CP-ZTV-A110-D	9/30/2013	CSP: ZTV 2004 to Certain 2009 Model Year Prius Vehicles Extension of Warranty Coverage for Combination Meter	Electrical	View

SB-0098-13	8/12/2013	T-SB-0098-13: '04-'09 Prius: HV Battery Cooling Fan Maintenance for Severe Usage Vehicles	Electrical	View
CP-SET009-A510-D	3/1/2013	Safety Recall 13V-014 (SET009) - Certain Toyota vehicle models interspersed through model years 2009 - 2013: Accessory leather seat covers, seat heaters or headrest DVD systems (Technical Instructions	Electrical	View
CP-SET009-A110-D	2/28/2013	Safety Recall 13V-014 (SET009) - Certain Toyota vehicle models interspersed through model years 2009 through 2013: Accessory leather seat covers, seat heaters or headrest DVD systems (Dealer Letter)	Electrical	View
SB-0033-13	2/19/2013	T-SB-0033-13: Applicable Toyota Vehicles: Smart Key Specifications	Electrical	View
SB-0229-12	11/21/2012	T-SB-0229-12: '00-'13 Toyota Models: Flood Damaged Vehicle Inspection & Handling	Electrical	View
SB-0101-11	8/17/2011	T-SB-0101-11: All '83-'12 Toyota Models: Interior Electrical Component Precautions	Electrical	View
SB-0042-11	5/23/2011	T-SB-0042-11: 04-09 Prius: SRS Light "ON" DTC B1821/B1826 Open Front Side Squib Circuit	Electrical	View
CP-ZTN-0001-D	1/10/2011	CSP: HID Headlight Customer Support Program on Certain 2006 through 2009 Model Year Prius Vehicles	Electrical	View
HID Headlight Customer Support Program	3/31/2010	CSP: HID Headlight Customer Support Program on Certain 2006 through 2009 Model Year Prius	Electrical	View
SB-0374-09	11/3/2009	T-SB-0374-09: 06-09 Prius: HID Bulb - Intermittent Operation / Flickering	Electrical	View
SB-0166-09	5/28/2009	T-SB-0166-09: 04-09 Prius: M.I.L. "ON" DTC P0AC0, P0A1F, P0A7F, and/or P0AFA	Electrical	View
SB-0079-09	3/4/2009	T-SB-0079-09: '98-'10 Applicable Toyota Models: Long Term Vehicle Storage Guidelines	Electrical	View
SB-0047-09	1/19/2009	T-SB-0047-09: 06-09 Corolla, Highlander, Matrix, Prius, RAV4, Sienna: IG1 Relay Freezing	Electrical	View
SB-0002-16	1/26/2006	PG001-06: Battery Maintenance for In-Stock Vehicles & Pre-Delivery: All Models & Model Years - OBSOLETE	Electrical	View

EMISSION CONTROL (5 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
-------	------------	-----------------	------	------

SB-0134-16	9/14/2016	Techstream ECU Flash Reprogramming Procedure	Emission Control	View
SB-0054-13	4/23/2013	T-SB-0054-13: '97-'14 Applicable Toyota Models: CA/FED/50 State Certified Emission Control Underhood Labels	Emission Control	View
SB-0012-13	1/29/2013	T-SB-0012-13: '01-'14 Applicable Toyota Models: Techstream ECU Flash Reprogramming Procedure	Emission Control	View
SB-0229-12	11/21/2012	T-SB-0229-12: '00-'13 Toyota Models: Flood Damaged Vehicle Inspection & Handling	Emission Control	View
SB-0064-10	2/4/2010	T-SB-0064-10: 01-11 Applicable Toyota Models: Techstream ECU Flash Reprogramming Procedure	Emission Control	View

EXHAUST (1 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
SB-0229-12	11/21/2012	T-SB-0229-12: '00-'13 Toyota Models: Flood Damaged Vehicle Inspection & Handling	Exhaust	View

FUEL & SPARK (2 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
SB-0033-13	2/19/2013	T-SB-0033-13: Applicable Toyota Vehicles: Smart Key Specifications	Fuel & Spark	View
SB-0229-12	11/21/2012	T-SB-0229-12: '00-'13 Toyota Models: Flood Damaged Vehicle Inspection & Handling	Fuel & Spark	View

HVAC (4 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
CP-SET013-A110-D	1/16/2015	Safety Recall SET-14A (SET013): 2005-2011 Various Toyota Models; Vehicles equipped with accessory leather seat heaters (Dealer Letter)	HVAC	View
SB-0142-13	9/12/2013	T-SB-0142-13: '04-'14 Applicable Toyota Models: HVAC Odor Maintenance	HVAC	View
SB-0229-12	11/21/2012	T-SB-0229-12: '00-'13 Toyota Models: Flood Damaged Vehicle Inspection & Handling	HVAC	View

CP-SET013-A510-D	2/16/1920	Safety Recall SET-14A (SET013): 2005-2011 Various Toyota Models; Vehicles equipped with accessory leather seat heaters (Technical Instructions)	HVAC	View
------------------	-----------	---	------	----------------------

POWERTRAIN (11 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
SB-0186-13	12/19/2013	T-SB-0186-13: '04-'09 Prius: HV Inverter Repair Components Available	Powertrain	View
CP-ELT-A110-D	7/24/2013	CSP ELT: Economic Loss Class Action Settlement (Dealer Letter)	Powertrain	View
SB-0012-13	1/29/2013	T-SB-0012-13: '01-'14 Applicable Toyota Models: Techstream ECU Flash Reprogramming Procedure	Powertrain	View
CP-C0U-A510-D	1/15/2013	Safety Recall C0U: 2004-2009 Prius; Hybrid Electric Water Pump (Technical Instructions)	Powertrain	View
CP-C0U-A110-D	1/9/2013	Safety Recall C0U: 2004-2009 Prius; Hybrid Electric Water Pump (Dealer Letter)	Powertrain	View
SB-0229-12	11/21/2012	T-SB-0229-12: '00-'13 Toyota Models: Flood Damaged Vehicle Inspection & Handling	Powertrain	View
SB-0142-11	9/14/2011	T-SB-0142-11: '04-'09 Prius: Vehicle Returns to Neutral	Powertrain	View
SB-0006-11	1/6/2011	T-SB-0006-11: 04-11 Applicable Toyota Models: World Standard Automatic Transmission Fluid	Powertrain	View
SB-0064-10	2/4/2010	T-SB-0064-10: 01-11 Applicable Toyota Models: Techstream ECU Flash Reprogramming Procedure	Powertrain	View
SB-0166-09	5/28/2009	T-SB-0166-09: 04-09 Prius: M.I.L. "ON" DTC P0AC0, P0A1F, P0A7F, and/or P0AFA	Powertrain	View
SB-0301-08	9/19/2008	T-SB-0301-08: 00-09 Applicable Models: Engine Serial Number Location	Powertrain	View

RECALL (18 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
CP-SET013-A110-D	1/16/2015	Safety Recall SET-14A (SET013): 2005-2011 Various Toyota Models; Vehicles equipped with accessory leather seat heaters (Dealer Letter)	Recall	View
CP-ZTV-	9/30/2013	CSP: ZTV 2004 to Certain 2009 Model Year Prius	Recall	

A110-D		Vehicles Extension of Warranty Coverage for Combination Meter		View
CP-SET012-A110-D	5/20/2013	Safety Recall 13V-123 (SET012): Certain Toyota and Scion vehicle models interspersed through model years 2008 through 2013; Load Carrying Capacity Label (Dealer Letter)	Recall	View
CP-SET009-A510-D	3/1/2013	Safety Recall 13V-014 (SET009) - Certain Toyota vehicle models interspersed through model years 2009 - 2013: Accessory leather seat covers, seat heaters or headrest DVD systems (Technical Instructions)	Recall	View
CP-SET009-A110-D	2/28/2013	Safety Recall 13V-014 (SET009) - Certain Toyota vehicle models interspersed through model years 2009 through 2013: Accessory leather seat covers, seat heaters or headrest DVD systems (Dealer Letter)	Recall	View
CP-C0U-A510-D	1/15/2013	Safety Recall C0U: 2004-2009 Prius; Hybrid Electric Water Pump (Technical Instructions)	Recall	View
CP-C0U-A110-D	1/9/2013	Safety Recall C0U: 2004-2009 Prius; Hybrid Electric Water Pump (Dealer Letter)	Recall	View
CP-C0T-A510-D	11/29/2012	Safety Recall C0T: 2004-2009 Prius; Steering Intermediate Extension Shaft (Technical Instructions)	Recall	View
CP-C0T-A110-D	11/14/2012	Safety Recall C0T: 2004-2009 Prius; Steering Intermediate Extension Shaft (Dealer Letter)	Recall	View
CP-C2T-A110-D	11/14/2012	Safety Recall C0T (C2T - Phase 2) Interim Notification: 2004-2009 Prius; Steering Intermediate Extension Shaft (Dealer Letter)	Recall	View
CP-SET011-A110-D	3/22/2012	Safety Recall 10V-036 (SET011): Certain Toyota and Scion vehicle models interspersed through model years 2005 through 2011; Load Carrying Capacity Label (Dealer Letter)	Recall	View
CP-90L-E510-D	4/12/2010	Safety Recall 90L - 2004-2009 Prius: Potential Floor Mat Interference (Technical Instructions)	Recall	View
HID Headlight Customer Support Program	3/31/2010	CSP: HID Headlight Customer Support Program on Certain 2006 through 2009 Model Year Prius	Recall	View
DEALER STOCK VEHICLE INSPECTION GUIDE	2/8/2010	Inspection Guide - CTS Accelerator Pedal Vehicle Stop Delivery	Recall	View
CP-90L-E110-D	3/1/2009	Safety Recall 90L - 2004-2009 Prius: Potential Floor Mat Interference (Dealer Letter)	Recall	View
CP-90L-Z110-D	7/20/1920	Supplemental Information for Safety Recall 90L - Pedal Replacement Process	Recall	View

CP-9SL-0001-D	3/12/1920	Vehicle Covered by Safety Recall 90L - PLEASE READ	Recall	View
CP-SET013-A510-D	2/16/1920	Safety Recall SET-14A (SET013): 2005-2011 Various Toyota Models; Vehicles equipped with accessory leather seat heaters (Technical Instructions)	Recall	View

STEERING &SUSPENSION (10 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
CP-C0T-A510-D	11/29/2012	Safety Recall C0T: 2004-2009 Prius; Steering Intermediate Extension Shaft (Technical Instructions)	Steering &Suspension	View
SB-0229-12	11/21/2012	T-SB-0229-12: '00-'13 Toyota Models: Flood Damaged Vehicle Inspection &Handling	Steering &Suspension	View
CP-C0T-A110-D	11/14/2012	Safety Recall C0T: 2004-2009 Prius; Steering Intermediate Extension Shaft (Dealer Letter)	Steering &Suspension	View
CP-C2T-A110-D	11/14/2012	Safety Recall C0T (C2T - Phase 2) Interim Notification: 2004-2009 Prius; Steering Intermediate Extension Shaft (Dealer Letter)	Steering &Suspension	View
SB-0187-12	10/4/2012	T-SB-0187-12: 2004-2012 Applicable Models: Tire Repair Resources	Steering &Suspension	View
SB-0145-11	9/28/2011	T-SB-0145-11: '06-'12 Toyota Models: Shock Absorber Replacement Criteria	Steering &Suspension	View
SB-0084-09	3/12/2009	T-SB-0084-09: '04-'09 Applicable Toyota Models: Tire Pressure Monitoring System (TPMS) Tire Registration "Lost Communication With ECU"	Steering &Suspension	View
SB-0391-08	12/24/2008	T-SB-0391-08: 02-09 Toyota Models: Repair Manual Supplement: Vehicle Pulling to One Side	Steering &Suspension	View
SB-0345-08	11/6/2008	T-SB-0345-08: 04-09 Applicable Models: Tire Inflation Pressure Compensation and Adjustment	Steering &Suspension	View
SB-0302-08	9/23/2008	T-SB-0302-08: 07 Applicable Models: Special Service Tools	Steering &Suspension	View

TOOLS &HARDWARE (3 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
-------	------------	-----------------	------	------

SB-0119-15	12/2/2015	T-SB-0119-15: '01-'15 Applicable Toyota Models: High Voltage (HV) Battery Rescue Charge (HEV Workstation / GRX-5100)	Tools &Hardware	View
SB-0014-15	3/27/2015	T-SB-0014-15: '86-'15 Applicable Toyota Models: Reception Diagnosis Using Antenna Test Kit	Tools &Hardware	View
SB-0302-08	9/23/2008	T-SB-0302-08: 07 Applicable Models: Special Service Tools	Tools &Hardware	View

WIPER AND WASHER (1 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
SB-0185-13	12/19/2013	T-SB-0185-13: All '85-'14 Toyota Models: Wiper Blade Maintenance and Cleaning	Wiper and Washer	View

Vehicle Title History

Your title history has been sent. Please check your email.

Ran on August 17, 2021 @ 9:51 PM | [Contact us](#)

Copyright 2021 CarMD Corp