

Premium Vehicle Maintenance Report

for your
2019 FORD FUSION

@ 12,311 miles






Average MPG: 23

Maintenance

20 items

If you have not completed the following items below, completing these services before they are due will help keep your car running smoothly.








This service is due at 20,000 mi










| Service Item (s) | Difficulty | Cost |
|---|---|---|
|  Replace Cabin Filter Buy Online Now |  Repair difficulty | \$79 Cost of repair \$28 in parts \$51 in labor |
| Change Engine Oil and Filter  Engine Oil Buy Online Now  Engine Oil Drain Plug Gasket Buy Online Now |  Repair difficulty | \$97 Cost of repair \$46 in parts \$51 in labor |



Engine Oil Filter

[Buy Online Now](#)


| | | |
|--|--|---|
| <p>Inspect Air Filter</p> | <p>N/A</p> | <p>\$0 Cost of repair \$0 in parts \$0 in labor</p> |
| <p>Inspect Automatic Transmission Fluid Level &Condition</p> |  <p>Repair difficulty</p> | <p>\$10 Cost of repair \$10 in parts \$0 in labor</p> |
| <p>Inspect Battery Performance</p> |  <p>Repair difficulty</p> | <p>\$220 Cost of repair \$220 in parts \$0 in labor</p> |
| <p>Inspect Brake System, Friction Material and Hydraulic System.</p> |  <p>Repair difficulty</p> | <p>\$135 Cost of repair \$135 in parts \$0 in labor</p> |
| <p>Inspect Cooling System</p> |  <p>Repair difficulty</p> | <p>\$37 Cost of repair \$37 in parts \$0 in labor</p> |
| <p>Inspect CV Joints and Boots.</p> |  <p>Repair difficulty</p> | <p>\$262 Cost of repair \$262 in parts \$0 in labor</p> |
| <p>Inspect Driving Hazard Alert System Operation</p> |  <p>Repair difficulty</p> | <p>\$0 Cost of repair \$0 in parts \$0 in labor</p> |
| <p>Inspect Exhaust System</p> |  <p>Repair difficulty</p> | <p>\$25 Cost of repair \$25 in parts \$0 in labor</p> |
| <p>Inspect Fluid Levels</p> | | <p>\$37 Cost of repair</p> |

| | | |
|--|--|--|
| |  Repair difficulty | \$37 in parts \$0 in labor |
| Inspect For Fluid Leaks |  Repair difficulty | \$37 Cost of repair \$37 in parts \$0 in labor |
| Inspect Horn, Lights, A/C & Heater For Proper Operation |  Repair difficulty | \$36 Cost of repair \$36 in parts \$0 in labor |
| Inspect Interior/Exterior Lights & Electrical Components |  Repair difficulty | \$21 Cost of repair \$21 in parts \$0 in labor |
| Inspect Radiator and Condenser |  Repair difficulty | \$242 Cost of repair \$242 in parts \$0 in labor |
| Inspect Steering & Suspension Components |  Repair difficulty | \$55 Cost of repair \$55 in parts \$0 in labor |
| Inspect Tire Wear and Adjust Tire Pressure |  Repair difficulty | \$0 Cost of repair \$0 in parts \$0 in labor |
| Inspect Windshield |  Repair difficulty | \$0 Cost of repair \$0 in parts \$0 in labor |
| Inspect Wiper & Washer System |  Repair difficulty | \$19 Cost of repair \$19 in parts \$0 in labor |
| Rotate Tires, Inspect Tire Wear, and Adjust Tire Pressure. |  Repair difficulty | \$51 Cost of repair \$0 in parts \$51 in labor |

Upcoming Issues

4 items

By analyzing other vehicles of the same year make model our results show you may need the following repairs in the next 12 months. It is recommended that you have these parts inspected by a trusted technician, and replace as needed.



Extend your vehicle warranty

 Customers Receive **\$100 OFF** With Purchase

Technical Service Bulletins (TSBs)

62 items

A technical service bulletins (TSB) is an advisory issued by an automotive manufacture to its dealership service departments. If your vehicle is still under warranty; you can usually get the related repairs covered

ACCESSORIES AND FLUIDS (3 TOTAL)

| OEM#s | Issue Date | TSB Description | Type | View |
|---------|------------|---|------------------------|----------------------|
| 19-2387 | 1/29/2020 | 2018-2019 Edge/MKX/Nautilus/Continental/Fusion/MKZ - 2.7L/3.0L EcoBoost - Oil Pan Leaking - Built On Or Before 15-Aug-2019 | Accessories and Fluids | View |
| 47922 | 6/27/2019 | Various Vehicles - 2.7L/3.0L EcoBoost Engine - Oil Filter Service Tip | Accessories and Fluids | View |
| 47948 | 6/27/2019 | 2010-2019 Various Vehicles - Turbocharged Engines - Oil Supply Filter Replacement When Replacing The Turbocharger Or The Turbocharger Oil Supply Tube | Accessories and Fluids | View |

BODY (16 TOTAL)

| OEM#s | Issue Date | TSB Description | Type | View |
|---------|------------|---|------|----------------------|
| 19-7091 | 1/29/2020 | Various Vehicles - Tape Stripe Concern Analysis | Body | View |
| 19-7092 | 1/29/2020 | Various Vehicles - Glass Concern Analysis | Body | View |
| 48130 | 1/29/2020 | 2010-2020 - Various Vehicles - Glass Hydrofluoric Acid Damage | Body | View |
| 19-7089 | 1/29/2020 | Various Vehicles - Grill Concern Analysis | Body | View |
| 19-7105 | 1/29/2020 | Various Vehicles - Interior Trim Steering Wheel Concern Analysis | Body | View |
| 48441 | 1/29/2020 | 2010-2020 Various Vehicles - Errors Caused By Swapping Modules From Like Vehicles Or Ordering Modules Using Another VIN | Body | View |
| 47765 | 6/27/2019 | 2013-2018 C-MAX, 2013-2019 Fusion Energi, And 2017-2019 Fusion/MKZ Hybrid - Illuminated Malfunction Indicator Lamp (MIL) With DTC P04B5 | Body | View |

| | | | | |
|---------|------------|---|------|----------------------|
| 47752 | 6/27/2019 | 2019 Fusion/Fusion Hybrid/Energi - Premium Or Sony Audio System - Parcel Shelf Air Extractor Grille No Longer Equipped – Built On Or After 04-Jan-2019 | Body | View |
| 47714 | 6/27/2019 | 2018-2019 Fusion 2.0L GTDI and 1.5L GTDI - Delete Engine Beauty Cover | Body | View |
| 18-2386 | 6/27/2019 | 2019 Fusion Energi – Illuminated Malfunction Indicator Lamp (MIL) With Diagnostic Trouble Code (DTC) U301D - Built On Or Before 2-Oct-2018 | Body | View |
| 19-7027 | 6/27/2019 | Parking Aid Sensor Diagnoses With No DTCs Present | Body | View |
| 47843 | 6/27/2019 | 2010-2019 Various Vehicles - Diagnostic Trouble Codes (DTCs) U2100 And/Or U2101 - Programmable Module Installation (PMI) Procedure | Body | View |
| 19-7033 | 6/27/2019 | Various Vehicles - Paint And Bumper Concern Analysis | Body | View |
| 47814 | 6/27/2019 | 2016-2019 Various Vehicles – Front Climate Controlled Seat Inoperative, Buzzing Noise, And/Or Feels Too Warm - Multiple Diagnostic Trouble Codes (DTCs) | Body | View |
| 19-7002 | 6/27/2019 | Various Vehicles - Clock Master | Body | View |
| 47664 | 12/11/2018 | 2018 and 2019 Various Ford Vehicles - Revised Horn System - Horn Tone Different From Prior Model Year(s) | Body | View |

COOLING (2 TOTAL)

| OEM#s | Issue Date | TSB Description | Type | View |
|---------|------------|---|---------|----------------------|
| 19-2375 | 1/29/2020 | 2014-2019 Fusion, 2017-2019 Escape - 1.5L EcoBoost - Low Coolant, White Exhaust Smoke And/Or Illuminated MIL - Built On Or Before 10-Jun-2019 | Cooling | View |
| 47849 | 6/27/2019 | 2014-2019 Fusion And 2017-2019 Escape - 1.5L EcoBoost - Coolant Consumption Information | Cooling | View |

ELECTRICAL (15 TOTAL)

| OEM#s | Issue Date | TSB Description | Type | View |
|---------|------------|--|------------|----------------------|
| 19-7094 | 1/29/2020 | 2012-2020 Plug-In Hybrid And Battery Electric Vehicles - Electric Vehicle Supply Equipment (EVSE) Charge Cord Concern Analysis | Electrical | View |

| | | | | |
|---------|------------|--|------------|----------------------|
| 19-7050 | 1/29/2020 | 2009-2019 FHEV - High Voltage Battery Charging Process | Electrical | View |
| 48123 | 1/29/2020 | 2012-2019 Various Vehicles - Battery Cable Clamp Corrosion Repair | Electrical | View |
| 47790 | 6/27/2019 | 2013-2019 Fusion/MKZ, 2013-2018 C-Max – Hybrid Electric Vehicle (HEV)/Plug-In Hybrid Electric Vehicle (PHEV) – Possible Water Intrusion In Multiple Connectors | Electrical | View |
| 18-2373 | 6/27/2019 | 2012-2018 Focus Electric, 2013-2017 C-Max Energi, 2013-2019 Fusion Energi - HV Battery Does Not Charge Using Second Generation 120-Volt Charge Cord (EVSE) | Electrical | View |
| 19-7023 | 6/27/2019 | LVDS and USB Cable Tester | Electrical | View |
| 19-7042 | 6/27/2019 | Various Vehicles - Exterior Lighting Concern Analysis | Electrical | View |
| 47749 | 6/27/2019 | 2012-2019 Various Vehicles - Smartlink Repairs | Electrical | View |
| 19-2158 | 6/27/2019 | 2017-2019 Fusion/MKZ Hybrid/Energi, 2017-2018 C-Max - Illuminated MIL With DTC P013A - Built On Or Before 27-Jan-2019 | Electrical | View |
| 19-7007 | 6/27/2019 | SYNC 3 Intermittent Blank/Black Screen Diagnostics | Electrical | View |
| 47825 | 6/27/2019 | 2016-2019 Various Vehicles - SYNC 3 - SYNC WiFi Update Message Displayed Every Key Cycle | Electrical | View |
| 19-7002 | 6/27/2019 | Various Vehicles - Clock Master | Electrical | View |
| 18-7070 | 12/12/2018 | HV Battery Charging Process for FHEV Vehicles | Electrical | View |
| 47630 | 12/11/2018 | 2019 Fusion Energi – Illuminated Malfunction Indicator Lamp (MIL) With Diagnostic Trouble Code (DTC) U301D - Built On Or Before 2-Oct-2018 | Electrical | View |
| 47635 | 12/11/2018 | Various Vehicles - Data Link Connector (DLC) Connection - Vehicles Equipped With Gateway Module (GWM) | Electrical | View |

EMISSION CONTROL (1 TOTAL)

| OEM#s | Issue Date | TSB Description | Type | View |
|---------|------------|---|------------------|----------------------|
| 19-7062 | 1/29/2020 | 2013-2019 Various Vehicle - Evaporative Emissions Diagnostics | Emission Control | View |

FUEL & SPARK (2 TOTAL)

| OEM#s | Issue Date | TSB Description | Type | View |
|-------|------------|--|--------------|----------------------|
| 48301 | 1/29/2020 | 2013–2017 C-MAX Energi, 2017–2018 C-MAX Hybrid, 2013-2020 Fusion Energi, 2017-2020 Fusion/MKZ Hybrid - Illuminated MIL With Various DTCs | Fuel & Spark | View |
| 47765 | 6/27/2019 | 2013-2018 C-MAX, 2013-2019 Fusion Energi, And 2017-2019 Fusion/MKZ Hybrid - Illuminated Malfunction Indicator Lamp (MIL) With DTC P04B5 | Fuel & Spark | View |

HVAC (3 TOTAL)

| OEM#s | Issue Date | TSB Description | Type | View |
|-------|------------|---|------|----------------------|
| 48282 | 1/29/2020 | 2015-2020 Various Vehicles - A/C Refrigerant Dye Installed In New Vehicles During Production | HVAC | View |
| 48135 | 1/29/2020 | 2013-2020 Various Vehicles - External Variable Displacement Control (EVDC) A/C Compressor Diagnostic Tool | HVAC | View |
| 47967 | 6/27/2019 | 2013-2019 Various Vehicles - External Variable Displacement Control (EVDC) A/C Compressor Diagnostic Tool | HVAC | View |

POWERTRAIN (16 TOTAL)

| OEM#s | Issue Date | TSB Description | Type | View |
|---------|------------|---|------------|----------------------|
| 48423 | 1/29/2020 | 2015-2020 Various Vehicles - Illuminated Malfunction Indicator Lamp (MIL) With Variable Cam Timing (VCT) DTCs - Diagnostic Information | Powertrain | View |
| 48108 | 1/29/2020 | 2015-2019 Various Vehicles - No Crank - Security Access Error Code 232: Key Table Not Allocated | Powertrain | View |
| 19-2375 | 1/29/2020 | 2014-2019 Fusion, 2017-2019 Escape - 1.5L EcoBoost - Low Coolant, White Exhaust Smoke And/Or Illuminated MIL - Built On Or Before 10-Jun-2019 | Powertrain | View |
| 19-2346 | 1/29/2020 | 2015-2019 Various Vehicles - 2.0L EcoBoost - Coolant In Cylinders, White Exhaust Smoke And/Or Illuminated MIL | Powertrain | View |
| 19-2387 | 1/29/2020 | 2018-2019 Edge/MKX/Nautilus/Continental/Fusion/MKZ - 2.7L/3.0L EcoBoost - Oil Pan Leaking - Built On Or Before 15-Aug-2019 | Powertrain | View |

| | | | | |
|---------|------------|---|------------|----------------------|
| 47971 | 6/27/2019 | 2019 Fusion, 2018-2019 MKZ - 2.0L - Auto Start/Stop - No Auto Restart After An Auto Stop Event With DTC P164C | Powertrain | View |
| 47714 | 6/27/2019 | 2018-2019 Fusion 2.0L GTDI and 1.5L GTDI - Delete Engine Beauty Cover | Powertrain | View |
| 18-2386 | 6/27/2019 | 2019 Fusion Energi – Illuminated Malfunction Indicator Lamp (MIL) With Diagnostic Trouble Code (DTC) U301D - Built On Or Before 2-Oct-2018 | Powertrain | View |
| 47922 | 6/27/2019 | Various Vehicles - 2.7L/3.0L EcoBoost Engine - Oil Filter Service Tip | Powertrain | View |
| 47976 | 6/27/2019 | Various Vehicles - Automatic Transmission - Multi Purpose Grease Application On Torque Converter Pilot Hub And Presence Of Engine And Crank Alignment Dowels | Powertrain | View |
| 47948 | 6/27/2019 | 2010-2019 Various Vehicles - Turbocharged Engines - Oil Supply Filter Replacement When Replacing The Turbocharger Or The Turbocharger Oil Supply Tube | Powertrain | View |
| 47849 | 6/27/2019 | 2014-2019 Fusion And 2017-2019 Escape - 1.5L EcoBoost - Coolant Consumption Information | Powertrain | View |
| 47791 | 6/27/2019 | 2015-2019 Various Vehicles - 2.7L - Illuminated MIL And/Or Wrench Lamp - DTCs P0116, P0117, P0118, P0119, P0217, P0330, P1026, And/Or P130D | Powertrain | View |
| 47632 | 12/11/2018 | 2001-2019 Various Vehicles - 2.0L, 2.3L, And 2.5L 4-Cylinder Engine - Rear Main Seal Kit Tool Usage | Powertrain | View |
| 47700 | 12/11/2018 | 2018-2019 Fusion - 2.0L Hybrid Electric Vehicle (HEV)/Plug-In Hybrid Electric Vehicle (PHEV), 1.5L EcoBoost and 2.5L - Delete Engine Compartment Hood Insulator - Built On Or After 20-Jul-2018 | Powertrain | View |
| 47625 | 12/11/2018 | 2014-2019 Fusion And 2017-2019 Escape - 1.5L EcoBoost - Coolant Consumption Information | Powertrain | View |

STEERING &SUSPENSION (5 TOTAL)

| OEM#s | Issue Date | TSB Description | Type | View |
|---------|------------|--|----------------------|----------------------|
| 47895 | 6/27/2019 | 2015-2019 Various Vehicles - Lack Of Power Steering Assist With DTC C200D - Diagnostic Procedure | Steering &Suspension | View |
| 19-7013 | 6/27/2019 | Various Vehicles - Wheel Concern Analysis General Service Bulletin | Steering &Suspension | View |
| 19-7001 | 6/27/2019 | Tire Pressure Monitoring Systems (TPMS) Identification | Steering &Suspension | View |

| | | | | |
|---------|------------|--|-----------------------|----------------------|
| 19-7008 | 6/27/2019 | Various Vehicles - Diagnostic Trouble Code (DTC) P1635 | Steering & Suspension | View |
| 18-7029 | 12/12/2018 | Various Vehicles - Wheel Concern Analysis General Service Bulletin | Steering & Suspension | View |

TOOLS & HARDWARE (2 TOTAL)

| OEM#s | Issue Date | TSB Description | Type | View |
|-------|------------|---|------------------|----------------------|
| 47632 | 12/11/2018 | 2001-2019 Various Vehicles - 2.0L, 2.3L, And 2.5L 4-Cylinder Engine - Rear Main Seal Kit Tool Usage | Tools & Hardware | View |
| 47635 | 12/11/2018 | Various Vehicles - Data Link Connector (DLC) Connection - Vehicles Equipped With Gateway Module (GWM) | Tools & Hardware | View |

Vehicle Title History

Title history requires a VIN#, rerun your report using your vehicle's VIN# for Vehicle Title Report

Ran on May 11, 2023 @ 8:59 PM | [Contact us](#)

Copyright 2023 CarMD Corp