Premium Vehicle Maintenance Report

for your

2013 DODGE CHALLENGER

@ 24,012 miles

VIN: 2C3CDYAG6DH578881

Average MPG: 21

Maintenance

9 items

If you have not completed the following items below, completing these services before they are due will help keep your car running smoothly.

This service is due at 30,000 mi

Service Item (s)	Difficulty	Cost
 Replace Engine Air Filter Buy Online Now	 Repair difficulty	**$92** Cost of repair $61 in parts $31 in labor
Change Engine Oil and Filter **Engine Oil Filter** Buy Online Now **Engine Oil** Buy Online Now	 Repair difficulty	**$105** Cost of repair $54 in parts $51 in labor
		$186

 Inspect Battery Condition &Charge Buy Online Now	Repair difficulty	Cost of repair $186 in parts $0 in labor
 Inspect Cooling System, Hoses &Clamps Buy Online Now	Repair difficulty	**$42** Cost of repair $42 in parts $0 in labor
Inspect Brake System, Hoses &Disc Pads	Repair difficulty	**$0** Cost of repair $0 in parts $0 in labor
Inspect CV Joints &Boots	N/A	**$0** Cost of repair $0 in parts $0 in labor
Inspect Exhaust System , Catalytic Converter and Heat Shield	Repair difficulty	**$0** Cost of repair $0 in parts $0 in labor
Inspect Transmission Fluid Level &Filter	Repair difficulty	**$0** Cost of repair $0 in parts $0 in labor
Rotate Tires, Inspect Tire Wear, &Adjust Tire Pressure	Repair difficulty	**$61** Cost of repair $0 in parts $61 in labor

Safety Recalls

5 items

Your vehicle has 5 Safety Recalls. These are announcements made by your vehicle's manufacturer that

there is a safety-related problem that needs immediate repair and should be repaired free of charge by your vehicle's dealership.

CAMPAIGN ID NUMBER: **19V018000** DATE: 1/15/2019

Recall Number: 31333

Description Defect: CHRYSLER (FCA US LLC) IS RECALLING CERTAIN 2010 DODGE RAM 3500, RAM 4500/5500, 2010-2011 DODGE DAKOTA, 2010-2014 DODGE CHALLENGER, 2010-2015 DODGE CHALLENGER, CHRYSLER 300, AND 2010-2016 JEEP WRANGLER VEHICLES. UPON DEPLOYMENT OF THE DRIVER'S FRONTAL AIR BAG, EXCESSIVE INTERNAL PRESSURE MAY CAUSE THE INFLATOR TO EXPLODE.

Consequence: IN THE EVENT OF A CRASH NECESSITATING DEPLOYMENT OF THE PASSENGER'S FRONTAL AIR BAG, THE INFLATOR COULD EXPLODE WITH METAL FRAGMENTS STRIKING THE VEHICLE OCCUPANTS POTENTIALLY RESULTING IN SERIOUS INJURY OR DEATH.

Corrective Action: CHRYSLER WILL NOTIFY OWNERS, AND DEALERS WILL REPLACE THE PASSENGER FRONTAL AIR BAG INFLATOR, FREE OF CHARGE. THE RECALL BEGAN FEBRUARY 4, 2019. OWNERS MAY CONTACT CHRYSLER CUSTOMER SERVICE AT 1-800-853-1403. CHRYSLER'S NUMBER FOR THIS RECALL IS V01.

CAMPAIGN ID NUMBER: **18V021000** DATE: 1/9/2018

Recall Number: 31331

Description Defect: CHRYSLER (FCA US LLC) IS RECALLING CERTAIN 2009-2013 JEEP WRANGLER, CHRYSLER 300, DODGE CHALLENGER AND DODGE CHARGER VEHICLES, AND 2009-2011 DODGE DAKOTA VEHICLES SOLD, OR EVER REGISTERED, IN THE STATES OF ALABAMA, CALIFORNIA, FLORIDA, GEORGIA, HAWAII, LOUISIANA, MISSISSIPPI, SOUTH CAROLINA, TEXAS, PUERTO RICO, AMERICAN SAMOA, GUAM, THE NORTHERN MARIANA ISLANDS (SAIPAN), AND THE U.S. VIRGIN ISLANDS OR ZONE A. ADDITIONALLY, CHRYSLER IS RECALLING CERTAIN 2009-2010 RAM 4500 CAB CHASSIS, RAM 5500 CAB CHASSIS, RAM 3500 CAB CHASSIS, JEEP WRANGLER, CHRYSLER 300, DODGE DAKOTA, DODGE CHALLENGER, AND DODGE CHARGER VEHICLES EVER REGISTERED IN THE STATES OF ARIZONA, ARKANSAS, DELAWARE, DISTRICT OF COLUMBIA, ILLINOIS, INDIANA, KANSAS, KENTUCKY, MARYLAND, MISSOURI, NEBRASKA, NEVADA, NEW JERSEY, NEW MEXICO, NORTH CAROLINA, OHIO, OKLAHOMA, PENNSYLVANIA, TENNESSEE, VIRGINIA, AND WEST VIRGINIA OR ZONE B. CHRYSLER IS ALSO RECALLING CERTAIN 2009 RAM 3500, RAM 2500, RAM 4500 CAB CHASSIS, RAM 5500 CAB CHASSIS, DODGE DURANGO, CHRYSLER ASPEN, RAM 3500 CAB CHASSIS, JEEP WRANGLER, CHRYSLER 300, DODGE DAKOTA, DODGE CHALLENGER, AND DODGE CHARGER VEHICLES EVER REGISTERED IN THE STATES OF ALASKA, COLORADO, CONNECTICUT, IDAHO, IOWA, MAINE, MASSACHUSETTS, MICHIGAN, MINNESOTA, MONTANA, NEW HAMPSHIRE, NEW YORK, NORTH DAKOTA, OREGON, RHODE ISLAND, SOUTH DAKOTA, UTAH, VERMONT, WASHINGTON, WISCONSIN, AND WYOMING. IN THE EVENT OF A CRASH NECESSITATING DEPLOYMENT OF THE PASSENGER FRONTAL AIR BAG, THESE PASSENGER AIR BAG INFLATOR MAY EXPLODE DUE TO PROPELLANT DEGRADATION OCCURRING AFTER

LONG-TERM EXPOSURE TO ABSOLUTE HUMIDITY AND TEMPERATURE CYCLING.

Consequence: AN INFLATOR EXPLOSION MAY RESULT IN SHARP METAL FRAGMENTS STRIKING THE DRIVER OR OTHER OCCUPANTS RESULTING IN SERIOUS INJURY OR DEATH.

Corrective Action: CHRYSLER WILL NOTIFY OWNERS, AND DEALERS WILL REPLACE THE PASSENGER FRONTAL AIR BAG INFLATOR, FREE OF CHARGE. THE RECALL BEGAN FEBRUARY 28, 2018. OWNERS MAY CONTACT CHRYSLER CUSTOMER SERVICE AT 1-800-853-1403. CHRYSLER'S NUMBER FOR THIS RECALL IS U03.

CAMPAIGN ID NUMBER: **17V435000** DATE: 1/10/2017

Recall Number: 31334

Description Defect: CHRYSLER (FCA US LLC) IS RECALLING CERTAIN MODEL YEAR 2011-2014 DODGE CHALLENGER, DODGE CHARGER, CHRYSLER 300, DODGE DURANGO, AND 2012-2014 JEEP GRAND CHEROKEE VEHICLES. THE AFFECTED VEHICLES HAVE ELECTRO-HYDRAULIC POWER STEERING (EHPS) AND ARE EQUIPPED WITH A 5.7L OR A 3.6L ENGINE AND A 160, 180 OR 220 AMP ALTERNATOR. IN THE AFFECTED VEHICLES, THE ALTERNATOR MAY SUDDENLY FAIL.

Consequence: IF THE ALTERNATOR FAILS, THE VEHICLE MAY STALL WITHOUT WARNING, INCREASING THE RISK OF A CRASH. THERE IS ALSO THE POSSIBILITY THAT THE ALTERNATOR MAY SHORT CIRCUIT, INCREASING THE RISK OF A FIRE.

Corrective Action: CHRYSLER WILL NOTIFY OWNERS, AND DEALERS WILL INSPECT THE ALTERNATOR AND DEPENDING ON THE PART NUMBER, WILL REPLACE THE ALTERNATOR, IF NECESSARY, FREE OF CHARGE. THE RECALL BEGAN FEBRUARY 12, 2018. OWNERS MAY CONTACT CHRYSLER CUSTOMER SERVICE AT 1-800-853-1403. CHRYSLER'S NUMBER FOR THIS RECALL IS T36.

CAMPAIGN ID NUMBER: **14V634000** DATE: 1/8/2014

Recall Number: 31332

Description Defect: CHRYSLER GROUP LLC (CHRYSLER) IS RECALLING CERTAIN MODEL YEAR 2011-2014 CHRYSLER 300, DODGE CHARGER, CHALLENGER, AND DURANGO; AND 2012-2014 JEEP GRAND CHEROKEE VEHICLES MANUFACTURED APRIL 22, 2010, TO JANUARY 2, 2014, AND EQUIPPED WITH A 3.6L ENGINE AND A 160 AMP ALTERNATOR. IN THE AFFECTED VEHICLES, THE ALTERNATOR MAY SUDDENLY FAIL.

Consequence: IF THE ALTERNATOR FAILS, THE VEHICLE MAY STALL WITHOUT WARNING, INCREASING THE RISK OF A CRASH.

Corrective Action: CHRYSLER HAS NOTIFIED OWNERS, AND DEALERS WILL REPLACE THE ALTERNATOR, FREE OF CHARGE. THE RECALL BEGAN ON FEBRUARY 27, 2015. OWNERS MAY CONTACT CHRYSLER CUSTOMER SERVICE AT 1-800-853-1403. CHRYSLER'S NUMBER FOR THIS RECALL IS P60.

CAMPAIGN ID NUMBER: **13V103000** DATE: 1/21/2013

Recall Number: 31330

Description Defect: CHRYSLER IS RECALLING CERTAIN MODEL YEAR 2013 DODGE CHALLENGER VEHICLES MANUFACTURED FROM DECEMBER 3, 2012, THROUGH JANUARY 24, 2013 AND EQUIPPED WITH A V6 ENGINE. THE BATTERY POSITIVE CABLE AT THE STARTER MOTOR MAY EXPERIENCE AN ELECTRICAL SHORT CIRCUIT TO GROUND.

Consequence: A SHORT CIRCUIT COULD LEAD TO A VEHICLE FIRE.

Corrective Action: CHRYSLER HAS BEGUN NOTIFYING OWNERS AND THEY ARE BEING ADVISED TO IMMEDIATELY REFRAIN FROM DRIVING THEIR VEHICLES AND TO CONTACT THEIR DEALERS. CHRYSLER GROUP FURTHER ADVISES AFFECTED OWNERS NOT TO PARK THEIR VEHICLES IN, OR NEAR, ANY STRUCTURES. DEALERS WILL REPLACE THE UNDER HOOD STARTER CABLE ASSEMBLY, FREE OF CHARGE. THE RECALL NOTIFICATION BEGAN ON MARCH 22, 2013. OWNERS MAY CONTACT CHRYSLER AT 1-800-247-9753.

Warranty Status

This vehicle is covered. If this vehicle has changed hands, the new owner is also covered by this warranty.

Below is your default warranty information. This excludes any additional warranty coverage you may have purchased.

Basic new car warranty	Powertrain warranty	Federal emissions warranty
3 years	5 years	8 years

Extend your vehicle warranty

CarMD Customers Receive $100 OFF With Purchase

Upcoming Issues

4 items

By analyzing other vehicles of the same year make model our results show you may need the following repairs in the next 12 months. It is recommended that you have these parts inspected by a trusted technician, and replace as needed.

14%

Likelihood of

Replace Emission System Integrity Monitor (ESIM)

$123

Cost of repair

$41 in parts

$82 in labor

14%

Likelihood of

Replace Thermostat and Housing Assembly

$178

Cost of repair

$96 in parts

$82 in labor

Repair difficulty

11%

Likelihood of

Replace Ignition Coil(s) and Spark Plug(s)

$388

Cost of repair

$131 in parts

$257 in labor

Repair difficulty

Repair difficulty

11%

Likelihood of

Replace Oil Pressure Switch

$255

Cost of repair

$68 in parts

$187 in labor

Repair difficulty

Extend your vehicle warranty

CarMD Customers Receive $100 OFF With Purchase

Technical Service Bulletins (TSBs)

66 items

A technical service bulletins (TSB) is an advisory issued by an automotive manufacture to its dealership service departments. If your vehicle is still under warranty; you can usually get the related repairs covered

ACCESSORIES AND FLUIDS (3 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
09-003-13	10/26/2013	Pentastar Engine Oil Filter Application Reference	Accessories and Fluids	View
07-004-12 REV. A	11/3/2012	Attention! Release Of New Engine Coolant Organic Additive Technology (OAT)	Accessories and Fluids	View
07-004-12	7/7/2012	Release Of New Organic Additive Technology (OAT)	Accessories	

	Coolant		and Fluids	View

BODY (7 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
04-001-17	3/18/2017	Failure Code Change	Body	View
21-020-16	5/25/2016	Manual Transmission Shifter Noise	Body	View
18-034-14 REV. A	7/15/2014	P0520- Engine Oil Pressure Sensor Circuit	Body	View
23-016-13	4/20/2013	Driver And/Or Passenger Seat Fore/Aft Movement During Acceleration And/Or Braking	Body	View
23-011-13 REV. A	3/8/2013	Passenger Compartment Odor	Body	View
31-002-13	1/31/2013	Blending Clearcoat During The Refinish Process	Body	View
31-001-13	1/11/2013	Overspray Removal	Body	View

BRAKE (1 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
08-043-13 REV. A	7/19/2013	Flash: SRT Auto Transmission, Adding Launch Control Feature	Brake	View

COOLING (2 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
07-004-12 REV. A	11/3/2012	Attention! Release Of New Engine Coolant Organic Additive Technology (OAT)	Cooling	View
07-004-12	7/7/2012	Release Of New Organic Additive Technology (OAT) Coolant	Cooling	View

ELECTRICAL (19 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
04-001-17	3/18/2017	Failure Code Change	Electrical	View
18-050-15 REV. A	7/2/2015	Flash: 3.6L Powertrain Diagnostic And System Enhancements	Electrical	View
18-052-15	7/2/2015	Flash: 5.7L Powertrain Diagnostic And System Enhancements	Electrical	View
18-050-15	6/13/2015	Flash: 3.6L Powertrain Diagnostic And System Enhancements	Electrical	View
21-035-15	5/27/2015	Flash: Transmission Shift Enhancements	Electrical	View
08-024-14	5/9/2014	RHW RHP Radio Software Enhancements	Electrical	View
21-014-14	4/16/2014	Flash: Transmission Shift Enhancements	Electrical	View
08-027-14	3/5/2014	RHR Radio Software Enhancements	Electrical	View
08-010-14	1/30/2014	Cruise Control Slow Or No Response	Electrical	View
08-087-13	11/9/2013	Flash: Audio Enhancement, Reduce Audio Distortion	Electrical	View
08-056-13 REV. A	8/21/2013	Flash: Cluster Incorrectly Displays Suspension And Shifting Track	Electrical	View
08-066-13	8/21/2013	RHR, RHW Or RHP Radio Software Enhancements	Electrical	View
08-061-13	8/9/2013	RBZ Or RHB Radio Software Enhancements	Electrical	View
08-043-13 REV. A	7/19/2013	Flash: SRT Auto Transmission, Adding Launch Control Feature	Electrical	View
08-046-13 REV. A	7/19/2013	Flash: SRT Manual Transmission, Adding Launch Control Feature	Electrical	View
08-033-13	5/11/2013	Flash: Two Or More Speakers Will Mute When Playing Certain Media Sources	Electrical	View

RC-IN18-13	4/1/2013	Safety Recall N18 - Engine Starter Battery Positive Terminal	Electrical	View
RC-N18-13	4/1/2013	Safety Recall N18 Rev. - Engine Starter Battery Positive Terminal	Electrical	View
RC-CN18-13	3/1/2013	SAFETY RECALL N18 - ENGINE STARTER BATTERY POSITIVE TERMINAL	Electrical	View

EMISSION CONTROL (11 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
18-033-17	4/5/2017	Flash: Powertrain Diagnostic And System Improvements	Emission Control	View
04-001-17	3/18/2017	Failure Code Change	Emission Control	View
18-088-16 REV. B	9/17/2016	Flash: Powertrain Diagnostic and System Enhancements	Emission Control	View
18-088-16 REV. A	8/17/2016	Flash: Powertrain Diagnostic And System Improvements	Emission Control	View
18-088-16	7/21/2016	Flash: Powertrain Diagnostic And System Improvements	Emission Control	View
18-084-16	7/15/2016	Flash: 5.7L Diagnostic And System Improvements	Emission Control	View
18-074-15 REV. A	12/8/2015	Flash: 6.4L Powertrain Diagnostic And System Enhancements	Emission Control	View
18-052-15 REV. A	11/21/2015	Flash: 5.7L Powertrain Diagnostic And System Enhancements	Emission Control	View
18-089-15	11/20/2015	Flash: Diagnostic And System Improvements/Enhancements	Emission Control	View
09-002-14	6/10/2014	MIL Illumination: P0300, P0302, P0304 or P0306 (X56 Warranty Extension)	Emission Control	View
18-038-13	9/5/2013	Flash: MIL Illumination P0456- Evap System Small Leak	Emission Control	View

FUEL &SPARK (2 TOTAL)

OEM#s	Issue	TSB Description	Type	View

	Date			
08-032-17	4/11/2017	Fuel Pump Connector Replacement	Fuel &Spark	View
18-007-13 REV. A	3/6/2013	MIL Illumination P0300 and/or Engine Runs Rough With Factory Fill Fuel	Fuel &Spark	View

HVAC (1 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
24 008 18	7/13/2018	A/C Systems Contain Fluorescent Leak Check Dye in Factory Fill	HVAC	View

POWERTRAIN (17 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
18-033-17	4/5/2017	Flash: Powertrain Diagnostic And System Improvements	Powertrain	View
04-001-17	3/18/2017	Failure Code Change	Powertrain	View
18-088-16 REV. B	9/17/2016	Flash: Powertrain Diagnostic and System Enhancements	Powertrain	View
18-088-16 REV. A	8/17/2016	Flash: Powertrain Diagnostic And System Improvements	Powertrain	View
18-050-15	6/13/2015	Flash: 3.6L Powertrain Diagnostic And System Enhancements	Powertrain	View
07-002-15 REV. A	3/31/2015	Idler Pulley Noise During Cold Start	Powertrain	View
07-002-15	1/7/2015	Idler Pulley Noise During Cold Start	Powertrain	View
09-002-14 REV. B	12/15/2014	MIL Illumination: P0300, P0302, P0304 or P0306 (X56 Warranty Extension)	Powertrain	View
09-002-14 REV. A	10/3/2014	MIL Illumination: P0300, P0302, P0304 or P0306 (X56 Warranty Extension)	Powertrain	View
18-034-14 REV. A	7/15/2014	P0520- Engine Oil Pressure Sensor Circuit	Powertrain	View

09-002-14	6/10/2014	MIL Illumination: P0300, P0302, P0304 or P0306 (X56 Warranty Extension)	Powertrain	View
18-034-14	6/6/2014	P0520- Engine Oil Pressure Sensor Circuit	Powertrain	View
18-034-14	6/6/2014	P0520- Engine Oil Pressure Sensor Circuit	Powertrain	View
21-014-14	4/16/2014	Flash: Transmission Shift Enhancements	Powertrain	View
09-003-13	10/26/2013	Pentastar Engine Oil Filter Application Reference	Powertrain	View
08-046-13 REV. A	7/19/2013	Flash: SRT Manual Transmission, Adding Launch Control Feature	Powertrain	View
09-001-13	2/6/2013	Gasoline Engine Diagnostic Inspection Procedure	Powertrain	View

RECALL (3 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
RC-IN18-13	4/1/2013	Safety Recall N18 - Engine Starter Battery Positive Terminal	Recall	View
RC-N18-13	4/1/2013	Safety Recall N18 Rev. - Engine Starter Battery Positive Terminal	Recall	View
RC-CN18-13	3/1/2013	SAFETY RECALL N18 - ENGINE STARTER BATTERY POSITIVE TERMINAL	Recall	View

STEERING &SUSPENSION (6 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
02 008 17	11/1/2017	Servicing Lower Control Arm Inner Pivot Bushings	Steering &Suspension	View
02-001-17 REV. A	4/14/2017	Tension Strut Bushing Replacement	Steering &Suspension	View
02-001-17	1/7/2017	Tension Strut Bushing Replacement	Steering &Suspension	View

22-002-14 REV. A	4/15/2014	Tire Flat Spotting Identification, Prevention and Resolution	Steering &Suspension	View
22-001-14	2/19/2014	Steering Wheel Vibration at Highway Speeds	Steering &Suspension	View
08-010-14	1/30/2014	Cruise Control Slow Or No Response	Steering &Suspension	View

TOOLS &HARDWARE (2 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
31-002-13	1/31/2013	Blending Clearcoat During The Refinish Process	Tools &Hardware	View
31-001-13	1/11/2013	Overspray Removal	Tools &Hardware	View

Vehicle Title History

Your title history has been sent. Please check your email.

Ran on August 13, 2021 @ 12:03 AM | Contact us

Copyright 2021 CarMD Corp