Premium Vehicle Maintenance Report

for your

2014 KIA CADENZA

@ 12,000 miles

VIN: KNALN4D73E5131802

Average MPG: 22

Maintenance

23 items

If you have not completed the following items below, completing these services before they are due will help keep your car running smoothly.

This service is due at 15,000 mi

Service Item (s)	Difficulty	Cost
Replace Cabin Air Filter Buy Online Now	Repair difficulty	**$59** Cost of repair $28 in parts $31 in labor
Change Engine Oil and Filter **Engine Oil** Buy Online Now BIG TIGER PARTS **Engine Oil Filter** Buy Online Now	Repair difficulty	**$100** Cost of repair $49 in parts $51 in labor
		$310 Cost of repair

 Inspect A/C System Buy Online Now	Repair difficulty	$310 in parts $0 in labor
 Inspect Body &Paint for Damages/Corrosion Buy Online Now	Repair difficulty	**$1** Cost of repair $1 in parts $0 in labor
 Inspect Brake System, Friction Material and Hydraulic System. Buy Online Now	Repair difficulty	**$110** Cost of repair $110 in parts $0 in labor
 **Inspect Chassis, Steering, Suspension &Fasteners** Buy Online Now	Repair difficulty	**$40** Cost of repair $40 in parts $0 in labor
BIG TIGER PARTS **Inspect CV Joints and Boots.** Buy Online Now	Repair difficulty	**$690** Cost of repair $690 in parts $0 in labor
 **Inspect Exhaust System** Buy Online Now	Repair difficulty	**$18** Cost of repair $18 in parts $0 in labor
 Inspect Intake System &Engine Air Filter	Repair difficulty	**$17** Cost of repair $17 in parts $0 in labor

Buy Online Now		
Inspect Interior/Exterior Lights &Electrical Components Buy Online Now	Repair difficulty	**$5** Cost of repair $5 in parts $0 in labor
Inspect Radiator and Condenser Buy Online Now	Repair difficulty	**$555** Cost of repair $555 in parts $0 in labor
 Inspect Seat Belts &Related Components Buy Online Now	Repair difficulty	**$327** Cost of repair $327 in parts $0 in labor
 **Inspect Steering &Suspension Components** Buy Online Now	Repair difficulty	**$103** Cost of repair $103 in parts $0 in labor
  Inspect Undercarriage For Leaks, Damage, and Corrosion Buy Online Now	Repair difficulty	**$5** Cost of repair $5 in parts $0 in labor
		$126 Cost of repair

Inspect Vacuum Hoses Buy Online Now	Repair difficulty	$126 in parts $0 in labor
 Check and/or Add Fuel System Additive Buy Online Now	Repair difficulty	**$22** Cost of repair $11 in parts $11 in labor
 Lube Lock Cylinders, Latches, Hinges &Pivots Buy Online Now	Repair difficulty	**$36** Cost of repair $15 in parts $21 in labor
Inspect Cooling System	Repair difficulty	**$28** Cost of repair $28 in parts $0 in labor
Inspect Wiper &Washer System	Repair difficulty	**$7** Cost of repair $7 in parts $0 in labor
Lube Transmission Controls &Linkages	Repair difficulty	**$26** Cost of repair $5 in parts $21 in labor
Lubricate Weatherstripping	Repair difficulty	**$36** Cost of repair $5 in parts $31 in labor
Measure Brake Linings, Rotor Thickness and Runout	Repair difficulty	**$31** Cost of repair $0 in parts $31 in labor
Rotate Tires, Inspect Tire Wear, and Adjust Tire Pressure.	Repair difficulty	**$51** Cost of repair $0 in parts $51 in labor

Safety Recalls

1 items

Your vehicle has 1 Safety Recalls. These are announcements made by your vehicle's manufacturer that there is a safety-related problem that needs immediate repair and should be repaired free of charge by your vehicle's dealership.

CAMPAIGN ID NUMBER: **14V289000** DATE: 1/30/2014

Recall Number: 83326

Description Defect: KIA MOTORS CORPORATION (KIA) IS RECALLING CERTAIN MODEL YEAR 2014 CADENZA VEHICLES MANUFACTURED FEBRUARY 1, 2013, THROUGH AUGUST 27, 2013, AND EQUIPPED WITH 19 NON-CHROME ALUMINUM WHEELS. THE WHEELS ON THE AFFECTED VEHICLES MAY FRACTURE FROM IMPACTS SUCH AS LARGE, DEEP POTHOLES.

Consequence: A WHEEL FRACTURE COULD CAUSE THE CIRCULAR RIM TO SEPARATE, RESULTING IN A LOSS OF TIRE PRESSURE, INCREASING THE RISK OF A CRASH.

Corrective Action: KIA WILL NOTIFY OWNERS, AND DEALERS WILL REPLACE THE WHEELS WITH NEW WHEELS, FREE OF CHARGE. THE RECALL BEGAN IN JUNE 2014. OWNERS MAY CONTACT KIA CUSTOMER SERVICE AT 1-800-333-4542. KIA'S NUMBER FOR THIS RECALL IS SC107.

Warranty Status

This vehicle is covered. If this vehicle has changed hands, the new owner is NOT covered by this warranty.

Below is your default warranty information. This excludes any additional warranty coverage you may have purchased.

Basic new car warranty
5 years

Powertrain warranty
10 years

Federal emissions warranty
8 years

Extend your vehicle warranty

CarMD Customers Receive $100 OFF With Purchase

Upcoming Issues

4 items

By analyzing other vehicles of the same year make model our results show you may need the following repairs in the next 12 months. It is recommended that you have these parts inspected by a trusted technician, and replace as needed.

32%	31%
Likelihood of	Likelihood of
Inspect for Loose Fuel Cap and Tighten or Replace as Necessary	**Replace Manifold Absolute Pressure (MAP) Sensor**
$0	**$208**
Cost of repair	Cost of repair
$0 in parts	$157 in parts
$0 in labor	$51 in labor

Repair difficulty

20%

Likelihood of

Replace Ignition Coil(s)

$213

Cost of repair

$102 in parts

$111 in labor

Repair difficulty

Repair difficulty

7%

Likelihood of

Replace ABS Wheel Speed Sensor

$201

Cost of repair

$130 in parts

$71 in labor

Repair difficulty

Extend your vehicle warranty

CarMD Customers Receive $100 OFF With Purchase

Technical Service Bulletins (TSBs)

46 items

A technical service bulletins (TSB) is an advisory issued by an automotive manufacture to its dealership service departments. If your vehicle is still under warranty; you can usually get the related repairs covered

ACCESSORIES AND FLUIDS (1 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
080	12/1/2015	Kia Global Information System (KGIS) - Search Enhancement and New Features (GEN 080)	Accessories and Fluids	View

BODY (8 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
4576	7/1/2018	BSD/BCW Troubleshooting Guide &Angle Measurement (SST 060)	Body	View
3827	11/1/2016	Mandatory Replacement of Locking/Security Hardware (GEN085)	Body	View
3246	10/1/2015	Pre-Delivery Inspection (PDI) and Owner Delivery Folder Program (GEN 078)	Body	View
3029	4/1/2015	Standard KDS Reflash Procedure (SST 037)	Body	View
2794	10/1/2014	General Information and Diagnosis for Smart Key Fob Systems and Start/Stop Buttons (GEN 057)	Body	View
2660	7/1/2014	New Vehicle Inventory Maintenance and Best Practices (GEN 070) (REV 1)	Body	View
2565	4/1/2014	Special Service Tool for Hood Release Lever Removal (SST 033)	Body	View
580	11/1/2009	Pre-Delivery Inspection (PDI) and Owner Delivery Folder Program (Closed)	Body	View

ELECTRICAL (17 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
4844	2/1/2019	Introduction to Pin Tension Gauge (SST062)	Electrical	View
4734	11/1/2018	Kia Smart Battery Tester v1.8 Replacement (SST061)	Electrical	View
4527	5/1/2018	Kia Smart Battery Tester User Guide (SST057) (Rev 1)	Electrical	View
4520	5/1/2018	Kia Smart Battery Tester Introduction (SST059)	Electrical	View
3851	11/1/2016	Audio Update Module (AUM) Firmware Update (SST049)	Electrical	View
082	6/1/2016	Replacement Wire Repair Connectors (GEN 082)	Electrical	View
083	6/1/2016	New Kia Wire Harness Repair Kit IV (GEN 083)	Electrical	View

3752	2/6/2016	Navigation Software Upgrade - No Sirius Traffic Display (ELE117)	Electrical	View
095	11/1/2015	Sirius XM Satellite Radio Troubleshooting (ELE 095)	Electrical	View
3213	8/1/2015	Identifying Head Unit Software Version For Direct Exchange (ELE 091)	Electrical	View
3162	7/1/2015	"C" State Error Message on Version 8.5 Map Update	Electrical	View
3129	6/1/2015	Kia Universal Multimedia Interface Test Update Kit (SST 038)	Electrical	View
3142	6/1/2015	Navigation Head Unit SD Card Replacement (ELE 089)	Electrical	View
2794	10/1/2014	General Information and Diagnosis for Smart Key Fob Systems and Start/Stop Buttons (GEN 057)	Electrical	View
2660	7/1/2014	New Vehicle Inventory Maintenance and Best Practices (GEN 070) (REV 1)	Electrical	View
2525	2/24/2014	Navigation Unit Software Update (ELE 062)	Electrical	View
2395	11/1/2013	Introduction to T Connectors (ELE 064)	Electrical	View

EMISSION CONTROL (3 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
4974	5/31/2019	New Web Based KDS IUMPR Data Collection (SST064)	Emission Control	View
3029	4/1/2015	Standard KDS Reflash Procedure (SST 037)	Emission Control	View
3028	4/1/2015	Standard GDS Reflash Procedure (SST 036)	Emission Control	View

EXHAUST (1 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
4974	5/31/2019	New Web Based KDS IUMPR Data Collection	Exhaust	

		(SST064)	View

FUEL &SPARK (2 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
2794	10/1/2014	General Information and Diagnosis for Smart Key Fob Systems and Start/Stop Buttons (GEN 057)	Fuel &Spark	View
2342	9/1/2013	MIL On With DTC P0087 -Diagnosis and Repair (FUE 026)	Fuel &Spark	View

HVAC (1 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
4129	2/1/2018	Servicing AC Systems Using the Mahle ACX1299 (SST054) (Rev 2)	HVAC	View

POWERTRAIN (5 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
4648	9/1/2018	Engine Replacement Practices Reminder (ENG190)	Powertrain	View
3233	9/1/2015	Chatter/Rattling Noise From Engine After Cold Soak (ENG 148)	Powertrain	View
2787	10/1/2014	Inhibitor Switch Diagnosis Information (TRA 055)	Powertrain	View
2593	5/1/2014	6 SPD A/T Solenoid Replacement - DTC P0741 (TRA 051)	Powertrain	View
3192	2/11/2013	TCM Upgrade - Shift Logic Improvement (TRA 056)	Powertrain	View

STEERING &SUSPENSION (4 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View

3686	8/1/2016	MDPS Flexible Coupling Replacement (CHA074) (Rev 1)	Steering &Suspension	View
2660	7/1/2014	New Vehicle Inventory Maintenance and Best Practices (GEN 070) (REV 1)	Steering &Suspension	View
2606	5/1/2014	MDPS Flexible Coupling Replacement (CHA 044) (REV 1)	Steering &Suspension	View
4737	2/1/2010	Steering Gear Yoke Plug and Assembly Replacement (CHA091)	Steering &Suspension	View

TOOLS &HARDWARE (23 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
4974	5/31/2019	New Web Based KDS IUMPR Data Collection (SST064)	Tools &Hardware	View
4844	2/1/2019	Introduction to Pin Tension Gauge (SST062)	Tools &Hardware	View
4734	11/1/2018	Kia Smart Battery Tester v1.8 Replacement (SST061)	Tools &Hardware	View
4576	7/1/2018	BSD/BCW Troubleshooting Guide &Angle Measurement (SST 060)	Tools &Hardware	View
4527	5/1/2018	Kia Smart Battery Tester User Guide (SST057) (Rev 1)	Tools &Hardware	View
4520	5/1/2018	Kia Smart Battery Tester Introduction (SST059)	Tools &Hardware	View
4477	3/1/2018	KVID App Installation on Existing KDS Tablets (SST058)	Tools &Hardware	View
4129	2/1/2018	Servicing AC Systems Using the Mahle ACX1299 (SST054) (Rev 2)	Tools &Hardware	View
4455	2/1/2018	KDS VCI-II Screws and/or Case Replacement	Tools &Hardware	View
3999	3/1/2017	Midtronics GR8-1299 Software Update (SST052)	Tools &Hardware	View
3882	12/1/2016	Introduction to the New KDS Trolley and KDS Magnetic Tablet Holder (SST050) (Rev 1)	Tools &Hardware	View
3851	11/1/2016	Audio Update Module (AUM) Firmware Update	Tools	

		(SST049)	&Hardware	View
3709	9/1/2016	Introduction to KDS Mobile and Visual Support Systems (SST046)	Tools &Hardware	View
083	6/1/2016	New Kia Wire Harness Repair Kit IV (GEN 083)	Tools &Hardware	View
080	12/1/2015	Kia Global Information System (KGIS) - Search Enhancement and New Features (GEN 080)	Tools &Hardware	View
041	10/1/2015	KDS - Audio Update Module (AUM) (SST041)	Tools &Hardware	View
3246	10/1/2015	Pre-Delivery Inspection (PDI) and Owner Delivery Folder Program (GEN 078)	Tools &Hardware	View
3129	6/1/2015	Kia Universal Multimedia Interface Test Update Kit (SST 038)	Tools &Hardware	View
3142	6/1/2015	Navigation Head Unit SD Card Replacement (ELE 089)	Tools &Hardware	View
3029	4/1/2015	Standard KDS Reflash Procedure (SST 037)	Tools &Hardware	View
3028	4/1/2015	Standard GDS Reflash Procedure (SST 036)	Tools &Hardware	View
2762	10/1/2014	Kia Diagnostic System / Dealership Wi-Fi Requirements (SST 034)	Tools &Hardware	View
2770	10/1/2014	Kia Diagnostic System (KDS) Requirements (SST 035)	Tools &Hardware	View

Vehicle Title History

Your title history has been sent. Please check your email.

Ran on July 28, 2021 @ 8:40 PM | Contact us

Copyright 2021 CarMD Corp