Premium Vehicle Maintenance Report

for your

2011 CADILLAC CTS

@ 21,890 miles

VIN: 1G6DH8EY1B0113579

Average MPG: 22

Maintenance

16 items

If you have not completed the following items below, completing these services before they are due will help keep your car running smoothly.

This service is due at 22,500 mi

Service Item (s)	Difficulty	Cost
 **Replace Cabin Filter** Buy Online Now	 Repair difficulty	**$106** Cost of repair $55 in parts $51 in labor
Change Engine Oil and Filter **Engine Oil Filter** Buy Online Now **Engine Oil** Buy Online Now	 Repair difficulty	**$129** Cost of repair $78 in parts $51 in labor
		$136

Inspect Accelerator Pedal Position Assembly Buy Online Now	Repair difficulty	Cost of repair $136 in parts $0 in labor
 **Inspect Air Filter** Buy Online Now	Repair difficulty	**$34** Cost of repair $34 in parts $0 in labor
 Inspect Automatic Shift Lock Buy Online Now	Repair difficulty	**$24** Cost of repair $24 in parts $0 in labor
 **Inspect Brake System, Friction Material &Hydraulic System** Buy Online Now	Repair difficulty	**$209** Cost of repair $209 in parts $0 in labor
 Inspect Cooling System Buy Online Now	Repair difficulty	**$18** Cost of repair $18 in parts $0 in labor
Inspect Exhaust System , Catalytic Converter and Heat Shield Buy Online Now	Repair difficulty	**$10** Cost of repair $10 in parts $0 in labor
		$27 Cost of repair

Inspect Fuel System Buy Online Now	Repair difficulty	$27 in parts $0 in labor
Inspect Parking Brake Operation &Tension Buy Online Now	Repair difficulty	**$71** Cost of repair $71 in parts $0 in labor
 Inspect Wiper &Washer System Buy Online Now	Repair difficulty	**$8** Cost of repair $8 in parts $0 in labor
 Lube Lock Cylinders, Latches, Hinges &Pivots Buy Online Now	Repair difficulty	**$36** Cost of repair $15 in parts $21 in labor
Inspect All Fluids and Correct Level	Repair difficulty	**$11** Cost of repair $11 in parts $0 in labor
Inspect SRS System	Repair difficulty	**$0** Cost of repair $0 in parts $0 in labor
Inspect Starter Safety Switch	Repair difficulty	**$24** Cost of repair $24 in parts $0 in labor
Rotate Tires, Inspect Tire Wear, &Adjust Tire Pressure	Repair difficulty	**$41** Cost of repair $0 in parts $41 in labor

Safety Recalls

3 items

Your vehicle has 3 Safety Recalls. These are announcements made by your vehicle's manufacturer that there is a safety-related problem that needs immediate repair and should be repaired free of charge by your vehicle's dealership.

CAMPAIGN ID NUMBER: **14V394000** DATE: 1/2/2014

Recall Number: 15870

Description Defect: THIS DEFECT CAN AFFECT THE SAFE OPERATION OF THE AIRBAG SYSTEM. UNTIL THIS RECALL IS PERFORMED, CUSTOMERS SHOULD REMOVE ALL ITEMS FROM THEIR KEY RINGS, LEAVING ONLY THE IGNITION KEY. THE KEY FOB (IF APPLICABLE), SHOULD ALSO BE REMOVED FROM THE KEY RING. GENERAL MOTORS LLC (GM) NOTIFIED THE AGENCY ON JULY 2, 2014 THAT THEY ARE RECALLING 554,328 MODEL YEAR 2003-2014 CADILLAC CTS VEHICLES MANUFACTURED AUGUST 16, 2001, TO APRIL 28, 2014, AND 2004-2006 CADILLAC SRX VEHICLES MANUFACTURED MARCH 20, 2003, TO AUGUST 11, 2006. IN THESE MODELS, THE WEIGHT ON THE KEY RING AND/OR ROAD CONDITIONS OR SOME OTHER JARRING EVENT MAY CAUSE THE IGNITION SWITCH TO MOVE OUT OF THE RUN POSITION, TURNING OFF THE ENGINE.

Consequence: IF THE KEY IS NOT IN THE RUN POSITION, THE AIR BAGS MAY NOT DEPLOY IF THE VEHICLE IS INVOLVED IN A CRASH, INCREASING THE RISK OF INJURY.

Corrective Action: GM WILL NOTIFY OWNERS, AND DEALERS WILL INSTALL TWO KEY RINGS AND AN INSERT IN THE KEY SLOT OR A COVER OVER THE KEY HEAD ON ALL IGNITION KEYS, FREE OF CHARGE. THE RECALL BEGAN ON SEPTEMBER 15, 2014. OWNERS MAY CONTACT CADILLAC CUSTOMER SERVICE AT 1-800-458-8006. GM'S NUMBER FOR THIS RECALL IS 14172.

CAMPAIGN ID NUMBER: **14V341000** DATE: 1/19/2014

Recall Number: 15868

Description Defect: GENERAL MOTORS LLC (GM) IS RECALLING CERTAIN MODEL YEAR 2011 CADILLAC CTS VEHICLES MANUFACTURED OCTOBER 18, 2010, TO JUNE 2, 2011. IN THE AFFECTED VEHICLES, VIBRATIONS FROM THE DRIVE SHAFT MAY CAUSE THE VEHICLE'S ROLL OVER SENSOR TO COMMAND THE ROOF RAIL AIR BAGS TO DEPLOY.

Consequence: IF THE ROOF RAIL AIR BAGS DEPLOY UNEXPECTEDLY, THERE IS AN INCREASED RISK OF CRASH AND INJURY TO THE OCCUPANTS.

Corrective Action: GM WILL NOTIFY OWNERS, AND DEALERS WILL REPLACE THE REAR DRIVE SHAFT ASSEMBLY, FREE OF CHARGE. GENERAL MOTORS DISTRIBUTED AN INTERIM LETTER TO OWNERS ON AUGUST 27, 2014. OWNERS MAY CONTACT

CADILLAC CUSTOMER SERVICE AT 1-800-458-8006. GM'S NUMBER FOR THIS RECALL IS 14233.

CAMPAIGN ID NUMBER: **14V341000** DATE: 1/19/2014

Recall Number: 15869

Description Defect: GENERAL MOTORS LLC (GM) IS RECALLING CERTAIN MODEL YEAR 2011 CADILLAC CTS VEHICLES MANUFACTURED OCTOBER 18, 2010, TO JUNE 2, 2011. IN THE AFFECTED VEHICLES, VIBRATIONS FROM THE DRIVE SHAFT MAY CAUSE THE VEHICLE'S ROLL OVER SENSOR TO COMMAND THE ROOF RAIL AIR BAGS TO DEPLOY.

Consequence: IF THE ROOF RAIL AIR BAGS DEPLOY UNEXPECTEDLY, THERE IS AN INCREASED RISK OF CRASH AND INJURY TO THE OCCUPANTS.

Corrective Action: GM WILL NOTIFY OWNERS, AND DEALERS WILL REPLACE THE REAR DRIVE SHAFT ASSEMBLY, FREE OF CHARGE. GENERAL MOTORS DISTRIBUTED AN INTERIM LETTER TO OWNERS ON AUGUST 27, 2014. OWNERS MAY CONTACT CADILLAC CUSTOMER SERVICE AT 1-800-458-8006. GM'S NUMBER FOR THIS RECALL IS 14233.

Warranty Status

This vehicle is NOT currently covered. All warranties have expired.

Below is your default warranty information. This excludes any additional warranty coverage you may have purchased.

Basic new car warranty
4 years

Powertrain warranty
5 years

Federal emissions warranty
8 years

Extend your vehicle warranty

CarMD Customers Receive $100 OFF With Purchase

Upcoming Issues

4 items

By analyzing other vehicles of the same year make model our results show you may need the following repairs in the next 12 months. It is recommended that you have these parts inspected by a trusted technician, and replace as needed.

21%

Likelihood of

Replace Evaporative Emissions (EVAP) Purge Solenoid

$159

Cost of repair

$57 in parts

$102 in labor

17%

Likelihood of

Replace Evaporative Emissions (EVAP) Purge Control Valve

$99

Cost of repair

$58 in parts

$41 in labor

Repair difficulty	Repair difficulty
9% Likelihood of **Replace Fuel Injector(s)** **$494** Cost of repair $159 in parts $335 in labor Repair difficulty	**9%** Likelihood of **Replace Catalytic Converter(s) with new OE Catalytic Converter(s)** **$1,888** Cost of repair $1,569 in parts $319 in labor Repair difficulty

Extend your vehicle warranty

CarMD Customers Receive $100 OFF With Purchase

Technical Service Bulletins (TSBs)

906 items

A technical service bulletins (TSB) is an advisory issued by an automotive manufacture to its dealership service departments. If your vehicle is still under warranty; you can usually get the related repairs covered

ACCESSORIES AND FLUIDS (44 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
PIP5540E	10/14/2019	Diagnostic Tip: Poor Engine Performance Or CEL On In Cold Ambient Temperatures On Vehicles Equipped With Turbocharged Gasoline Engines May Set One Or More Of The Following DTCs P0299 P2227	Accessories and Fluids	View
01-06-01-011K	10/9/2019	Information on Engine Oil Consumption Guidelines	Accessories and Fluids	View
PIT3099S	9/5/2019	Concerns or Questions Regarding Installation of	Accessories	

		Dealer Installed Accessories	and Fluids	View
PIP4158H	8/7/2019	Low Oil Pump Pressure Due To Sticking Oil Pressure Relief Valve	Accessories and Fluids	View
PIT3099R	7/10/2019	Concerns Or Questions Regarding Installation Of Dealer Installed Accessories	Accessories and Fluids	View
PIP5540D	2/19/2019	Diagnostic Tip: Poor Engine Performance Or CEL On In Cold Ambient Temperatures On Vehicles Equipped With Turbocharged Gasoline Engines May Set One Or More Of The Following DTCs P0299 P2227	Accessories and Fluids	View
12-06-01-003C	2/13/2019	Information for Repairing Engine Front Cover Oil Leak, Sealing Surface Preparation and Applying RTV Sealant	Accessories and Fluids	View
PIP5540C	1/11/2019	Poor Engine Performance Or CEL On In Cold Ambient Temperatures On Vehicles Equipped With Turbocharged Gasoline Engines May Set One Or More Of The Following DTCs P0299 P2227	Accessories and Fluids	View
PIP5540B	12/6/2018	Poor Engine Performance Or CEL On In Cold Ambient Temperatures On Vehicles Equipped With Turbocharged Gasoline Engines May Set One Or More Of The Following DTCs P0171 P0172 P0299 P2227	Accessories and Fluids	View
00-00-89-027J	3/16/2018	Eliminating Unwanted Odors in Vehicles	Accessories and Fluids	View
09-00-89-002N	10/7/2016	Properly Maintaining Vehicles in Dealer Inventory	Accessories and Fluids	View
PIP5282A	9/30/2016	Engine Oil Life Monitor Operation Calculation	Accessories and Fluids	View
09-00-89-016E	9/27/2016	Warranty Administration - Labor Operation 0600014 - Suspected Tampering or Vehicle Modifications	Accessories and Fluids	View
05-00-89-072D	9/1/2016	Fuel and Oil Additives - Facts and Myths - Maximizing Gasoline Fuel Economy	Accessories and Fluids	View
12-08-132-001D	5/13/2016	Accessory Power Outlet and Trailer Lighting Fuse Replacement - Use Global Labor Operation 5430130 Fuse Replacement	Accessories and Fluids	View
PIP3140G	5/10/2016	Abnormal Noise And Or Vibration While Driving Due To Non-GM Aftermarket Accessory	Accessories and Fluids	View
16-NA-117	4/12/2016	Information Regarding Magnetic Drain Plugs	Accessories and Fluids	View
02-08-98-002F	2/5/2016	Hem Flange Rust Repair	Accessories and Fluids	View
PIP5318	10/31/201	P0300 Misfire At Speeds Of 70 MPH - 3rd Gear - 3500	Accessories	

	5	â€“ 4500 RPMS	and Fluids	View
01-06-01-011I	10/31/2015	Information on Engine Oil Consumption Guidelines	Accessories and Fluids	View
06-00-89-031C	10/31/2015	Engine and Automatic Transmission/Transaxle Identification	Accessories and Fluids	View
15-NA-017	10/31/2015	Warranty Administration - Causal Part Requirements for Transactions Submitted to GM for Payment	Accessories and Fluids	View
15-00-90-001	10/31/2015	Diagnostic Tips for Preventing Oil Leaks After Changing Oil and Filter	Accessories and Fluids	View
10-04-20-001F	10/31/2015	Rear Axle Clunk and/or Chatter Type Noise on Turns (Drain/Refill Rear Differential Fluid)	Accessories and Fluids	View
99-01-39-004H	9/12/2015	Air Conditioning Odor (Install Evaporator Core Dryer Kit and Apply Cooling Coil Coating)	Accessories and Fluids	View
00-00-89-027I	9/5/2015	Eliminating Unwanted Odors in Vehicles	Accessories and Fluids	View
06-00-89-029L	7/25/2015	Interior Cleaning - Instrument Panel (IP), Hard or Plastic Surfaces, Seats, Carpet, Leather, Vinyl, Fabric Cleaner, Stain Remover, Restorer - Product Availability	Accessories and Fluids	View
06-00-89-029K	7/18/2015	Interior Cleaning - Instrument Panel (IP), Hard or Plastic Surfaces, Seats, Carpet, Leather, Vinyl, Fabric Cleaner, Stain Remover, Restorer - Product Availability	Accessories and Fluids	View
09-00-89-002K	6/6/2015	Properly Maintaining Vehicles in Dealer Inventory	Accessories and Fluids	View
12-06-01-008B	3/14/2015	Unscheduled Supplemental Services (Including Flushing Services and Additives) and Proper Use of GM Simplified Maintenance Schedules (Canada Only)	Accessories and Fluids	View
PIC4921B	2/15/2014	Paint Color Codes For Special Edition Vehicles (Mary Kay or Neiman Marcus)	Accessories and Fluids	View
11-00-89-002B	1/24/2014	GM Accessories - Dealer-Installed, Repaired or Replaced During Warranty Coverage Period	Accessories and Fluids	View
07-08-49-020H	6/7/2013	IPC Odometer Programming Method Quick Reference Guide	Accessories and Fluids	View
09-00-89-002H	1/14/2012	Properly Maintaining Vehicles in Dealer Inventory	Accessories and Fluids	View
06-00-89-029I	1/13/2012	Interior Cleaning - Instrument Panel (IP), Hard or Plastic Surfaces, Seats, Carpet, Leather, Vinyl, Fabric Cleaner, Stain Remover, Restorer - Product Availability	Accessories and Fluids	View

09-00-89-002I	1/13/2012	Properly Maintaining Vehicles in Dealer Inventory	Accessories and Fluids	View
10-00-89-017H	7/22/2011	Car and Truck Fix it Right the First Time Issues	Accessories and Fluids	View
11-00-90-001	3/14/2011	Global Information for GM dexos 1 and GM dexos 2 Engine Oil Specifications for Spark Ignited and Diesel Engines, Available Licensed Brands, and Service Fill for Adding or Complete Oil Change	Accessories and Fluids	View
11-00-89-002	3/8/2011	GM Accessories - Dealer-Installed, Repaired or Replaced During Warranty Coverage Period	Accessories and Fluids	View
09-00-89-002D	2/24/2011	Properly Maintaining Vehicles in Dealer Inventory	Accessories and Fluids	View
04-06-04-054B	11/18/2010	Information - Non-GM Parts and Accessories (Aftermarket)	Accessories and Fluids	View
04-06-01-029E	4/29/2010	Unnecessary Flushing Services, Additive Recommendations and Proper Utilization of GM Simplified Maintenance Schedule to Enhance Customer Service Experience	Accessories and Fluids	View
05-03-10-003F	4/27/2010	Low Tire Pressure, Leaking Cast Aluminum Wheels (Repair with Adhesive Sealant)	Accessories and Fluids	View
09-03-16-002A	4/27/2010	Dealership Service Consultant Procedure as Vehicle Comes into Service Drive for Tire Pressure Monitor (TPM) System Message, Light and Customer Information	Accessories and Fluids	View

BODY (371 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
20-NA-016	1/21/2020	Warranty Administration - Repurchase Vehicle Dealer Processing Fee Labor Operation and Submission Guidelines (U.S. ONLY)	Body	View
PI0592F	12/12/2019	Service Programming System (SPS) Errors (E4398, E4399, E4403, M4404, M4413, M6954, M6955, E4414, E4423, E4491 or E6961)	Body	View
08-00-89-014F	11/25/2019	Use of Dealer Case Management (DCM) and Technician Preparedness for Contacting U.S. Technical Assistance (TAC)	Body	View
10-00-89-006G	10/16/2019	Information for Dealers on How to Submit a Product Information Report (PIR) (Canada Only)	Body	View
PIP5632B	9/6/2019	Procedure For Attaching GDS2 Session Logs To Technical Assistance Cases Using Dealer Case Management (US Dealers Only).	Body	View

PIT5705	9/5/2019	Creak/Pop Noise From Front Over Bumps	Body	View
13-00-89-008B	8/19/2019	GM Wiring Repair Strategy Information	Body	View
10-08-45-001G	6/26/2019	Information for Electrical Ground Repair - Use New Replacement Fasteners with Conductive Finish	Body	View
06-08-47-001O	6/19/2019	Warranty Administration - Warranty SPS Control Module Reprogramming	Body	View
08-00-89-014E	5/2/2019	Use of Dealer Case Management (DCM) and Technician Preparedness for Contacting U.S. Technical Assistance (TAC)	Body	View
PIC5260C	4/23/2019	Intermittent Sunroof Operation, Bind, Noise, Auto-reverse, and/or Water Leaks	Body	View
PIC6042B	4/10/2019	Diagnostic Tip - Replacement of Manual Shift Paddles on Steering Wheel	Body	View
10-08-110-001H	4/1/2019	Information on Proper Use of Floor Mats	Body	View
99-00-89-019Q	3/28/2019	Global Warranty Management (GWM) Warranty Parts Center (WPC) Parts Return Program Information	Body	View
03-00-89-006Q	3/25/2019	New Vehicle Pre-Delivery Inspection (PDI) - Delivering Quality Vehicles and Generating Higher CSi Scores	Body	View
06-00-89-029O	3/25/2019	Interior Cleaning - Instrument Panel (IP), Hard or Plastic Surfaces, Seats, Carpet, Leather, Vinyl, Fabric Cleaner, Stain Remover, Restorer - Product Availability	Body	View
10-08-110-001G	3/22/2019	Information on Proper Use of Floor Mats	Body	View
04-00-89-053G	3/22/2019	Engineering Information (EI) Process	Body	View
10-08-45-001F	3/18/2019	Information for Electrical Ground Repair - Use New Replacement Fasteners with Conductive Finish	Body	View
09-00-89-002Q	3/14/2019	Properly Maintaining Vehicles in Dealer Inventory	Body	View
PIP4902M	3/13/2019	Procedure For Emailing Global Diagnostic System 2 (GDS2) Session Log To GM TAC (US and Canada Dealers Only).	Body	View
PIP5632	3/13/2019	Procedure For Attaching GDS2 Session Logs To Technical Assistance Cases Using Dealer Case Management (US Dealers Only)	Body	View
PIP4902L	3/8/2019	Procedure For Emailing Global Diagnostic System 2	Body	

		(GDS2) Session Log To GM TAC (US and Canada Dealers Only)		View
PIC3100G	3/6/2019	Verifying Odometer Accuracy	Body	View
12-00-89-002C	2/26/2019	Requesting a New Key Code for Customer with Lost or Stolen Keys	Body	View
PIP5627	2/15/2019	Diagnostic Tips For I/M Flags Resetting After Ignition Cycled	Body	View
PIC5494J	2/8/2019	Difference Between Analog and Digital Vehicle Speed Display	Body	View
09-00-89-016F	2/8/2019	Warranty Administration â€“ Labor Operation 0600014 â€“ Suspected Tampering or Vehicle Modifications	Body	View
09-00-89-002P	2/5/2019	Properly Maintaining Vehicles in Dealer Inventory	Body	View
01-00-89-010M	1/31/2019	Comeback Prevention Information and Using Customer Concern Verification Sheets (CCVS)	Body	View
08-00-89-014D	1/31/2019	Use of Dealer Case Management (DCM) and Technician Preparedness for Contacting U.S. Technical Assistance (TAC)	Body	View
10-00-89-005H	1/18/2019	Warranty Administration - Revised Wiring Repair Labor Operations and Required Additional Information	Body	View
04-00-89-015T	1/14/2019	Warranty Administration - Required Operating Procedures (U.S. Only)	Body	View
PIC6346	1/2/2019	Photographing Various Vehicle Concerns and Submitting Them to the GM Technical Assistance Center (TAC)	Body	View
06-00-89-026O	12/21/2018	Warranty Administration - Customer Concern Not Duplicated (CCND) Labor Operation Numbers	Body	View
PIT5214D	12/17/2018	GM TAC Support of Vehicle Vibration Complaints - U.S. and Canada Dealers Only	Body	View
08-00-89-014C	12/13/2018	Use of Dealer Case Management (DCM) and Being Prepared for Contacting U.S. Technical Assistance (TAC)	Body	View
06-08-47-001N	12/5/2018	Warranty Administration - Warranty, SPS, Control Module Diagnostics and Configuration Information, Programming, Set-Up	Body	View
06-08-50-009J	12/5/2018	Information on Passenger Presence Sensing System (PPS or PSS) Concerns with Custom Upholstery, Accessory Seat Heaters or Other Comfort Enhancing Devices	Body	View

18-NA-306	11/27/2018	Information for Dealers/Service Advisors on When and How to Submit a Pre-Repair Authorization (PRA) (U.S. Dealers Only)	Body	View
PIC6107A	11/20/2018	Requirements For OnStar Over The Air Programming And Updates	Body	View
02-00-89-002R	11/20/2018	Information for Dealers/Technicians on When and How to Submit a Field Product Report (FPR) (U.S. Dealers Only)	Body	View
PIT5353C	11/20/2018	Diagnostic Tips: XM Audio Traffic And Travel Link Availability And Operation	Body	View
PIP5191C	11/6/2018	Engine Ticking Noise or oil pressure fluctuation On Cold Start	Body	View
18-NA-099	11/5/2018	Working with GM on a Product Assistance Claim (PAC)	Body	View
12-00-89-003A	11/2/2018	Warranty Administration - Guidelines for Multiple Repairs with Independent Causes (GM Canada Dealers only)	Body	View
09-00-89-008D	10/30/2018	Warranty Administration - Labor Operation 0600018 - Personal Property Damage	Body	View
00-06-01-012I	10/26/2018	Use of Surface Conditioning Disks When Cleaning Gasket Sealing Surfaces and/or Reused Parts	Body	View
PIP5601	10/23/2018	Vehicle Vibration Diagnosis and TAC Requests For Assistance With Vibration Related Complaints	Body	View
PIP5338B	10/19/2018	Vehicle Vibration Diagnosis and TAC Requests For Assistance With Vibration Related Complaints	Body	View
PIPXXXXB	10/17/2018	Vehicle Vibration Diagnosis and TAC Requests For Assistance With Vibration Related Complaints	Body	View
PIP4138R	10/15/2018	SES Light, Misfire, DTC P0300, And/or A Chirp, Squeak, Squeal, Or Tick Noise - Potential	Body	View
PIT5099D	10/10/2018	AC Blows Warm or Poor Performance	Body	View
13-00-89-010B	10/8/2018	PAC Courtesy Transportation Assistance Program	Body	View
07-08-49-020O	10/3/2018	IPC Odometer Programming Method Quick Reference Guide	Body	View
PIP5596	10/3/2018	Diagnostic Tip: Fuel Injected Gasoline Engines Possible No Start Extended Crank or Fuel Pressure Related DTCs	Body	View
00-06-01-026L	10/3/2018	Engine Replacement After Severe Internal Engine Damage - Replace Intake Manifold	Body	View

18-NA-115	10/1/2018	Cold Start Misfire and/or Rough Idle - DTC P0300 May Be Set	Body	View
PIC5650E	9/26/2018	Diagnostic Tip - Security Light on Intermittently / No Crank/No Start or Start Stall / Keyless Access Vehicles May Display No Remote/Fob Detected / Poor or No RKE Range / Service TPM	Body	View
15-00-89-005B	9/11/2018	Warranty Administration - Essential Tools that Include Consumable Parts (U.S. Only)	Body	View
18-NA-271	9/5/2018	Information on A/C Odors During Start Up in Hot Humid Climates	Body	View
PIP4902K	8/28/2018	Procedure For Emailing Global Diagnostic System 2 (GDS2) Session Log To GM TAC (US and Canada Dealers Only)	Body	View
18-NA-263	8/24/2018	Variable Diagnostic Time Allowances (U.S. Only)	Body	View
02-08-98-002H	8/22/2018	Hem Flange Rust Repair	Body	View
06-00-89-031E	8/22/2018	OEM and Remanufactured Engine and Automatic Transmission/Transaxle Identification	Body	View
PI0653E	8/22/2018	Damaged, Disassembled or Improperly Packaged Turbochargers Returned to Warranty Part Center	Body	View
PI0754C	8/22/2018	Rear and Side Tempered Glass Spots (Quench Marks)	Body	View
PI1440	8/22/2018	Diagnostic Tips for Odor Emanating from HVAC System	Body	View
PIP5163D	8/8/2018	Alleged Cylinders Out Of Round	Body	View
PIP3423P	8/8/2018	DTC P0016 P0017 P0018 P0019 P0008 P0009	Body	View
PIP5095F	8/8/2018	Fluid In Spark Plug Tubes	Body	View
00-06-01-026K	7/24/2018	Intake Manifold Inspection/Replacement After Severe Internal Engine Damage	Body	View
07-06-01-016E	7/24/2018	Information on Internal Engine Noise or Damage After Oil Filter Replacement	Body	View
13-08-116-001D	7/23/2018	Aftermarket ALDL or DLC Interface Devices Causing Multiple Issues	Body	View
PIP5257B	7/11/2018	Cooling System Contaminated With Engine Oil	Body	View

PIC5260B	7/3/2018	Intermittent Sunroof Operation, Bind, Noise, Auto-reverse, and/or Water Leaks	Body	View
12-00-89-007B	6/22/2018	Dealer Responsibility for Cargo Carrying Capacity Labeling	Body	View
PIT5099C	6/20/2018	AC Blows Warm or Poor Performance	Body	View
99-00-89-019P	5/30/2018	Global Warranty Management (GWM) Warranty Parts Center (WPC) Parts Return Program Information	Body	View
PIT5399A	5/23/2018	Diagnostic Tip: Apple Device Connectivity Issues due to USB Cord Concern	Body	View
04-00-89-015S	5/14/2018	Warranty Administration - Required Operating Procedures (U.S. Only)	Body	View
07-00-89-037N	5/10/2018	Warranty Administration - Courtesy Transportation and Roadside Assistance Programs	Body	View
18-NA-146	5/4/2018	Warranty Administration - Proper Labor Operation Selection and Causal Part Identification for Warranty Transactions	Body	View
12-08-132-001E	4/20/2018	Accessory Power Outlet and Trailer Lighting Fuse Replacement Labor Operation 5430130 Fuse Replacement	Body	View
18-NA-125	4/19/2018	Information on Engine Oil Life Monitor Operation Calculation	Body	View
08-07-30-035C	4/9/2018	Information on Water or Ethylene Glycol in Transmission Fluid	Body	View
PI0281G	4/6/2018	Underbody Component Corrosion	Body	View
00-00-89-027J	3/16/2018	Eliminating Unwanted Odors in Vehicles	Body	View
PIP4112S	3/12/2018	Normal Characteristic - Sag Or Hesitation On Acceleration	Body	View
11-00-89-002C	3/9/2018	GM Accessories - Dealer-Installed, Repaired or Replaced During Warranty Coverage Period	Body	View
03-00-89-006P	3/7/2018	New Vehicle Pre-Delivery Inspection (PDI) - Delivering Quality Vehicles and Generating Higher CSi Scores	Body	View
17-NA-215	2/28/2018	Red LED, No WiFi Operation, and/or Limited OnStar Module Functionality After OnStar Module Replacement for Another Condition	Body	View
PIC4921E	2/20/2018	Paint Color Codes For Special Edition Vehicles (Mary Kay - Hot Wheels - Green Flash Or Neiman Marcus)	Body	View

03-06-03-004W	2/1/2018	Warranty Administration - Battery Testing and Warranty Replacement Requirements (North America ONLY)	Body	View
10-08-64-002D	1/17/2018	Warranty Administration - Warranty Claims Submission - Outside Rear View Mirrors	Body	View
12-00-89-007A	12/7/2017	Dealer Responsibility for Cargo Carrying Capacity Labeling	Body	View
09-06-03-004E	12/5/2017	Intermittent No Crank/No Start, No Module Communication, MIL, Warning Lights, Vehicle Messages or DTCs Set by Various Control Modules - Diagnosing and Repairing Fretting Corrosion (Disconnect Affected Connector and Apply Dielectric Lubricant)	Body	View
PIP5528	11/21/2017	Information assistance for HFV6 re-manufactured engine misfire diagnosis	Body	View
PIT4730B	11/20/2017	Diagnostic Tip- Information for U0140 or U0073 (BCM Appears Off Line On The High Speed Buss)	Body	View
07-06-04-019F	11/17/2017	Intermittent Malfunction Indicator Lamp (MIL) Illuminated, DTC P2138 with Reduced Engine Power (Repair Instrument Panel (IP) to Body Harness Connector)	Body	View
17-NA-346	11/17/2017	Information on COAX Repair Kit Availability	Body	View
PIC3100F	11/7/2017	Verifying Odometer Accuracy	Body	View
PIC6042A	11/7/2017	Diagnostic Tip - Replacement Of Manual Shift Paddles On Steering Wheel	Body	View
PIC5492F	10/6/2017	Diagnostic Tip - Diagnosing Vehicles with OnStar DTC B101D -37	Body	View
PIT5236K	9/28/2017	Diagnostic Tip: OnStar Vehicles with B101D and Symptom Codes	Body	View
13-08-116-001C	8/30/2017	Aftermarket ALDL or DLC Interface Devices Causing Multiple Issues	Body	View
99-08-51-001D	8/23/2017	Paint-less Dent Repair Process	Body	View
17-NA-244	7/25/2017	Information on How to Prevent Inadvertent Vehicle Starting from Key Fob or OnStar Mobile Application	Body	View
PIC5494H	7/17/2017	Difference Between Analog and Digital Vehicle Speed Display	Body	View
07-00-89-037K	6/23/2017	Warranty Administration - Courtesy Transportation and Roadside Assistance Programs	Body	View

06-00-89-029N	6/22/2017	Interior Cleaning -- Instrument Panel (IP), Hard or Plastic Surfaces, Seats, Carpet, Leather, Vinyl, Fabric Cleaner, Stain Remover, Restorer --Product Availability	Body	View
09-00-89-002O	6/16/2017	Properly Maintaining Vehicles in Dealer Inventory	Body	View
99-09-40-005H	6/16/2017	Seat Belt Extender Availability	Body	View
99-01-39-004I	6/14/2017	Air Conditioning Odor (Install Evaporator Core Dryer Kit and Apply Cooling Coil Coating)	Body	View
14497C	6/12/2017	Product Safety Recall - Unintended Ignition Key Rotation	Body	View
PIP5216F	6/8/2017	Engine Replacement Recommendations for HFV6 Gen 1 and Gen 2	Body	View
17-NA-066	5/10/2017	Warranty Administration - Automatic Transmission Oil Cooler Flush and Flow Test	Body	View
PI0896A	5/10/2017	Broken or Separated Auxiliary Floor Mat Retainers, Floor Mat Retainer Wonâ€™t Seat on Carpet	Body	View
PIP4925A	4/25/2017	SES Light with Fuel Trim and or Oxygen Sensor Codes	Body	View
17-NA-126	4/19/2017	Non-Design Intent Wheel Lock Nuts and Lug Nuts	Body	View
PI0281F	4/12/2017	Underbody Component Corrosion	Body	View
10-08-110-001F	4/10/2017	Information on Proper Use of Floor Mats	Body	View
99-04-20-002J	3/29/2017	Information on Driveline Clunk Noise	Body	View
17-NA-087	3/21/2017	Characteristics of Wide Low Aspect Ratio Tires, Vehicle Pulls Left or Right, Wanders, Follows Depressions in Road Surface, Tramlining	Body	View
17-NA-073	3/15/2017	Warranty Administration - Field Action Courtesy Transportation Policy	Body	View
PIC5481A	3/14/2017	Power Liftgate Inoperative from Key Fob	Body	View
17-NA-067	3/10/2017	Security Code Input Message with SPS Error Code E5659, M5304 and/or M5530 During TIS2web Programming	Body	View
17-NA-047	2/20/2017	EBCM Wheel Speed Sensor Diagnostic Aid for ABS	Body	

		Message - Click or Ratchet Noise - Service Traction Message - Service Stabilitrak Message - Service Steering Message		View
07-06-04-025L	2/13/2017	Information on Clicking/Ticking Sound/Noise Heard During Cold Start	Body	View
08-08-44-015H	12/19/2016	Information on Inappropriate Warranty Claims Submitted for Damaged Radios and Instrument Panel Clusters (IPCs)	Body	View
05-00-89-055F	12/5/2016	Warranty Administration - GM Dealer Empowerment Program and Goodwill Procedures	Body	View
PIP5163B	11/15/2016	Alleged Cylinders Out Of Round	Body	View
08-09-41-002H	11/15/2016	Diagnostic Information for Supplemental Inflatable Restraint (SIR) System, Intermittent AIR BAG Indicator/Lamp Illuminated with DTC(s) B0012, B0013, B0015, B0016, B0019, B0020, B0022, B0023, B0026, B0033, B0040, B0042 or B0044 Set	Body	View
06-08-64-001D	11/10/2016	Information on Side Door Window Glass Chipping Caused by Hanging Vehicle Key Lock Box	Body	View
16-NA-356	10/24/2016	Audio Muting When Listening to Some Sirius XM Channels Due to Interference in Some Geographic Locations	Body	View
16-NA-355	10/21/2016	Information on Using MyBuick, MyCadillac, MyChevrolet, and MyGMC Phone Applications to Control GM Accessory Remote Start Kits	Body	View
16-NA-338	10/7/2016	PQC Assembly Replacement Process - Dealers Required to Contact PQC Prior to Replacing an Assembly	Body	View
09-00-89-002N	10/7/2016	Properly Maintaining Vehicles in Dealer Inventory	Body	View
PI0744	9/30/2016	Instructions for Installing Techline Infotainment DVD (GMNA Only)	Body	View
PI0751	9/30/2016	HomeLinkÂ® Programming to a Genie IntellicodeÂ® 2 Garage Door Opener	Body	View
PI0568	9/30/2016	Inadvertent Horn, Light, Remote Start, Lock/Unlock Activation or Charging Schedule Change	Body	View
PI0853	9/30/2016	Radio Static on All AM Stations	Body	View
PI0569A	9/30/2016	Wheel Weights for Black Painted Wheels	Body	View
PI0706A	9/30/2016	Exhaust Noise/Moan/Drone/Resonance Just Above Warm Idle Speed While in Drive with Foot on Brake	Body	View

09-00-89-008C	9/30/2016	Warranty Administration - Labor Operation 0600018 - Personal Property Damage	Body	View
06-08-64-001C	9/30/2016	Information on Side Door Window Glass Chipping Caused by Hanging Vehicle Key Lock Box	Body	View
10-08-64-002C	9/30/2016	Warranty Administration - Warranty Claims Submission - Outside Rear View Mirrors	Body	View
09-08-44-013D	9/30/2016	Information on USB Command and Control Multimedia Player Interface/List of Supported Devices	Body	View
PI0773	9/30/2016	Diagnostic Tips for DTC P0796, Slip or No 4th, 5th or 6th Gear	Body	View
11-08-44-003A	9/30/2016	Generation 9 OnStar Modules Inoperative, Bluetooth Inoperative and Possible Battery Discharge Condition	Body	View
03-00-89-005A	9/30/2016	Changes to Essential and Available Tool Numbering System	Body	View
09-03-10-016B	9/30/2016	Wheel Balancing Machine Finish Damage to Chrome Clad or ChromeTechÂ® Wheels	Body	View
PI0774B	9/30/2016	Handsfree/Bluetooth Audio Quality Issues	Body	View
PI0757A	9/30/2016	AM Radio Interference When Operating Rear Window Defroster (Defogger)	Body	View
09-00-89-016E	9/27/2016	Warranty Administration - Labor Operation 0600014 - Suspected Tampering or Vehicle Modifications	Body	View
08-08-44-015G	9/22/2016	Information on Inappropriate Warranty Claims Submitted for Damaged Radios and Instrument Panel Clusters (IPCs)	Body	View
02-08-98-002G	9/22/2016	Hem Flange Rust Repair	Body	View
07-08-49-020K	9/16/2016	IPC Odometer Programming Method Quick Reference Guide	Body	View
PIC5491J	9/14/2016	OnStar Will Not Power Up	Body	View
PIP5029G	9/9/2016	Rough Idle Crank No Start Extended Crank Or Misfire Due to Excessive Carbon On Top of the Valves or Sticking Valves	Body	View
16-NA-260	8/26/2016	Key Replacement Due to Incorrect Keys Purchased	Body	View
16-NA-119	8/12/2016	Warranty Administration - Servicing Vehicles from Canada (U.S. Dealers Only)	Body	View

PIC5494G	8/12/2016	Difference Between Analog And Digital Vehicle Speed Display	Body	View
07-08-98-001B	8/3/2016	Non-approval of Clipping (Sectioning of Two Vehicles) for Collision Repair	Body	View
16-NA-241	7/28/2016	Engine Misfire, Ticking/Knocking Noise, No Compression due to Piston Damage, Malfunction Indicator Lamp (MIL) Illuminated	Body	View
16-NA-222	7/11/2016	Information for Engine Concerns Resulting from Lack of Scheduled Maintenance, Improper Service or Aftermarket Calibrations	Body	View
16-NA-223	7/11/2016	Traction Control Light Flashes Under Hard Acceleration at Higher Road Speeds	Body	View
16-NA-085	6/22/2016	New Design Cylinder Heads	Body	View
PI0388F	6/17/2016	Seat Belt Webbing/Latch Plate Becomes Twisted	Body	View
10-08-110-001E	6/10/2016	Information on Proper Use of Floor Mats	Body	View
16-NA-158	5/16/2016	New U.S. Dealer Special Tool Loan Program	Body	View
12-08-132-001D	5/13/2016	Accessory Power Outlet and Trailer Lighting Fuse Replacement - Use Global Labor Operation 5430130 Fuse Replacement	Body	View
08-08-49-006D	5/10/2016	Front Floor Console Rear Ashtray/Bin Door May Not Close (Align Pivot Pins)	Body	View
PIP3140G	5/10/2016	Abnormal Noise And Or Vibration While Driving Due To Non-GM Aftermarket Accessory	Body	View
10-08-46-001C	4/20/2016	Radio Does Not Mute Enough When OnStar Turn-By-Turn Navigation Directions Are Announced (Increase Volume Setting or Request Soft Mute Feature Change Through OnStar Customer Service)	Body	View
16-NA-117	4/12/2016	Information Regarding Magnetic Drain Plugs	Body	View
PI0754B	4/12/2016	Rear and Side Tempered Glass Spots (Quench Marks)	Body	View
PI0281E	4/7/2016	Underbody Component Corrosion	Body	View
PIC5260A	4/5/2016	Intermittent Sunroof Operation, Bind, Noise, Auto-reverse, and/or Water Leaks	Body	View
16-NA-109	4/5/2016	Grease or Sealant Visible on Electronic Power	Body	

		Steering Gear - Should Not Be Interpreted as Leak		View
08-00-89-014B	3/29/2016	Being Prepared for TAC, Caller Preparedness and Checklist - Contacting U.S. Technical Assistance (TAC) and Use of Strategy Based Diagnostics	Body	View
16-NA-075	3/14/2016	Power Foldaway Mirror Glass Shakes, Flutters at Normal Driving Speeds	Body	View
16-NA-055	3/11/2016	Information Regarding Servicing Components Located Near SIR Components	Body	View
08-07-30-026C	3/7/2016	Information on Slight Vehicle Movement in Park at Start Up After Cold Soak	Body	View
16-NA-069	3/3/2016	Side Detection System Unavailable or Intermittently Side Blind Zone Stops Working	Body	View
03-00-89-006M	3/2/2016	New Vehicle Pre-Delivery Inspection (PDI) - Delivering Quality Vehicles and Generating Higher CSi Scores	Body	View
06-00-89-029M	3/2/2016	Interior Cleaning - Instrument Panel (IP), Hard or Plastic Surfaces, Seats, Carpet, Leather, Vinyl, Fabric Cleaner, Stain Remover, Restorer - Product Availability	Body	View
09-00-89-002M	3/2/2016	Properly Maintaining Vehicles in Dealer Inventory	Body	View
08-08-44-015F	2/9/2016	Information on Inappropriate Warranty Claims Submitted for Damaged Radios and Instrument Panel Clusters (IPCs)	Body	View
PIT4720D	2/8/2016	Odometer Servicing When The Odometer Cannot Be Set To The Actual Mileage	Body	View
02-08-98-002F	2/5/2016	Hem Flange Rust Repair	Body	View
06-08-50-009I	1/28/2016	Information on Passenger Presence Sensing System (PPS or PSS) Concerns with Custom Upholstery, Accessory Seat Heaters or Other Comfort Enhancing Devices	Body	View
05-03-08-002G	1/1/2016	Information on Diagnosis and Replacement of Shock Absorber and Strut Due to Fluid Leak	Body	View
07-08-49-020J	12/22/2015	IPC Odometer Programming Method Quick Reference Guide	Body	View
06-00-89-031D	12/15/2015	OEM and Remanufactured Engine and Automatic Transmission/Transaxle Identification	Body	View
PIT5214B	11/25/2015	GM TAC Support of Vehicle Vibration Complaints - U.S. and Canada Dealers Only	Body	View

PIC3100E	11/23/2015	Verifying Odometer Accuracy	Body	View
10-00-89-005E	11/12/2015	Warranty Administration - Revised Wiring Repair Labor Operations and Required Additional Information	Body	View
PI1344B	11/6/2015	Diagnostic Tips for Reduced Acceleration at Low Speed and/or Transmission Slipping from a Launch, DTC P0751 Set	Body	View
15-06-01-003	11/4/2015	Supercharger Noise	Body	View
15-NA-048	11/2/2015	Clunk Noise Under Vehicle When Accelerating	Body	View
04-03-10-013J	10/31/2015	Driving Characteristics of Rear Wheel Drive Vehicles and Available Winter Tires	Body	View
15-08-44-001F	10/31/2015	GM of Canada OnStar Cellular Communication Upgrade	Body	View
14582	10/31/2015	Special Coverage Adjustment - Throttle Body - Reduced Power Mode	Body	View
PI0388E	10/31/2015	Seat Belt Webbing/Latch Plate Becomes Twisted	Body	View
05-03-07-009H	10/31/2015	Wheel Alignment Specifications, Requirements and Recommendations for GM Vehicles	Body	View
13-00-89-010A	10/31/2015	PAC Courtesy Transportation Assistance Program	Body	View
06-00-89-026M	10/31/2015	Warranty Administration - Revised Customer Concern Not Duplicated (CCND) / Verified Labor Operation Numbers/How to Submit CCND Transactions in Global Warranty Management	Body	View
PIP5338	10/31/2015	Vehicle Vibration Diagnosis and TAC Requests For Assistance With Vibration Related Complaints	Body	View
PI0799A	10/31/2015	White Film/Residue on Vehicle Interior, Door Trim Panels and/or Instrument Panel (IP)	Body	View
10-08-98-002A	10/31/2015	Information on Drilling High Strength Steel Related to Collision Repair	Body	View
08-08-44-029F	10/31/2015	Updated Warranty and Policy Exchange Program for Electronic Products (U.S. and Canada)	Body	View
01-06-01-011I	10/31/2015	Information on Engine Oil Consumption Guidelines	Body	View
09-00-89-008B	10/31/2015	Warranty Administration - Labor Operation 0600018 - Personal Property Damage	Body	View

04-07-30-013C	10/31/2015	Automatic Transmission Shift and Engine Driveability Concerns and/or MIL ON Due to Aftermarket Oil Bath Type Air Filter Use	Body	View
PIT5465	10/31/2015	Turn By Turn Directions Not Displayed After Canada Upgrade	Body	View
15-NA-030	10/31/2015	Information on the Use of Non GM Approved Battery Chargers and Booster Packs	Body	View
08-08-44-029E	10/31/2015	Updated Warranty and Policy Program for Electronic Products (U.S. and Canada)	Body	View
15-NA-017	10/31/2015	Warranty Administration - Causal Part Requirements for Transactions Submitted to GM for Payment	Body	View
15-00-89-001	10/31/2015	Warranty Administration - New Vehicle Maintenance Program Cross-Border Servicing between the U.S. and Canada	Body	View
14497B	10/31/2015	Product Safety - Unintended Ignition Key Rotation	Body	View
10-08-45-001E	10/31/2015	Information for Electrical Ground Repair - Use New Replacement Fasteners with Conductive Finish	Body	View
05-08-51-001G	10/31/2015	Information on Paint Stain Under Protective Shipping Film	Body	View
05-03-10-020F	10/31/2015	Use of Nitrogen Gas in Tires	Body	View
PI1404	10/31/2015	Diagnostic Tip for Low Line Pressure or Pressure Regulator Valve Stuck After Pump Cover Replacement	Body	View
06-08-47-001K	10/31/2015	Warranty, SPS, Control Module Diagnostics and Configuration Information, Programming, Set-Up	Body	View
PIC5494E	10/31/2015	Difference Between Analog And Digital Vehicle Speed Display	Body	View
PIC4921D	10/31/2015	Paint Color Codes For Special Edition Vehicles (Mary Kay - Hot Wheels - Green Flash Or Neiman Marcus)	Body	View
12-06-01-009F	10/31/2015	Information on High Feature V6 Timing Chain Kits and Chain Guide Replacements, DTCs P0008, P0009, P0016, P0017, P0018 and/or P0019	Body	View
08-08-49-006C	10/31/2015	Front Floor Console Rear Ashtray/Bin Door May Not Close (Align Pivot Pins)	Body	View
15-00-90-001	10/31/2015	Diagnostic Tips for Preventing Oil Leaks After Changing Oil and Filter	Body	View
05-06-04-060A	10/31/2015	Control Module Diagnostic Trouble Code(s) (DTC)(s) P0601, P0602, P0603, P0604, P0606, P062F, P06F3,	Body	View

		P1621 Shared In Multiple Modules		
PI1018A	10/31/2015	Information on Poor, Limited, Reduced Remote Keyless Entry (RKE) or Remote Vehicle Start (RVS) Range	Body	View
15-08-42-001	10/31/2015	Exterior Lighting Components Tinted or Smoked by an Outside Vendor	Body	View
10-04-20-001F	10/31/2015	Rear Axle Clunk and/or Chatter Type Noise on Turns (Drain/Refill Rear Differential Fluid)	Body	View
08-03-10-004B	10/31/2015	Mounting, Balancing and Installation of Accessory Wheels and Tires Available Through GM Accessories	Body	View
PI0655A	10/31/2015	Information on Removal/Cracking of Stainless Steel Wheel Nut Caps	Body	View
PI0734A	10/31/2015	Rear Door Glass Lowers without Window Switch Activation, Especially after Car Wash or Rain	Body	View
09-08-110-011C	10/31/2015	Front or Rear Door Lock Lever Bezel Loose or Detached (Replace Bezel)	Body	View
03-08-48-006J	10/31/2015	Repair Information for Reconnection of Rear Window (Defroster) Contact or Tab	Body	View
10-08-110-001C	10/31/2015	Information on Proper Use of Floor Mats	Body	View
03-00-91-001G	10/31/2015	Vibration Analysis Worksheet	Body	View
14515A	10/31/2015	Product Safety - Chassis Electronic Control Module Internal Contamination	Body	View
00-00-89-027I	9/5/2015	Eliminating Unwanted Odors in Vehicles	Body	View
07-00-89-036H	9/5/2015	Enhancing Field Product Reports with Digital Pictures	Body	View
07-06-04-019E	9/5/2015	Intermittent Malfunction Indicator Lamp (MIL) Illuminated, DTC P2138 with Reduced Engine Power (Repair Instrument Panel (IP) to Body Harness Connector)	Body	View
15-00-89-005	8/22/2015	Warranty Administration - Essential Tools that Include Consumable Parts (U.S. Only)	Body	View
09-09-40-001C	8/8/2015	Seat Belt Buckle Latching Issues and/or Seat Belt Warning Lights Illuminated	Body	View
10-08-110-001D	8/8/2015	Information on Proper Use of Floor Mats	Body	View

06-00-89-029L	7/25/2015	Interior Cleaning - Instrument Panel (IP), Hard or Plastic Surfaces, Seats, Carpet, Leather, Vinyl, Fabric Cleaner, Stain Remover, Restorer - Product Availability	Body	View
03-06-03-003E	7/25/2015	ACDelco Replacement Battery Warranty Procedures	Body	View
03-00-89-006L	7/18/2015	New Vehicle Pre-Delivery Inspection (PDI) - Delivering Quality Vehicles and Generating Higher CSi Scores	Body	View
06-00-89-029K	7/18/2015	Interior Cleaning - Instrument Panel (IP), Hard or Plastic Surfaces, Seats, Carpet, Leather, Vinyl, Fabric Cleaner, Stain Remover, Restorer - Product Availability	Body	View
01-08-51-003E	7/12/2015	Application of Anti-Corrosion Materials	Body	View
05-06-04-022M	7/12/2015	TOP TIER Detergent Gasoline Information and Available Brands	Body	View
02-00-89-002O	6/27/2015	Information for Dealers/Technicians on When and How to Submit a Field Product Report (FPR) (U.S. Dealers Only)	Body	View
09-00-89-002K	6/6/2015	Properly Maintaining Vehicles in Dealer Inventory	Body	View
02-07-30-052J	5/30/2015	Automatic Transmission Oil Cooler Flow Test Essential Tool J-45096 TransFlow	Body	View
05-06-04-035E	5/30/2015	Usage of E85 Fuel in GM Vehicles	Body	View
15-00-89-004A	5/23/2015	Information Regarding the Differences Between Leakage and Seepage	Body	View
10-08-42-001E	5/16/2015	Low Beam Headlamp Bulb Diagnosis/Replacement (Inspect Bulb and Connector)	Body	View
PI0091B	5/2/2015	Intermittently Key Will Not Rotate in Door or Ignition Lock Cylinder	Body	View
13-08-116-001B	3/28/2015	Aftermarket ALDL or DLC Interface Devices Causing Multiple Issues	Body	View
06-08-50-009H	1/31/2015	Information on Passenger Presence Sensing System (PPS or PSS) Concerns with Custom Upholstery, Accessory Seat Heaters or Other Comfort Enhancing Devices	Body	View
PIT5236A	12/7/2014	Diagnostic Tip: OnStar Module Does Not Support All B101D Symptom Codes	Body	View
PIC6042	10/31/2014	Diagnostic Tip - Replacement Of Manual Shift Paddles On Steering Wheel	Body	View

PIC5514D	9/8/2014	Unwanted Decklid Opening On Vehicles With Keyless Access	Body	View
PIC5514C	8/28/2014	Unwanted Decklid Opening On Vehicles With Keyless Access	Body	View
PI1296	8/24/2014	Diagnostic Tip for Engine Misfire and/or Popping Noise on Cold Startup after Cylinder Head or Fuel Rail/Injector Repair	Body	View
PIP5216	8/18/2014	Engine Replacement Recommendations HFV6 Only	Body	View
PIT3099M	8/8/2014	Concerns Or Questions Regarding The Installation Of Dealer Installed Accessories	Body	View
PI1290	8/7/2014	Inside Rear View Mirror is Loose and/or Mirror Mounting Bracket Fell Off	Body	View
PI0938A	7/14/2014	Powertrain and Various Electrical/Electronic Control Issues	Body	View
PI1277	7/11/2014	Information Regarding A/C Service Valve Tethered Cap Requirements in the State of Idaho	Body	View
PIP4902H	7/8/2014	Procedure For Emailing Global Diagnostic System 2 (GDS2) Session Log To	Body	View
PI1266	6/19/2014	Radio Reprogramming Using Techline/Service Programming System (SPS) - Ensuring Correct Vehicle Selection	Body	View
PIC6002	5/20/2014	Diagnostic Tip - Repeat BCM Replacement	Body	View
PI1233	5/16/2014	DTC Symptom Byte Documentation	Body	View
PIC4921C	3/1/2014	Paint Color Codes For Special Edition Vehicles (Mary Kay, Hot Wheels, or Neiman Marcus)	Body	View
PIC4921B	2/15/2014	Paint Color Codes For Special Edition Vehicles (Mary Kay or Neiman Marcus)	Body	View
08-03-10-006E	2/6/2014	Tire Slowly Goes Flat, Tire Air Loss, Low Tire Pressure Warning Light Illuminated, Aluminum Wheel Bead Seat Corrosion (Clean and Resurface Wheel Bead Seat)	Body	View
PIC5959	2/1/2014	No Audio On Certain XM Radio Channels	Body	View
11-00-89-002B	1/24/2014	GM Accessories - Dealer-Installed, Repaired or Replaced During Warranty Coverage Period	Body	View
12-03-10-	1/4/2014	Proper Wheel Installation and Wheel Torque	Body	

002A		Techniques		View
PIC5492B	10/4/2013	Diagnostic Tip: Diagnosing Vehicles with OnStar DTC B101D-37	Body	View
PIT3237G	10/1/2013	Information on Glass Ultra Violet UV Ray Protection And Tint Percentage	Body	View
PI0218A	9/13/2013	Information on Rear Bumper Fascia and Quarter Panel Paint Appearance	Body	View
09-03-16-002B	6/19/2013	Dealership Service Consultant Procedure as Vehicle Comes into Service Drive for Tire Pressure Monitor (TPM) System Message, Light and Customer Information	Body	View
PI0430B	6/19/2013	Magnaride Magnetically Controlled Suspension Electrical Connector Not Seated, Service Suspension System Message, DTCs C0575, C0580, C0585 or C0590	Body	View
11-00-90-001B	6/19/2013	Global Information for GM dexos 1 and dexos 2 Engine Oil Specifications, Licensed Brands, and Service Fill	Body	View
10-00-89-016A	6/19/2013	Correct Selection Of Labor Codes	Body	View
08-07-30-026B	6/19/2013	Information on Slight Vehicle Movement in Park at Start Up After Cold Soak	Body	View
PI0785B	6/19/2013	DTC C027B, Low Brake Pedal Feel After Master Cylinder Repairs	Body	View
03-08-48-006I	6/19/2013	Repair Information for Reconnection of Rear Window Defroster (Defogger) Contact or Tab	Body	View
PI0086E	5/31/2013	Unexpected Loss of Radio Audio (Radio Goes Silent/No Sound) and Other Blackberry Phone - Bluetooth Issues	Body	View
PIT4720C	4/23/2013	Odometer Servicing When The Odometer Cannot Be Set To The Actual Mileage	Body	View
99-04-20-002H	4/12/2013	Information on Driveline Clunk Noise	Body	View
13-00-89-003	3/29/2013	Vehicle Software Enhancements	Body	View
12-06-01-007A	3/22/2013	New Service Cam Bearings For Gen IV V8 Engines	Body	View
03-00-91-001F	3/22/2013	Vibration Analysis Worksheet	Body	View

99-08-51-001C	3/1/2013	Paint-less Dent Repair Process	Body	View
PI0412B	3/1/2013	No Crank/No Start, Dead Battery Due to Parasitic Drain/Discharge	Body	View
06-08-43-003D	2/15/2013	Windshield Wiper Performance, Cleaning Instructions and Maintenance	Body	View
10-08-45-001D	2/15/2013	Information for Electrical Ground Repair - Use New Replacement Fasteners with Conductive Finish	Body	View
PIP5094	2/11/2013	Prior To Any Circuit Testing	Body	View
PIC5267B	1/18/2013	Various Noises From Sunroof Area	Body	View
03-06-04-030H	1/1/2013	Various Driveability Symptoms Due to Clogged Fuel Injectors, MIL/SES DTCs P0171, P0172, P0174, P0300, P1174, P1175 (Clean Fuel Injectors and/or Perform Injector Test With AFIT CH-47976)	Body	View
08-07-30-040C	9/4/2012	Information on Normal Maintenance or Warranty Service for 4T40, 4T45, 4T65, 4L60 Automatic Transmission Oil Pan Magnet Upgrade	Body	View
07-08-49-020F	9/4/2012	IPC Odometer Programming Method Quick Reference Guide	Body	View
08-08-49-006B	9/4/2012	Front Floor Console Rear Ashtray/Bin Door May Not Close (Align Pivot Pins)	Body	View
09-08-50-004B	9/4/2012	Front Seat(s) Lateral Seat Clunk (Install Felt Washer, Replace Clip)	Body	View
08-00-89-024D	9/4/2012	XM/OnStar Antenna Cover Installation Procedure During PDI	Body	View
00-03-10-006K	5/3/2012	Information on Tire Radial Force Variation (RFV)	Body	View
03-08-44-005L	4/18/2012	Poor Radio Reception or Radio Static/Increased Interference with Rear Window Defogger On or Some Rear Window Defogger Grids May Be Inoperative	Body	View
08-09-41-007I	4/15/2012	Passenger Presence System (PPS) May Command Seat Belt Reminder Chime and Passenger Airbag Indicator On When Electronic Devices or Conductive Objects are Placed on Front Passenger Seat, DTCs 5045 or B0074 0F May Set in PPS Module	Body	View
11-08-44-002A	4/11/2012	Audio System Speaker Noise, Distorted, Inoperative (Follow Procedure Outlined Below)	Body	View
07-06-04-025K	3/20/2012	Information on Clicking/Ticking Sound/Noise Heard During Cold Start	Body	View

02-08-98-002D	3/19/2012	Hem Flange Rust Repair	Body	View
PI0488D	2/4/2012	Diagnostic Information for Transmission No Forward, No Reverse, Slips, Cracked/Split Fluid Filter	Body	View
09-00-89-002F	1/19/2012	Properly Maintaining Vehicles in Dealer Inventory	Body	View
06-00-89-029H	1/19/2012	Interior Cleaning - Instrument Panel (IP), Hard or Plastic Surfaces, Seats, Carpet, Leather, Vinyl, Fabric Cleaner, Stain Remover, Restorer - Product Availability	Body	View
09-00-89-002H	1/14/2012	Properly Maintaining Vehicles in Dealer Inventory	Body	View
06-00-89-029I	1/13/2012	Interior Cleaning - Instrument Panel (IP), Hard or Plastic Surfaces, Seats, Carpet, Leather, Vinyl, Fabric Cleaner, Stain Remover, Restorer - Product Availability	Body	View
09-00-89-002I	1/13/2012	Properly Maintaining Vehicles in Dealer Inventory	Body	View
09-00-89-002J	1/13/2012	Properly Maintaining Vehicles in Dealer Inventory	Body	View
06-00-89-029J	1/12/2012	Interior Cleaning - Instrument Panel (IP), Hard or Plastic Surfaces, Seats, Carpet, Leather, Vinyl, Fabric Cleaner, Stain Remover, Restorer - Product Availability	Body	View
PI0401B	11/20/2011	Rear Vision Camera Appears Obstructed	Body	View
00-06-01-012E	10/24/2011	Use of Surface Conditioning Disks When Cleaning Engine Gasket Sealing Surfaces and/or Reused Engine Parts	Body	View
03-06-03-004H	10/22/2011	Warranty Code Generated By EL-50313 Midtronics GR8 Battery Tester/Charger Required for Claim Processing On Labor Operation 4041510 and Battery Part Restriction (North America ONLY)	Body	View
05-09-40-002G	10/17/2011	Safety Belt Locking Conditions (Normal Operating Characteristics)	Body	View
00-00-89-027H	10/13/2011	Eliminating Unwanted Odors in Vehicles	Body	View
08-08-49-018E	10/1/2011	Scratches or Scuffs on Console, Center Stack, Door Panels and Steering Wheel Trim Panels (Polish Trim Panels)	Body	View
07-08-47-004E	9/14/2011	Information on Body Control Module (BCM) Grounds	Body	View
PI0388B	9/11/2011	Seat Belt Webbing/Latch Plate Becomes Twisted	Body	

				View
PI0388C	9/8/2011	Seat Belt Webbing/Latch Plate Becomes Twisted	Body	View
PI0388D	9/7/2011	Seat Belt Webbing/Latch Plate Becomes Twisted	Body	View
10-00-89-017H	7/22/2011	Car and Truck Fix it Right the First Time Issues	Body	View
10-00-89-017H	7/22/2011	Car and Truck Fix it Right the First Time Issues	Body	View
08-00-89-024C	7/19/2011	XM/OnStar Antenna Cover Installation Procedure During PDI	Body	View
10-00-89-010A	7/15/2011	Key Code Security Rules and Information on GM KeyCode Look-Up Application (Canada Only)	Body	View
06-00-89-029G	6/7/2011	Interior Cleaning - Instrument Panel (IP), Hard or Plastic Surfaces, Seats, Carpet, Leather, Vinyl, Fabric Cleaner, Stain Remover, Restorer - Product Availability	Body	View
11-08-44-002	5/20/2011	Audio System Speaker Noise, Distorted, Inoperative (Follow Procedure Outlined Below)	Body	View
09-08-64-025B	5/9/2011	Power Front Door Glass Slow, Noisy When Being Raised or Lowered (Reposition Glass Run Channel)	Body	View
09-08-110-011B	5/6/2011	Front or Rear Door Lock Lever Bezel Loose or Detached (Replace Bezel)	Body	View
11-04-21-005A	4/27/2011	Water Leaks Attributed to Right Front Area of Sunroof and/or Service All Wheel Drive Message Displayed in Driver Information Center (DIC), DTCs C0399, C0400, C0401 and/or U0102 Set	Body	View
03-00-89-006H	4/14/2011	New Vehicle Pre-Delivery Inspection (PDI) - Delivering Quality Vehicles and Generating Higher CSi Scores	Body	View
10-08-50-003A	3/24/2011	Information on Driver or Passenger Seat Head Restraint Concerns with Comfort, Custom Upholstery or Other Comfort Enhancing Devices	Body	View
10-00-89-017D	3/21/2011	Car and Truck Fix it Right the First Time Issues	Body	View
99-08-51-001B	3/1/2011	Paint-less Dent Repair Process	Body	View
09-00-89-002D	2/24/2011	Properly Maintaining Vehicles in Dealer Inventory	Body	View

06-08-43-003C	2/21/2011	Windshield Wiper Performance, Cleaning Instructions and Maintenance	Body	View
08-08-49-018B	2/8/2011	Scratches or Scuffs on Console, Cener Stack, Door Panels and Steering Wheel Trim Panels (Polish Trim Panels)	Body	View
09-09-40-001A	2/2/2011	Seat Belt Buckle Latching Issues and/or Seat Belt Warning Lights Illuminated	Body	View
06-08-50-009F	12/23/2010	Information on Passenger Presence Sensing System (PPS or PSS) Concerns with Custom Upholstery, Accessory Seat Heaters or Other Comfort Enhancing Devices	Body	View
10-08-62-003	12/21/2010	Warranty Information-Fascia Refinish Labor Operations	Body	View
01-08-51-003B	11/19/2010	Application of Anti-Corrosion Materials	Body	View
05-09-40-002E	10/21/2010	Safety Belt Locking Conditions (Normal Operating Characteristics)	Body	View
09-08-110-008C	10/14/2010	Driver/Passenger Side Windshield Pillar Garnish Molding Loose, Gap at Top (Install N	Body	View
10-08-64-002	10/14/2010	Warranty Administration-Warranty Claims Submission-Outside Rearview Mirrors	Body	View
08-00-89-029Y	9/14/2010	Car and Truck Fix It Right the First Time Issues	Body	View
00-08-48-005D	9/10/2010	Distortion in Outer Surface of Vehicle Glass	Body	View
04-08-50-006D	9/9/2010	Minor Wrinkles, Discoloration, Cuts on Seats with Leather, Vinyl or Cloth Seat Covers	Body	View
09-08-110-008B	7/20/2010	Driver and/or Passenger Side Windshield Pillar Garnish Molding Loose, Gap at Top (Install New Fasteners)	Body	View
06-08-51-005A	6/30/2010	Information on Hem Flange Sealer for Corrosion Protection	Body	View
08-00-89-024B	6/22/2010	XM/OnStar Antenna Cover Installation Procedure During PDI	Body	View
10-00-89-010	5/27/2010	Key Code Security Rules and Information on GM KeyCode Look-Up Application (Canada Only)	Body	View
10-00-89-009	5/27/2010	Key Code Security Rules and Information on GM KeyCode Look-Up Application (U.S. Only)	Body	View
03-00-89-	4/28/2010	New Vehicle Pre-Delivery Inspection (PDI) - Delivering	Body	

006G		Quality Vehicles and Generating Higher CSi Scores		View
06-00-89-029F	4/27/2010	Interior Cleaning-Instrument Panel (IP), Hard or Plastic Surfaces, Seats, Carpet, Leather, Vinyl, Fabric Cleaner, Stain Remover, Restorer-Product Availability	Body	View
10-08-110-001	3/30/2010	Information on Proper Use of Floor Mats	Body	View
97-17-1	1/17/1997	Car and Truck Fix it Right the First Time Issues	Body	View

BRAKE (29 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
06-08-47-001N	12/5/2018	Warranty Administration - Warranty, SPS, Control Module Diagnostics and Configuration Information, Programming, Set-Up	Brake	View
PIC6162B	6/27/2017	Questions Regarding The Use Of High Performance / High Temperature Brake Fluid During Track Use	Brake	View
09-00-89-002O	6/16/2017	Properly Maintaining Vehicles in Dealer Inventory	Brake	View
PI0281F	4/12/2017	Underbody Component Corrosion	Brake	View
17-NA-047	2/20/2017	EBCM Wheel Speed Sensor Diagnostic Aid for ABS Message - Click or Ratchet Noise - Service Traction Message - Service Stabilitrak Message - Service Steering Message	Brake	View
09-00-89-002N	10/7/2016	Properly Maintaining Vehicles in Dealer Inventory	Brake	View
PIC5428G	6/21/2016	EBCM Wheel Speed Sensor Diagnostic Aid for ABS Message -Click Or Ratchet Noise- Service Traction Message - Service Stabilitrak Message - Service Steering Message	Brake	View
03-00-89-006M	3/2/2016	New Vehicle Pre-Delivery Inspection (PDI) - Delivering Quality Vehicles and Generating Higher CSi Scores	Brake	View
09-00-89-002M	3/2/2016	Properly Maintaining Vehicles in Dealer Inventory	Brake	View
06-00-89-026M	10/31/2015	Warranty Administration - Revised Customer Concern Not Duplicated (CCND) / Verified Labor Operation Numbers/How to Submit CCND Transactions in Global Warranty Management	Brake	View
14515B	10/31/201	Product Safety - Chassis Electronic Control Module	Brake	

	5	Internal Contamination		View
14515A	10/31/2015	Product Safety - Chassis Electronic Control Module Internal Contamination	Brake	View
00-05-22-002O	9/5/2015	Brake Lathe Calibration Procedure	Brake	View
09-00-89-002L	8/1/2015	Properly Maintaining Vehicles in Dealer Inventory	Brake	View
09-00-89-002K	6/6/2015	Properly Maintaining Vehicles in Dealer Inventory	Brake	View
PIC5214D	7/23/2014	Excessive Brake Dust On Wheels	Brake	View
PIC5136P	6/13/2014	Clicking Noise From Front Wheels	Brake	View
PIC5428F	5/2/2014	EBCM Wheel Speed Sensor Diagnostic Aid for ABS Message -Click Or Ratchet Noise- Service Traction Message - Service Stabilitrak Message - Service Steering Message	Brake	View
PI0785B	6/19/2013	DTC C027B, Low Brake Pedal Feel After Master Cylinder Repairs	Brake	View
PIC5428E	5/10/2013	EBCM Wheel Speed Sensor Diagnostic Aid for ABS Message - Click Or Ratchet Noise - Service Traction Message - Service Stabilitrak Message - Service Steering Message	Brake	View
13-08-116-001A	3/22/2013	Aftermarket ALDL or DLC Interface Devices Causing Multiple Issues	Brake	View
PIC5428D	3/19/2013	EBCM Wheel Speed Sensor Diagnostic Aid for ABS Message - Click Or Ratchet Noise - Service Traction Message - Service Stabilitrak Message	Brake	View
09-00-89-002F	1/19/2012	Properly Maintaining Vehicles in Dealer Inventory	Brake	View
09-00-89-002H	1/14/2012	Properly Maintaining Vehicles in Dealer Inventory	Brake	View
09-00-89-002I	1/13/2012	Properly Maintaining Vehicles in Dealer Inventory	Brake	View
10-00-89-017H	7/22/2011	Car and Truck Fix it Right the First Time Issues	Brake	View
00-05-22-002M	4/19/2011	Disc Brake Warranty Service and Procedures	Brake	View

10-00-89-017D	3/21/2011	Car and Truck Fix it Right the First Time Issues	Brake	View
97-17-1	1/17/1997	Car and Truck Fix it Right the First Time Issues	Brake	View

COOLING (13 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
PIP5257C	7/9/2019	Cooling System Contaminated With Engine Oil	Cooling	View
PIP5257B	7/11/2018	Cooling System Contaminated With Engine Oil	Cooling	View
17-NA-066	5/10/2017	Warranty Administration - Automatic Transmission Oil Cooler Flush and Flow Test	Cooling	View
00-06-01-012F	8/2/2016	Use of Surface Conditioning Disks When Cleaning Engine Gasket Sealing Surfaces and/or Reused Engine Parts	Cooling	View
04-06-01-029H	2/11/2016	Unscheduled Supplemental Services (Including Flushing Services and Additives) and Proper Use of GM Simplified Maintenance Schedules (U.S. Only)	Cooling	View
06-00-89-026M	10/31/2015	Warranty Administration - Revised Customer Concern Not Duplicated (CCND) / Verified Labor Operation Numbers/How to Submit CCND Transactions in Global Warranty Management	Cooling	View
02-07-30-052J	5/30/2015	Automatic Transmission Oil Cooler Flow Test Essential Tool J-45096 TransFlow	Cooling	View
12-06-01-008B	3/14/2015	Unscheduled Supplemental Services (Including Flushing Services and Additives) and Proper Use of GM Simplified Maintenance Schedules (Canada Only)	Cooling	View
PIP4158E	4/4/2013	Low Engine Oil Pump Pressure Due To Sticking Oil Pressure Relief Valve	Cooling	View
02-07-30-052H	3/26/2012	Automatic Transmission Oil Cooler Flow Test Essential Tool J-45096 TransFlow	Cooling	View
10-00-89-017D	3/21/2011	Car and Truck Fix it Right the First Time Issues	Cooling	View
02-07-30-052G	3/2/2011	Automatic Transmission Oil Cooler Flush and Flow Test Essential Tool J-45096 TransFlow	Cooling	View
04-06-01-029E	4/29/2010	Unnecessary Flushing Services, Additive Recommendations and Proper Utilization of GM Simplified Maintenance Schedule to Enhance	Cooling	View

Customer Service Experience

ELECTRICAL (184 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
10-00-89-009D	11/26/2019	Key Code Security Rules and Information on GM KeyCode Look-Up Application (U.S. Only)	Electrical	View
PIT5074M	11/5/2019	J-35616-64B Or EL-35616-58 Terminal Test Probe Information/Repair	Electrical	View
13-00-89-008B	8/19/2019	GM Wiring Repair Strategy Information	Electrical	View
PIT5074L	6/3/2019	J-35616-64B Terminal Test Probe / Replacement Terminal / Terminated Lead	Electrical	View
PIP5632A	5/28/2019	Procedure For Attaching GDS2 Session Logs To Technical Assistance Cases Using Dealer Case Management (US Dealers Only).	Electrical	View
PIC5260C	4/23/2019	Intermittent Sunroof Operation, Bind, Noise, Auto-reverse, and/or Water Leaks	Electrical	View
15-06-03-001E	1/29/2019	Cold Weather and Long Stand Time Battery Maintenance and Testing Tips	Electrical	View
PIC5650F	1/22/2019	Diagnostic Tip - Security Light on Intermittently / No Crank/No Start or Start Stall / Keyless Access Vehicles May Display No Remote/Fob Detected / Poor or No RKE Range / Service TPo	Electrical	View
10-00-89-005H	1/18/2019	Warranty Administration - Revised Wiring Repair Labor Operations and Required Additional Information	Electrical	View
01-08-42-001L	12/13/2018	Exterior Lamp Condensation and Replacement Guidelines	Electrical	View
PIC6107A	11/20/2018	Requirements For OnStar Over The Air Programming And Updates	Electrical	View
PIT5353C	11/20/2018	Diagnostic Tips: XM Audio Traffic And Travel Link Availability And Operation	Electrical	View
PIP5191C	11/6/2018	Engine Ticking Noise or oil pressure fluctuation On Cold Start	Electrical	View
PIP5601	10/23/2018	Vehicle Vibration Diagnosis and TAC Requests For Assistance With Vibration Related Complaints	Electrical	View
07-08-49-020O	10/3/2018	IPC Odometer Programming Method Quick Reference Guide	Electrical	View

18-NA-115	10/1/2018	Cold Start Misfire and/or Rough Idle - DTC P0300 May Be Set	Electrical	View
PIC5650E	9/26/2018	Diagnostic Tip - Security Light on Intermittently / No Crank/No Start or Start Stall / Keyless Access Vehicles May Display No Remote/Fob Detected / Poor or No RKE Range / Service TPM	Electrical	View
PIP4902K	8/28/2018	Procedure For Emailing Global Diagnostic System 2 (GDS2) Session Log To GM TAC (US and Canada Dealers Only)	Electrical	View
18-NA-263	8/24/2018	Variable Diagnostic Time Allowances (U.S. Only)	Electrical	View
PIP3423P	8/8/2018	DTC P0016 P0017 P0018 P0019 P0008 P0009	Electrical	View
07-06-01-016E	7/24/2018	Information on Internal Engine Noise or Damage After Oil Filter Replacement	Electrical	View
13-08-116-001D	7/23/2018	Aftermarket ALDL or DLC Interface Devices Causing Multiple Issues	Electrical	View
PIC5260B	7/3/2018	Intermittent Sunroof Operation, Bind, Noise, Auto-reverse, and/or Water Leaks	Electrical	View
PIT5399A	5/23/2018	Diagnostic Tip: Apple Device Connectivity Issues due to USB Cord Concern	Electrical	View
12-08-132-001E	4/20/2018	Accessory Power Outlet and Trailer Lighting Fuse Replacement Labor Operation 5430130 Fuse Replacement	Electrical	View
03-00-89-006P	3/7/2018	New Vehicle Pre-Delivery Inspection (PDI) - Delivering Quality Vehicles and Generating Higher CSi Scores	Electrical	View
17-NA-215	2/28/2018	Red LED, No WiFi Operation, and/or Limited OnStar Module Functionality After OnStar Module Replacement for Another Condition	Electrical	View
03-06-03-004W	2/1/2018	Warranty Administration - Battery Testing and Warranty Replacement Requirements (North America ONLY)	Electrical	View
15-06-03-001C	12/7/2017	Cold Weather and Long Stand Time Battery Maintenance and Testing Tips	Electrical	View
09-06-03-004E	12/5/2017	Intermittent No Crank/No Start, No Module Communication, MIL, Warning Lights, Vehicle Messages or DTCs Set by Various Control Modules - Diagnosing and Repairing Fretting Corrosion (Disconnect Affected Connector and Apply Dielectric Lubricant)	Electrical	View
PIT4730B	11/20/2017	Diagnostic Tip- Information for U0140 or U0073 (BCM Appears Off Line On The High Speed Buss)	Electrical	View
17-NA-346	11/17/201	Information on COAX Repair Kit Availability	Electrical	

	7			View
PIC3100F	11/7/2017	Verifying Odometer Accuracy	Electrical	View
PIC5492F	10/6/2017	Diagnostic Tip - Diagnosing Vehicles with OnStar DTC B101D -37	Electrical	View
08-08-44-029H	9/5/2017	Updated Warranty and Policy Exchange Program for Electronic Products (U.S. and Canada)	Electrical	View
13-08-116-001C	8/30/2017	Aftermarket ALDL or DLC Interface Devices Causing Multiple Issues	Electrical	View
17-NA-244	7/25/2017	Information on How to Prevent Inadvertent Vehicle Starting from Key Fob or OnStar Mobile Application	Electrical	View
09-00-89-002O	6/16/2017	Properly Maintaining Vehicles in Dealer Inventory	Electrical	View
03-06-03-004U	4/6/2017	Warranty Administration - Battery Testing and Warranty Replacement Requirements (North America ONLY)	Electrical	View
PIC5481A	3/14/2017	Power Liftgate Inoperative from Key Fob	Electrical	View
08-09-41-002H	11/15/2016	Diagnostic Information for Supplemental Inflatable Restraint (SIR) System, Intermittent AIR BAG Indicator/Lamp Illuminated with DTC(s) B0012, B0013, B0015, B0016, B0019, B0020, B0022, B0023, B0026, B0033, B0040, B0042 or B0044 Set	Electrical	View
13-00-89-006	10/17/2016	Warranty Administration - Changes in Powertrain Warranty Coverage Effective with 2010 Model Year	Electrical	View
03-06-03-004T	10/13/2016	Warranty Administration - Battery Testing and Warranty Replacement Requirements (North America ONLY)	Electrical	View
09-00-89-002N	10/7/2016	Properly Maintaining Vehicles in Dealer Inventory	Electrical	View
03-06-03-004S	10/6/2016	Warranty Administration - Battery Testing and Warranty Replacement Requirements (North America ONLY)	Electrical	View
08-09-41-002G	9/30/2016	Diagnostic Information for Supplemental Inflatable Restraint (SIR) System, Intermittent AIR BAG Indicator/Lamp Illuminated with DTC(s) B0012, B0013, B0015, B0016, B0019, B0020, B0022, B0023, B0026, B0033, B0040, B0042 or B0044 Set	Electrical	View
09-00-89-016E	9/27/2016	Warranty Administration - Labor Operation 0600014 - Suspected Tampering or Vehicle Modifications	Electrical	View
07-08-49-	9/16/2016	IPC Odometer Programming Method Quick Reference	Electrical	

020K		Guide		View
PIT5074J	8/30/2016	J-35616-64B Terminal Test Probe / Replacement Terminal / Terminated Lead	Electrical	View
PIC5494G	8/12/2016	Difference Between Analog And Digital Vehicle Speed Display	Electrical	View
03-06-03-004R	8/12/2016	Warranty Administration - Battery Testing and Warranty Replacement Requirements (North America ONLY)	Electrical	View
PIC6166	7/1/2016	Diagnostic Tip - Service Power Steering Message, Reduced Steering Assist, ABS / Traction Control / Stability Lamps Illuminated, Loss of EBCM communication, Various DTCs Intermittently	Electrical	View
PIP5094A	6/14/2016	Prior To Any Circuit Testing	Electrical	View
10-00-89-005F	5/16/2016	Warranty Administration - Revised Wiring Repair Labor Operations and Required Additional Information	Electrical	View
15-08-42-001A	5/13/2016	Exterior Lighting Components Tinted or Smoked by an Outside Vendor	Electrical	View
12-08-132-001D	5/13/2016	Accessory Power Outlet and Trailer Lighting Fuse Replacement - Use Global Labor Operation 5430130 Fuse Replacement	Electrical	View
03-06-03-004Q	4/22/2016	Warranty Administration - Battery Testing and Warranty Replacement Requirements (North America ONLY)	Electrical	View
15-06-03-001B	4/20/2016	Cold Weather and Long Stand Time Battery Maintenance and Testing Tips	Electrical	View
PIC4935E	4/19/2016	Normal Characteristic - OnStar Power Consumption	Electrical	View
16-NA-055	3/11/2016	Information Regarding Servicing Components Located Near SIR Components	Electrical	View
PIP5232C	3/4/2016	Premature Catalytic Converter Failures	Electrical	View
03-06-03-004O	3/2/2016	Warranty Code Generated By EL-50313 Midtronics GR8 Battery Tester/Charger Required for Claim Processing On Labor Operation 4041510, 4041520 and 250 Mile/400 Km Labor Operation Restriction (North America ONLY)	Electrical	View
03-00-89-006M	3/2/2016	New Vehicle Pre-Delivery Inspection (PDI) - Delivering Quality Vehicles and Generating Higher CSi Scores	Electrical	View
09-00-89-002M	3/2/2016	Properly Maintaining Vehicles in Dealer Inventory	Electrical	View

02-08-42-001I	2/12/2016	Headlamp, Tail Lamp, License Lamp or Fog/Driving Lamp Damage	Electrical	View
PIT4720D	2/8/2016	Odometer Servicing When The Odometer Cannot Be Set To The Actual Mileage	Electrical	View
01-08-42-001K	2/8/2016	Exterior Lamp Condensation and Replacement Guidelines	Electrical	View
06-08-50-009I	1/28/2016	Information on Passenger Presence Sensing System (PPS or PSS) Concerns with Custom Upholstery, Accessory Seat Heaters or Other Comfort Enhancing Devices	Electrical	View
PIC3100E	11/23/2015	Verifying Odometer Accuracy	Electrical	View
10-00-89-005E	11/12/2015	Warranty Administration - Revised Wiring Repair Labor Operations and Required Additional Information	Electrical	View
PI1533	10/31/2015	Poor Radio Hands-free Voice Recognition Performance or Sound Quality After OnStar Upgrade	Electrical	View
15-08-44-001F	10/31/2015	GM of Canada OnStar Cellular Communication Upgrade	Electrical	View
06-00-89-026M	10/31/2015	Warranty Administration - Revised Customer Concern Not Duplicated (CCND) / Verified Labor Operation Numbers/How to Submit CCND Transactions in Global Warranty Management	Electrical	View
PIC4740F	10/31/2015	No Crank - Multiple Warning Telltales On - Trans Shifts Hard	Electrical	View
15-06-03-001A	10/31/2015	Cold Weather and Long Stand Time Battery Maintenance and Testing Tips	Electrical	View
08-08-44-029F	10/31/2015	Updated Warranty and Policy Exchange Program for Electronic Products (U.S. and Canada)	Electrical	View
15-NA-030	10/31/2015	Information on the Use of Non GM Approved Battery Chargers and Booster Packs	Electrical	View
10-08-45-001E	10/31/2015	Information for Electrical Ground Repair - Use New Replacement Fasteners with Conductive Finish	Electrical	View
PIC4740E	10/31/2015	No Crank Multiple Warning Telltales On Trans Shifts Hard	Electrical	View
03-06-03-003D	10/31/2015	ACDelco® Replacement Battery Warranty Procedures	Electrical	View
06-08-47-001K	10/31/2015	Warranty, SPS, Control Module Diagnostics and Configuration Information, Programming, Set-Up	Electrical	View
PI1018A	10/31/201	Information on Poor, Limited, Reduced Remote	Electrical	

	5	Keyless Entry (RKE) or Remote Vehicle Start (RVS) Range		View
PIC5261B	10/31/2015	Tail Lamp Lens Sticking Out From Body	Electrical	View
15-08-42-001	10/31/2015	Exterior Lighting Components Tinted or Smoked by an Outside Vendor	Electrical	View
10-08-42-001D	10/31/2015	Low Beam Headlamp Bulb Diagnosis/Replacement (Inspect Bulb and Connector)	Electrical	View
PI0734A	10/31/2015	Rear Door Glass Lowers without Window Switch Activation, Especially after Car Wash or Rain	Electrical	View
10-00-89-005D	10/31/2015	Warranty Administration - Revised Wiring Repair Labor Operations and Required Additional Information	Electrical	View
PIT5074H	10/31/2015	J-35616-64B Terminal Test Probe / Replacement Terminal / Terminated Lead	Electrical	View
15-06-03-001	10/31/2015	Cold Weather and Long Stand Time Battery Maintenance and Testing Tips	Electrical	View
12-08-132-001C	9/12/2015	Accessory Power Outlet and Trailer Lighting Fuse Replacement - Use Global Labor Operation 5430130 Fuse Replacement	Electrical	View
03-06-03-004N	9/5/2015	Warranty Code Generated By EL-50313 Midtronics GR8 Battery Tester/Charger Required for Claim Processing On Labor Operation 4041510, 4041520 and 250 Mile/400 Km Labor Operation Restriction (North America ONLY)	Electrical	View
13-00-89-008A	9/5/2015	GM Wiring Repair Strategy Information	Electrical	View
09-00-89-002L	8/1/2015	Properly Maintaining Vehicles in Dealer Inventory	Electrical	View
03-06-03-003E	7/25/2015	ACDelco Replacement Battery Warranty Procedures	Electrical	View
PIC5650B	7/4/2015	Diagnostic Tip - Security Light On Intermittently / No Crank/No Start Or Start Stall And Keyless Access Vehicles May Display No Remote/Fob Detected	Electrical	View
09-00-89-002K	6/6/2015	Properly Maintaining Vehicles in Dealer Inventory	Electrical	View
02-08-42-001H	5/2/2015	Headlamp, Tail Lamp, License Lamp or Fog/Driving Lamp Damage	Electrical	View
PIT5028B	4/25/2015	Diagnostic Tip - Vehicle Start And Stalls After Theft Deterrent Module Replacement	Electrical	View

13-08-116-001B	3/28/2015	Aftermarket ALDL or DLC Interface Devices Causing Multiple Issues	Electrical	View
09-00-89-016D	3/14/2015	Warranty Administration â€“ Labor Operation 0600014 â€“ Suspected Tampering or Vehicle Modifications	Electrical	View
06-08-50-009H	1/31/2015	Information on Passenger Presence Sensing System (PPS or PSS) Concerns with Custom Upholstery, Accessory Seat Heaters or Other Comfort Enhancing Devices	Electrical	View
10-08-46-001B	1/1/2015	Radio Does Not Mute Enough When OnStar Turn-By-Turn Navigation Directions Are Announced (Increase Volume Setting or Request Soft Mute Feature Change Through OnStar Customer Service)	Electrical	View
PIC5514D	9/8/2014	Unwanted Decklid Opening On Vehicles With Keyless Access	Electrical	View
14233	8/20/2014	Product Safety - Inadvertent Air Bag Deployment	Electrical	View
PIP5209A	8/18/2014	P00C6 P228C Diagnostic Assistance	Electrical	View
PIT3099M	8/8/2014	Concerns Or Questions Regarding The Installation Of Dealer Installed Accessories	Electrical	View
12-08-132-001B	7/17/2014	Accessory Power Outlet and Trailer Lighting Fuse Replacement - Use GLC Labor Operation 5430130 Fuse Replacement	Electrical	View
PI0938A	7/14/2014	Powertrain and Various Electrical/Electronic Control Issues	Electrical	View
PIP5209	6/27/2014	P00C6 P228C Diagnostic Assistance	Electrical	View
PI1266	6/19/2014	Radio Reprogramming Using Techline/Service Programming System (SPS) - Ensuring Correct Vehicle Selection	Electrical	View
PIP4653E	6/3/2014	DTCs P0601 P0603 P0604 P062F or P1621 (Stored In The TCM)	Electrical	View
PIC6002	5/20/2014	Diagnostic Tip - Repeat BCM Replacement	Electrical	View
PI1233	5/16/2014	DTC Symptom Byte Documentation	Electrical	View
PIP5180	2/8/2014	Diagnostic Tips For SIDI Hard Start Cold	Electrical	View
PI0360C	2/4/2014	Accessory Remote Start Does Not Work with OnStar Remote Link Phone Application	Electrical	View

PIC5959	2/1/2014	No Audio On Certain XM Radio Channels	Electrical	View
PIC5491D	10/5/2013	OnStar Will Not Power Up	Electrical	View
PIC5491C	9/14/2013	OnStar Will Not Power Up	Electrical	View
11-00-90-001B	6/19/2013	Global Information for GM dexos 1 and dexos 2 Engine Oil Specifications, Licensed Brands, and Service Fill	Electrical	View
08-07-30-026B	6/19/2013	Information on Slight Vehicle Movement in Park at Start Up After Cold Soak	Electrical	View
03-08-48-006I	6/19/2013	Repair Information for Reconnection of Rear Window Defroster (Defogger) Contact or Tab	Electrical	View
PI0086E	5/31/2013	Unexpected Loss of Radio Audio (Radio Goes Silent/No Sound) and Other Blackberry Phone - Bluetooth Issues	Electrical	View
PIT5074G	5/15/2013	J-35616-64B Terminal Test Probe And Replacement Terminal	Electrical	View
PIT4720C	4/23/2013	Odometer Servicing When The Odometer Cannot Be Set To The Actual Mileage	Electrical	View
99-04-20-002H	4/12/2013	Information on Driveline Clunk Noise	Electrical	View
13-00-89-003	3/29/2013	Vehicle Software Enhancements	Electrical	View
12-08-132-001A	3/29/2013	Accessory Power Outlet and Trailer Lighting Fuse Replacement Labor Operation N1720 Fuse Replacement	Electrical	View
PI0938	3/29/2013	Powertrain and Various Electrical/Electronic Control Issues	Electrical	View
03-00-91-001F	3/22/2013	Vibration Analysis Worksheet	Electrical	View
PIC5491B	3/22/2013	OnStar Will Not Power Up	Electrical	View
13-08-116-001A	3/22/2013	Aftermarket ALDL or DLC Interface Devices Causing Multiple Issues	Electrical	View
99-08-51-001C	3/1/2013	Paint-less Dent Repair Process	Electrical	View
06-08-44-012F	3/1/2013	DVD Navigation Update Program, Navigation Disc Diagnostic Aid, AVN Software Update Discs and	Electrical	View

		Ordering Information		
PI0412B	3/1/2013	No Crank/No Start, Dead Battery Due to Parasitic Drain/Discharge	Electrical	View
06-08-43-003D	2/15/2013	Windshield Wiper Performance, Cleaning Instructions and Maintenance	Electrical	View
10-08-45-001D	2/15/2013	Information for Electrical Ground Repair - Use New Replacement Fasteners with Conductive Finish	Electrical	View
PIP5094	2/11/2013	Prior To Any Circuit Testing	Electrical	View
PI0412A	1/11/2013	No Crank/No Start, Dead Battery Due to Parasitic Drain/Discharge	Electrical	View
07-08-49-020G	1/1/2013	IPC Odometer Programming Method Quick Reference Guide	Electrical	View
12-08-132-001	1/1/2013	Accessory Power Outlet and Trailer Lighting Fuse Replacement Labor Operation N1720 Fuse Replacement	Electrical	View
PIC5687C	12/17/2012	Checking Smartphone Bluetooth Software Update Status	Electrical	View
PIC5723A	12/17/2012	Navigation Map Update May Fail To Load	Electrical	View
09-00-89-002G	5/8/2012	Properly Maintaining Vehicles in Dealer Inventory	Electrical	View
03-08-44-005L	4/18/2012	Poor Radio Reception or Radio Static/Increased Interference with Rear Window Defogger On or Some Rear Window Defogger Grids May Be Inoperative	Electrical	View
08-09-41-007I	4/15/2012	Passenger Presence System (PPS) May Command Seat Belt Reminder Chime and Passenger Airbag Indicator On When Electronic Devices or Conductive Objects are Placed on Front Passenger Seat, DTCs 5045 or B0074 0F May Set in PPS Module	Electrical	View
13-00-89-004C	4/7/2012	Car and Truck Fix it Right the First Time Issues	Electrical	View
03-08-46-004L	3/5/2012	Part Restriction and Ordering Process Information for OnStar Vehicle Communication Interface Modules (VCIM)	Electrical	View
06-08-47-001I	3/3/2012	Warranty, SPS, Control Module Diagnostics and Configuration Information, Programming, Set-Up	Electrical	View
08-09-41-007G	2/29/2012	Passenger Presence System (PPS) May Command Passenger Airbag Indicator and Seat Belt Reminder On When Electronic Devices are Placed on Front Passenger Seat, DTCs 5045 or B0074 0F Set in PPS Module	Electrical	View

PI0592B	2/10/2012	Service Programming System (SPS) Errors (E4398, E4399, E4403, E4404 E4413, E4414, E4423 or E4491, E4494)	Electrical	View
10-08-42-001C	1/26/2012	Low Beam Headlamp Bulb Diagnosis/Replacement (Inspect Bulb and Connector)	Electrical	View
09-00-89-002F	1/19/2012	Properly Maintaining Vehicles in Dealer Inventory	Electrical	View
09-00-89-002H	1/14/2012	Properly Maintaining Vehicles in Dealer Inventory	Electrical	View
09-00-89-002I	1/13/2012	Properly Maintaining Vehicles in Dealer Inventory	Electrical	View
09-00-89-002J	1/13/2012	Properly Maintaining Vehicles in Dealer Inventory	Electrical	View
03-06-03-004H	10/22/2011	Warranty Code Generated By EL-50313 Midtronics GR8 Battery Tester/Charger Required for Claim Processing On Labor Operation 4041510 and Battery Part Restriction (North America ONLY)	Electrical	View
07-08-47-004E	9/14/2011	Information on Body Control Module (BCM) Grounds	Electrical	View
08-09-41-007F	8/29/2011	PPS May Command Passenger Airbag Indicator and Seat Belt Reminder On When Electronic Devices are Placed on Front Passenger Seat, DTCs 5045 or B0074 0F Set in PPS Module	Electrical	View
07-08-47-004D	8/17/2011	Information on Body Control Module (BCM) Grounds	Electrical	View
10-00-89-017H	7/22/2011	Car and Truck Fix it Right the First Time Issues	Electrical	View
09-08-48-001B	6/7/2011	Reduced AM and/or FM Station Reception (Remove/Clean Urethane from Glass or Replace Rear Window)	Electrical	View
10-08-45-001C	6/6/2011	Information for Electrical Ground Repair - Use New Replacement Fasteners with Conductive Finish	Electrical	View
11-08-44-002	5/20/2011	Audio System Speaker Noise, Distorted, Inoperative (Follow Procedure Outlined Below)	Electrical	View
07-08-49-020E	5/19/2011	IPC Odometer Programming Method Quick Reference Guide	Electrical	View
02-08-42-001E	5/13/2011	Headlamp, Tail Lamp or Fog/Driving Lamp Damage	Electrical	View
11-04-21-005A	4/27/2011	Water Leaks Attributed to Right Front Area of Sunroof and/or Service All Wheel Drive Message Displayed in Driver Information Center (DIC), DTCs C0399, C0400,	Electrical	View

		C0401 and/or U0102 Set		
10-00-89-017D	3/21/2011	Car and Truck Fix it Right the First Time Issues	Electrical	View
09-00-89-002D	2/24/2011	Properly Maintaining Vehicles in Dealer Inventory	Electrical	View
08-08-42-006B	2/18/2011	Door Trim Panel LED Pin Spot or Light Pipe Lamps Inoperative (Replace Lamps Instead of Entire Door Trim Panel Assembly)	Electrical	View
09-09-40-001A	2/2/2011	Seat Belt Buckle Latching Issues and/or Seat Belt Warning Lights Illuminated	Electrical	View
10-08-42-001B	1/24/2011	Low Beam Headlamp Bulb Diagnosis/Replacement (Inspect Bulb and Connector)	Electrical	View
01-08-42-001H	1/5/2011	Exterior Lamp Condensation and Replacement Guidelines	Electrical	View
05-08-46-004C	12/23/2010	OnStar Phone Number Concerns (Phone Number Incorrect/Assigned to Another Vehicle/Phone) That Occur During Diagnosis of OnStar System	Electrical	View
09-06-03-004D	12/8/2010	Intermittent No Crank/No Start, No Module Communication, MIL, Warning Lights, Messages or DTCs Set by Various Control Modules-Diagnosing and Repairing Fretting Corrosion	Electrical	View
07-08-49-020D	12/6/2010	IPC Odometer Programming Method Quick Reference Guide	Electrical	View
10-08-45-001B	10/25/2010	Information for Electrical Ground Repair - Use New Replacement Fasteners with Conductive Finish	Electrical	View
03-06-03-004D	10/18/2010	Warranty Code Generated by EI-50313/Charger Required for N0110, Battery Parts Rest	Electrical	View
08-00-89-029Y	9/14/2010	Car and Truck Fix It Right the First Time Issues	Electrical	View
03-08-46-004I	8/23/2010	Parts Restriction on Ordering OnStar Generation 8 and Generation 9 Vehicle Communication Interface Modules (VCIM)	Electrical	View
10-08-42-001A	8/6/2010	Low Beam Headlamp Bulb Diagnosis/Replacement (Inspect Bulb and Connector)	Electrical	View
07-06-04-019D	6/28/2010	Intermittent Malfunction Indicator Lamp (MIL) Illuminated, DTC P2138 with Reduced Engine Power (Repair Instrument Panel (IP) to Body Harness Connector)	Electrical	View
08-08-44-015B	6/11/2010	Information on Inappropriate Warranty Claims Submitted for Damaged Radios and Instrument Panel Clusters (IPCs)	Electrical	View
03-00-89-	4/28/2010	New Vehicle Pre-Delivery Inspection (PDI) - Delivering	Electrical	

006G		Quality Vehicles and Generating Higher CSi Scores		View
97-17-1	1/17/1997	Car and Truck Fix it Right the First Time Issues	Electrical	View

EMISSION CONTROL (29 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
19-NA-044	3/1/2019	Information on Black Smoke, Rough Idle and Minimal Misfires on Cold Start	Emission Control	View
PIP4112S	3/12/2018	Normal Characteristic - Sag Or Hesitation On Acceleration	Emission Control	View
03-00-89-006P	3/7/2018	New Vehicle Pre-Delivery Inspection (PDI) - Delivering Quality Vehicles and Generating Higher CSi Scores	Emission Control	View
09-06-03-004E	12/5/2017	Intermittent No Crank/No Start, No Module Communication, MIL, Warning Lights, Vehicle Messages or DTCs Set by Various Control Modules - Diagnosing and Repairing Fretting Corrosion (Disconnect Affected Connector and Apply Dielectric Lubricant)	Emission Control	View
17-NA-067	3/10/2017	Security Code Input Message with SPS Error Code E5659, M5304 and/or M5530 During TIS2web Programming	Emission Control	View
13-00-89-006	10/17/2016	Warranty Administration - Changes in Powertrain Warranty Coverage Effective with 2010 Model Year	Emission Control	View
PIC5453B	9/26/2016	Handling Requests For Modifications To Permanently Import / Export Vehicles Between The US And Canada	Emission Control	View
PIP4112Q	1/1/2016	Normal Characteristic - Sag Or Hesitation On Acceleration	Emission Control	View
15317	10/31/2015	Special Coverage Adjustment - Positive Crankcase Ventilation (PCV) Hose Replacement	Emission Control	View
PIP5325	10/31/2015	How to Identify Factory or Aftermarket CNG, LPG, Bi-Fuel Systems	Emission Control	View
14582A	10/31/2015	Special Coverage Adjustment - Throttle Body - Reduced Power Mode	Emission Control	View
06-08-47-001K	10/31/2015	Warranty, SPS, Control Module Diagnostics and Configuration Information, Programming, Set-Up	Emission Control	View
PIP5209C	10/31/2015	P00C6 P228C Diagnostic Assistance	Emission Control	View

05-06-04-060A	10/31/2015	Control Module Diagnostic Trouble Code(s) (DTC)(s) P0601, P0602, P0603, P0604, P0606, P062F, P06F3, P1621 Shared In Multiple Modules	Emission Control	View
PIP5209B	10/31/2015	P00C6 P228C Diagnostic Assistance	Emission Control	View
PIP4919D	4/4/2015	Black Smoke and Rough Idle On Cold Start	Emission Control	View
PIP5209A	8/18/2014	P00C6 P228C Diagnostic Assistance	Emission Control	View
PI0938A	7/14/2014	Powertrain and Various Electrical/Electronic Control Issues	Emission Control	View
PIP4653E	6/3/2014	DTCs P0601 P0603 P0604 P062F or P1621 (Stored In The TCM)	Emission Control	View
PIP4919B	1/24/2014	Black Smoke And Rough Idle On Cold Start	Emission Control	View
09-06-04-026G	3/22/2013	Identifying Non-GM (Aftermarket) Engine and Transmission Calibrations for V6 and V8 Gasoline Engines Using Tech 2 or Global Diagnostic System 2 (GDS 2)	Emission Control	View
13-08-116-001	2/1/2013	Aftermarket ALDL or DLC Interface Devices Causing Multiple Issues	Emission Control	View
09-06-04-026D	9/4/2012	Identifying Non-GM (Aftermarket) Engine and Transmission Calibrations for V8 Gasoline Engines Using Tech 2 or Global Diagnostic System 2 (GDS 2)	Emission Control	View
06-08-47-001I	3/3/2012	Warranty, SPS, Control Module Diagnostics and Configuration Information, Programming, Set-Up	Emission Control	View
PI0592B	2/10/2012	Service Programming System (SPS) Errors (E4398, E4399, E4403, E4404 E4413, E4414, E4423 or E4491, E4494)	Emission Control	View
10-00-89-017H	7/22/2011	Car and Truck Fix it Right the First Time Issues	Emission Control	View
10-00-89-017D	3/21/2011	Car and Truck Fix it Right the First Time Issues	Emission Control	View
10-08-98-002	8/6/2010	Information on Drilling High Strength Steel Related to Collision Repair	Emission Control	View
97-17-1	1/17/1997	Car and Truck Fix it Right the First Time Issues	Emission Control	View

EXHAUST (18 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
06-06-01-010D	1/31/2018	Information on Close-Coupled Converter and Engine Replacement	Exhaust	View
00-06-01-026J	8/31/2017	Intake Manifold Inspection/Replacement After Severe Internal Engine Damage	Exhaust	View
PIP4925A	4/25/2017	SES Light with Fuel Trim and or Oxygen Sensor Codes	Exhaust	View
PI0281F	4/12/2017	Underbody Component Corrosion	Exhaust	View
PI0706A	9/30/2016	Exhaust Noise/Moan/Drone/Resonance Just Above Warm Idle Speed While in Drive with Foot on Brake	Exhaust	View
PIP5232C	3/4/2016	Premature Catalytic Converter Failures	Exhaust	View
03-00-89-006M	3/2/2016	New Vehicle Pre-Delivery Inspection (PDI) - Delivering Quality Vehicles and Generating Higher CSi Scores	Exhaust	View
09-00-89-002M	3/2/2016	Properly Maintaining Vehicles in Dealer Inventory	Exhaust	View
06-06-01-010C	1/14/2016	Information on Close-Coupled Converter and Engine Replacement	Exhaust	View
PIP5232B	11/30/2015	Premature Catalytic Converter Failures	Exhaust	View
06-00-89-026M	10/31/2015	Warranty Administration - Revised Customer Concern Not Duplicated (CCND) / Verified Labor Operation Numbers/How to Submit CCND Transactions in Global Warranty Management	Exhaust	View
09-00-89-002K	6/6/2015	Properly Maintaining Vehicles in Dealer Inventory	Exhaust	View
PIP4964C	1/17/2014	SES Light With A P2097 Or P2099	Exhaust	View
PIP4964B	4/9/2013	SES Light With A P2097 Or P2099	Exhaust	View
09-06-04-026F	2/1/2013	Identifying Non-GM (Aftermarket) Engine and Transmission Calibrations for V6 and V8 Gasoline Engines Using Tech 2 or Global Diagnostic System 2 (GDS 2)	Exhaust	View
09-06-04-026E	1/1/2013	Identifying Non-GM (Aftermarket) Engine and Transmission Calibrations for V8 Gasoline Engines Using Tech 2 or Global Diagnostic System 2 (GDS 2)	Exhaust	View

10-00-89-017D	3/21/2011	Car and Truck Fix it Right the First Time Issues	Exhaust	View
08-00-89-029Y	9/14/2010	Car and Truck Fix It Right the First Time Issues	Exhaust	View

FUEL &SPARK (83 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
PIP5540F	1/14/2020	Diagnostic Tip: Poor Engine Performance Or CEL On In Cold Ambient Temperatures On Vehicles Equipped With Turbocharged Gasoline Engines May Set One Or More Of The Following DTCs P0299 P2227	Fuel &Spark	View
PIP5684	10/22/2019	GE-52250 Power Smoke Diagnostic Leak Detector Turbocharger Charge Air And Induction System Tester MIL Reduced Engine Power	Fuel &Spark	View
PIP5528D	9/6/2019	Information Assistance for HFV6 Re-Manufactured Engine Misfire Diagnosis	Fuel &Spark	View
05-06-04-022Q	6/26/2019	TOP TIER Detergent Gasoline and TOP TIER Diesel Fuel Information and Licensed Brands	Fuel &Spark	View
06-08-47-001O	6/19/2019	Warranty Administration - Warranty SPS Control Module Reprogramming	Fuel &Spark	View
PIP4964D	6/18/2019	SES Light With A P2097 Or P2099	Fuel &Spark	View
05-06-04-022P	3/7/2019	TOP TIER Detergent Gasoline and TOP TIER Diesel Fuel Information and Licensed Brands	Fuel &Spark	View
19-NA-044	3/1/2019	Information on Black Smoke, Rough Idle and Minimal Misfires on Cold Start	Fuel &Spark	View
PIP5627	2/15/2019	Diagnostic Tips For I/M Flags Resetting After Ignition Cycled	Fuel &Spark	View
PIP4925B	12/3/2018	SES Light with Fuel Trim and or Oxygen Sensor Codes	Fuel &Spark	View
PIP5596	10/3/2018	Diagnostic Tip: Fuel Injected Gasoline Engines Possible No Start Extended Crank or Fuel Pressure Related DTCs	Fuel &Spark	View
09-06-04-015C	2/27/2018	Information on Vehicles Sitting Outside on Dealer Lots for Extended Periods of Time with Hard Start or Crank/No Start Condition	Fuel &Spark	View
PIP5180B	2/6/2018	Diagnostic Tips For Direct Injected Engines Hard Start Cold	Fuel &Spark	View

04-07-30-013D	11/22/2017	Automatic Transmission Shift and Engine Driveability Concerns and/or MIL ON Due to Aftermarket Oil Bath Type Air Filter Use	Fuel &Spark	View
17-NA-244	7/25/2017	Information on How to Prevent Inadvertent Vehicle Starting from Key Fob or OnStar Mobile Application	Fuel &Spark	View
09-00-89-002O	6/16/2017	Properly Maintaining Vehicles in Dealer Inventory	Fuel &Spark	View
14497C	6/12/2017	Product Safety Recall - Unintended Ignition Key Rotation	Fuel &Spark	View
44180-02	2/20/2017	Customer Satisfaction Program - Vehicles with Key Codes Improperly Handled by Third Party	Fuel &Spark	View
07-06-04-025L	2/13/2017	Information on Clicking/Ticking Sound/Noise Heard During Cold Start	Fuel &Spark	View
PIP5180A	1/24/2017	Diagnostic Tips For SIDI Hard Start Cold	Fuel &Spark	View
15-06-01-003A	12/22/2016	Supercharger Noise	Fuel &Spark	View
13-00-89-006	10/17/2016	Warranty Administration - Changes in Powertrain Warranty Coverage Effective with 2010 Model Year	Fuel &Spark	View
09-00-89-002N	10/7/2016	Properly Maintaining Vehicles in Dealer Inventory	Fuel &Spark	View
05-06-04-022N	10/6/2016	TOP TIER Detergent Gasoline Information and Available Brands	Fuel &Spark	View
05-00-89-072D	9/1/2016	Fuel and Oil Additives - Facts and Myths - Maximizing Gasoline Fuel Economy	Fuel &Spark	View
16-NA-260	8/26/2016	Key Replacement Due to Incorrect Keys Purchased	Fuel &Spark	View
00-06-01-012F	8/2/2016	Use of Surface Conditioning Disks When Cleaning Engine Gasket Sealing Surfaces and/or Reused Engine Parts	Fuel &Spark	View
PIC6166	7/1/2016	Diagnostic Tip - Service Power Steering Message, Reduced Steering Assist, ABS / Traction Control / Stability Lamps Illuminated, Loss of EBCM communication, Various DTCs Intermittently	Fuel &Spark	View
03-00-89-006M	3/2/2016	New Vehicle Pre-Delivery Inspection (PDI) - Delivering Quality Vehicles and Generating Higher CSi Scores	Fuel &Spark	View
09-00-89-002M	3/2/2016	Properly Maintaining Vehicles in Dealer Inventory	Fuel &Spark	View
PIP4112Q	1/1/2016	Normal Characteristic - Sag Or Hesitation On	Fuel	

		Acceleration	&Spark	View
15-06-01-003	11/4/2015	Supercharger Noise	Fuel &Spark	View
14582	10/31/2015	Special Coverage Adjustment - Throttle Body - Reduced Power Mode	Fuel &Spark	View
06-00-89-026M	10/31/2015	Warranty Administration - Revised Customer Concern Not Duplicated (CCND) / Verified Labor Operation Numbers/How to Submit CCND Transactions in Global Warranty Management	Fuel &Spark	View
14172D	10/31/2015	Product Safety - Unintended Ignition Key Rotation	Fuel &Spark	View
05-06-04-022L	10/31/2015	TOP TIER Detergent Gasoline Information and Available Brands	Fuel &Spark	View
PIP5318	10/31/2015	P0300 Misfire At Speeds Of 70 MPH - 3rd Gear - 3500 â€“ 4500 RPMS	Fuel &Spark	View
PIP4919E	10/31/2015	Black Smoke and Rough Idle on Cold Start	Fuel &Spark	View
PIP5325	10/31/2015	How to Identify Factory or Aftermarket CNG, LPG, Bi-Fuel Systems	Fuel &Spark	View
04-07-30-013C	10/31/2015	Automatic Transmission Shift and Engine Driveability Concerns and/or MIL ON Due to Aftermarket Oil Bath Type Air Filter Use	Fuel &Spark	View
14582A	10/31/2015	Special Coverage Adjustment - Throttle Body - Reduced Power Mode	Fuel &Spark	View
14497B	10/31/2015	Product Safety - Unintended Ignition Key Rotation	Fuel &Spark	View
14515B	10/31/2015	Product Safety - Chassis Electronic Control Module Internal Contamination	Fuel &Spark	View
04-06-04-051D	10/31/2015	Maintenance Cleaning of Fuel Injectors	Fuel &Spark	View
05-06-04-022M	7/12/2015	TOP TIER Detergent Gasoline Information and Available Brands	Fuel &Spark	View
14172C	6/1/2015	Product Safety - Unintended Ignition Key Rotation	Fuel &Spark	View
14497A	6/1/2015	Product Safety - Unintended Ignition Key Rotation	Fuel &Spark	View
14172A	6/1/2015	Product Safety - Unintended Ignition Key Rotation	Fuel &Spark	View

14172B	6/1/2015	Product Safety - Unintended Ignition Key Rotation	Fuel &Spark	View
05-06-04-035E	5/30/2015	Usage of E85 Fuel in GM Vehicles	Fuel &Spark	View
15-00-89-004A	5/23/2015	Information Regarding the Differences Between Leakage and Seepage	Fuel &Spark	View
PI0091B	5/2/2015	Intermittently Key Will Not Rotate in Door or Ignition Lock Cylinder	Fuel &Spark	View
15-00-89-004	5/2/2015	Information Regarding the Differences Between Leakage and Seepage	Fuel &Spark	View
12-07-30-001E	3/28/2015	Product Quality Center (PQC) Assembly Replacement Process - For Service Agents Not Required to Contact PQC Prior to Assembly Replacement	Fuel &Spark	View
14497	9/15/2014	Product Safety - Unintended Ignition Key Rotation	Fuel &Spark	View
PIP5192B	9/11/2014	Supercharger Rattle Or Buzz	Fuel &Spark	View
13313	7/17/2014	Special Coverage Adjustment - Supercharger Warranty Extension	Fuel &Spark	View
14172	7/2/2014	Product Safety - Unintended Ignition Key Rotation	Fuel &Spark	View
PIP5187	3/7/2014	P0174 After Cylinder Head Replacement	Fuel &Spark	View
PIP5180	2/8/2014	Diagnostic Tips For SIDI Hard Start Cold	Fuel &Spark	View
PIP4919B	1/24/2014	Black Smoke And Rough Idle On Cold Start	Fuel &Spark	View
PIP4924D	1/22/2014	SES Light And Misfire With Injector Codes	Fuel &Spark	View
PIP4964C	1/17/2014	SES Light With A P2097 Or P2099	Fuel &Spark	View
PIP4919A	1/8/2014	Black Smoke On Cold Start	Fuel &Spark	View
PIP5095B	10/3/2013	Fluid In Spark Plug Tubes	Fuel &Spark	View
PIP4964B	4/9/2013	SES Light With A P2097 Or P2099	Fuel &Spark	View

PIP4924C	4/9/2013	SES Light And Misfire With Injector Codes	Fuel &Spark	View
PIP4819A	2/5/2013	SES Light due to P0300-P0308 and Engine Misfires - Inspect Plug Wire	Fuel &Spark	View
03-06-04-030H	1/1/2013	Various Driveability Symptoms Due to Clogged Fuel Injectors, MIL/SES DTCs P0171, P0172, P0174, P0300, P1174, P1175 (Clean Fuel Injectors and/or Perform Injector Test With AFIT CH-47976)	Fuel &Spark	View
07-06-04-025G	3/25/2012	Information on Clicking/Ticking Sound/Noise Heard During Cold Start, Sound/Noise Decreases But Continues as Engine Warms - Normal Operation of High Pressure Fuel Pump and Injectors	Fuel &Spark	View
07-06-04-025H	3/21/2012	Information on Clicking/Ticking Sound/Noise Heard During Cold Start	Fuel &Spark	View
07-06-04-025I	3/20/2012	Information on Clicking/Ticking Sound/Noise Heard During Cold Start	Fuel &Spark	View
07-06-04-025K	3/20/2012	Information on Clicking/Ticking Sound/Noise Heard During Cold Start	Fuel &Spark	View
09-00-89-002F	1/19/2012	Properly Maintaining Vehicles in Dealer Inventory	Fuel &Spark	View
09-00-89-002H	1/14/2012	Properly Maintaining Vehicles in Dealer Inventory	Fuel &Spark	View
10-00-89-017H	7/22/2011	Car and Truck Fix it Right the First Time Issues	Fuel &Spark	View
10-00-89-010A	7/15/2011	Key Code Security Rules and Information on GM KeyCode Look-Up Application (Canada Only)	Fuel &Spark	View
10-00-89-017D	3/21/2011	Car and Truck Fix it Right the First Time Issues	Fuel &Spark	View
07-06-04-025F	12/13/2010	Information on Clicking/Ticking Sound/Noise Heard During Cold Start, Sound/Noise Decreases But Continues As Engine Warms - Normal Operation of High Pressure Fuel Pump and Injectors	Fuel &Spark	View
10-06-04-015	12/8/2010	General Motors Position Regarding the Environmental Protection Agencys Partial Waiver Announcement Allowing the Use of E 15 in MY 2007 and Newer Vehicles	Fuel &Spark	View
05-06-04-022G	10/27/2010	TOP TIER Detergent Gasoline Information and Available Brands (Deposits, Fuel Economy, No Start, Stall Concerns) Canada Only	Fuel &Spark	View
09-06-04-015A	7/2/2010	Information on Vehicles Sitting Outside on Dealer Lots for Extended Periods of Time with Hard Start or Crank/No Start Condition	Fuel &Spark	View
04-06-01-	4/29/2010	Unnecessary Flushing Services, Additive	Fuel	

029E		Recommendations and Proper Utilization of GM Simplified Maintenance Schedule to Enhance Customer Service Experience	&Spark	View

HVAC (24 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
PIT5099D	10/10/2018	AC Blows Warm or Poor Performance	HVAC	View
18-NA-271	9/5/2018	Information on A/C Odors During Start Up in Hot Humid Climates	HVAC	View
PI1440	8/22/2018	Diagnostic Tips for Odor Emanating from HVAC System	HVAC	View
PIT5099C	6/20/2018	AC Blows Warm or Poor Performance	HVAC	View
99-01-39-004I	6/14/2017	Air Conditioning Odor (Install Evaporator Core Dryer Kit and Apply Cooling Coil Coating)	HVAC	View
PI0757A	9/30/2016	AM Radio Interference When Operating Rear Window Defroster (Defogger)	HVAC	View
04-06-01-029H	2/11/2016	Unscheduled Supplemental Services (Including Flushing Services and Additives) and Proper Use of GM Simplified Maintenance Schedules (U.S. Only)	HVAC	View
06-08-50-009I	1/28/2016	Information on Passenger Presence Sensing System (PPS or PSS) Concerns with Custom Upholstery, Accessory Seat Heaters or Other Comfort Enhancing Devices	HVAC	View
99-01-39-004F	12/5/2015	Air Conditioning Odor (Install Evaporator Core Dryer Kit and Apply Cooling Coil Coating)	HVAC	View
06-00-89-026M	10/31/2015	Warranty Administration - Revised Customer Concern Not Duplicated (CCND) / Verified Labor Operation Numbers/How to Submit CCND Transactions in Global Warranty Management	HVAC	View
03-08-48-006J	10/31/2015	Repair Information for Reconnection of Rear Window (Defroster) Contact or Tab	HVAC	View
99-01-39-004H	9/12/2015	Air Conditioning Odor (Install Evaporator Core Dryer Kit and Apply Cooling Coil Coating)	HVAC	View
99-01-39-004G	7/25/2015	Air Conditioning Odor (Install Evaporator Core Dryer Kit and Apply Cooling Coil Coating)	HVAC	View
15-00-89-004A	5/23/2015	Information Regarding the Differences Between Leakage and Seepage	HVAC	View

15-00-89-004	5/2/2015	Information Regarding the Differences Between Leakage and Seepage	HVAC	View
12-06-01-008B	3/14/2015	Unscheduled Supplemental Services (Including Flushing Services and Additives) and Proper Use of GM Simplified Maintenance Schedules (Canada Only)	HVAC	View
PI1277	7/11/2014	Information Regarding A/C Service Valve Tethered Cap Requirements in the State of Idaho	HVAC	View
00-00-89-027H	10/13/2011	Eliminating Unwanted Odors in Vehicles	HVAC	View
99-01-39-004D	8/10/2011	Air Conditioning Odor (Install Evaporator Core Dryer Kit and Apply Cooling Coil Coating)	HVAC	View
10-00-89-017H	7/22/2011	Car and Truck Fix it Right the First Time Issues	HVAC	View
03-08-48-006H	4/11/2011	Repair Information for Reconnection of Rear Window Defroster Contact or Tab	HVAC	View
10-00-89-017D	3/21/2011	Car and Truck Fix it Right the First Time Issues	HVAC	View
06-08-50-009F	12/23/2010	Information on Passenger Presence Sensing System (PPS or PSS) Concerns with Custom Upholstery, Accessory Seat Heaters or Other Comfort Enhancing Devices	HVAC	View
04-06-01-029E	4/29/2010	Unnecessary Flushing Services, Additive Recommendations and Proper Utilization of GM Simplified Maintenance Schedule to Enhance Customer Service Experience	HVAC	View

POWERTRAIN (240 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
19-NA-256	11/18/2019	Diagnostic Tips for Knocking, Rattle, Squeak and/or Squeal Type Noise from Engine - Engine Replacement Recommendations for HFV6 Gen 1 and Gen 2	Powertrain	View
99-04-20-002K	10/29/2019	Information on Driveline Clunk Noise	Powertrain	View
01-06-01-011K	10/9/2019	Information on Engine Oil Consumption Guidelines	Powertrain	View
19-NA-219	9/20/2019	Diagnostic Tip on Misfire, Chirp, Squeak, Squeal or Tick Noise, Malfunction Indicator Lamp (MIL) Illuminated - DTC P0300, P0301, P0302, P0303, P0304, P0305, P0306, P0307 and/or P0308 Set	Powertrain	View
PIP5528D	9/6/2019	Information Assistance for HFV6 Re-Manufactured	Powertrain	

		Engine Misfire Diagnosis		View
13-00-89-008B	8/19/2019	GM Wiring Repair Strategy Information	Powertrain	View
00-06-01-026M	8/15/2019	Engine Replacement After Severe Internal Engine Damage - Replace Intake Manifold	Powertrain	View
07-06-01-016F	8/13/2019	Information on Internal Engine Noise or Damage After Oil Filter Replacement	Powertrain	View
08-07-30-026F	8/12/2019	Information on Slight Vehicle Movement in Park at Start Up After Cold Soak	Powertrain	View
PIP4158H	8/7/2019	Low Oil Pump Pressure Due To Sticking Oil Pressure Relief Valve	Powertrain	View
PI1344C	7/16/2019	Diagnostic Tips for Reduced Acceleration at Low Speed and/or Transmission Slipping from a Launch, DTC P0751 Set	Powertrain	View
PIP5257C	7/9/2019	Cooling System Contaminated With Engine Oil	Powertrain	View
13-08-116-001E	6/26/2019	Aftermarket ALDL or DLC Interface Devices Causing Multiple Issues	Powertrain	View
00-06-01-012J	6/25/2019	Use of Surface Conditioning Disks When Cleaning Gasket Sealing Surfaces and/or Reused Parts	Powertrain	View
PIP5528C	6/24/2019	Information Assistance for HFV6 Re-Manufactured Engine Misfire Diagnosis	Powertrain	View
06-08-47-001O	6/19/2019	Warranty Administration - Warranty SPS Control Module Reprogramming	Powertrain	View
08-07-30-035D	5/20/2019	Information on Water or Ethylene Glycol in Transmission Fluid	Powertrain	View
PIP5528B	5/10/2019	Information Assistance for HFV6 Re-Manufactured Engine Misfire Diagnosis	Powertrain	View
PIP5640	5/7/2019	Avoiding Torque Converter Or Crankshaft Damage While Diagnosing Noise Concerns Do Not Separate The Torque Converter From the Flex Plate	Powertrain	View
PIP5226C	5/6/2019	Needle Bearings Found In The Oil Pan During An Oil Change	Powertrain	View
PIP5569A	4/24/2019	Module Damage From Incorrect AFIT Usage On Vehicles With Direct Fuel Injection	Powertrain	View
PIP5216G	4/8/2019	Engine Replacement Recommendations for HFV6 Gen 1 and Gen 2	Powertrain	View

03-07-29-004L	4/2/2019	Manual Transmission Operating Characteristics	Powertrain	View
19-NA-044	3/1/2019	Information on Black Smoke, Rough Idle and Minimal Misfires on Cold Start	Powertrain	View
PIP4021D	2/21/2019	High Pitch Whine or Buzz Noise Heard From Under The Vehicle	Powertrain	View
PIP5528A	2/19/2019	Information Assistance for HFV6 Re-Manufactured Engine Misfire Diagnosis	Powertrain	View
PIP5628	2/18/2019	Misfire Template	Powertrain	View
12-06-01-003C	2/13/2019	Information for Repairing Engine Front Cover Oil Leak, Sealing Surface Preparation and Applying RTV Sealant	Powertrain	View
PIC5650F	1/22/2019	Diagnostic Tip - Security Light on Intermittently / No Crank/No Start or Start Stall / Keyless Access Vehicles May Display No Remote/Fob Detected / Poor or No RKE Range / Service TPo	Powertrain	View
PIP5540C	1/11/2019	Poor Engine Performance Or CEL On In Cold Ambient Temperatures On Vehicles Equipped With Turbocharged Gasoline Engines May Set One Or More Of The Following DTCs P0299 P2227	Powertrain	View
PIP5540B	12/6/2018	Poor Engine Performance Or CEL On In Cold Ambient Temperatures On Vehicles Equipped With Turbocharged Gasoline Engines May Set One Or More Of The Following DTCs P0171 P0172 P0299 P2227	Powertrain	View
06-08-47-001N	12/5/2018	Warranty Administration - Warranty, SPS, Control Module Diagnostics and Configuration Information, Programming, Set-Up	Powertrain	View
PIP4925B	12/3/2018	SES Light with Fuel Trim and or Oxygen Sensor Codes	Powertrain	View
PIP5191C	11/6/2018	Engine Ticking Noise or oil pressure fluctuation On Cold Start	Powertrain	View
09-00-89-008D	10/30/2018	Warranty Administration - Labor Operation 0600018 - Personal Property Damage	Powertrain	View
PIP5601	10/23/2018	Vehicle Vibration Diagnosis and TAC Requests For Assistance With Vibration Related Complaints	Powertrain	View
PIP5338B	10/19/2018	Vehicle Vibration Diagnosis and TAC Requests For Assistance With Vibration Related Complaints	Powertrain	View
PIPXXXXB	10/17/2018	Vehicle Vibration Diagnosis and TAC Requests For Assistance With Vibration Related Complaints	Powertrain	View
PIP4138R	10/15/201	SES Light, Misfire, DTC P0300, And/or A Chirp,	Powertrain	

	8	Squeak, Squeal, Or Tick Noise - Potential		View
00-06-01-026L	10/3/2018	Engine Replacement After Severe Internal Engine Damage - Replace Intake Manifold	Powertrain	View
18-NA-115	10/1/2018	Cold Start Misfire and/or Rough Idle - DTC P0300 May Be Set	Powertrain	View
PIC5650E	9/26/2018	Diagnostic Tip - Security Light on Intermittently / No Crank/No Start or Start Stall / Keyless Access Vehicles May Display No Remote/Fob Detected / Poor or No RKE Range / Service TPM	Powertrain	View
06-00-89-031E	8/22/2018	OEM and Remanufactured Engine and Automatic Transmission/Transaxle Identification	Powertrain	View
PI0653E	8/22/2018	Damaged, Disassembled or Improperly Packaged Turbochargers Returned to Warranty Part Center	Powertrain	View
PIP5163D	8/8/2018	Alleged Cylinders Out Of Round	Powertrain	View
PIP5095F	8/8/2018	Fluid In Spark Plug Tubes	Powertrain	View
00-06-01-026K	7/24/2018	Intake Manifold Inspection/Replacement After Severe Internal Engine Damage	Powertrain	View
07-06-01-016E	7/24/2018	Information on Internal Engine Noise or Damage After Oil Filter Replacement	Powertrain	View
PIP5257B	7/11/2018	Cooling System Contaminated With Engine Oil	Powertrain	View
18-NA-125	4/19/2018	Information on Engine Oil Life Monitor Operation Calculation	Powertrain	View
08-07-30-035C	4/9/2018	Information on Water or Ethylene Glycol in Transmission Fluid	Powertrain	View
PIP4112S	3/12/2018	Normal Characteristic - Sag Or Hesitation On Acceleration	Powertrain	View
PIP5095E	2/21/2018	Fluid In Spark Plug Tubes	Powertrain	View
PIP5136A	2/13/2018	Oil Odor From The Engine With No Leaks	Powertrain	View
05-06-04-022O	12/21/2017	TOP TIER Detergent Gasoline and TOP TIER Diesel Fuel Information and Licensed Brands	Powertrain	View
09-06-03-004E	12/5/2017	Intermittent No Crank/No Start, No Module Communication, MIL, Warning Lights, Vehicle	Powertrain	View

		Messages or DTCs Set by Various Control Modules - Diagnosing and Repairing Fretting Corrosion (Disconnect Affected Connector and Apply Dielectric Lubricant)		
01-06-01-011J	11/30/2017	Information on Engine Oil Consumption Guidelines	Powertrain	View
PIP5528	11/21/2017	Information assistance for HFV6 re-manufactured engine misfire diagnosis	Powertrain	View
PIP3423N	11/14/2017	DTC P0016 P0017 P0018 P0019 P0008 P0009	Powertrain	View
PIC6042A	11/7/2017	Diagnostic Tip - Replacement Of Manual Shift Paddles On Steering Wheel	Powertrain	View
17-NA-307	9/26/2017	Information On Remanufactured Engine Misfire Diagnosis After Installation	Powertrain	View
00-06-01-026J	8/31/2017	Intake Manifold Inspection/Replacement After Severe Internal Engine Damage	Powertrain	View
PIP4959F	8/23/2017	Cold Start Misfires	Powertrain	View
PIP5163C	8/21/2017	Alleged Cylinders Out Of Round	Powertrain	View
PIP5216F	6/8/2017	Engine Replacement Recommendations for HFV6 Gen 1 and Gen 2	Powertrain	View
PIP5191B	6/8/2017	Engine Ticking Noise On Cold Start	Powertrain	View
PIT5214C	5/26/2017	GM TAC Support of Vehicle Vibration Complaints - U.S. and Canada Dealers Only	Powertrain	View
17-NA-066	5/10/2017	Warranty Administration - Automatic Transmission Oil Cooler Flush and Flow Test	Powertrain	View
PIP4925A	4/25/2017	SES Light with Fuel Trim and or Oxygen Sensor Codes	Powertrain	View
PI0281F	4/12/2017	Underbody Component Corrosion	Powertrain	View
99-04-20-002J	3/29/2017	Information on Driveline Clunk Noise	Powertrain	View
PIP4112R	3/24/2017	Normal Characteristic - Sag Or Hesitation On Acceleration	Powertrain	View
PIP5216E	3/14/2017	Engine Replacement Recommendations HFV6 Gen 1 Only	Powertrain	View

17-NA-067	3/10/2017	Security Code Input Message with SPS Error Code E5659, M5304 and/or M5530 During TIS2web Programming	Powertrain	View
PIP5095D	2/22/2017	Fluid in Spark Plug Tubes	Powertrain	View
PIP5180A	1/24/2017	Diagnostic Tips For SIDI Hard Start Cold	Powertrain	View
PIP4138P	12/23/2016	SES Light, Misfire, DTC P0300, and/or a Chirp, Squeak, Squeal, Or Tick Noise - Potential Valvetrain Concern	Powertrain	View
PIP5429	11/16/2016	2-3 Upshift Slip or Flare	Powertrain	View
PIP5163B	11/15/2016	Alleged Cylinders Out Of Round	Powertrain	View
08-07-30-026D	10/27/2016	Information on Slight Vehicle Movement in Park at Start Up After Cold Soak	Powertrain	View
13-00-89-006	10/17/2016	Warranty Administration - Changes in Powertrain Warranty Coverage Effective with 2010 Model Year	Powertrain	View
09-07-30-018D	10/12/2016	Warranty Administration - Change in Automatic Transmission Add Condition Documentation and Claim Submission	Powertrain	View
05-06-04-022N	10/6/2016	TOP TIER Detergent Gasoline Information and Available Brands	Powertrain	View
PI0773	9/30/2016	Diagnostic Tips for DTC P0796, Slip or No 4th, 5th or 6th Gear	Powertrain	View
PIP5282A	9/30/2016	Engine Oil Life Monitor Operation Calculation	Powertrain	View
PIP5029G	9/9/2016	Rough Idle Crank No Start Extended Crank Or Misfire Due to Excessive Carbon On Top of the Valves or Sticking Valves	Powertrain	View
PI1394A	8/29/2016	Engine Repair Tip for Installation of Pistons	Powertrain	View
00-06-01-012F	8/2/2016	Use of Surface Conditioning Disks When Cleaning Engine Gasket Sealing Surfaces and/or Reused Engine Parts	Powertrain	View
16-NA-241	7/28/2016	Engine Misfire, Ticking/Knocking Noise, No Compression due to Piston Damage, Malfunction Indicator Lamp (MIL) Illuminated	Powertrain	View
16-NA-222	7/11/2016	Information for Engine Concerns Resulting from Lack of Scheduled Maintenance, Improper Service or Aftermarket Calibrations	Powertrain	View
16-NA-085	6/22/2016	New Design Cylinder Heads	Powertrain	

				View
PIP5276F	6/10/2016	SES Lamp P0521 Setting After An Oil Change And Or Low Oil Pressure Indicated On The Instrument Panel	Powertrain	View
PIP4554M	5/4/2016	Clunk Noise After Shifting From Reverse To Drive Or Drive To Reverse And Then Accelerating	Powertrain	View
16-NA-130	4/27/2016	No Reverse, No Second After Upper Valve Body Replacement	Powertrain	View
02-07-30-029Z	4/27/2016	PQC Assembly Replacement Process - For Dealers Required to Contact PQC Prior to Replacing an Assembly (U.S. and Canada Only)	Powertrain	View
PIC4986F	4/19/2016	Normal Characteristic - Binding Felt Driving Forward Or In Reverse With Steering At Or Near Full Lock	Powertrain	View
16-NA-117	4/12/2016	Information Regarding Magnetic Drain Plugs	Powertrain	View
03-07-29-004K	4/7/2016	Manual Transmission Operating Characteristics	Powertrain	View
08-07-30-026C	3/7/2016	Information on Slight Vehicle Movement in Park at Start Up After Cold Soak	Powertrain	View
PIP4936C	3/3/2016	New Design Cylinder Heads	Powertrain	View
09-00-89-002M	3/2/2016	Properly Maintaining Vehicles in Dealer Inventory	Powertrain	View
PIP5226A	2/11/2016	Needle Bearings Found in the oil pan During An Oil Change	Powertrain	View
04-06-01-029H	2/11/2016	Unscheduled Supplemental Services (Including Flushing Services and Additives) and Proper Use of GM Simplified Maintenance Schedules (U.S. Only)	Powertrain	View
06-06-01-010C	1/14/2016	Information on Close-Coupled Converter and Engine Replacement	Powertrain	View
PIP4112Q	1/1/2016	Normal Characteristic - Sag Or Hesitation On Acceleration	Powertrain	View
06-00-89-031D	12/15/2015	OEM and Remanufactured Engine and Automatic Transmission/Transaxle Identification	Powertrain	View
PIP5216D	12/1/2015	Engine Replacement Recommendations HFV6 Gen 1 Only	Powertrain	View
PIP5216C	11/23/2015	Engine Replacement Recommendations HFV6 Gen 1 Only	Powertrain	View

PI1344B	11/6/2015	Diagnostic Tips for Reduced Acceleration at Low Speed and/or Transmission Slipping from a Launch, DTC P0751 Set	Powertrain	View
PIP5216B	11/4/2015	Engine Replacement Recommendations HFV6 Gen 1 Only	Powertrain	View
15-NA-048	11/2/2015	Clunk Noise Under Vehicle When Accelerating	Powertrain	View
99-04-20-002I	10/31/2015	Information on Driveline Clunk Noise	Powertrain	View
PIP5191A	10/31/2015	Engine Ticking Noise On Cold Start	Powertrain	View
13-00-89-010A	10/31/2015	PAC Courtesy Transportation Assistance Program	Powertrain	View
06-00-89-026M	10/31/2015	Warranty Administration - Revised Customer Concern Not Duplicated (CCND) / Verified Labor Operation Numbers/How to Submit CCND Transactions in Global Warranty Management	Powertrain	View
PIP5029F	10/31/2015	Rough Idle Crank No Start Extended Crank or Misfire Due to Excessive Carbon On Top of the Valves or Sticking Valves	Powertrain	View
PI1344A	10/31/2015	Diagnostic Tips for Reduced Acceleration at Low Speed and/or Transmission Slipping from a Launch, DTC P0751 Set	Powertrain	View
PIC4740F	10/31/2015	No Crank - Multiple Warning Telltales On - Trans Shifts Hard	Powertrain	View
PIP5318	10/31/2015	P0300 Misfire At Speeds Of 70 MPH - 3rd Gear - 3500 â€“ 4500 RPMS	Powertrain	View
PIP3423M	10/31/2015	DTC P0016 P0017 P0018 P0019 P0008 P0009	Powertrain	View
PIP5095C	10/31/2015	Fluid In Spark Plug Tubes	Powertrain	View
01-06-01-011I	10/31/2015	Information on Engine Oil Consumption Guidelines	Powertrain	View
06-00-89-031C	10/31/2015	Engine and Automatic Transmission/Transaxle Identification	Powertrain	View
PIP3423L	10/31/2015	DTC P0016 P0017 P0018 P0019 P0008 P0009	Powertrain	View
PIP4404F	10/31/2015	Slight Roughness at Idle with No DTCs - Possible Characteristic	Powertrain	View
14515B	10/31/201	Product Safety - Chassis Electronic Control Module	Powertrain	

	5	Internal Contamination		View
PIP5264	10/31/2015	Deceleration Misfire On All Cylinders 1400 RPM To 1800 RPM Diagnosis	Powertrain	View
PI1404	10/31/2015	Diagnostic Tip for Low Line Pressure or Pressure Regulator Valve Stuck After Pump Cover Replacement	Powertrain	View
PIP5257	10/31/2015	Cooling System Contaminated With Engine Oil	Powertrain	View
PIC4740E	10/31/2015	No Crank Multiple Warning Telltales On Trans Shifts Hard	Powertrain	View
PIP5209C	10/31/2015	P00C6 P228C Diagnostic Assistance	Powertrain	View
12-06-01-009F	10/31/2015	Information on High Feature V6 Timing Chain Kits and Chain Guide Replacements, DTCs P0008, P0009, P0016, P0017, P0018 and/or P0019	Powertrain	View
15-00-90-001	10/31/2015	Diagnostic Tips for Preventing Oil Leaks After Changing Oil and Filter	Powertrain	View
PIP4554L	10/31/2015	Clunk Noise after Shifting from Reverse to Drive Or Drive to Reverse and then Accelerating	Powertrain	View
10-04-20-001F	10/31/2015	Rear Axle Clunk and/or Chatter Type Noise on Turns (Drain/Refill Rear Differential Fluid)	Powertrain	View
03-00-91-001G	10/31/2015	Vibration Analysis Worksheet	Powertrain	View
PI1394	10/31/2015	Engine Repair Tip for Installation of Pistons	Powertrain	View
03-07-29-004I	10/31/2015	Manual Transmission Operating Characteristics	Powertrain	View
PIP5276E	8/15/2015	SES Lamp P0521 Setting After An Oil Change And Or Low Oil Pressure Indicated On The Instrument Panel	Powertrain	View
00-06-01-026G	8/8/2015	Intake Manifold Inspection/Replacement After Severe Internal Engine Damage	Powertrain	View
03-07-29-004J	7/18/2015	Manual Transmission Operating Characteristics	Powertrain	View
PIP5216A	6/13/2015	Engine Replacement Recommendations HFV6 Gen 1 Only	Powertrain	View
PIP5276D	6/13/2015	SES Lamp P0521 Setting After An Oil Change And Or Low Oil Pressure Indicated On The Instrument Panel	Powertrain	View

PIP5276C	6/6/2015	SES Lamp P0521 Setting After An Oil Change And Or Low Oil Pressure Indicated On The Instrument Panel	Powertrain	View
PI1344	6/1/2015	Diagnostic Tips for Reduced Acceleration at Low Speed and/or Transmission Slipping from a Launch, DTC P0751 Set	Powertrain	View
02-07-30-052J	5/30/2015	Automatic Transmission Oil Cooler Flow Test Essential Tool J-45096 TransFlow	Powertrain	View
15-00-89-004A	5/23/2015	Information Regarding the Differences Between Leakage and Seepage	Powertrain	View
00-06-01-026F	5/23/2015	Intake Manifold Inspection/Replacement After Severe Internal Engine Damage	Powertrain	View
15-00-89-004	5/2/2015	Information Regarding the Differences Between Leakage and Seepage	Powertrain	View
PIP5282	4/18/2015	Engine Oil Life Monitor Operation Calculation	Powertrain	View
PIP4919D	4/4/2015	Black Smoke and Rough Idle On Cold Start	Powertrain	View
12-07-30-001E	3/28/2015	Product Quality Center (PQC) Assembly Replacement Process - For Service Agents Not Required to Contact PQC Prior to Assembly Replacement	Powertrain	View
12-06-01-008B	3/14/2015	Unscheduled Supplemental Services (Including Flushing Services and Additives) and Proper Use of GM Simplified Maintenance Schedules (Canada Only)	Powertrain	View
PIP5276A	3/14/2015	SES Lamp P0521 Setting In Cold Ambient Temperatures	Powertrain	View
PIP4690G	11/3/2014	Normal Characteristic - High Oil Pressure Gauge Readings	Powertrain	View
PIC4986E	9/18/2014	Normal Characteristic - Binding Felt Driving Forward Or In Reverse With Steering At Full Lock	Powertrain	View
PI1296	8/24/2014	Diagnostic Tip for Engine Misfire and/or Popping Noise on Cold Startup after Cylinder Head or Fuel Rail/Injector Repair	Powertrain	View
14233	8/20/2014	Product Safety - Inadvertent Air Bag Deployment	Powertrain	View
PIP5216	8/18/2014	Engine Replacement Recommendations HFV6 Only	Powertrain	View
12-06-01-009E	7/17/2014	Information on High Feature V6 Timing Chain Kits and Chain Guide Replacements, DTCs P0008, P0009, P0016, P0017, P0018 and/or P0019	Powertrain	View
PIP5163A	7/17/2014	Alleged Cylinders Out Of Round	Powertrain	

				View
PIP4653E	6/3/2014	DTCs P0601 P0603 P0604 P062F or P1621 (Stored In The TCM)	Powertrain	View
PIP4919C	4/26/2014	Black Smoke And Rough Idle On Cold Start	Powertrain	View
PIP5191	4/22/2014	Engine Ticking Noise On Cold Start	Powertrain	View
PIP3423K	3/28/2014	DTC P0016 P0017 P0018 P0019 P0008 P0009	Powertrain	View
PIP4554J	2/12/2014	Clunk Noise After Shifting From Reverse To Drive Or Drive To Reverse And Then Accelerating	Powertrain	View
PIP4924D	1/22/2014	SES Light And Misfire With Injector Codes	Powertrain	View
PIP4112N	1/18/2014	Normal Characteristic - Sag Or Hesitation On Acceleration	Powertrain	View
PIP4919A	1/8/2014	Black Smoke On Cold Start	Powertrain	View
PIP5029E	11/11/2013	Engine Misfires Due To Major Carbon Deposits On The Intake And/Or Exhaust Valves	Powertrain	View
PIP4690F	10/14/2013	Normal Characteristic - High Oil Pressure Gauge Readings	Powertrain	View
PIC5492B	10/4/2013	Diagnostic Tip: Diagnosing Vehicles with OnStar DTC B101D-37	Powertrain	View
PIP5095B	10/3/2013	Fluid In Spark Plug Tubes	Powertrain	View
PIP5029D	8/19/2013	Engine Misfires due to Major Carbon Deposits on the Intake and or Exhaust Valves	Powertrain	View
PIP4404E	8/12/2013	Slight Roughness at Idle with No DTCs - Possible Characteristic	Powertrain	View
PIP5075A	8/8/2013	Rear Axle Leak From The Vent	Powertrain	View
PIP4112M	8/5/2013	Normal Characteristic - Sag Or Hesitation On Acceleration	Powertrain	View
PIP4138N	8/5/2013	SES Light, Misfire, DTC P0300, And/or A Chirp, Squeak, Squeal, Or Tick Noise - Potential Valvetrain Concern	Powertrain	View

12-06-01-009D	8/2/2013	Information on High Feature V6 Timing Chain Kits and Chain Guide Replacements, DTCs P0008, P0009, P0016, P0017, P0018 and/or P0019	Powertrain	View
PIP4112L	8/1/2013	Normal Characteristic - Sag Or Hesitation On Acceleration	Powertrain	View
PIP5136	7/24/2013	Oil Odor From The Engine With No Leaks	Powertrain	View
11-00-90-001B	6/19/2013	Global Information for GM dexos 1 and dexos 2 Engine Oil Specifications, Licensed Brands, and Service Fill	Powertrain	View
08-07-30-026B	6/19/2013	Information on Slight Vehicle Movement in Park at Start Up After Cold Soak	Powertrain	View
PIP4158G	6/10/2013	Low Oil Pump Pressure Due To Sticking Oil Pressure Relief Valve	Powertrain	View
PIP4158F	5/23/2013	Low Oil Pump Pressure Due To Sticking Oil Pressure Relief Valve	Powertrain	View
PIT5214	5/21/2013	GM TAC Support of Vehicle Vibration Complaints - U.S. Dealers Only	Powertrain	View
PIP5029C	4/23/2013	Engine Misfires Due To Major Carbon Deposits On The Intake And Or Exhaust Valves	Powertrain	View
99-04-20-002H	4/12/2013	Information on Driveline Clunk Noise	Powertrain	View
PIP4964B	4/9/2013	SES Light With A P2097 Or P2099	Powertrain	View
PIP4924C	4/9/2013	SES Light And Misfire With Injector Codes	Powertrain	View
PIP4158E	4/4/2013	Low Engine Oil Pump Pressure Due To Sticking Oil Pressure Relief Valve	Powertrain	View
12-06-01-007A	3/22/2013	New Service Cam Bearings For Gen IV V8 Engines	Powertrain	View
09-06-04-026G	3/22/2013	Identifying Non-GM (Aftermarket) Engine and Transmission Calibrations for V6 and V8 Gasoline Engines Using Tech 2 or Global Diagnostic System 2 (GDS 2)	Powertrain	View
03-00-91-001F	3/22/2013	Vibration Analysis Worksheet	Powertrain	View
13-08-116-001A	3/22/2013	Aftermarket ALDL or DLC Interface Devices Causing Multiple Issues	Powertrain	View
12-06-01-	3/8/2013	Information on High Feature V6 Timing Chain Kits and	Powertrain	

009B		Chain Guide Replacements, DTCs P0008, P0009, P0016, P0017, P0018 and/or P0019		View
12-06-01-009C	3/8/2013	Information on High Feature V6 Timing Chain Kits and Chain Guide Replacements, DTCs P0008, P0009, P0016, P0017, P0018 and/or P0019	Powertrain	View
PIP5095A	3/6/2013	Fluid In Spark Plug Tubes	Powertrain	View
PIP5095	2/13/2013	Fluid In Spark Plug Tubes	Powertrain	View
PIP4690E	2/4/2013	Normal Characteristic - High Oil Pressure Gauge Readings	Powertrain	View
09-06-04-026F	2/1/2013	Identifying Non-GM (Aftermarket) Engine and Transmission Calibrations for V6 and V8 Gasoline Engines Using Tech 2 or Global Diagnostic System 2 (GDS 2)	Powertrain	View
PIP5091	2/1/2013	Service Stabilitrak Message And Possible Multiple Powertrain DTCs	Powertrain	View
12-06-01-009A	1/18/2013	Information on High Feature V6 Timing Chain Kits and Chain Guide Replacements, DTCs P0008, P0009, P0016, P0017, P0018 and/or P0019	Powertrain	View
PIP4138M	1/8/2013	SES Light, Misfire, DTC P0300, and/or a Chirp, Squeak, Squeal, or Tick Noise - Potential Valvetrain Concern	Powertrain	View
PIE0223A	1/4/2013	Engineering Information - Service Vehicle Soon Displayed on Driver Information Center (DIC), DTC P0803, P080C or P080D Set	Powertrain	View
PIC4740D	1/3/2013	No Crank Multiple Warning Telltales On Trans Shifts Hard	Powertrain	View
09-06-04-026E	1/1/2013	Identifying Non-GM (Aftermarket) Engine and Transmission Calibrations for V8 Gasoline Engines Using Tech 2 or Global Diagnostic System 2 (GDS 2)	Powertrain	View
PIP4138L	12/25/2012	SES Light Misfire DTC P0300 And/Or A Chirp Squeak Squeal Or Tick Noise - Potential Valvetrain Concern	Powertrain	View
12-06-01-009	12/21/2012	Information on High Feature V6 Timing Chain Kits and Chain Guide Replacements, DTCs P0008, P0009, P0016, P0017, P0018 and/or P0019	Powertrain	View
08-07-30-040C	9/4/2012	Information on Normal Maintenance or Warranty Service for 4T40, 4T45, 4T65, 4L60 Automatic Transmission Oil Pan Magnet Upgrade	Powertrain	View
09-04-95-001D	9/4/2012	Clicking Type Noise from Front or Rear of Vehicle When Shifting Between Reverse and Drive or on Hard Acceleration (Add Washer to Wheel Drive Shaft)	Powertrain	View
09-06-04-026D	9/4/2012	Identifying Non-GM (Aftermarket) Engine and Transmission Calibrations for V8 Gasoline Engines	Powertrain	View

		Using Tech 2 or Global Diagnostic System 2 (GDS 2)		
09-00-89-002G	5/8/2012	Properly Maintaining Vehicles in Dealer Inventory	Powertrain	View
02-07-30-052H	3/26/2012	Automatic Transmission Oil Cooler Flow Test Essential Tool J-45096 TransFlow	Powertrain	View
07-06-04-025G	3/25/2012	Information on Clicking/Ticking Sound/Noise Heard During Cold Start, Sound/Noise Decreases But Continues as Engine Warms - Normal Operation of High Pressure Fuel Pump and Injectors	Powertrain	View
07-06-04-025H	3/21/2012	Information on Clicking/Ticking Sound/Noise Heard During Cold Start	Powertrain	View
07-06-04-025J	3/20/2012	Information on Clicking/Ticking Sound/Noise Heard During Cold Start	Powertrain	View
06-08-47-001H	3/5/2012	Warranty, SPS, Control Module Diagnostics and Configuration Information, Programming, Set-Up	Powertrain	View
06-08-47-001I	3/3/2012	Warranty, SPS, Control Module Diagnostics and Configuration Information, Programming, Set-Up	Powertrain	View
PI0488C	2/5/2012	Diagnostic Information for Transmission No Forward, No Reverse, Slips, Cracked/Split Fluid Filter	Powertrain	View
PI0488D	2/4/2012	Diagnostic Information for Transmission No Forward, No Reverse, Slips, Cracked/Split Fluid Filter	Powertrain	View
09-00-89-002F	1/19/2012	Properly Maintaining Vehicles in Dealer Inventory	Powertrain	View
09-00-89-002H	1/14/2012	Properly Maintaining Vehicles in Dealer Inventory	Powertrain	View
00-06-01-012E	10/24/2011	Use of Surface Conditioning Disks When Cleaning Engine Gasket Sealing Surfaces and/or Reused Engine Parts	Powertrain	View
10-00-89-017H	7/22/2011	Car and Truck Fix it Right the First Time Issues	Powertrain	View
08-07-30-026A	5/17/2011	Information on Slight Vehicle Movement in Park at Start Up After Cold Soak	Powertrain	View
99-04-20-002G	5/6/2011	Information on Driveline Clunk Noise when Shifting Between PARK and DRIVE, PARK and REVERSE or DRIVE and REVERSE	Powertrain	View
10-04-20-001C	4/19/2011	Rear Axle Clunk and/or Chatter Type Noise on Turns (Drain/Refill Rear Differential Fluid)	Powertrain	View
06-00-89-031B	3/28/2011	Engine and Automatic Transmission/Transaxle Identification	Powertrain	View

10-00-89-017D	3/21/2011	Car and Truck Fix it Right the First Time Issues	Powertrain	View
02-07-30-029P	3/7/2011	Product Quality Center (PQC) for Engine, Transmission Assembly and Transfer Case Repalcement	Powertrain	View
07-07-30-032D	3/7/2011	Shifter Binds, Ignition Key Sticks, Shift to Park Message Displayed on Driver Information Center (DIC), Dead Battery (Adjust Shift Linkage)	Powertrain	View
03-07-29-004G	12/15/2010	Manual Transmission Operating Characteristics	Powertrain	View
04-06-04-054B	11/18/2010	Information - Non-GM Parts and Accessories (Aftermarket)	Powertrain	View
08-07-30-035B	11/1/2010	Information on Water or Ethylene Glycol in Transmission Fluid	Powertrain	View
08-00-89-029Y	9/14/2010	Car and Truck Fix It Right the First Time Issues	Powertrain	View
10-08-98-002	8/6/2010	Information on Drilling High Strength Steel Related to Collision Repair	Powertrain	View
05-06-01-034L	7/23/2010	5.3L, 5.7L, 6.0L, 6.2L, 7.0L-Engine Oil Leak at Rear Cover Assembly Area (Engine Block Porosity RTV Repair Procedure)	Powertrain	View
04-06-01-029E	4/29/2010	Unnecessary Flushing Services, Additive Recommendations and Proper Utilization of GM Simplified Maintenance Schedule to Enhance Customer Service Experience	Powertrain	View
97-17-1	1/17/1997	Car and Truck Fix it Right the First Time Issues	Powertrain	View

RECALL (18 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
17398	3/9/2018	Customer Satisfaction Program - Vehicle Communication Interface Module (VCIM) Programming Not Completed	Recall	View
PIT5236K	9/28/2017	Diagnostic Tip: OnStar Vehicles with B101D and Symptom Codes	Recall	View
14497C	6/12/2017	Product Safety Recall - Unintended Ignition Key Rotation	Recall	View
17-NA-073	3/15/2017	Warranty Administration - Field Action Courtesy Transportation Policy	Recall	View

44180-02	2/20/2017	Customer Satisfaction Program - Vehicles with Key Codes Improperly Handled by Third Party	Recall	View
38660	7/13/2016	38660 - A16-2038660 GMI700 31UX Missing GM Roadside Kit	Recall	View
14582	10/31/2015	Special Coverage Adjustment - Throttle Body - Reduced Power Mode	Recall	View
14172D	10/31/2015	Product Safety - Unintended Ignition Key Rotation	Recall	View
14497B	10/31/2015	Product Safety - Unintended Ignition Key Rotation	Recall	View
14515B	10/31/2015	Product Safety - Chassis Electronic Control Module Internal Contamination	Recall	View
14515A	10/31/2015	Product Safety - Chassis Electronic Control Module Internal Contamination	Recall	View
14172C	6/1/2015	Product Safety - Unintended Ignition Key Rotation	Recall	View
14497A	6/1/2015	Product Safety - Unintended Ignition Key Rotation	Recall	View
14172A	6/1/2015	Product Safety - Unintended Ignition Key Rotation	Recall	View
14172B	6/1/2015	Product Safety - Unintended Ignition Key Rotation	Recall	View
14497	9/15/2014	Product Safety - Unintended Ignition Key Rotation	Recall	View
14233	8/20/2014	Product Safety - Inadvertent Air Bag Deployment	Recall	View
14172	7/2/2014	Product Safety - Unintended Ignition Key Rotation	Recall	View

STEERING &SUSPENSION (117 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
PI0430C	6/20/2019	Magnaride Magnetically Controlled Suspension Electrical Connector Not Seated, Service Suspension System Message, DTCs C0575, C0580, C0585 or C0590	Steering &Suspension	View
06-08-47-	6/19/2019	Warranty Administration - Warranty SPS Control	Steering	

001O		Module Reprogramming	&Suspensio n	View
00-03-10-006N	5/9/2019	Information on Tire Radial Force Variation (RFV)	Steering &Suspensio n	View
PIT5214D	12/17/2018	GM TAC Support of Vehicle Vibration Complaints - U.S. and Canada Dealers Only	Steering &Suspensio n	View
00-03-10-003X	12/5/2018	Warranty Administration - General Motors New Vehicle Tire Warranty Program (U.S. Dealers Only)	Steering &Suspensio n	View
03-00-89-006P	3/7/2018	New Vehicle Pre-Delivery Inspection (PDI) - Delivering Quality Vehicles and Generating Higher CSi Scores	Steering &Suspensio n	View
00-03-10-003W	12/15/2017	Warranty Administration - General Motors New Vehicle Tire Warranty Program (U.S. Dealers Only)	Steering &Suspensio n	View
09-00-89-002O	6/16/2017	Properly Maintaining Vehicles in Dealer Inventory	Steering &Suspensio n	View
PIT5214C	5/26/2017	GM TAC Support of Vehicle Vibration Complaints - U.S. and Canada Dealers Only	Steering &Suspensio n	View
17-NA-126	4/19/2017	Non-Design Intent Wheel Lock Nuts and Lug Nuts	Steering &Suspensio n	View
PI0281F	4/12/2017	Underbody Component Corrosion	Steering &Suspensio n	View
17-NA-087	3/21/2017	Characteristics of Wide Low Aspect Ratio Tires, Vehicle Pulls Left or Right, Wanders, Follows Depressions in Road Surface, Tramlining	Steering &Suspensio n	View
PI0671A	3/17/2017	Power Steering Fluid Leak at Fluid Reservoir or Reservoir Connection	Steering &Suspensio n	View
04-03-10-013K	1/13/2017	Driving Characteristics of Rear Wheel Drive Vehicles and Available Winter Tires	Steering &Suspensio n	View
05-03-08-002H	12/9/2016	Information on Diagnosis and Replacement of Shock Absorber and Strut Due to Fluid Leak	Steering &Suspensio n	View
05-00-89-055F	12/5/2016	Warranty Administration - GM Dealer Empowerment Program and Goodwill Procedures	Steering &Suspensio n	View
00-03-10-003V	11/7/2016	Warranty Administration - General Motors New Vehicle Tire Warranty Program (U.S. Dealers Only)	Steering &Suspensio n	View
07-03-10-	10/13/201	General Motors New Vehicle Wheel Warranty	Steering	

015C	6	Coverage	&Suspensio n	View
09-00-89-002N	10/7/2016	Properly Maintaining Vehicles in Dealer Inventory	Steering &Suspensio n	View
PI0569A	9/30/2016	Wheel Weights for Black Painted Wheels	Steering &Suspensio n	View
PI0671	9/30/2016	Power Steering Fluid Leak at Fluid Reservoir or Reservoir Connection	Steering &Suspensio n	View
00-03-10-003U	9/30/2016	Warranty Administration - General Motors New Vehicle Tire Warranty Program (U.S. Dealers Only)	Steering &Suspensio n	View
09-03-10-016B	9/30/2016	Wheel Balancing Machine Finish Damage to Chrome Clad or ChromeTechÂ® Wheels	Steering &Suspensio n	View
09-00-89-016E	9/27/2016	Warranty Administration - Labor Operation 0600014 - Suspected Tampering or Vehicle Modifications	Steering &Suspensio n	View
05-00-89-072D	9/1/2016	Fuel and Oil Additives - Facts and Myths - Maximizing Gasoline Fuel Economy	Steering &Suspensio n	View
38660	7/13/2016	38660 - A16-2038660 GMI700 31UX Missing GM Roadside Kit	Steering &Suspensio n	View
16-NA-223	7/11/2016	Traction Control Light Flashes Under Hard Acceleration at Higher Road Speeds	Steering &Suspensio n	View
07-03-10-008E	6/22/2016	Information on Slight or Mild Tire Feathering and Recommended Practices (Normal Tire Wear Condition)	Steering &Suspensio n	View
99-08-51-007G	5/25/2016	Refinishing Aluminum Wheels	Steering &Suspensio n	View
03-03-10-007J	5/20/2016	Information on Tire/Wheel Characteristics (Vibration, Balance, Shake, Flat Spotting) of GM Original Equipment Tires	Steering &Suspensio n	View
PIC4986F	4/19/2016	Normal Characteristic - Binding Felt Driving Forward Or In Reverse With Steering At Or Near Full Lock	Steering &Suspensio n	View
16-NA-109	4/5/2016	Grease or Sealant Visible on Electronic Power Steering Gear - Should Not Be Interpreted as Leak	Steering &Suspensio n	View
00-03-10-002J	3/30/2016	Chemical Staining, Pitting, Corrosion and/or Spotted Appearance of Chromed Aluminum Wheels	Steering &Suspensio n	View
03-00-89-	3/2/2016	New Vehicle Pre-Delivery Inspection (PDI) - Delivering	Steering	

006M		Quality Vehicles and Generating Higher CSi Scores	&Suspensio n	View
09-00-89-002M	3/2/2016	Properly Maintaining Vehicles in Dealer Inventory	Steering &Suspensio n	View
12-03-10-001C	2/23/2016	Vibration Shortly After Tires are Mounted/Preventing Vibration from Wheel Slip (Tire Sliding on Wheel)	Steering &Suspensio n	View
11-00-89-005I	2/12/2016	Clarification of Use - Dealer Empowerment Labor Operations and Customer Enthusiasm (U.S. Only)	Steering &Suspensio n	View
04-06-01-029H	2/11/2016	Unscheduled Supplemental Services (Including Flushing Services and Additives) and Proper Use of GM Simplified Maintenance Schedules (U.S. Only)	Steering &Suspensio n	View
05-03-08-002G	1/1/2016	Information on Diagnosis and Replacement of Shock Absorber and Strut Due to Fluid Leak	Steering &Suspensio n	View
00-03-10-003T	1/1/2016	General Motors New Vehicle Tire Warranty Program (U.S. Dealers Only)	Steering &Suspensio n	View
00-03-10-006L	11/25/2015	Information on Tire Radial Force Variation (RFV)	Steering &Suspensio n	View
PIT5214B	11/25/2015	GM TAC Support of Vehicle Vibration Complaints - U.S. and Canada Dealers Only	Steering &Suspensio n	View
05-03-07-009G	10/31/2015	Wheel Alignment Specifications, Requirements and Recommendations for GM Vehicles	Steering &Suspensio n	View
04-03-10-013J	10/31/2015	Driving Characteristics of Rear Wheel Drive Vehicles and Available Winter Tires	Steering &Suspensio n	View
05-03-07-009H	10/31/2015	Wheel Alignment Specifications, Requirements and Recommendations for GM Vehicles	Steering &Suspensio n	View
06-00-89-026M	10/31/2015	Warranty Administration - Revised Customer Concern Not Duplicated (CCND) / Verified Labor Operation Numbers/How to Submit CCND Transactions in Global Warranty Management	Steering &Suspensio n	View
00-03-10-002I	10/31/2015	Chemical Staining, Pitting, Corrosion and/or Spotted Appearance of Chromed Aluminum Wheels	Steering &Suspensio n	View
05-03-10-020F	10/31/2015	Use of Nitrogen Gas in Tires	Steering &Suspensio n	View
08-03-10-004B	10/31/2015	Mounting, Balancing and Installation of Accessory Wheels and Tires Available Through GM Accessories	Steering &Suspensio n	View

PI0655A	10/31/2015	Information on Removal/Cracking of Stainless Steel Wheel Nut Caps	Steering &Suspension	View
04-03-10-013I	10/31/2015	Driving Characteristics of Rear Wheel Drive Vehicles and Available Winter Tires	Steering &Suspension	View
03-00-91-001G	10/31/2015	Vibration Analysis Worksheet	Steering &Suspension	View
PIT3271G	10/31/2015	Guidelines when Changing Tire and Wheel Size	Steering &Suspension	View
PI1385	10/31/2015	Tire Pressure Monitor (TPM) Concerns After Accessory Wheel Installation	Steering &Suspension	View
00-03-10-003S	9/12/2015	General Motors New Vehicle Tire Warranty Program (U.S. Dealers Only)	Steering &Suspension	View
PI0512B	9/5/2015	Characteristics of Wide Low Aspect Ratio Tires, Vehicle Pulls Left or Right, Wanders, Follows Depressions in Road Surface, Tramlining	Steering &Suspension	View
09-00-89-002L	8/1/2015	Properly Maintaining Vehicles in Dealer Inventory	Steering &Suspension	View
03-00-89-006L	7/18/2015	New Vehicle Pre-Delivery Inspection (PDI) - Delivering Quality Vehicles and Generating Higher CSi Scores	Steering &Suspension	View
PIT5214A	6/20/2015	GM TAC Support of Vehicle Vibration Complaints - US And Canada Dealers Only	Steering &Suspension	View
99-00-89-019M	6/13/2015	Global Warranty Management (GWM) Warranty Parts Center (WPC) Parts Return Program Information	Steering &Suspension	View
09-00-89-002K	6/6/2015	Properly Maintaining Vehicles in Dealer Inventory	Steering &Suspension	View
15-00-89-004	5/2/2015	Information Regarding the Differences Between Leakage and Seepage	Steering &Suspension	View
12-06-01-008B	3/14/2015	Unscheduled Supplemental Services (Including Flushing Services and Additives) and Proper Use of GM Simplified Maintenance Schedules (Canada Only)	Steering &Suspension	View
09-00-89-016D	3/14/2015	Warranty Administration â€“ Labor Operation 0600014 â€“ Suspected Tampering or Vehicle Modifications	Steering &Suspension	View
14497	9/15/2014	Product Safety - Unintended Ignition Key Rotation	Steering &Suspension	View

PIC5214D	7/23/2014	Excessive Brake Dust On Wheels	Steering &Suspension	View
12-03-10-001B	2/6/2014	Vibration Shortly After Tires are Mounted/Preventing Vibration from Wheel Slip (Tire Sliding on Wheel)	Steering &Suspension	View
07-03-10-008D	2/6/2014	Information on Slight or Mild Tire Feathering and Recommended Practices (Normal Tire Wear Condition)	Steering &Suspension	View
08-03-10-006E	2/6/2014	Tire Slowly Goes Flat, Tire Air Loss, Low Tire Pressure Warning Light Illuminated, Aluminum Wheel Bead Seat Corrosion (Clean and Resurface Wheel Bead Seat)	Steering &Suspension	View
12-03-10-002A	1/4/2014	Proper Wheel Installation and Wheel Torque Techniques	Steering &Suspension	View
09-03-16-002B	6/19/2013	Dealership Service Consultant Procedure as Vehicle Comes into Service Drive for Tire Pressure Monitor (TPM) System Message, Light and Customer Information	Steering &Suspension	View
PI0430B	6/19/2013	Magnaride Magnetically Controlled Suspension Electrical Connector Not Seated, Service Suspension System Message, DTCs C0575, C0580, C0585 or C0590	Steering &Suspension	View
PIT5214	5/21/2013	GM TAC Support of Vehicle Vibration Complaints - U.S. Dealers Only	Steering &Suspension	View
PIC4986D	4/3/2013	Normal Characteristic - Binding Felt Driving Forward Or In Reverse With Steering At Full Lock	Steering &Suspension	View
03-00-91-001F	3/22/2013	Vibration Analysis Worksheet	Steering &Suspension	View
13-08-116-001A	3/22/2013	Aftermarket ALDL or DLC Interface Devices Causing Multiple Issues	Steering &Suspension	View
12-03-10-002	1/1/2013	Proper Wheel Installation and Wheel Torque Techniques	Steering &Suspension	View
07-03-10-008C	5/17/2012	Information on Slight or Mild Tire Feathering and Recommended Practices (Normal Tire Wear Condition)	Steering &Suspension	View
09-00-89-002G	5/8/2012	Properly Maintaining Vehicles in Dealer Inventory	Steering &Suspension	View
00-03-10-006K	5/3/2012	Information on Tire Radial Force Variation (RFV)	Steering &Suspension	View
07-02-32-	3/27/2012	Hydraulic Power Steering System Leak - Required	Steering	

002M		Diagnostic Actions	&Suspensio n	View
07-02-32-002L	1/23/2012	Hydraulic Power Steering System Leak - Required Diagnostic Actions	Steering &Suspensio n	View
09-00-89-002F	1/19/2012	Properly Maintaining Vehicles in Dealer Inventory	Steering &Suspensio n	View
09-00-89-002H	1/14/2012	Properly Maintaining Vehicles in Dealer Inventory	Steering &Suspensio n	View
09-00-89-002I	1/13/2012	Properly Maintaining Vehicles in Dealer Inventory	Steering &Suspensio n	View
09-00-89-002J	1/13/2012	Properly Maintaining Vehicles in Dealer Inventory	Steering &Suspensio n	View
05-03-08-002F	12/3/2011	Information on Diagnosis and Replacement of Shock Absorber and Strut Due to Fluid Leak	Steering &Suspensio n	View
04-03-10-013G	10/31/2011	Driving Characteristics of Rear Wheel Drive Vehicles and Available Winter Tires	Steering &Suspensio n	View
04-03-10-013H	10/27/2011	Driving Characteristics of Rear Wheel Drive Vehicles and Available Winter Tires	Steering &Suspensio n	View
10-00-89-017H	7/22/2011	Car and Truck Fix it Right the First Time Issues	Steering &Suspensio n	View
08-02-35-001B	6/14/2011	Blemishes on Steering Wheel Lower Spoke Cover and/or Steering Wheel Spoke Control Bezels (Replace Steering Wheel Cover or Bezel, as Needed)	Steering &Suspensio n	View
07-03-10-010C	5/13/2011	18 Inch Accessory Wheels Available Through GM Accessories	Steering &Suspensio n	View
00-03-10-002F	4/21/2011	Chemical Staining, Pitting, Corrosion and/or Spotted Appearance of Chromed Aluminum Wheels	Steering &Suspensio n	View
03-00-89-006H	4/14/2011	New Vehicle Pre-Delivery Inspection (PDI) - Delivering Quality Vehicles and Generating Higher CSi Scores	Steering &Suspensio n	View
10-00-89-017D	3/21/2011	Car and Truck Fix it Right the First Time Issues	Steering &Suspensio n	View
07-03-10-015B	3/21/2011	General Motors New Vehicle Wheel Warranty Coverage	Steering &Suspensio n	View
99-08-51-	3/17/2011	Refinishing Aluminum Wheels	Steering	

007E			&Suspensio n	View
09-00-89-002D	2/24/2011	Properly Maintaining Vehicles in Dealer Inventory	Steering &Suspensio n	View
04-03-10-013E	12/23/2010	Driving Characteristics of Rear Wheel Drive and Available Winter Tires	Steering &Suspensio n	View
01-03-10-012G	12/13/2010	Guidelines for Using Labor Operations E0200, E0201, E0203, E0204 - Wheel Balance	Steering &Suspensio n	View
05-03-07-009C	12/9/2010	Wheel Alignment Specifications, Requirements and Recommendations for GM Vehicles	Steering &Suspensio n	View
09-04-95-001C	10/18/2010	Clicking Noise from Front/Rear of Vehicle When Shifting Btwn R and D on Hard Accel	Steering &Suspensio n	View
08-00-89-029Y	9/14/2010	Car and Truck Fix It Right the First Time Issues	Steering &Suspensio n	View
06-03-10-010A	6/9/2010	Information on Proper Wheel Changing Procedures and Cautions	Steering &Suspensio n	View
01-03-10-012F	6/7/2010	Guidelines for Using Labor Operations E2020 - Wheel Alignments, E2000 - Toe Adjust and E0200, E0201, E0203, E0204 - Wheel Balance	Steering &Suspensio n	View
09-00-89-016A	5/19/2010	Warranty Administration - Labor Operation Z1111 - Suspected Tampering or Vehicle Modifications	Steering &Suspensio n	View
00-03-10-006F	5/4/2010	Information on Tire Radial Force Variation (RFV)	Steering &Suspensio n	View
04-06-01-029E	4/29/2010	Unnecessary Flushing Services, Additive Recommendations and Proper Utilization of GM Simplified Maintenance Schedule to Enhance Customer Service Experience	Steering &Suspensio n	View
03-00-89-006G	4/28/2010	New Vehicle Pre-Delivery Inspection (PDI) - Delivering Quality Vehicles and Generating Higher CSi Scores	Steering &Suspensio n	View
05-03-10-003F	4/27/2010	Low Tire Pressure, Leaking Cast Aluminum Wheels (Repair with Adhesive Sealant)	Steering &Suspensio n	View
08-03-10-006C	4/27/2010	Tire Slowly Goes Flat, Tire Air Loss, Low Tire Pressure Warning Light Illuminated, Aluminum Wheel Bead Seat Corrosion (Clean and Resurface Wheel Bead Seat)	Steering &Suspensio n	View
09-03-16-002A	4/27/2010	Dealership Service Consultant Procedure as Vehicle Comes into Service Drive for Tire Pressure Monitor (TPM) System Message, Light and Customer	Steering &Suspensio n	View

		Information		
05-03-10-020C	4/27/2010	Use of Nitrogen Gas in Tires	Steering &Suspension	View
04-03-10-001F	4/27/2010	Tire Puncture Repair Procedures for All Cars and Light Duty Trucks	Steering &Suspension	View
07-03-16-004C	4/26/2010	TPM System Overview, Diagnosing Tire Pressure Monitor System (TPM) Concerns and TPM Frequently Asked Questions (FAQ)	Steering &Suspension	View
01-03-10-003H	4/13/2010	Revised GM of Canada New Vehicle Limited Warranty Tire Program and Global Warranty Management (GWM) Submission Rollout Information	Steering &Suspension	View
00-03-10-003O	3/29/2010	Revised General Motors New Vehicle Tire Warranty Program and Global Warranty Management (GWM) Submission Rollout Information (U.S. Dealers Only)	Steering &Suspension	View

TOOLS &HARDWARE (149 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
10-00-89-009D	11/26/2019	Key Code Security Rules and Information on GM KeyCode Look-Up Application (U.S. Only)	Tools &Hardware	View
PIT5074M	11/5/2019	J-35616-64B Or EL-35616-58 Terminal Test Probe Information/Repair	Tools &Hardware	View
PIP5601A	10/10/2019	Vehicle Vibration Diagnosis and TAC Requests For Assistance With Vibration Related Complaints	Tools &Hardware	View
10-00-89-009C	10/9/2019	Key Code Security Rules and Information on GM KeyCode Look-Up Application (U.S. Only)	Tools &Hardware	View
99-00-89-019R	9/17/2019	Global Warranty Management (GWM) Warranty Parts Center (WPC) Parts Return Program Information	Tools &Hardware	View
PIT5074L	6/3/2019	J-35616-64B Terminal Test Probe / Replacement Terminal / Terminated Lead	Tools &Hardware	View
00-03-10-006N	5/9/2019	Information on Tire Radial Force Variation (RFV)	Tools &Hardware	View
18-NA-306	11/27/2018	Information for Dealers/Service Advisors on When and How to Submit a Pre-Repair Authorization (PRA) (U.S. Dealers Only)	Tools &Hardware	View
02-00-89-002R	11/20/2018	Information for Dealers/Technicians on When and How to Submit a Field Product Report (FPR) (U.S. Dealers Only)	Tools &Hardware	View
18-NA-099	11/5/2018	Working with GM on a Product Assistance Claim	Tools	

		(PAC)	&Hardware	View
00-06-01-012I	10/26/2018	Use of Surface Conditioning Disks When Cleaning Gasket Sealing Surfaces and/or Reused Parts	Tools &Hardware	View
13-00-89-010B	10/8/2018	PAC Courtesy Transportation Assistance Program	Tools &Hardware	View
15-00-89-005B	9/11/2018	Warranty Administration - Essential Tools that Include Consumable Parts (U.S. Only)	Tools &Hardware	View
12-00-89-007B	6/22/2018	Dealer Responsibility for Cargo Carrying Capacity Labeling	Tools &Hardware	View
99-00-89-019P	5/30/2018	Global Warranty Management (GWM) Warranty Parts Center (WPC) Parts Return Program Information	Tools &Hardware	View
04-00-89-015S	5/14/2018	Warranty Administration - Required Operating Procedures (U.S. Only)	Tools &Hardware	View
07-00-89-037N	5/10/2018	Warranty Administration - Courtesy Transportation and Roadside Assistance Programs	Tools &Hardware	View
03-06-03-004W	2/1/2018	Warranty Administration - Battery Testing and Warranty Replacement Requirements (North America ONLY)	Tools &Hardware	View
04-00-89-015R	12/15/2017	Warranty Administration - Required Operating Procedures (U.S. Only)	Tools &Hardware	View
07-00-89-036I	12/4/2017	Enhancing Field Product Reports with Digital Pictures	Tools &Hardware	View
99-08-51-001D	8/23/2017	Paint-less Dent Repair Process	Tools &Hardware	View
04-00-89-015Q	8/10/2017	Warranty Administration - Required Operating Procedures (U.S. Only)	Tools &Hardware	View
04-00-89-015P	7/25/2017	Warranty Administration - Required Operating Procedures (U.S. Only)	Tools &Hardware	View
07-00-89-037K	6/23/2017	Warranty Administration - Courtesy Transportation and Roadside Assistance Programs	Tools &Hardware	View
06-00-89-029N	6/22/2017	Interior Cleaning -- Instrument Panel (IP), Hard or Plastic Surfaces, Seats, Carpet, Leather, Vinyl, Fabric Cleaner, Stain Remover, Restorer --Product Availability	Tools &Hardware	View
03-00-89-006O	6/8/2017	New Vehicle Pre-Delivery Inspection (PDI) - Delivering Quality Vehicles and Generating Higher CSi Scores	Tools &Hardware	View
PIT3099P	6/2/2017	Concerns Or Questions Regarding Installation Of Dealer Installed Accessories	Tools &Hardware	View

PIT5214C	5/26/2017	GM TAC Support of Vehicle Vibration Complaints - U.S. and Canada Dealers Only	Tools &Hardware	View
03-06-03-004U	4/6/2017	Warranty Administration - Battery Testing and Warranty Replacement Requirements (North America ONLY)	Tools &Hardware	View
PIP4902J	3/15/2017	Procedure For Emailing Global Diagnostic System 2 (GDS2) Session Log To GM TAC (US and Canada Dealers Only)	Tools &Hardware	View
17-NA-073	3/15/2017	Warranty Administration - Field Action Courtesy Transportation Policy	Tools &Hardware	View
99-00-89-019N	12/14/2016	Global Warranty Management (GWM) Warranty Parts Center (WPC) Parts Return Program Information	Tools &Hardware	View
05-00-89-055F	12/5/2016	Warranty Administration - GM Dealer Empowerment Program and Goodwill Procedures	Tools &Hardware	View
PIT3099N	11/18/2016	Concerns Or Questions Regarding Installation Of Dealer Installed Accessories	Tools &Hardware	View
11-00-89-004B	11/14/2016	Warranty Administration - Change in Product Field Action Customer Reimbursement Procedure (U.S. Dealers Only)	Tools &Hardware	View
11-00-89-005J	11/1/2016	Warranty Administration - Updated - Dealer Empowerment Labor Operations and Customer Enthusiasm (U.S. Only)	Tools &Hardware	View
04-00-89-015N	10/13/2016	Warranty Administration - Required Operating Procedures (U.S. Only)	Tools &Hardware	View
11-00-89-007C	10/10/2016	Warranty Administration - Revised Exterior Labor Operations (Labor Only-No Part Replaced) and Required Warranty Claim Submission Information	Tools &Hardware	View
16-NA-338	10/7/2016	PQC Assembly Replacement Process - Dealers Required to Contact PQC Prior to Replacing an Assembly	Tools &Hardware	View
03-06-03-004S	10/6/2016	Warranty Administration - Battery Testing and Warranty Replacement Requirements (North America ONLY)	Tools &Hardware	View
07-00-89-037J	9/30/2016	Warranty Administration - Courtesy Transportation and Roadside Assistance Programs	Tools &Hardware	View
03-00-89-005A	9/30/2016	Changes to Essential and Available Tool Numbering System	Tools &Hardware	View
13-00-89-005	9/27/2016	Warranty Administration - New Global Labor Codes	Tools &Hardware	View
01-00-89-010L	9/19/2016	Comeback Prevention Information and Using Customer Concern Verification Sheets (CCVS)	Tools &Hardware	View
16-NA-119	8/12/2016	Warranty Administration - Servicing Vehicles from	Tools	

		Canada (U.S. Dealers Only)	&Hardware	View
03-06-03-004R	8/12/2016	Warranty Administration - Battery Testing and Warranty Replacement Requirements (North America ONLY)	Tools &Hardware	View
38660	7/13/2016	38660 - A16-2038660 GMI700 31UX Missing GM Roadside Kit	Tools &Hardware	View
04-00-89-015M	6/8/2016	Warranty Administration - Required Operating Procedures (U.S. Only)	Tools &Hardware	View
04-00-89-015L	5/20/2016	Warranty Administration - Required Operating Procedures (U.S. Only)	Tools &Hardware	View
PI0592D	5/20/2016	Service Programming System (SPS) Errors (E4398, E4399, E4403, M4404 M4413, E4414, E4423 or E4491)	Tools &Hardware	View
16-NA-158	5/16/2016	New U.S. Dealer Special Tool Loan Program	Tools &Hardware	View
03-06-03-004Q	4/22/2016	Warranty Administration - Battery Testing and Warranty Replacement Requirements (North America ONLY)	Tools &Hardware	View
06-08-47-001L	4/18/2016	Warranty, SPS, Control Module Diagnostics and Configuration Information, Programming, Set-Up	Tools &Hardware	View
03-06-03-004P	4/14/2016	Battery Testing and Warranty Replacement Requirements (North America ONLY)	Tools &Hardware	View
PI0572C	3/29/2016	Information on COAX Repair Kit Availability	Tools &Hardware	View
08-00-89-014B	3/29/2016	Being Prepared for TAC, Caller Preparedness and Checklist - Contacting U.S. Technical Assistance (TAC) and Use of Strategy Based Diagnostics	Tools &Hardware	View
07-00-89-037I	3/14/2016	Warranty Administration - Courtesy Transportation and Roadside Assistance Programs	Tools &Hardware	View
04-00-89-015K	3/1/2016	Warranty Administration - Required Operating Procedures (U.S. Only)	Tools &Hardware	View
02-08-98-002F	2/5/2016	Hem Flange Rust Repair	Tools &Hardware	View
PIT5214B	11/25/2015	GM TAC Support of Vehicle Vibration Complaints - U.S. and Canada Dealers Only	Tools &Hardware	View
04-00-89-015I	10/31/2015	Warranty Administration - Required Operating Procedures (U.S. Only)	Tools &Hardware	View
PIP5338	10/31/2015	Vehicle Vibration Diagnosis and TAC Requests For Assistance With Vibration Related Complaints	Tools &Hardware	View

02-07-30-029Y	10/31/2015	PQC Assembly Replacement Process - For Dealers Required to Contact PQC Prior to Replacing an Assembly (U.S. and Canada Only)	Tools &Hardware	View
10-08-98-002A	10/31/2015	Information on Drilling High Strength Steel Related to Collision Repair	Tools &Hardware	View
15-NA-030	10/31/2015	Information on the Use of Non GM Approved Battery Chargers and Booster Packs	Tools &Hardware	View
15-NA-017	10/31/2015	Warranty Administration - Causal Part Requirements for Transactions Submitted to GM for Payment	Tools &Hardware	View
15-00-89-001	10/31/2015	Warranty Administration - New Vehicle Maintenance Program Cross-Border Servicing between the U.S. and Canada	Tools &Hardware	View
01-00-89-010K	10/31/2015	Comeback Prevention Information and Using Customer Concern Verification Sheets (CCVS)	Tools &Hardware	View
15-00-89-003	10/31/2015	Dealer Reimbursement Procedures for CAC Tier 1 and Tier 2 Empowerment Tool: Diagnostic Fee, Short Term Rental, and Up-Front Towing (U.S. Only)	Tools &Hardware	View
02-07-30-029X	10/31/2015	Product Quality Center (PQC) Assembly Replacement Process - For Dealers Required to Contact PQC Prior to Replacing an Assembly (U.S. and Canada Only)	Tools &Hardware	View
05-00-89-055E	10/31/2015	Warranty Administration - GM Dealer Empowerment Program and Goodwill Procedures	Tools &Hardware	View
PIT5074H	10/31/2015	J-35616-64B Terminal Test Probe / Replacement Terminal / Terminated Lead	Tools &Hardware	View
11-00-89-004A	10/31/2015	Warranty Administration - Change in Product Field Action Customer Reimbursement Procedure (U.S. Dealers Only)	Tools &Hardware	View
PI1394	10/31/2015	Engine Repair Tip for Installation of Pistons	Tools &Hardware	View
99-01-39-004H	9/12/2015	Air Conditioning Odor (Install Evaporator Core Dryer Kit and Apply Cooling Coil Coating)	Tools &Hardware	View
15-08-73-001	9/5/2015	Information on Communication with OnStar® Module After Canadian Cellular Upgrade	Tools &Hardware	View
00-05-22-002O	9/5/2015	Brake Lathe Calibration Procedure	Tools &Hardware	View
07-00-89-036H	9/5/2015	Enhancing Field Product Reports with Digital Pictures	Tools &Hardware	View
13-00-89-008A	9/5/2015	GM Wiring Repair Strategy Information	Tools &Hardware	View
15-00-89-	8/22/2015	Warranty Administration - Essential Tools that Include	Tools	

005		Consumable Parts (U.S. Only)	&Hardware	View
07-00-89-037H	8/8/2015	Warranty Administration - Courtesy Transportation and Roadside Assistance Programs	Tools &Hardware	View
06-00-89-029L	7/25/2015	Interior Cleaning - Instrument Panel (IP), Hard or Plastic Surfaces, Seats, Carpet, Leather, Vinyl, Fabric Cleaner, Stain Remover, Restorer - Product Availability	Tools &Hardware	View
06-00-89-029K	7/18/2015	Interior Cleaning - Instrument Panel (IP), Hard or Plastic Surfaces, Seats, Carpet, Leather, Vinyl, Fabric Cleaner, Stain Remover, Restorer - Product Availability	Tools &Hardware	View
01-08-51-003E	7/12/2015	Application of Anti-Corrosion Materials	Tools &Hardware	View
PIT5214A	6/20/2015	GM TAC Support of Vehicle Vibration Complaints - US And Canada Dealers Only	Tools &Hardware	View
02-07-30-052J	5/30/2015	Automatic Transmission Oil Cooler Flow Test Essential Tool J-45096 TransFlow	Tools &Hardware	View
04-00-89-015J	3/14/2015	Warranty Administration - Required Operating Procedures (U.S. Only)	Tools &Hardware	View
10-00-89-006D	12/5/2014	Information for Dealers on How to Submit a Product Information Report (PIR) (Canada Only)	Tools &Hardware	View
PIP4902H	7/8/2014	Procedure For Emailing Global Diagnostic System 2 (GDS2) Session Log To	Tools &Hardware	View
03-06-03-004M	5/22/2014	Warranty Code Generated By EL-50313 Midtronics GR8 Battery Tester/Charger Required for Claim Processing On Labor Operation 4041510, 4041520 and 250 Mile/400 Km Labor Operation Restriction (North America ONLY)	Tools &Hardware	View
07-03-10-008D	2/6/2014	Information on Slight or Mild Tire Feathering and Recommended Practices (Normal Tire Wear Condition)	Tools &Hardware	View
PI0218A	9/13/2013	Information on Rear Bumper Fascia and Quarter Panel Paint Appearance	Tools &Hardware	View
10-00-89-016A	6/19/2013	Correct Selection Of Labor Codes	Tools &Hardware	View
07-08-49-020H	6/7/2013	IPC Odometer Programming Method Quick Reference Guide	Tools &Hardware	View
PIT5214	5/21/2013	GM TAC Support of Vehicle Vibration Complaints - U.S. Dealers Only	Tools &Hardware	View
PIT5074G	5/15/2013	J-35616-64B Terminal Test Probe And Replacement	Tools	

		Terminal	&Hardware	View
09-06-04-026G	3/22/2013	Identifying Non-GM (Aftermarket) Engine and Transmission Calibrations for V6 and V8 Gasoline Engines Using Tech 2 or Global Diagnostic System 2 (GDS 2)	Tools &Hardware	View
99-08-51-001C	3/1/2013	Paint-less Dent Repair Process	Tools &Hardware	View
07-08-49-020G	1/1/2013	IPC Odometer Programming Method Quick Reference Guide	Tools &Hardware	View
11-00-89-002A	9/4/2012	GM Accessories - Dealer-Installed, Repaired or Replaced During Warranty Coverage Period	Tools &Hardware	View
03-08-44-005L	4/18/2012	Poor Radio Reception or Radio Static/Increased Interference with Rear Window Defogger On or Some Rear Window Defogger Grids May Be Inoperative	Tools &Hardware	View
02-07-30-052H	3/26/2012	Automatic Transmission Oil Cooler Flow Test Essential Tool J-45096 TransFlow	Tools &Hardware	View
02-08-98-002D	3/19/2012	Hem Flange Rust Repair	Tools &Hardware	View
03-08-46-004L	3/5/2012	Part Restriction and Ordering Process Information for OnStar Vehicle Communication Interface Modules (VCIM)	Tools &Hardware	View
06-08-47-001H	3/5/2012	Warranty, SPS, Control Module Diagnostics and Configuration Information, Programming, Set-Up	Tools &Hardware	View
06-00-89-029I	1/13/2012	Interior Cleaning - Instrument Panel (IP), Hard or Plastic Surfaces, Seats, Carpet, Leather, Vinyl, Fabric Cleaner, Stain Remover, Restorer - Product Availability	Tools &Hardware	View
00-06-01-012E	10/24/2011	Use of Surface Conditioning Disks When Cleaning Engine Gasket Sealing Surfaces and/or Reused Engine Parts	Tools &Hardware	View
03-06-03-004H	10/22/2011	Warranty Code Generated By EL-50313 Midtronics GR8 Battery Tester/Charger Required for Claim Processing On Labor Operation 4041510 and Battery Part Restriction (North America ONLY)	Tools &Hardware	View
02-00-89-002M	10/22/2011	Information for Dealers/Technicians on When and How to Submit a Field Product Report (FPR) (U.S. Dealers Only)	Tools &Hardware	View
01-00-89-010I	8/10/2011	Comeback Prevention Information and Using Customer Concern Verification Sheets (CCVS)	Tools &Hardware	View
07-00-89-036D	7/22/2011	Enhancing Field Product Reports with Digital Pictures	Tools &Hardware	View
11-00-89-	7/22/2011	Clarification of Use - Dealer Empowerment Labor	Tools	

005		Operations and Customer Enthusiasm	&Hardware	View
PI0135A	6/17/2011	Improperly Formatted SI Screen Characters	Tools &Hardware	View
06-00-89-026G	6/9/2011	Warranty Administration-Revised Customer Concern Not Duplicated (CCND)/Verified Labor Operation Numbers/How to Submit CCND Transactions in GWM / Elimination of E9995, J9993, J9994 and J9995	Tools &Hardware	View
99-00-89-019H	5/23/2011	Global Warranty Management (GWM) Warranty Parts Center (WPC) Parts Return Program Information	Tools &Hardware	View
07-08-49-020E	5/19/2011	IPC Odometer Programming Method Quick Reference Guide	Tools &Hardware	View
10-00-89-006A	5/9/2011	Information for Dealers on How to Submit a Product Information Report (PIR) (Canada Only)	Tools &Hardware	View
11-00-89-004	5/5/2011	Change in Product Field Action Customer Reimbursement Procedure (U.S. Dealers Only)	Tools &Hardware	View
07-00-89-037D	4/18/2011	Warranty Administration - Courtesy Transportation and Roadside Assistance Programs	Tools &Hardware	View
11-00-89-003	4/13/2011	Warranty Parts Center (WPC) Special Part Request Enhancement - New Expedited Overnight Shipping Process and Form Information	Tools &Hardware	View
99-00-89-021G	4/7/2011	Expediting Warranty Parts	Tools &Hardware	View
02-07-30-052G	3/2/2011	Automatic Transmission Oil Cooler Flush and Flow Test Essential Tool J-45096 TransFlow	Tools &Hardware	View
06-00-89-026F	2/3/2011	Expanded Customer Concern Not Duplicated (CCND)/Verified Labor Operation Numbers/How to Submit CCND Transactions in Global Warranty Management	Tools &Hardware	View
01-08-51-003B	11/19/2010	Application of Anti-Corrosion Materials	Tools &Hardware	View
03-06-03-004D	10/18/2010	Warranty Code Generated by EI-50313/Charger Required for N0110, Battery Parts Rest	Tools &Hardware	View
05-00-89-029B	10/13/2010	General Motors Dealership Critical Equipment Requirements and Recommendations	Tools &Hardware	View
04-00-89-053D	9/2/2010	Engineering Information (EI) Process	Tools &Hardware	View
10-00-89-016	9/1/2010	Correct Selection Of Labor Codes	Tools &Hardware	View

03-08-46-004I	8/23/2010	Parts Restriction on Ordering OnStar Generation 8 and Generation 9 Vehicle Communication Interface Modules (VCIM)	Tools &Hardware	View
10-08-98-002	8/6/2010	Information on Drilling High Strength Steel Related to Collision Repair	Tools &Hardware	View
03-00-89-013E	7/30/2010	Electronic Exchange Program Changes	Tools &Hardware	View
09-08-110-008B	7/20/2010	Driver and/or Passenger Side Windshield Pillar Garnish Molding Loose, Gap at Top (Install New Fasteners)	Tools &Hardware	View
05-00-89-037A	7/1/2010	Out-of-Warranty Parts for Engineering Analysis	Tools &Hardware	View
10-00-89-008	6/17/2010	Free Agent Best Practices for HUMMER, Pontiac, Saab and Saturn Customers or Those Affected by Dealership Consolidation (U.S. Only) (SB10168)	Tools &Hardware	View
99-00-89-021F	5/28/2010	Expediting Warranty Parts	Tools &Hardware	View
10-00-89-010	5/27/2010	Key Code Security Rules and Information on GM KeyCode Look-Up Application (Canada Only)	Tools &Hardware	View
06-00-89-054C	5/26/2010	Warranty Admin - Warranty Claims Submission-Importance of GM Part Numbers and Parts with Date Codes	Tools &Hardware	View
PI0135	5/21/2010	Improperly Formatted SI Screen Characters	Tools &Hardware	View
07-00-89-037C	5/20/2010	Warranty Administration - Courtesy Transportation and Roadside Assistance Programs	Tools &Hardware	View
99-00-89-019F	5/20/2010	Global Warranty Management (GWM) Warranty Parts Center (WPC) Parts Return Program Information	Tools &Hardware	View
09-00-89-016A	5/19/2010	Warranty Administration - Labor Operation Z1111 - Suspected Tampering or Vehicle Modifications	Tools &Hardware	View
02-00-89-002J	5/18/2010	Information for Dealers on How to Submit a Field Product Report (FPR) (U.S. Dealers Only)	Tools &Hardware	View
10-00-89-006	5/17/2010	Information for Dealers on How to Submit a Product Information Report (PIR) (Canada Only)	Tools &Hardware	View
00-03-10-006F	5/4/2010	Information on Tire Radial Force Variation (RFV)	Tools &Hardware	View
07-00-89-036C	5/4/2010	Enhancing Field Product Reports with Digital Pictures	Tools &Hardware	View
10-00-89-005	5/3/2010	Warranty Administration-Revised Wiring Repair Labor Operations and Required Additional Information	Tools &Hardware	View

04-06-01-029E	4/29/2010	Unnecessary Flushing Services, Additive Recommendations and Proper Utilization of GM Simplified Maintenance Schedule to Enhance Customer Service Experience	Tools &Hardware	View
05-08-45-002E	4/26/2010	Required Return Criteria of Complete Electrical Center (EC) and Body Control Module (BCM) with Integrated Electrical Center to Warranty Parts Center (WPC)	Tools &Hardware	View
00-03-10-003O	3/29/2010	Revised General Motors New Vehicle Tire Warranty Program and Global Warranty Management (GWM) Submission Rollout Information (U.S. Dealers Only)	Tools &Hardware	View

WIPER AND WASHER (13 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
03-00-89-006P	3/7/2018	New Vehicle Pre-Delivery Inspection (PDI) - Delivering Quality Vehicles and Generating Higher CSi Scores	Wiper and Washer	View
09-00-89-002O	6/16/2017	Properly Maintaining Vehicles in Dealer Inventory	Wiper and Washer	View
09-00-89-002N	10/7/2016	Properly Maintaining Vehicles in Dealer Inventory	Wiper and Washer	View
03-00-89-006M	3/2/2016	New Vehicle Pre-Delivery Inspection (PDI) - Delivering Quality Vehicles and Generating Higher CSi Scores	Wiper and Washer	View
09-00-89-002M	3/2/2016	Properly Maintaining Vehicles in Dealer Inventory	Wiper and Washer	View
03-00-89-006L	7/18/2015	New Vehicle Pre-Delivery Inspection (PDI) - Delivering Quality Vehicles and Generating Higher CSi Scores	Wiper and Washer	View
09-00-89-002K	6/6/2015	Properly Maintaining Vehicles in Dealer Inventory	Wiper and Washer	View
06-08-43-003D	2/15/2013	Windshield Wiper Performance, Cleaning Instructions and Maintenance	Wiper and Washer	View
09-00-89-002F	1/19/2012	Properly Maintaining Vehicles in Dealer Inventory	Wiper and Washer	View
09-00-89-002J	1/13/2012	Properly Maintaining Vehicles in Dealer Inventory	Wiper and Washer	View
06-08-43-003C	2/21/2011	Windshield Wiper Performance, Cleaning Instructions and Maintenance	Wiper and Washer	View
08-00-89-029Y	9/14/2010	Car and Truck Fix It Right the First Time Issues	Wiper and Washer	View

03-00-89-006G	4/28/2010	New Vehicle Pre-Delivery Inspection (PDI) - Delivering Quality Vehicles and Generating Higher CSi Scores	Wiper and Washer	View

Vehicle Title History

Your title history has been sent. Please check your email.

Ran on August 2, 2021 @ 1:49 AM | Contact us

Copyright 2021 CarMD Corp