

# Premium Vehicle Maintenance Report

for your  
**2011 JEEP Wrangler Unlimited**

@ 12,311 miles

VIN: 1J4HA6H15BL611556


Average MPG: 16

## Maintenance

8 items

If you have not completed the following items below, completing these services before they are due will help keep your car running smoothly.

**This service is due at 16,000 mi**

Service Item (s)	Difficulty	Cost
 <b>Lube Door Latch &amp; Fastening Bolts</b> <a href="#">Buy Online Now</a>	Repair difficulty	<b>\$32</b> Cost of repair \$11 in parts \$21 in labor
Change Engine Oil and Filter	N/A	<b>\$0</b> Cost of repair \$0 in parts \$0 in labor
Inspect Brake Hoses & Lines	N/A	<b>\$0</b> Cost of repair \$0 in parts \$0 in labor
Inspect Brake System, Friction Material and Hydraulic System.	Repair difficulty	<b>\$8</b> Cost of repair \$8 in parts \$0 in labor

Inspect Chassis, Steering, Suspension & Fasteners	N/A	<b>\$0</b> Cost of repair \$0 in parts \$0 in labor
Inspect Exhaust System, Catalytic Converter and Heat Shield	Repair difficulty	<b>\$0</b> Cost of repair \$0 in parts \$0 in labor
Inspect Manual Transmission Fluid Level & Condition	Repair difficulty	<b>\$21</b> Cost of repair \$0 in parts \$21 in labor
Rotate Tires, Inspect Tire Wear, and Adjust Tire Pressure.	Repair difficulty	<b>\$51</b> Cost of repair \$0 in parts \$51 in labor

## Warranty Status

**This vehicle is NOT currently covered. All warranties have expired.**

Below is your default warranty information. This excludes any additional warranty coverage you may have purchased.

Basic new car  
warranty  
3 years

Powertrain  
warranty  
5 years

Federal emissions  
warranty  
8 years

[Extend your vehicle warranty](#)

## Upcoming Issues

4 items

By analyzing other vehicles of the same year make model our results show you may need the following repairs in the next 12 months. It is recommended that you have these parts inspected by a trusted technician, and replace as needed.

**31%**

**12%**

<p>Likelihood of</p> <p><b>Replace Emission System Integrity Monitor (ESIM)</b></p> <p><b>\$106</b></p> <p>Cost of repair</p> <p>\$41 in parts</p> <p>\$65 in labor</p> <p>Repair difficulty</p>	<p>Likelihood of</p> <p><b>Replace Exhaust Gas Recirculation (EGR) Valve and Clean All EGR ports</b></p> <p><b>\$375</b></p> <p>Cost of repair</p> <p>\$212 in parts</p> <p>\$163 in labor</p> <p>Repair difficulty</p>
<p><b>6%</b></p> <p>Likelihood of</p> <p><b>Replace Spark Plug Wires and Spark Plugs</b></p> <p><b>\$276</b></p> <p>Cost of repair</p> <p>\$154 in parts</p> <p>\$122 in labor</p> <p>Repair difficulty</p>	<p><b>5%</b></p> <p>Likelihood of</p> <p><b>Replace Oxygen Sensor(s) (O2S)</b></p> <p><b>\$169</b></p> <p>Cost of repair</p> <p>\$118 in parts</p> <p>\$51 in labor</p> <p>Repair difficulty</p>

[Extend your vehicle warranty](#)

## Technical Service Bulletins (TSBs)

110 items

A technical service bulletins (TSB) is an advisory issued by an automotive manufacture to its dealership service departments. If your vehicle is still under warranty; you can usually get the related repairs covered

### ACCESSORIES AND FLUIDS (3 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
23-027-12	9/13/2012	Driver Seat Squeak	Accessories	

			and Fluids	<a href="#">View</a>
23-025-12	9/1/2012	Replacing Door, Hood And/Or Tailgate Hinges	Accessories and Fluids	<a href="#">View</a>
26-004-12	6/6/2012	Fluid Flushing Requirements	Accessories and Fluids	<a href="#">View</a>

## BODY (39 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
04-001-17	3/18/2017	Failure Code Change	Body	<a href="#">View</a>
23-009-17	2/10/2017	Out of Tolerance Door and Windshield Frame Gaps Causing Water Leaks	Body	<a href="#">View</a>
23-037-16	7/19/2016	Out Of Tolerance Door And Windshield Frame Gaps Causing Water Leaks	Body	<a href="#">View</a>
31-001-16	3/4/2016	Do Not Apply Corrosion Protection On Sheet Molding Compound (SMC) Plastic Panels	Body	<a href="#">View</a>
23-038-15	10/22/2015	Cracked Vinyl Soft Top Window	Body	<a href="#">View</a>
06-001-15	8/21/2015	Squeak Noise While Depressing The Clutch Pedal	Body	<a href="#">View</a>
23-034-14 REV. A	12/16/2014	Cowl Trim Panel Fastener Water Leak	Body	<a href="#">View</a>
23-034-14	11/8/2014	Cowl Trim Panel Fastener Water Leak	Body	<a href="#">View</a>
08-058-14	7/19/2014	Clock In The Radio Loses Time	Body	<a href="#">View</a>
08-049-14	5/16/2014	Intermittently Front Heated Seats Inoperative	Body	<a href="#">View</a>
RC-IN53-13	11/1/2013	Safety Recall N53 - Weight Label	Body	<a href="#">View</a>
23-021-13	5/30/2013	Replacing Door, Hood And/Or Tailgate Hinges	Body	<a href="#">View</a>
08-003-13 REV. A	5/3/2013	Clock In The Radio Loses Time	Body	<a href="#">View</a>

23-010-13	2/27/2013	Water Dripping Across Door Sill And/Or Damp Front Floor	Body	<a href="#">View</a>
31-002-13	1/31/2013	Blending Clearcoat During The Refinish Process	Body	<a href="#">View</a>
31-001-13	1/11/2013	Overspray Removal	Body	<a href="#">View</a>
23-001-13	1/10/2013	Soft Top Rear Window Zipper Will Not Disengage	Body	<a href="#">View</a>
23-027-12	9/13/2012	Driver Seat Squeak	Body	<a href="#">View</a>
23-025-12	9/1/2012	Replacing Door, Hood And/Or Tailgate Hinges	Body	<a href="#">View</a>
31-007-12	8/14/2012	Welded Sheet Metal Repairs and Replacements	Body	<a href="#">View</a>
31-006-12	8/10/2012	Repair Procedures For Front Fender Supports (AKA Fender Closure, Front Upper Hydroform And Shotguns)	Body	<a href="#">View</a>
31-004-12	7/26/2012	Front Fascia Repair When License Plate Bracket Has Been Removed	Body	<a href="#">View</a>
23-001-12 REV. A	5/30/2012	Water Dripping Across Door Sill And/Or Damp Front Floor	Body	<a href="#">View</a>
31-003-12	3/30/2012	Adaptive Cruise Control (ACC) Module Sensor and Bracket Guidelines During Collision Repair and Damage Estimating	Body	<a href="#">View</a>
23-003-12	2/7/2012	Light To Moderate Paint Surface Imperfections On Factory Applied Paint Finish	Body	<a href="#">View</a>
23-001-12	1/5/2012	Water Dripping Across Door Sill And/Or Damp Front Floor	Body	<a href="#">View</a>
31-001-11	11/10/2011	Use of Heat To Straighten Damaged Components	Body	<a href="#">View</a>
31-004-11	11/10/2011	Replacement Seat Covers And Seat Cover Repairs	Body	<a href="#">View</a>
31-002-11	11/10/2011	Repair Parts Used For Structural Repairs	Body	<a href="#">View</a>
23-025-11	9/9/2011	Damp Right Front Floor	Body	<a href="#">View</a>
RC-CL24-11	8/31/2011	CUSTOMER SATISFACTION NOTIFICATION L24 - SOFT TOP PREMATURE WEAR AT ROOF BOWS	Body	<a href="#">View</a>

23-034-11	8/27/2011	Manual Mirror May Lose Adjustment Over Time	Body	<a href="#">View</a>
RC-IL24-11	8/1/2011	Customer Satisfaction Notification L24 - Soft Top Premature Wear at Roof Bows	Body	<a href="#">View</a>
23-027-11	8/1/2011	SUPERSEDED BY :RC-L24-11(Customer Satisfaction Notification L24 - Soft Top Premature Wear at Roof Bows)	Body	<a href="#">View</a>
23-025-11	6/25/2011	Damp Right Front Floor	Body	<a href="#">View</a>
RC-CL03-11	3/15/2011	CUSTOMER SATISFACTION NOTIFICATION L03 - DOOR LATCHES	Body	<a href="#">View</a>
RC-CL03-11	3/15/2011	CUSTOMER SATISFACTION NOTIFICATION L03 - DOOR LATCHES	Body	<a href="#">View</a>
RC-L03-11	3/1/2011	Customer Satisfaction Notification L03 - Door Latches	Body	<a href="#">View</a>
RC-IL03-11	3/1/2011	Customer Satisfaction Notification L03 - Door Latches	Body	<a href="#">View</a>

## BRAKE (4 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
31-005-12	8/3/2012	Do Not Apply Corrosion Protection On SMC (Plastic) Panels	Brake	<a href="#">View</a>
26-004-12	6/6/2012	Fluid Flushing Requirements	Brake	<a href="#">View</a>
RC-IL31-12	1/1/2012	Safety Recall L31 - Front Brake Fles Hoses	Brake	<a href="#">View</a>
05-006-11	3/30/2011	Flash: ABS Module Brake Assist Software Update	Brake	<a href="#">View</a>

## COOLING (1 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
26-004-12	6/6/2012	Fluid Flushing Requirements	Cooling	<a href="#">View</a>

## ELECTRICAL (23 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
08-005-17 REV. B	5/19/2017	Clockspring Replacement (X68 Warranty Extension)	Electrical	<a href="#">View</a>
08-005-17 REV. A	3/24/2017	Clockspring Replacement (X68 Warranty Extension)	Electrical	<a href="#">View</a>
04-001-17	3/18/2017	Failure Code Change	Electrical	<a href="#">View</a>
08-005-17	1/21/2017	Clockspring Replacement (X68 Warranty Extension)	Electrical	<a href="#">View</a>
08-019-15	3/4/2015	Loss Of Power Heated Mirror Function - Recall P61	Electrical	<a href="#">View</a>
08-100-14	12/2/2014	Loss Of Power Heated Mirror Function - Recall P61 Interim Repair	Electrical	<a href="#">View</a>
08-058-14	7/19/2014	Clock In The Radio Loses Time	Electrical	<a href="#">View</a>
08-049-14	5/16/2014	Intermittently Front Heated Seats Inoperative	Electrical	<a href="#">View</a>
08-024-14	5/9/2014	RHW RHP Radio Software Enhancements	Electrical	<a href="#">View</a>
08-027-14	3/5/2014	RHR Radio Software Enhancements	Electrical	<a href="#">View</a>
08-066-13	8/21/2013	RHR, RHW Or RHP Radio Software Enhancements	Electrical	<a href="#">View</a>
RC-M31-13	5/1/2013	Safety Recall M31 - Airbag System Clockspring	Electrical	<a href="#">View</a>
08-029-12	4/25/2012	Flash: Vehicle Theft Alarm Intermittently Sounds	Electrical	<a href="#">View</a>
31-003-12	3/30/2012	Adaptive Cruise Control (ACC) Module Sensor and Bracket Guidelines During Collision Repair and Damage Estimating	Electrical	<a href="#">View</a>
RC-L37-12	3/1/2012	Safety Recall L37 - Airbag System Clockspring	Electrical	<a href="#">View</a>
31-003-11	11/10/2011	Salvaged Airbags Or Other Salvaged Restraint System Component Usage	Electrical	<a href="#">View</a>

08-058-11	10/20/2011 1	Steering Wheel Mounted Audio, EVIC Switches Function Intermittently Or Not At All	Electrical	<a href="#">View</a>
18-036-11	10/6/2011	Flash: MIL Illumination And Cruise Control Improvements And Driveability Improvements	Electrical	<a href="#">View</a>
08-055-11	10/5/2011	Compass Reading 90 Degrees Off	Electrical	<a href="#">View</a>
08-053-11	8/27/2011	Flash: Vehicle Theft Alarm Intermittently Sounds, No Start	Electrical	<a href="#">View</a>
08-039-11	7/11/2011	Alarm System Sensitivity	Electrical	<a href="#">View</a>
08-038-11	7/9/2011	Flash: Steering Wheel Mounted Audio, EVIC Switches Function Intermittently Or Not At All	Electrical	<a href="#">View</a>
08-015-11	4/6/2011	Loss Of Communications With HFM	Electrical	<a href="#">View</a>

## EMISSION CONTROL (17 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
04-001-17	3/18/2017	Failure Code Change	Emission Control	<a href="#">View</a>
18-024-16 REV. B	7/30/2016	Flash: Powertrain Diagnostic And System Improvements	Emission Control	<a href="#">View</a>
18-024-16 REV. A	4/1/2016	Flash: 3.8L Diagnostic And System Improvements	Emission Control	<a href="#">View</a>
18-024-16	3/11/2016	Flash: 3.8L Diagnostic And System Improvements	Emission Control	<a href="#">View</a>
18-027-12	9/19/2012	MIL Illumination Diagnostic Trouble Code P0102 Mass Air Flow Sensor 1 Circuit Low.	Emission Control	<a href="#">View</a>
21-004-12	1/26/2012	Flash: MIL Illumination P0706 Transmission Range Sensor Performance Is Set	Emission Control	<a href="#">View</a>
31-002-11	11/10/2011	Repair Parts Used For Structural Repairs	Emission Control	<a href="#">View</a>
RC-CL34-11	11/10/2011	EMISSIONS RECALL L34 - REPROGRAM PCM - DOWNSTREAM OXYGEN SENSOR SLOW RESPONSE MONITOR	Emission Control	<a href="#">View</a>
RC-CL35-11	11/10/2011	EMISSIONS RECALL L35 - REPROGRAM PCM - DOWNSTREAM OXYGEN SENSOR SLOW	Emission Control	<a href="#">View</a>



RESPONSE MONITORAND EGR MONITOR

18-036-11	10/6/2011	Flash: MIL Illumination And Cruise Control Improvements And Driveability Improvements	Emission Control	<a href="#">View</a>
18-027-10	10/1/2011	SUPERSEDED BY :RC-L34-11(Emissions Recall L34 - Reprogram PCM - Downstream Oxygen Sensor Slow Response Monitor)	Emission Control	<a href="#">View</a>
RC-L35-11	10/1/2011	Emissions Recall L35 - Reprogram PCM - Downstream Oxygen Sensor Slow Response Monitor and EGR Monitors	Emission Control	<a href="#">View</a>
18-036-11	8/19/2011	Flash: MIL Illumination And Cruise Control Improvements And Driveability Improvements	Emission Control	<a href="#">View</a>
18-024-11	5/14/2011	Flash: MIL Illumination And Cruise Switch Inoperative And Idle Buffeting Condition	Emission Control	<a href="#">View</a>
18-025-11	5/14/2011	Flash: MIL Illumination And Driveability Improvements	Emission Control	<a href="#">View</a>
18-027-10	10/26/2010	Flash: PCM For OBD Readiness For Downstream O2 Slow Response Monitor	Emission Control	<a href="#">View</a>
18-027-10	10/20/2010	Flash: PCM For OBD Readiness For Downstream O2 Slow Response Monitor	Emission Control	<a href="#">View</a>

EXHAUST (3 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
11-002-14	4/24/2014	Exhaust Rattle At Idle Speeds	Exhaust	<a href="#">View</a>
11-002-13	12/13/2013	Exhaust Rattle At Idle Speeds	Exhaust	<a href="#">View</a>
11-002-12	5/8/2012	Supplemental Exhaust Shield For Extreme Desert Duty Cycles Off Road	Exhaust	<a href="#">View</a>

FUEL & SPARK (2 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
14-004-13	10/31/2013	Premature Fuel Shut Off When Filling Tank	Fuel & Spark	<a href="#">View</a>
14-004-13	7/17/2013	Premature Fuel Shut Off When Filling Tank	Fuel & Spark	<a href="#">View</a>

## HVAC (4 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
24 008 18	7/13/2018	A/C Systems Contain Fluorescent Leak Check Dye in Factory Fill	HVAC	<a href="#">View</a>
24-010-14	10/4/2014	Flash: HVAC System Improvements	HVAC	<a href="#">View</a>
26-004-12	6/6/2012	Fluid Flushing Requirements	HVAC	<a href="#">View</a>
24-002-11	2/25/2011	Air Conditioning Inoperative	HVAC	<a href="#">View</a>

## POWERTRAIN (10 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
04-001-17	3/18/2017	Failure Code Change	Powertrain	<a href="#">View</a>
06-001-15	8/21/2015	Squeak Noise While Depressing The Clutch Pedal	Powertrain	<a href="#">View</a>
06-001-13	7/30/2013	Squeak When Depressing The Clutch	Powertrain	<a href="#">View</a>
09-001-13	2/6/2013	Gasoline Engine Diagnostic Inspection Procedure	Powertrain	<a href="#">View</a>
21-002-12 REV. A	6/7/2012	Manual Transmission Pops Out Of 2nd, 4th, And 6th Gear Positions	Powertrain	<a href="#">View</a>
26-004-12	6/6/2012	Fluid Flushing Requirements	Powertrain	<a href="#">View</a>
21-002-12	1/13/2012	Manual Transmission Pops Out Of 2nd, 4th, And 6th Gear Positions	Powertrain	<a href="#">View</a>
RC-IL22-11	6/1/2011	Safety Recall L22 - Transmission Fluid Temperature Warning	Powertrain	<a href="#">View</a>
21-004-11	5/14/2011	Manual Transmission Pops Out Of 2nd, 4th, And 6th Gear Positions	Powertrain	<a href="#">View</a>
18-020-11	4/19/2011	Flash: MIL Illumination And Driveability/Transmission Improvements	Powertrain	<a href="#">View</a>

## RECALL (19 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
08-019-15	3/4/2015	Loss Of Power Heated Mirror Function - Recall P61	Recall	<a href="#">View</a>
08-100-14	12/2/2014	Loss Of Power Heated Mirror Function - Recall P61 Interim Repair	Recall	<a href="#">View</a>
RC-IN53-13	11/1/2013	Safety Recall N53 - Weight Label	Recall	<a href="#">View</a>
RC-M31-13	5/1/2013	Safety Recall M31 - Airbag System Clockspring	Recall	<a href="#">View</a>
RC-L37-12	3/1/2012	Safety Recall L37 - Airbag System Clockspring	Recall	<a href="#">View</a>
RC-IL31-12	1/1/2012	Safety Recall L31 - Front Brake Flies Hoses	Recall	<a href="#">View</a>
RC-CL34-11	11/10/2011	EMISSIONS RECALL L34 - REPROGRAM PCM - DOWNSTREAM OXYGEN SENSOR SLOW RESPONSE MONITOR	Recall	<a href="#">View</a>
RC-CL35-11	11/10/2011	EMISSIONS RECALL L35 - REPROGRAM PCM - DOWNSTREAM OXYGEN SENSOR SLOW RESPONSE MONITOR AND EGR MONITOR	Recall	<a href="#">View</a>
18-027-10	10/1/2011	SUPERSEDED BY :RC-L34-11(Emissions Recall L34 - Reprogram PCM - Downstream Oxygen Sensor Slow Response Monitor)	Recall	<a href="#">View</a>
RC-L35-11	10/1/2011	Emissions Recall L35 - Reprogram PCM - Downstream Oxygen Sensor Slow Response Monitor and EGR Monitors	Recall	<a href="#">View</a>
RC-CL24-11	8/31/2011	CUSTOMER SATISFACTION NOTIFICATION L24 - SOFT TOP PREMATURE WEAR AT ROOF BOWS	Recall	<a href="#">View</a>
RC-CL23-11	7/15/2011	SAFETY RECALL L23 - STEERING COLUMN PIVOT RIVETS	Recall	<a href="#">View</a>
RC-L23-11	7/1/2011	Safety Recall L23 - Steering Column Pivot Rivets	Recall	<a href="#">View</a>
RC-IL23-11	7/1/2011	Safety Recall L23 - Steering Column Pivot Rivets	Recall	<a href="#">View</a>
RC-IL22-11	6/1/2011	Safety Recall L22 - Transmission Fluid Temperature Warning	Recall	<a href="#">View</a>
RC-CL09-11	3/22/2011	SAFETY RECALL L09 - AXLE FASTENER TORQUE	Recall	<a href="#">View</a>

RC-CL03-11	3/15/2011	CUSTOMER SATISFACTION NOTIFICATION L03 - DOOR LATCHES	Recall	<a href="#">View</a>
RC-IL09-11	3/1/2011	Safety Recall L09 - Axle Fastener Torque	Recall	<a href="#">View</a>
RC-L09-11	3/1/2011	Safety Recall L09 - Axle Fastener Torque	Recall	<a href="#">View</a>

## STEERING &SUSPENSION (12 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
08-005-17	1/21/2017	Clockspring Replacement (X68 Warranty Extension)	Steering &Suspension	<a href="#">View</a>
22-002-14 REV. A	4/15/2014	Tire Flat Spotting Identification, Prevention and Resolution	Steering &Suspension	<a href="#">View</a>
22-001-14	2/19/2014	Steering Wheel Vibration at Highway Speeds	Steering &Suspension	<a href="#">View</a>
19-002-12	7/12/2012	A Self-Sustaining Vibration (Shimmy) Of The Vehicle And Steering Wheel While Driving At Speeds Typically Above 50 MPH (80 KMH)	Steering &Suspension	<a href="#">View</a>
08-037-12 REV. A	6/9/2012	Steering Wheel Mounted Audio And Electronic Vehicle Information Center (EVIC) Switches Function Intermittently Or Not At All	Steering &Suspension	<a href="#">View</a>
26-004-12	6/6/2012	Fluid Flushing Requirements	Steering &Suspension	<a href="#">View</a>
RC-CL23-11	7/15/2011	SAFETY RECALL L23 - STEERING COLUMN PIVOT RIVETS	Steering &Suspension	<a href="#">View</a>
RC-L23-11	7/1/2011	Safety Recall L23 - Steering Column Pivot Rivets	Steering &Suspension	<a href="#">View</a>
RC-IL23-11	7/1/2011	Safety Recall L23 - Steering Column Pivot Rivets	Steering &Suspension	<a href="#">View</a>
RC-CL09-11	3/22/2011	SAFETY RECALL L09 - AXLE FASTENER TORQUE	Steering &Suspension	<a href="#">View</a>
RC-IL09-11	3/1/2011	Safety Recall L09 - Axle Fastener Torque	Steering &Suspension	<a href="#">View</a>
RC-L09-11	3/1/2011	Safety Recall L09 - Axle Fastener Torque	Steering	

&Suspension

[View](#)

## TOOLS & HARDWARE (3 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
31-002-13	1/31/2013	Blending Clearcoat During The Refinish Process	Tools & Hardware	<a href="#">View</a>
31-001-13	1/11/2013	Overspray Removal	Tools & Hardware	<a href="#">View</a>
24-002-11	2/25/2011	Air Conditioning Inoperative	Tools & Hardware	<a href="#">View</a>

## WIPER AND WASHER (1 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
23-037-15	10/14/2015	Windshield Wiper Blade/Element Maintenance	Wiper and Washer	<a href="#">View</a>

# Vehicle Title History

Your title history has been sent. Please check your email.

Ran on February 1, 2023 @ 7:47 PM | [Contact us](#)

Copyright 2023 CarMD Corp