

CarMD Report for

2011 NISSAN ALTIMA

@ 123 mi
VIN: 1N4AL2APXBN414370



Unavailable

This report was created without a tool
some information will not be available

\$8,360

Market
Value

\$16,369

5 year
cost ownership

27

miles per
gallon



Diagnostic
Results

4

Maintenance
items



Emissions "Smog"
Check

1 / 164

Safety Recall(s)/
TSB(s)



Warranty
Status

4

Upcoming
Repairs

Diagnostic



This report was created without a tool. Some information is unavailable. To view this information please run another report with a tool.

Maintenance

4

CarMD has found completing the following maintenance items will help keep your car running smoothly. Your next service is due at 7,500 mi.

Item	Cost
Change Engine Oil and Filter	\$157
Inspect All Fluids and Correct Level	\$0
Inspect Brake System, Friction Material &Hydraulic System	\$39
Rotate Tires, Inspect Tire Wear, &Adjust Tire Pressure	\$51
Total	\$247

Technical Service Bulletins (TSBs)

164

A technical service bulletins (TSB) is an advisory issued by an automotive manufacture to its dealership service departments. If your vehicle is still under warranty; you can usually get the related repairs covered

ACCESSORIES AND FLUIDS (9 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
NTB10-009b	3/20/2018	REMOVAL PROCEDURE FOR SEIZED EXHAUST SENSOR	Accessories and Fluids	View
NTB15-043b	3/19/2018	PRECAUTIONS FOR CLEANING WHEELS	Accessories and Fluids	View
NTB10-114d	3/9/2018	INFLATING TIRES EQUIPPED WITH TPMS	Accessories and Fluids	View
NTB11-029b	3/9/2018	TIRE MOUNTING INFORMATION	Accessories	

			and Fluids	View
NTB10-009a	12/13/2017	REMOVAL PROCEDURE FOR SEIZED EXHAUST SENSOR	Accessories and Fluids	View
NTB11-029a	9/25/2017	TIRE MOUNTING INFORMATION	Accessories and Fluids	View
NTB12-055f	6/20/2017	CLICKING NOISE FROM FRONT OR REAR AXLE DURING TAKE-OFF/ACCELERATION	Accessories and Fluids	View
NTB12068	8/20/2012	SB Nissan; CVT Fluid Information	Accessories and Fluids	View
NTB04049	4/13/2011	SB Nissan; Trailer Light Wiring	Accessories and Fluids	View

BODY (47 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
NTB09-081g	5/15/2019	WINDSHIELD CRACKING	Body	View
NTB08-097g	5/14/2018	DIAGNOSIS OF VEHICLE PULL (DRIFT) AND/OR STEERING WHEEL OFF CENTER	Body	View
NTB09-081f	4/9/2018	WINDSHIELD CRACKING	Body	View
NTB08-107c	3/21/2018	INTELLIGENT KEY INOPERATIVE	Body	View
NTB13-028c	3/19/2018	REMOVING FOREIGN MATERIAL FROM THE WINDOW GLASS	Body	View
NTB18-004a	3/19/2018	REDUCED VEHICLE LOAD CAPACITY LABEL (REGULATORY REQUIREMENT)	Body	View
NTB18-004	1/23/2018	REDUCED VEHICLE LOAD CAPACITY LABEL (REGULATORY REQUIREMENT)	Body	View
NTB09-081e	11/29/2017	WINDSHIELD CRACKING	Body	View
NTB17-019a	11/29/2017	WINDOW GLASS WARRANTY INFORMATION	Body	

				View
NTB17024	4/10/2017	SB Nissan; Navigation System Reboots When SXM Traffic is Enabled	Body	View
NTB17030	3/20/2017	SB Nissan; Fuel Tank is Slow or Difficult to Fill	Body	View
NTB13-028b	2/22/2017	REMOVING FOREIGN MATERIAL FROM THE WINDOW GLASS	Body	View
NTB09-081d	2/21/2017	WINDSHIELD CRACKING	Body	View
NTB08-107b	8/23/2016	INTELLIGENT KEY INOPERATIVE	Body	View
NTB16003	1/5/2016	SB Nissan; Intelligent Key Replacement or Swapping Between Vehicles	Body	View
NTB14057	6/23/2014	SB Nissan; Fluid Leak Repair Service Information	Body	View
NTB14032	4/29/2014	SB Nissan; Electrical Harness Repair Information	Body	View
NTB13088	9/26/2013	Low Tire Pressure Warning System; Bulletins Summary	Body	View
NTB13079	7/31/2013	2007-2012 Altima; Reduced Performance due to CVT Fluid Temp Protection	Body	View
NTB00042c	7/22/2013	Recommendation against Making Changes to Front Seat Trim Material	Body	View
NTB13007	6/17/2013	Altima; Steering Wheel Switch Service Parts	Body	View
NTB13038	4/3/2013	SB Nissan; Lock/Unlock Request Button on Outside Door Handle does not Respon	Body	View
NTB13015	2/15/2013	SB Nissan; MIL ON with DTC B2190	Body	View
NTB12070	1/9/2013	SB Nissan - 2010-2013; NAVI Software Update	Body	View
NTB12082	9/21/2012	SB Altima Sedan, Hybrid; Buzz/Rattle/Vibration From Speakers In Rear Parcel	Body	View

NTB12075	9/14/2012	SB 2009-2012 Altima Sedan; Rattle Noise From Front Door Panel(s)	Body	View
NTB12051	6/19/2012	SB 2011-2012 Altima; MIL "ON" with DTC P0101	Body	View
NTB09118	6/8/2012	SB Nissan; Intelligent Key Battery Replacement & Battery Discharge Indicator	Body	View
TECHTALK	6/7/2012	TT Altima Armrest Removal	Body	View
NTB03074	2/21/2012	SB Nissan; Exterior Lamp Fogging	Body	View
NTB12-009	2/3/2012	SB Nissan; Door Lock/Unlock Inoperative With Intelligent Key	Body	View
NTB10120	10/7/2011	SB 2007-2012 Altima; Manual Driver Or Passenger Seat Binds, Or Will Not Move	Body	View
NTB07095	10/3/2011	SB 2007-2012 Altima; Driver Seat Lumbar Support Repair Procedure	Body	View
NTB01032	9/30/2011	SB Nissan; New Paint Guard Film Removal Information	Body	View
NTB09022	8/31/2011	SB Nissan; 12 Volt Battery Storage & Maintenance - New Vehicles in Dealer In	Body	View
NTB09131	8/15/2011	SB Certification Label and VIN Plate Replacement	Body	View
NTB11-078	8/11/2011	SB 2008-2012 Altima Coupe; Door Weather Strip Wind Noise	Body	View
NTB11-050	5/13/2011	SB 2007-2011 Altima; Revised Front Seat Back Service Procedures	Body	View
NTB08090	4/26/2011	SB Altima and Maxima; Door Panel Looks Discolored/Faded	Body	View
NTB11-045	4/25/2011	SB Altima & Maxima; Sunroof Front Drain Hose Kinked, Pinched, or Disconnect	Body	View
NTB11-023	3/2/2011	SB 2007-2011 Altima; Glove Box Assembly Service Part Change	Body	View
NTB11-013	2/15/2011	SB 2010-2011 Altima; Front Pillar Finisher Removal	Body	View

NTB99060	2/11/2011	SB Nissan; Paint Swell/Stain/Spot Under Paint Guard Film	Body	View
NTB06065	11/8/2010	SB Nissan; Power Window Auto Up Initialization	Body	View
NTB10-119	10/28/2010	CP 2011 Altima 2.5; California PZEV Emissions Label Recall Campaign	Body	View
NTB10-120	10/8/2010	SB 2007-2010 Altima; Manual Driver Or Passenger Seat Binds, Or Will Not Move	Body	View
NTB10-100	8/23/2010	SB Maxima And Altima Coupe; Driver Or Passenger Power Seat Will Not Move For	Body	View

BRAKE (12 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
NTB00-033f	11/28/2017	BRAKE NOISE/JUDDER/PEDAL FEEL DIAGNOSIS AND REPAIR	Brake	View
NTB14107	11/20/2014	SB Nissan; Diagnosis of Poor Acceleration or Lack of Power	Brake	View
NTB13039	4/4/2013	SB Nissan; Cruise Control Will Not Set and DTC P0605 is Stored	Brake	View
NTB12011	4/3/2012	CP 2007-2012 Altima Sedan & Coupe; Brake Master Cylinder - Service Campaign	Brake	View
NTB12-011	3/8/2012	CP 2007-2012 Altima Sedan & Coupe; Brake Master Cylinder - Service Campaign	Brake	View
NTB10112	11/3/2011	SB Nissan; Brake Rotor Care During New Vehicle Storage	Brake	View
NTB10077	9/21/2011	SB ABS Self Check Noise	Brake	View
NTB11043	4/21/2011	SB Diagnostic Information for DTC P0725 and P1722	Brake	View
NTB10-153	12/23/2010	SB 2010-2011 Altima & Maxima; Brakes Feel More Sensitive Than Expected	Brake	View
NTB10-145	12/15/2010	SB Nissan; ABS/VDC CAN Diagnosis Information	Brake	View

				View
NTB10-112	9/24/2010	SB Nissan; Brake Rotor Care During New Vehicle Storage	Brake	View
NTB10-110	9/15/2010	SB Altima &Maxima; Low Brake Fluid Warning Light "ON" Diagnostic Procedure	Brake	View

COOLING (3 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
NTB13079	7/31/2013	2007-2012 Altima; Reduced Performance due to CVT Fluid Temp Protection	Cooling	View
NTB12039	4/20/2012	SB 2007-2012 Altima; Engine Cooling Fan Service Parts	Cooling	View
NTB11-015a	9/6/2011	SB Altima Sedan/Coupe, Sentra, &Rogue w/QR25; Oil Leak	Cooling	View

ELECTRICAL (29 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
NTB03-074L	3/19/2018	HEADLAMP FOGGING	Electrical	View
NTB17024	4/10/2017	SB Nissan; Navigation System Reboots When SXM Traffic is Enabled	Electrical	View
NTB03-074k	3/27/2017	HEADLAMP FOGGING	Electrical	View
NTB08-107b	8/23/2016	INTELLIGENT KEY INOPERATIVE	Electrical	View
NTB16003	1/5/2016	SB Nissan; Intelligent Key Replacement or Swapping Between Vehicles	Electrical	View
NTB14107	11/20/2014	SB Nissan; Diagnosis of Poor Acceleration or Lack of Power	Electrical	View

NTB14032	4/29/2014	SB Nissan; Electrical Harness Repair Information	Electrical	View
NTB13007	6/17/2013	Altima; Steering Wheel Switch Service Parts	Electrical	View
NTB13038	4/3/2013	SB Nissan; Lock/Unlock Request Button on Outside Door Handle does not Respon	Electrical	View
NTB13027	3/22/2013	SB 2005-2013 Nissan; CAN Communication - Network Diagnostic Flow Chart	Electrical	View
NTB13015	2/15/2013	SB Nissan; MIL ON with DTC B2190	Electrical	View
NTB12070	1/9/2013	SB Nissan - 2010-2013; NAVI Software Update	Electrical	View
NTB12060	7/24/2012	SB Nissan; XM Satellite Radio/Weather/Traffic Activation	Electrical	View
NTB08044	7/2/2012	SB 2007-2011 Altima Hybrid; 12V Battery for Service	Electrical	View
NTB12041	4/27/2012	SB Nissan; Ignition Switch (Push Button) Will Not Respond	Electrical	View
NTB03074	2/21/2012	SB Nissan; Exterior Lamp Fogging	Electrical	View
NTB12-010	2/15/2012	CP 2012 Altima Sedan &Versa Sedan; Curtain Air Bag Module - Recall Campaign	Electrical	View
NTB10124	2/10/2012	SB Nissan; Extended Storage Switch and BCM Transit Mode	Electrical	View
NTB12-009	2/3/2012	SB Nissan; Door Lock/Unlock Inoperative With Intelligent Key	Electrical	View
NTB12-004	1/9/2012	SB Nissan; SRS Front Door Side Satellite Sensor Introduction	Electrical	View
NTB11103	12/19/2011	SB Nissan; Procedure To Order Premium Audio Visual Control Unit	Electrical	View
NTB10125	11/3/2011	SB Nissan; Navigation Software Update	Electrical	View
NTB09022	8/31/2011	SB Nissan; 12 Volt Battery Storage &Maintenance - New Vehicles in Dealer In	Electrical	View

NTB11-079	8/22/2011	CP 2012 Altima &NV; Air Bag Control Unit Voluntary Safety Recall Campaign	Electrical	View
NTB04049	4/13/2011	SB Nissan; Trailer Light Wiring	Electrical	View
NTB10-124b	12/16/2010	SB Nissan; Extended Storage Switch and BCM Transit Mode	Electrical	View
NTB10-139	11/23/2010	SB Altima Sedan, Coupe, And Hybrid; Engine No Crank/No Start	Electrical	View
NTB10-107	9/10/2010	SB Nissan MY 2005 - 2008; Engine No-Start With NATS DTC P1610	Electrical	View
NTB10-106	9/10/2010	SB Nissan; NATS Security - VBC Logic	Electrical	View

EMISSION CONTROL (23 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
NTB13-097g	1/29/2019	ALL MODEL YEAR 2012 AND NEWER NISSAN VEHICLES; EVAP LEAK DTC P0442, P0455, P0456 INFORMATION	Emission Control	View
NTB17-030a	8/16/2018	NISSAN; FUEL TANK IS EXTREMELY DIFFICULT TO FILL	Emission Control	View
NTB17-082a	8/21/2017	NISSAN; DTC P0456 CAUSED BY EVAP LEAK AT VENT CONTROL VALVE O-RING	Emission Control	View
NTB15055	6/24/2015	SB 2005-2015 Nissan Vehicles; ECM Reprogramming Service Information	Emission Control	View
NTB14109	11/25/2014	SB Nissan; Permanent DTC (P-DTC) Information	Emission Control	View
NTB12093	10/24/2012	SB 2011-2013 Maxima, Altima; Hard to Start when Ambient Temp near Freezing	Emission Control	View
NTB12074	9/12/2012	SB Nissan; Saved Data List - Reprogramming With CONSULT-III Plus	Emission Control	View
NTB11074	7/6/2012	SB Nissan; Reprogramming with CONSULT	Emission Control	View
NTB12051	6/19/2012	SB 2011-2012 Altima; MIL "ON" with DTC P0101	Emission	

			Control	View
NTB12035	4/10/2012	SB Nissan - ECM Replacement Procedures with Consult III plus	Emission Control	View
NTB12-018	2/16/2012	SB 2010 - 2012 Altima With QR25 for Calif; MIL on With DTC P050B	Emission Control	View
NTB08010	12/15/2011	SB 2007-2011 Altima Hybrid; DTC P0128	Emission Control	View
NTB09020	11/18/2011	SB Nissan; EVAP Leak DTC Diagnosis	Emission Control	View
NTB11049	11/10/2011	SB 2010-2012 Altima Sedan & Coupe; Idle Fluctuation When Engine Is Cold	Emission Control	View
NTB11-097	10/21/2011	SB Nissan - Intake Air Volume Learn Will Not Complete	Emission Control	View
NTB11-085	9/12/2011	SB 2008-2010 Altima With QR25DE Engine; MIL ON With DTC P1421/P050E Stored	Emission Control	View
NTB11-053	5/23/2011	SB 2011 Altima; MIL On With DTC P015B Stored	Emission Control	View
NTB11-049	5/12/2011	SB 2011 Altima Sedan & Coupe; Idle Fluctuation When Engine is Cold	Emission Control	View
NTB11043	4/21/2011	SB Diagnostic Information for DTC P0725 and P1722	Emission Control	View
NTB11-031	3/24/2011	SB 2007-2011 Altima Hybrid; MIL 'ON' with DTC P0448	Emission Control	View
NTB10-144	12/15/2010	SB 2009 Altima; MIL ON With DTC P0116	Emission Control	View
NTB10-133	11/17/2010	SB 2007-2010 Altima; MIL ON With DTC P1421/P050E Stored	Emission Control	View
NTB10-119	10/28/2010	CP 2011 Altima 2.5; California PZEV Emissions Label Recall Campaign	Emission Control	View

EXHAUST (4 TOTAL)

OEM#s	Issue	TSB Description	Type	View
-------	-------	-----------------	------	------

Date				
NTB10-009b	3/20/2018	REMOVAL PROCEDURE FOR SEIZED EXHAUST SENSOR	Exhaust	View
NTB10-009a	12/13/2017	REMOVAL PROCEDURE FOR SEIZED EXHAUST SENSOR	Exhaust	View
NTB09020	11/18/2011	SB Nissan; EVAP Leak DTC Diagnosis	Exhaust	View
NTB10-097	8/23/2010	SB Exhaust Heat Shield Noise	Exhaust	View

FUEL & SPARK (4 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
NTB17-082b	1/29/2019	NISSAN; DTC P0456 CAUSED BY EVAP LEAK AT VENT CONTROL VALVE O-RING	Fuel & Spark	View
NTB17030	3/20/2017	SB Nissan; Fuel Tank is Slow or Difficult to Fill	Fuel & Spark	View
NTB08-107b	8/23/2016	INTELLIGENT KEY INOPERATIVE	Fuel & Spark	View
NTB12041	4/27/2012	SB Nissan; Ignition Switch (Push Button) Will Not Respond	Fuel & Spark	View

HVAC (3 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
NTB12069	8/20/2012	SB 2007-12 Altima & 2009-12 Maxima; A/C is Not Cooling/ Poor Performance	HVAC	View
NTB10033	3/14/2012	SB Nissan; AV Control Unit Replacement Requires CONSULT-III Plus Configurati	HVAC	View
NTB11090	3/8/2012	2004-2005 TITAN AND ARMADA; HEATER WATER CONTROL VALVE SERVICE PART INSTALLATION	HVAC	View

POWERTRAIN (23 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
NTB17-082b	1/29/2019	NISSAN; DTC P0456 CAUSED BY EVAP LEAK AT VENT CONTROL VALVE O-RING	Powertrain	View
NTB16-109b	5/17/2018	INFORMATION TO PREVENT CVT REPLACEMENT DUE TO MISDIAGNOSIS OF NOISE	Powertrain	View
NTB99-020h	3/19/2018	LIMITATIONS ON FLAT TOWING OF NISSAN VEHICLES	Powertrain	View
NTB16-109a	8/2/2017	INFORMATION TO PREVENT CVT REPLACEMENT DUE TO MISDIAGNOSIS OF NOISE	Powertrain	View
NTB12-055f	6/20/2017	CLICKING NOISE FROM FRONT OR REAR AXLE DURING TAKE-OFF/ACCELERATION	Powertrain	View
NTB09-140a	4/28/2017	CVT OIL LEAK DIAGNOSIS USING FLORESCENT DYE	Powertrain	View
NTB17030	3/20/2017	SB Nissan; Fuel Tank is Slow or Difficult to Fill	Powertrain	View
NTB16109	11/11/2016	SB Nissan; Information to Prevent CVT Replacement Due to Misdiagnosis of N	Powertrain	View
NTB16098	10/13/2016	SB 2011-2012 Altima: Reduced Performance Due to CVT Fluid Temp Protection L	Powertrain	View
NTB14057	6/23/2014	SB Nissan; Fluid Leak Repair Service Information	Powertrain	View
NTB13079	7/31/2013	2007-2012 Altima; Reduced Performance due to CVT Fluid Temp Protection	Powertrain	View
NTB12068	8/20/2012	SB Nissan; CVT Fluid Information	Powertrain	View
NTB12055	7/9/2012	SB 2009-2012; Clicking Noise from Front Axles during Take-Off/Accel	Powertrain	View
NTB12057	7/6/2012	SB Altima/Sentra/Rogue; CVTFail-Safe Condition Service Information	Powertrain	View
NTB12-020	2/29/2012	SB Nissan; Vehicle Vibration Customer Diagnostic Worksheet	Powertrain	View

NTB10-121a	6/28/2011	SB 2007 - 2011 Altima; Hesitation or Surge Feel at Low Speeds	Powertrain	View
NTB11-043	4/21/2011	SB Diagnostic Information for DTC P0725 and P1722	Powertrain	View
NTB11042	4/20/2011	SB Altima, Juke, Rogue, Sentra; CVT Output Speed Sensor Service	Powertrain	View
NTB11-037	4/11/2011	SB 2009 Altima, Sentra, Versa, Murano, Maxima; DTC P0710 Stored	Powertrain	View
NTB10-150	12/22/2010	SB 2010 Altima, Sentra, and Rogue; MIL ON and/or Slow Acceleration From a Stop	Powertrain	View
NTB10-147	12/20/2010	SB 2007 Altima; Delayed Engagement When Shifting In Drive Or Reverse	Powertrain	View
NTB10-143	12/15/2010	SB 2007-2009 Altima; Whine Noise From CVT At Highway Speeds	Powertrain	View
NTB10-126	10/21/2010	SB Nissan; Wheel Bearing Collision Damage	Powertrain	View

RECALL (3 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
NTB12-010	2/15/2012	CP 2012 Altima Sedan & Versa Sedan; Curtain Air Bag Module - Recall Campaign	Recall	View
NTB11-079	8/22/2011	CP 2012 Altima & NV; Air Bag Control Unit Voluntary Safety Recall Campaign	Recall	View
NTB10-119	10/28/2010	CP 2011 Altima 2.5; California PZEV Emissions Label Recall Campaign	Recall	View

STEERING & SUSPENSION (43 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
NTB08-097h	6/21/2018	DIAGNOSIS OF VEHICLE PULL (DRIFT) AND/OR STEERING WHEEL OFF CENTER	Steering & Suspension	View

NTB08-097g	5/14/2018	DIAGNOSIS OF VEHICLE PULL (DRIFT) AND/OR STEERING WHEEL OFF CENTER	Steering & Suspension	View
NTB11-044c	3/23/2018	WHEEL BALANCING SERVICE INFORMATION	Steering & Suspension	View
NTB11-054b	3/21/2018	RECOMMENDED SETUP INFORMATION FOR HUNTER GSP9700	Steering & Suspension	View
NTB15-043b	3/19/2018	PRECAUTIONS FOR CLEANING WHEELS	Steering & Suspension	View
NTB99-020h	3/19/2018	LIMITATIONS ON FLAT TOWING OF NISSAN VEHICLES	Steering & Suspension	View
NTB11-062c	3/14/2018	ROAD WHEEL BALANCING WITH HUNTER ROAD FORCE® GSP9700 TIRE BALANCER	Steering & Suspension	View
NTB10-114d	3/9/2018	INFLATING TIRES EQUIPPED WITH TPMS	Steering & Suspension	View
NTB11-029b	3/9/2018	TIRE MOUNTING INFORMATION	Steering & Suspension	View
NTB11-029a	9/25/2017	TIRE MOUNTING INFORMATION	Steering & Suspension	View
NTB11-062b	9/25/2017	ROAD WHEEL BALANCING WITH HUNTER ROAD FORCE® GSP9700 TIRE BALANCER	Steering & Suspension	View
NTB11-044b	9/25/2017	WHEEL BALANCING SERVICE INFORMATION	Steering & Suspension	View
NTB99-001b	9/22/2017	STRUT AND SHOCK ABSORBER REPLACEMENT GUIDELINES	Steering & Suspension	View
NTB15043	11/16/2016	SB Nissan; Precautions for Cleaning Wheels	Steering & Suspension	View
NTB15060	7/6/2015	SB Nissan; Servicing Run Flat Tires & Low Profile Tires Equipped With TPMS	Steering & Suspension	View
NTB14057	6/23/2014	SB Nissan; Fluid Leak Repair Service Information	Steering & Suspension	View

NTB13088	9/26/2013	Low Tire Pressure Warning System; Bulletins Summary	Steering & Suspension	View
NTB13007	6/17/2013	Altima; Steering Wheel Switch Service Parts	Steering & Suspension	View
NTB10102	9/25/2012	SB Nissan; ABS/VDC Wheel Speed Sensor Diagnosis	Steering & Suspension	View
NTB12078	9/19/2012	SB Nissan; Power Steering System Service Information	Steering & Suspension	View
NTB12055	7/9/2012	SB 2009-2012; Clicking Noise from Front Axles during Take-Off/Accel	Steering & Suspension	View
NTB11062	6/22/2012	SB Nissan; Road Wheel Balancing With Hunter Road Force GSP9700 Tire Balancer	Steering & Suspension	View
NTB10114	6/14/2012	SB Nissan; Inflating Tires Equipped with TPMS	Steering & Suspension	View
NTB12033	3/29/2012	SB Nissan - Alignment Toe Setting Tolerance Increase	Steering & Suspension	View
NTB12030	3/22/2012	SB Altima, Maxima; Power Steering Hose Service Part Change	Steering & Suspension	View
NTB12-020	2/29/2012	SB Nissan; Vehicle Vibration Customer Diagnostic Worksheet	Steering & Suspension	View
NTB12-017	2/10/2012	SB 2010-2012 Altima Coupe; Noise from Rear Suspension Over Bumps	Steering & Suspension	View
NTB11-110a	1/5/2012	SB TPMS Application Changes Due To Thailand Flood	Steering & Suspension	View
NTB08097	11/21/2011	SB Nissan; Diagnosis of Vehicle Pull (Drift) and Steering Wheel Off-center	Steering & Suspension	View
NTB04054	11/21/2011	SB Nissan; Wheel Alignment Information	Steering & Suspension	View
NTB11027	11/9/2011	SB Nissan; New Vehicle Tire Flat Spotting	Steering & Suspension	View

NTB11-092	10/10/2011	SB Release of Separate OP Codes For Power Steering Hoses	Steering & Suspension	View
NTB08033	10/3/2011	SB Nissan; Tire Pressure Information For Vehicles With TPMS	Steering & Suspension	View
NTB09101	10/3/2011	SB Nissan; TPMS Warning Light Diagnostic Procedure	Steering & Suspension	View
NTB11-080	8/24/2011	SB Altima and Maxima; Axle Bolt and Torque Change	Steering & Suspension	View
NTB11-067a	8/19/2011	CP 2011-12 Altima; Front Transverse Link Bolts -- Voluntary Recall Campaign	Steering & Suspension	View
NTB11-062	6/17/2011	SB Nissan; Road Wheel Balancing With Hunter Road Force GSP9700 Tire Balancer	Steering & Suspension	View
NTB11-054	5/26/2011	SB Nissan; Recommended Setup Information For Hunter GSP9700	Steering & Suspension	View
NTB08090	4/26/2011	SB Altima and Maxima; Door Panel Looks Discolored/Faded	Steering & Suspension	View
NTB11-044	4/21/2011	SB Nissan; Wheel Balancing Service Information	Steering & Suspension	View
NTB11-027	3/10/2011	SB Nissan; New Vehicle Tire Flat Spotting	Steering & Suspension	View
NTB10-114	9/27/2010	SB Nissan; Inflating Tires Equipped with TPMS	Steering & Suspension	View
NTB10-112	9/24/2010	SB Nissan; Brake Rotor Care During New Vehicle Storage	Steering & Suspension	View

TOOLS & HARDWARE (18 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
NTB11-044c	3/23/2018	WHEEL BALANCING SERVICE INFORMATION	Tools & Hardware	View

NTB11-054b	3/21/2018	RECOMMENDED SETUP INFORMATION FOR HUNTER GSP9700	Tools &Hardware	View
NTB10-009b	3/20/2018	REMOVAL PROCEDURE FOR SEIZED EXHAUST SENSOR	Tools &Hardware	View
NTB15-043b	3/19/2018	PRECAUTIONS FOR CLEANING WHEELS	Tools &Hardware	View
NTB11-062c	3/14/2018	ROAD WHEEL BALANCING WITH HUNTER ROAD FORCE® GSP9700 TIRE BALANCER	Tools &Hardware	View
NTB10-114d	3/9/2018	INFLATING TIRES EQUIPPED WITH TPMS	Tools &Hardware	View
NTB10-009a	12/13/2017	REMOVAL PROCEDURE FOR SEIZED EXHAUST SENSOR	Tools &Hardware	View
NTB11-054a	9/25/2017	RECOMMENDED SETUP INFORMATION FOR HUNTER GSP9700	Tools &Hardware	View
NTB11-044b	9/25/2017	WHEEL BALANCING SERVICE INFORMATION	Tools &Hardware	View
NTB11-062b	9/25/2017	ROAD WHEEL BALANCING WITH HUNTER ROAD FORCE® GSP9700 TIRE BALANCER	Tools &Hardware	View
TECHTALK	9/18/2015	TT Abbreviation and Acronym Guide - Amended	Tools &Hardware	View
TECHTALK	3/25/2015	TT TechTalk Online Anywhere, Anytime	Tools &Hardware	View
NTB10048	10/3/2011	SB Nissan; Signal Tech II Diagnostic Tool	Tools &Hardware	View
NTB01032	9/30/2011	SB Nissan; New Paint Guard Film Removal Information	Tools &Hardware	View
NTB11-062	6/17/2011	SB Nissan; Road Wheel Balancing With Hunter Road Force GSP9700 Tire Balancer	Tools &Hardware	View
NTB11-054	5/26/2011	SB Nissan; Recommended Setup Information For Hunter GSP9700	Tools &Hardware	View
NTB99060	2/11/2011	SB Nissan; Paint Swell/Stain/Spot Under Paint Guard Film	Tools &Hardware	View
NTB10-114	9/27/2010	SB Nissan; Inflating Tires Equipped with TPMS	Tools &Hardware	View

WIPER AND WASHER (1 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
NTB08111	10/6/2011	SB Nissan; Wiper Blade Cover Removal	Wiper and Washer	View

Recall Notices

1

Your vehicle has **1** Safety Recalls. These are announcements made by your vehicle's manufacturer that there is a safety-related problem that needs immediate repair and should be repaired free of charge by your vehicle's dealership.

CAMPAIGN ID NUMBER: **11V371000** DATE: 1/19/2011

Recall Number: 96179

Description Defect: NISSAN IS RECALLING CERTAIN MODEL YEAR 2011-2012 NISSAN ALTIMA SEDAN VEHICLES MANUFACTURED FROM APRIL 25, 2011, THROUGH JUNE 10, 2011 AT THE CANTON, MISSISSIPPI PLANT. THE TRANSVERSE LINK BOLT MAY NOT HAVE BEEN TORQUED TO THE PROPER SPECIFICATION. THIS CONDITION COULD CAUSE THE BOLT TO BECOME LOOSE WHILE THE VEHICLE IS BEING DRIVEN, CREATING A RATTLING NOISE AND VIBRATION.

Consequence: IF THE BOLT COMES OUT COMPLETELY, THE DRIVER MAY EXPERIENCE DIFFICULTY CONTROLLING THE DIRECTION OF THE VEHICLE WHICH COULD RESULT IN A CRASH.

Corrective Action: NISSAN WILL REPLACE THE TRANSVERSE LINK BOLTS AND NUTS AND TIGHTEN THEM TO THE PROPER TORQUE SPECIFICATION FREE OF CHARGE. THE SAFETY RECALL BEGAN ON AUGUST 8, 2011. OWNERS MAY CONTACT NISSAN AT 1-800-647-7261.

Warranty Status



This vehicle is covered. If this vehicle has changed hands, the new owner is also covered by this warranty. Below is your default warranty information. This excludes any additional warranty coverage you may have purchased.



Basic new car warranty



Powertrain warranty





Federal emissions warranty

Upcoming Repairs

4

CarMD has analyzed your vehicle's condition and found that its likely additional repairs may be needed within the next 12 months. It is recommended that you have these parts inspected by a trusted technician, and replace as needed.

<p>66%</p> <p>Likelihood of</p> <p>Reprogram Engine Control Module (ECM)</p> <p>with</p> <p>\$127</p> <p>Cost of repair</p> <p>\$0 in parts</p> <p>\$102 in labor</p> <p>\$25 in misc</p>  <p>Repair difficulty</p>	<p>10%</p> <p>Likelihood of</p> <p>Replace Catalytic Converter(s) with new OE Catalytic Converter(s)</p> <p>with</p> <p>\$921</p> <p>Cost of repair</p> <p>\$662 in parts</p> <p>\$234 in labor</p> <p>\$25 in misc</p>  <p>Repair difficulty</p>
<p>10%</p> <p>Likelihood of</p> <p>Replace Mass Air Flow (MAF) Sensor</p> <p>with</p> <p>\$318</p> <p>Cost of repair</p> <p>\$191 in parts</p> <p>\$102 in labor</p> <p>\$25 in misc</p>	<p>10%</p> <p>Likelihood of</p> <p>Replace Cylinder Head Gasket(s)</p> <p>with</p> <p>\$1,744</p> <p>Cost of repair</p> <p>\$78 in parts</p> <p>\$1,566 in labor</p> <p>\$100 in misc</p>



Repair difficulty



Repair difficulty

Thank you for taking the time to run a
CarMD Vehicle Health Report ... please
drive safely!

Thank you for using CarMD. The information provided here is meant to supplement, not replace, regular automotive maintenance programs or advice by a qualified automotive technician. Always seek the advice of your personal mechanic, dealership, or an ASE-certified automotive technician prior to attempting any repairs to your vehicle. The check engine light may not immediately turn off after repair and may need a repair verification drive cycle (refer to your vehicle's repair manual) after completion of the needed repairs.