

# Premium Vehicle Maintenance Report

for your  
**2010 BMW 528**

@ 40,000 miles




Average MPG: 21









## Maintenance

8 items

If you have not completed the following items below, completing these services before they are due will help keep your car running smoothly.

**This service is due at 45,000 mi**

Service Item (s)	Difficulty	Cost
 <b>Replace Cabin Air Filter</b> <a href="#">Buy Online Now</a>	 Repair difficulty	<b>\$177</b> Cost of repair \$136 in parts \$41 in labor
<b>Change Engine Oil and Filter</b>  <b>Engine Oil Drain Plug Gasket</b> <a href="#">Buy Online Now</a>  <b>Engine Oil Filter</b> <a href="#">Buy Online Now</a> 	 Repair difficulty	<b>\$168</b> Cost of repair \$107 in parts \$61 in labor

<p><b>Engine Oil</b>  <a href="#">Buy Online Now</a></p>		
<p>  <b>Inspect Parking Brake Operation &amp; Tension</b>  <a href="#">Buy Online Now</a></p>	<p>  Repair difficulty</p>	<p><b>\$123</b>  Cost of repair  \$123 in parts  \$0 in labor</p>
<p>  <b>Inspect Wiper &amp; Washer System</b>  <a href="#">Buy Online Now</a></p>	<p>  Repair difficulty</p>	<p><b>\$10</b>  Cost of repair  \$10 in parts  \$0 in labor</p>
<p>Inspect On-Board Diagnostic Memory</p>	<p>  Repair difficulty</p>	<p><b>\$0</b>  Cost of repair  \$0 in parts  \$0 in labor</p>
<p>Inspect Tire Wear and Adjust Tire Pressure</p>	<p>  Repair difficulty</p>	<p><b>\$0</b>  Cost of repair  \$0 in parts  \$0 in labor</p>
<p>Inspect Warning System Operation</p>	<p>  Repair difficulty</p>	<p><b>\$0</b>  Cost of repair  \$0 in parts  \$0 in labor</p>
<p>Measure Brake Linings, Rotor Thickness and Runout</p>	<p>  Repair difficulty</p>	<p><b>\$31</b>  Cost of repair  \$0 in parts  \$31 in labor</p>

## Warranty Status



This vehicle is NOT currently covered. All warranties have expired.

Below is your default warranty information. This excludes any additional warranty coverage you may have purchased.



Basic new car warranty  
4 years



Powertrain warranty  
4 years



Federal emissions warranty  
8 years

Extend your vehicle warranty





Customers Receive **\$100 OFF** With Purchase

## Upcoming Issues

4 items

By analyzing other vehicles of the same year make model our results show you may need the following repairs in the next 12 months. It is recommended that you have these parts inspected by a trusted technician, and replace as needed.

<p><b>26%</b></p> <p>Likelihood of</p> <p><b>Replace Ignition Coil(s)</b></p> <p><b>\$195</b></p> <p>Cost of repair</p> <p>\$93 in parts</p> <p>\$102 in labor</p>  <p>Repair difficulty</p>	<p><b>25%</b></p> <p>Likelihood of</p> <p><b>Inspect for Loose Fuel Cap and Tighten or Replace as Necessary</b></p> <p><b>\$5</b></p> <p>Cost of repair</p> <p>\$5 in parts</p> <p>\$0 in labor</p>  <p>Repair difficulty</p>
<p><b>12%</b></p> <p>Likelihood of</p> <p><b>Replace Ignition Coil(s) and</b></p>	<p><b>6%</b></p> <p>Likelihood of</p> <p><b>Replace Thermostat and Housing</b></p>

### Spark Plug(s)

**\$427**

Cost of repair

\$236 in parts

\$191 in labor



Repair difficulty

### Assembly

**\$443**

Cost of repair

\$230 in parts

\$213 in labor



Repair difficulty

Extend your vehicle warranty



Customers Receive **\$100 OFF** With Purchase

## Technical Service Bulletins (TSBs)

467 items

A technical service bulletins (TSB) is an advisory issued by an automotive manufacture to its dealership service departments. If your vehicle is still under warranty; you can usually get the related repairs covered

### ACCESSORIES AND FLUIDS (11 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
SI B06 02 17	1/1/2017	Service Roundtable: January Show	Accessories and Fluids	<a href="#">View</a>
SI B31 02 14	4/1/2014	Front Differential Replacement Assemblies: Non-prefilled from Factory	Accessories and Fluids	<a href="#">View</a>
SI B06 12 12	12/1/2012	Service Roundtable: December 2012 Show	Accessories and Fluids	<a href="#">View</a>
SI B06 11 12	11/1/2012	Service Roundtable: November 2012 Show	Accessories and Fluids	<a href="#">View</a>
SI B06 09 12	9/1/2012	Service Roundtable: September 2012 Show	Accessories and Fluids	<a href="#">View</a>
SI B06 08 12	8/1/2012	Service Roundtable: August 2012 Show	Accessories and Fluids	<a href="#">View</a>

SI B06 12 10	12/1/2010	Service Roundtable: December 2010 Show	Accessories and Fluids	<a href="#">View</a>
SI B65 02 10	2/1/2010	Aftersales Retrofit Installation Problems	Accessories and Fluids	<a href="#">View</a>
SI B06 12 09	12/1/2009	Service Roundtable: December 2009 Show	Accessories and Fluids	<a href="#">View</a>
SI B06 11 09	11/1/2009	Service Roundtable: November 2009 Show	Accessories and Fluids	<a href="#">View</a>
SI B51 29 09	9/1/2009	1-Hour Windshield Urethane	Accessories and Fluids	<a href="#">View</a>

## BODY (156 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
SI B00 09 19	6/1/2019	CBS DISPLAYS AN IMPLAUSIBLE AVERAGE MILEAGE PER WEEK VALUE OF 1,584 IN ISPA NEX	Body	<a href="#">View</a>
SI B00 06 19	5/1/2019	BMW VEHICLES - LEATHER CARE	Body	<a href="#">View</a>
SI B00 08 19	4/1/2019	PROCESS FOR NOTIFYING BMW NA OF SAFETY-RELATED COMPLAINTS	Body	<a href="#">View</a>
SI B06 01 19	2/1/2019	Service Roundtable: February 2019	Body	<a href="#">View</a>
SI B00 06 18	12/1/2018	2018 CARLISLE TECHNICIAN SURVEY FEEDBACK	Body	<a href="#">View</a>
SI B08 03 18	11/1/2018	G05 CAMPAIGNS OVERVIEW	Body	<a href="#">View</a>
SI B08 04 18	11/1/2018	TAKATA AIR BAG RECALL ? TOWING OF CUSTOMER VEHICLES	Body	<a href="#">View</a>
SI B08 01 18	9/1/2018	TAKATA OUTREACH PROGRAM: USED CAR DEALERS RECALL DATA	Body	<a href="#">View</a>
SI B01 25 18	8/1/2018	MAINTENANCE REFRESH UPDATE: NEW SYSTEM ENHANCEMENTS FOR STANDARD MAINTENANCE	Body	<a href="#">View</a>
SI B06 07 18	7/1/2018	Service Roundtable: July Show	Body	<a href="#">View</a>
SI B06 06 18	7/1/2018	Service Roundtable: June Show	Body	<a href="#">View</a>

SI B01 20 18	6/1/2018	2018 MODEL YEAR G01 (X3) VEHICLES WERE SHIPPED WITH 2019MODEL YEAR WARRANTY/MA	Body	<a href="#">View</a>
SI B09 01 18	5/1/2018	IRAP CONTROL UNIT RECOVERY	Body	<a href="#">View</a>
SI B01 01 18	5/1/2018	FRONT PASSENGER SEAT OCCUPANCY (OC3) MAT FOR SRS: LIMITEDWARRANTY EXTENSION TO	Body	<a href="#">View</a>
SI B06 03 18	3/1/2018	Service Roundtable: March Show	Body	<a href="#">View</a>
SI B08 09 17	1/1/2018	TWO NEW DELIVERY STOPS ANNOUNCED FOR CERTAIN X3 AND 3SERIES VEHICLES	Body	<a href="#">View</a>
SI B08 06 17	12/1/2017	SYSTEM ENHANCEMENTS TO INCREASE CAMPAIGN VISIBILITY	Body	<a href="#">View</a>
SI B08 08 17	12/1/2017	USE OF MOBILE SERVICE VEHICLES FOR TAKATA RECALLS	Body	<a href="#">View</a>
SI B00 10 17	11/1/2017	G01 QUALITY FEEDBACK	Body	<a href="#">View</a>
SI B01 28 17	9/1/2017	CLASS ACTION LAW SUIT SETTLEMENT: WATER INTRUSION ANDACCUMULATION IN THE TRUN	Body	<a href="#">View</a>
SI B06 07 17	8/1/2017	Service Roundtable July Show	Body	<a href="#">View</a>
SI B08 07 17	8/1/2017	DELIVERY STOP OR RECALL NOTIFICATION VIA MOBILE DEVICE	Body	<a href="#">View</a>
SI B06 06 17	7/1/2017	Service Roundtable: June Show	Body	<a href="#">View</a>
SI B01 13 17	6/1/2017	Shipping Specific Non-Deployed Vehicle Safety Devices to Lighting Resources, LLC	Body	<a href="#">View</a>
SI B01 12 17	6/1/2017	VDC (Port-Installed) Accessories: Defects In Material or Workmanship Or Not Inst	Body	<a href="#">View</a>
SI B01 11 17	6/1/2017	Visual Inspection Of Brake Discs/Rotors for New Car Deliveries	Body	<a href="#">View</a>
SI B08 05 17	6/1/2017	Takata Outreach Program - Stericycle	Body	<a href="#">View</a>
SI B06 05 17	5/1/2017	Service Roundtable: May Show	Body	<a href="#">View</a>
SI B06 04 17	4/1/2017	Service Roundtable: April Show	Body	<a href="#">View</a>

SI B08 02 17	3/1/2017	TAKATA PARTS ALLOCATION PLAN GUIDE TO ALLOCATION AND CUSTOMER COMMUNICATION	Body	<a href="#">View</a>
SI B06 03 17	2/1/2017	Service Roundtable: February Show	Body	<a href="#">View</a>
SI B06 02 17	1/1/2017	Service Roundtable: January Show	Body	<a href="#">View</a>
SI B06 01 17	1/1/2017	Service Roundtable: 2016 Topics	Body	<a href="#">View</a>
SI B01 29 16	12/1/2016	BMW RECALL/SERVICE ACTION REPAIRS – ALTERNATIVE MOBILITY SOLUTIONS (AMS)	Body	<a href="#">View</a>
SI B08 04 16	11/1/2016	RECALL CAMPAIGN: CUSTOMER NOTIFICATION	Body	<a href="#">View</a>
SI B01 25 16	11/1/2016	DCSNET REPAIR ORDER/CLAIM DISABLED VEHICLE: TOW/EMERGENCY SERVICE INDICATOR ...	Body	<a href="#">View</a>
SI B01 22 16	11/1/2016	Dangerous Goods (DG) Part Return Program	Body	<a href="#">View</a>
SI B52 06 16	11/1/2016	Driver's Seat Groans/Creaks Under Load	Body	<a href="#">View</a>
TRI B00 01 16	10/1/2016	GOOGLE SEARCH NETWORK SECURITY SETTINGS	Body	<a href="#">View</a>
SI B01 26 16	10/1/2016	ADMINISTRATIVE PAYMENT - ELIGIBILITY FOR VALID AND APPROVED TEILECLEARING CASES	Body	<a href="#">View</a>
SI B00 09 16	10/1/2016	2016 Technician Survey From Carlisle	Body	<a href="#">View</a>
SI B84 02 16	9/1/2016	BMW ASSIST: CDMA SERVICE DISCONTINUATION	Body	<a href="#">View</a>
SI B06 09 16	9/1/2016	Service Roundtable: September Show	Body	<a href="#">View</a>
SI B06 08 16	8/1/2016	Service Roundtable: August Show	Body	<a href="#">View</a>
SI B51 21 16	8/1/2016	WIND NOISE FROM KIDNEY GRILL	Body	<a href="#">View</a>
SI B10 03 16	8/1/2016	GOOGLE SEARCH NETWORK SECURITY SETTINGS	Body	<a href="#">View</a>
SI B01 21 16	7/1/2016	REMOTE KEY READ AND SERVICE CONSULTATION	Body	<a href="#">View</a>

SI B10 01 16	7/1/2016	Deactivated Service Information Bulletin List	Body	<a href="#">View</a>
SI B10 02 16	6/1/2016	Changes to Service Bulletins	Body	<a href="#">View</a>
SI B07 01 16	5/1/2016	Integrated Measurement Interface Box - IMIB R2 V6	Body	<a href="#">View</a>
SI B09 02 16	4/1/2016	IRAP Next	Body	<a href="#">View</a>
SI B00 05 16	4/1/2016	Submitting PuMA/TeileClearing Cases via PuMA App on Android Devices	Body	<a href="#">View</a>
SI B65 09 16	3/1/2016	Radio / Navigation / Head Unit Identification	Body	<a href="#">View</a>
SI B65 02 16	2/1/2016	Audio System Speaker Testing	Body	<a href="#">View</a>
SI B01 02 15	1/1/2016	N54 Engine Fuel Injectors-Limited Warranty Extension to 10 Years/120,000 Miles	Body	<a href="#">View</a>
SI B00 06 15	9/1/2015	SMS/Text Messaging for PuMA/ TeileClearing Cases	Body	<a href="#">View</a>
SI B01 09 15	7/1/2015	BMW Engine Oil: New Repair Order Invoicing Procedure	Body	<a href="#">View</a>
SI B01 16 15	7/1/2015	An "Add Engine Oil" Check Control Message Display	Body	<a href="#">View</a>
SI B09 02 15	7/1/2015	"The Headunit has an Invalid IP address" Message Appears at Start of ISTA/P	Body	<a href="#">View</a>
SI B07 02 15	7/1/2015	ISTA 3.50 Information	Body	<a href="#">View</a>
SI B00 05 15	6/1/2015	BMW Group Technical Support and "New" PuMA Hotline	Body	<a href="#">View</a>
SI B06 05 15	5/1/2015	Service Roundtable: May 2015 Show	Body	<a href="#">View</a>
SI B00 04 15	4/1/2015	Discontinuation of Recall/Service Action Label Use	Body	<a href="#">View</a>
SI B10 01 15	4/1/2015	Deactivated Service Information Bulletin List	Body	<a href="#">View</a>
SI B07 03 14	2/1/2015	Diagnosing Stored Fault Codes to Help Avoid Repeat Repair Visits	Body	<a href="#">View</a>



SI B00 08 14	10/1/2014	US Dealer Meeting: September 2014	Body	<a href="#">View</a>
SI B06 09 14	9/1/2014	Service Roundtable: September 2014 Show	Body	<a href="#">View</a>
SI B01 09 14	9/1/2014	Front Passenger Air Bag OC3 Mat: Limited Warranty Extension to 15 Years	Body	<a href="#">View</a>
SI B01 16 14	9/1/2014	BMW "AMP-up" Customer Care Fleet Increases	Body	<a href="#">View</a>
SI B65 08 14	9/1/2014	Recall Campaign 13V-564: Replace Front Passenger Air Bag Seat Occupancy Sensor	Body	<a href="#">View</a>
SI B06 08 14	8/1/2014	Service Roundtable: August 2014 Show	Body	<a href="#">View</a>
SI B01 08 14	7/1/2014	Updated Requirements for BMW Electronic Archiving System (EAS)	Body	<a href="#">View</a>
SI B01 04 14	7/1/2014	External Engine Oil Leaks and Repairs	Body	<a href="#">View</a>
SI B84 02 14	7/1/2014	ConnectedDrive/BMW Assist System Diagnosis Information	Body	<a href="#">View</a>
SI B01 11 14	7/1/2014	Council of Warranty Administrators	Body	<a href="#">View</a>
SI B07 02 14	7/1/2014	ISTA Premium Repair Instructions	Body	<a href="#">View</a>
SI B01 05 14	6/1/2014	BMW Product Quality Analysis: Special Parts Return Requests	Body	<a href="#">View</a>
SI B84 03 14	6/1/2014	iPhone: Connection Failures with iOS 7	Body	<a href="#">View</a>
SI B06 06 14	6/1/2014	Service Roundtable: June 2014 Show	Body	<a href="#">View</a>
SI B06 04 14	4/1/2014	Service Roundtable: April 2014 Show	Body	<a href="#">View</a>
SI B00 05 14	3/1/2014	Service Quality Toolbox	Body	<a href="#">View</a>
SI B06 03 14	3/1/2014	Service Roundtable: March 2014 Show	Body	<a href="#">View</a>
SI B06 02 14	2/1/2014	Service Roundtable: February 2014 Show	Body	<a href="#">View</a>

SI B51 04 14	1/1/2014	BMW Group ColorSystem Document	Body	<a href="#">View</a>
SI B06 12 13	12/1/2013	Service Roundtable: December 2013 Show	Body	<a href="#">View</a>
SI B72 02 13	12/1/2013	Lower Belt Buckle for Front or Rear Seat May Not Function	Body	<a href="#">View</a>
SI B06 09 13	9/1/2013	Service Roundtable: September 2013 Show	Body	<a href="#">View</a>
SI B01 04 13	8/1/2013	Bodyguard® Exterior Paint Finish Protection	Body	<a href="#">View</a>
SI B06 05 13	5/1/2013	Service Roundtable: May 2013 Show	Body	<a href="#">View</a>
SI B06 03 13	3/1/2013	Service Roundtable: March 2013 Show	Body	<a href="#">View</a>
SI B06 02 13	2/1/2013	Service Roundtable: February 2013 Show	Body	<a href="#">View</a>
SI B06 01 13	1/1/2013	Service Roundtable: January 2013 Show	Body	<a href="#">View</a>
SI B06 12 12	12/1/2012	Service Roundtable: December 2012 Show	Body	<a href="#">View</a>
SI B06 11 12	11/1/2012	Service Roundtable: November 2012 Show	Body	<a href="#">View</a>
SI B06 10 12	10/1/2012	Service Roundtable: October 2012 Show	Body	<a href="#">View</a>
SI B06 09 12	9/1/2012	Service Roundtable: September 2012 Show	Body	<a href="#">View</a>
SI B06 08 12	8/1/2012	Service Roundtable: August 2012 Show	Body	<a href="#">View</a>
SI B04 18 12	8/1/2012	Wire Pull Handle with Suction Cup for Windshield Removal	Body	<a href="#">View</a>
SI B06 07 12	7/1/2012	Service Roundtable: July 2012 Show	Body	<a href="#">View</a>
SI B06 06 12	6/1/2012	Service Roundtable: June 2012 Show	Body	<a href="#">View</a>
SI B06 05 12	5/1/2012	Service Roundtable: May 2012 Show	Body	<a href="#">View</a>

SI B10 01 12	5/1/2012	BMW TIS Website Changes	Body	<a href="#">View</a>
SI B06 04 12	4/1/2012	Service Roundtable: April 2012 Show	Body	<a href="#">View</a>
SI B06 03 12	3/1/2012	Service Roundtable: March 2012 Show	Body	<a href="#">View</a>
SI B06 02 12	2/1/2012	Service Roundtable: February 2012 Show	Body	<a href="#">View</a>
SI B06 01 12	1/1/2012	Service Roundtable: January 2012 Show	Body	<a href="#">View</a>
SI B06 12 11	12/1/2011	Service Roundtable: December 2011 Show	Body	<a href="#">View</a>
SI B06 11 11	11/1/2011	Service Roundtable: November 2011 Show	Body	<a href="#">View</a>
SI B06 10 11	10/1/2011	Service Roundtable: October 2011 Show	Body	<a href="#">View</a>
SI B84 03 11	9/1/2011	Combox Replacement Part Activation via DCSnet for BMW Assist	Body	<a href="#">View</a>
SI B06 08 11	8/1/2011	Service Roundtable: August 2011 Show	Body	<a href="#">View</a>
SI B01 06 11	8/1/2011	New BMW Vehicles - Environmental Paint Finish Damage	Body	<a href="#">View</a>
SI B06 07 11	7/1/2011	Service Roundtable: July 2011 Show	Body	<a href="#">View</a>
SI B06 06 11	6/1/2011	Service Roundtable: June 2011 Show	Body	<a href="#">View</a>
SI B06 05 11	5/1/2011	Service Roundtable: May 2011 Show	Body	<a href="#">View</a>
SI B65 05 11	5/1/2011	CCC - "Presets" List in Satellite Radio Mode Is Erased	Body	<a href="#">View</a>
SI B32 05 11	5/1/2011	Steering Wheel Leather Cover Is Peeling	Body	<a href="#">View</a>
SI B06 04 11	4/1/2011	Service Roundtable: April 2011 Show	Body	<a href="#">View</a>
SI B06 03 11	3/1/2011	Service Roundtable: March 2011 Show	Body	<a href="#">View</a>

SI B54 01 11	2/1/2011	Test Plans for Panoramic Roof	Body	<a href="#">View</a>
SI B06 02 11	2/1/2011	Service Roundtable: February 2011 Show	Body	<a href="#">View</a>
SI B06 12 10	12/1/2010	Service Roundtable: December 2010 Show	Body	<a href="#">View</a>
SI B21 01 10	11/1/2010	Dual Mass Flywheel - Diagnosis and Inspection	Body	<a href="#">View</a>
SI B06 11 10	11/1/2010	Service Roundtable: November 2010 Show	Body	<a href="#">View</a>
SI B06 10 10	10/1/2010	Service Roundtable: October 2010 Show	Body	<a href="#">View</a>
SI B09 06 10	9/1/2010	Service Roundtable: September 2010 Show	Body	<a href="#">View</a>
SI B51 28 10	9/1/2010	Creaking Noise from Top of Door Frame and Window	Body	<a href="#">View</a>
SI B06 09 10	9/1/2010	Service Roundtable - September 2010	Body	<a href="#">View</a>
SI B01 04 10	8/1/2010	BMW Maint. Program Annual Low-mileage & Customer Pay Addtl Engine Oil Changes	Body	<a href="#">View</a>
SI B07 03 10	8/1/2010	Non-electric Diagnosis	Body	<a href="#">View</a>
SI B06 06 10	6/1/2010	Service Roundtable: June 2010 Show	Body	<a href="#">View</a>
SI B06 05 10	5/1/2010	Service Roundtable: May 2010 Show	Body	<a href="#">View</a>
SI B06 04 10	4/1/2010	Service Roundtable: April 2010 Show	Body	<a href="#">View</a>
SI B62 03 10	3/1/2010	Head-up Display Is Inoperative	Body	<a href="#">View</a>
SI B06 03 10	3/1/2010	Service Roundtable - March 2010	Body	<a href="#">View</a>
SI B00 13 09	2/1/2010	BMW Product Content Changes	Body	<a href="#">View</a>
SI B06 02 10	2/1/2010	Service Roundtable: February 2010 Show	Body	<a href="#">View</a>

SI B62 02 10	2/1/2010	Time and Date Lost When Vehicle Sleeps	Body	<a href="#">View</a>
SI B06 01 10	1/1/2010	Service Roundtable: January 2010 Show	Body	<a href="#">View</a>
SI B09 04 09	1/1/2010	Loading/Activation of Enabling Codes with ISTA/P	Body	<a href="#">View</a>
SI B06 12 09	12/1/2009	Service Roundtable: December 2009 Show	Body	<a href="#">View</a>
SI B51 39 09	12/1/2009	Damage to the Interior Trim and/or Vents	Body	<a href="#">View</a>
SI B51 33 09	11/1/2009	Ashtray Cover Sticking	Body	<a href="#">View</a>
SI B06 11 09	11/1/2009	Service Roundtable: November 2009 Show	Body	<a href="#">View</a>
SI B06 10 09	10/1/2009	Service Roundtable: October 2009 Show	Body	<a href="#">View</a>
SI B52 13 09	10/1/2009	Front Seat Noise Symptom Diagnosis	Body	<a href="#">View</a>
SI B06 09 09	9/1/2009	Service Roundtable: September 2009 Show	Body	<a href="#">View</a>
SI B51 31 09	9/1/2009	Power Fold Mirror Position Incorrect	Body	<a href="#">View</a>
SI B51 29 09	9/1/2009	1-Hour Windshield Urethane	Body	<a href="#">View</a>
SI B62 03 09	7/1/2009	Outside Temperature Display Is Incorrect	Body	<a href="#">View</a>
SI B54 04 09	5/1/2009	Wind Noise or Water Leak from the Sunroof	Body	<a href="#">View</a>
SI B65 10 09	5/1/2009	Vehicle Position Is Missing or Incorrect On the Navigation Map	Body	<a href="#">View</a>
SI B61 07 09	5/1/2009	One-Touch Windows Inoperative After General Module Replacement	Body	<a href="#">View</a>
SI B65 07 09	4/1/2009	Navigation System Has Missing or Incorrect Road Map Data	Body	<a href="#">View</a>
SI B04 09 09	4/1/2009	New Special Blades for Drawing Knife Set 652 010	Body	<a href="#">View</a>

SI B04 12 09	4/1/2009	Universal Seat Adapter	Body	<a href="#">View</a>
--------------	----------	------------------------	------	----------------------

## BRAKE (49 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
SI B04 10 17	11/1/2017	BRAKE ROTOR GAUGE KIT	Brake	<a href="#">View</a>
SI B01 11 17	6/1/2017	Visual Inspection Of Brake Discs/Rotors for New Car Deliveries	Brake	<a href="#">View</a>
SI B34 07 17	6/1/2017	Visual Inspection Of Brake Discs/Rotors for New Car Deliveries	Brake	<a href="#">View</a>
SI B06 03 17	2/1/2017	Service Roundtable: February Show	Brake	<a href="#">View</a>
SI B06 01 17	1/1/2017	Service Roundtable: 2016 Topics	Brake	<a href="#">View</a>
SI B34 10 16	12/1/2016	BRAKE PAD MAINTENANCE SERVICES: BRAKE DISC RESURFACING GUIDELINES	Brake	<a href="#">View</a>
SI B34 12 16	11/1/2016	Brake Squeal Repair Guide	Brake	<a href="#">View</a>
SI B34 11 16	11/1/2016	On-Car Brake Lathe	Brake	<a href="#">View</a>
SI B34 01 15	1/1/2015	BMW Brake Systems: Customer Information Brochure	Brake	<a href="#">View</a>
SI B34 04 14	12/1/2014	Diagnosis of Compound Brake System Complaints in M Vehicles	Brake	<a href="#">View</a>
SI B34 01 14	4/1/2014	Vibration When Braking: Diagnosing and Repairing	Brake	<a href="#">View</a>
SI B06 02 14	2/1/2014	Service Roundtable: February 2014 Show	Brake	<a href="#">View</a>
SI B34 06 13	11/1/2013	Brake Disc and Brake Pad Guidelines and Reference Information	Brake	<a href="#">View</a>
SI B06 09 13	9/1/2013	Service Roundtable: September 2013 Show	Brake	<a href="#">View</a>
SI B06 05 13	5/1/2013	Service Roundtable: May 2013 Show	Brake	<a href="#">View</a>

SI B06 04 13	4/1/2013	Service Roundtable: April 2013 Show	Brake	<a href="#">View</a>
SI B06 03 13	3/1/2013	Service Roundtable: March 2013 Show	Brake	<a href="#">View</a>
SI B06 02 13	2/1/2013	Service Roundtable: February 2013 Show	Brake	<a href="#">View</a>
SI B06 01 13	1/1/2013	Service Roundtable: January 2013 Show	Brake	<a href="#">View</a>
SI B06 12 12	12/1/2012	Service Roundtable: December 2012 Show	Brake	<a href="#">View</a>
SI B06 11 12	11/1/2012	Service Roundtable: November 2012 Show	Brake	<a href="#">View</a>
SI B06 10 12	10/1/2012	Service Roundtable: October 2012 Show	Brake	<a href="#">View</a>
SI B06 09 12	9/1/2012	Service Roundtable: September 2012 Show	Brake	<a href="#">View</a>
SI B06 08 12	8/1/2012	Service Roundtable: August 2012 Show	Brake	<a href="#">View</a>
SI B06 07 12	7/1/2012	Service Roundtable: July 2012 Show	Brake	<a href="#">View</a>
SI B06 04 12	4/1/2012	Service Roundtable: April 2012 Show	Brake	<a href="#">View</a>
SI B06 12 11	12/1/2011	Service Roundtable: December 2011 Show	Brake	<a href="#">View</a>
SI B06 11 11	11/1/2011	Service Roundtable: November 2011 Show	Brake	<a href="#">View</a>
SI B06 10 11	10/1/2011	Service Roundtable: October 2011 Show	Brake	<a href="#">View</a>
SI B06 08 11	8/1/2011	Service Roundtable: August 2011 Show	Brake	<a href="#">View</a>
SI B06 07 11	7/1/2011	Service Roundtable: July 2011 Show	Brake	<a href="#">View</a>
SI B06 06 11	6/1/2011	Service Roundtable: June 2011 Show	Brake	<a href="#">View</a>
SI B06 05 11	5/1/2011	Service Roundtable: May 2011 Show	Brake	<a href="#">View</a>

SI B06 04 11	4/1/2011	Service Roundtable: April 2011 Show	Brake	<a href="#">View</a>
SI B34 04 10	4/1/2011	Recall Campaign 10V-446: Inspect Brake Booster Vacuum Supply Line	Brake	<a href="#">View</a>
SI B06 03 11	3/1/2011	Service Roundtable: March 2011 Show	Brake	<a href="#">View</a>
SI B06 02 11	2/1/2011	Service Roundtable: February 2011 Show	Brake	<a href="#">View</a>
SI B06 01 11	1/1/2011	Service Roundtable: January 2011 Show	Brake	<a href="#">View</a>
SI B06 12 10	12/1/2010	Service Roundtable: December 2010 Show	Brake	<a href="#">View</a>
SI B06 11 10	11/1/2010	Service Roundtable: November 2010 Show	Brake	<a href="#">View</a>
SI B06 10 10	10/1/2010	Service Roundtable: October 2010 Show	Brake	<a href="#">View</a>
SI B09 06 10	9/1/2010	Service Roundtable: September 2010 Show	Brake	<a href="#">View</a>
SI B06 09 10	9/1/2010	Service Roundtable - September 2010	Brake	<a href="#">View</a>
SI B06 01 10	1/1/2010	Service Roundtable: January 2010 Show	Brake	<a href="#">View</a>
SI B06 12 09	12/1/2009	Service Roundtable: December 2009 Show	Brake	<a href="#">View</a>
SI B06 11 09	11/1/2009	Service Roundtable: November 2009 Show	Brake	<a href="#">View</a>
SI B04 27 09	10/1/2009	Brake Rotor Puller	Brake	<a href="#">View</a>
SI B34 04 09	10/1/2009	Repair Procedures - Brake Disc/Rotor Removal	Brake	<a href="#">View</a>
SI B34 03 09	9/1/2009	Brake Squeal from Pad Wear Sensor	Brake	<a href="#">View</a>

## COOLING (28 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
-------	------------	-----------------	------	------



SI B06 04 17	4/1/2017	Service Roundtable: April Show	Cooling	<a href="#">View</a>
SI B06 04 17	4/1/2017	Service Roundtable: April Show	Cooling	<a href="#">View</a>
SI B06 03 17	2/1/2017	Service Roundtable: February Show	Cooling	<a href="#">View</a>
SI B06 02 17	1/1/2017	Service Roundtable: January Show	Cooling	<a href="#">View</a>
SI B06 01 17	1/1/2017	Service Roundtable: 2016 Topics	Cooling	<a href="#">View</a>
SI B17 02 16	9/1/2016	Cooling System Contaminated with Oil	Cooling	<a href="#">View</a>
SI B01 09 15	7/1/2015	BMW Engine Oil: New Repair Order Invoicing Procedure	Cooling	<a href="#">View</a>
SI B06 02 14	2/1/2014	Service Roundtable: February 2014 Show	Cooling	<a href="#">View</a>
SI B06 09 13	9/1/2013	Service Roundtable: September 2013 Show	Cooling	<a href="#">View</a>
SI B06 04 13	4/1/2013	Service Roundtable: April 2013 Show	Cooling	<a href="#">View</a>
SI B06 03 13	3/1/2013	Service Roundtable: March 2013 Show	Cooling	<a href="#">View</a>
SI B06 02 13	2/1/2013	Service Roundtable: February 2013 Show	Cooling	<a href="#">View</a>
SI B06 12 12	12/1/2012	Service Roundtable: December 2012 Show	Cooling	<a href="#">View</a>
SI B06 11 12	11/1/2012	Service Roundtable: November 2012 Show	Cooling	<a href="#">View</a>
SI B06 10 12	10/1/2012	Service Roundtable: October 2012 Show	Cooling	<a href="#">View</a>
SI B06 03 12	3/1/2012	Service Roundtable: March 2012 Show	Cooling	<a href="#">View</a>
SI B06 02 12	2/1/2012	Service Roundtable: February 2012 Show	Cooling	<a href="#">View</a>
SI B06 12 11	12/1/2011	Service Roundtable: December 2011 Show	Cooling	<a href="#">View</a>

SI B06 11 11	11/1/2011	Service Roundtable: November 2011 Show	Cooling	<a href="#">View</a>
SI B06 08 11	8/1/2011	Service Roundtable: August 2011 Show	Cooling	<a href="#">View</a>
SI B06 12 10	12/1/2010	Service Roundtable: December 2010 Show	Cooling	<a href="#">View</a>
SI B06 10 10	10/1/2010	Service Roundtable: October 2010 Show	Cooling	<a href="#">View</a>
SI B09 06 10	9/1/2010	Service Roundtable: September 2010 Show	Cooling	<a href="#">View</a>
SI B06 09 10	9/1/2010	Service Roundtable - September 2010	Cooling	<a href="#">View</a>
SI B06 05 10	5/1/2010	Service Roundtable: May 2010 Show	Cooling	<a href="#">View</a>
SI B17 01 10	3/1/2010	Proper Evacuation and/or Filling of Cooling System after Repairs	Cooling	<a href="#">View</a>
SI B06 12 09	12/1/2009	Service Roundtable: December 2009 Show	Cooling	<a href="#">View</a>
SI B06 11 09	11/1/2009	Service Roundtable: November 2009 Show	Cooling	<a href="#">View</a>

## ELECTRICAL (153 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
SI B00 09 19	6/1/2019	CBS DISPLAYS AN IMPLAUSIBLE AVERAGE MILEAGE PER WEEK VALUE OF 1,584 IN ISPA NEX	Electrical	<a href="#">View</a>
SI B04 02 19	2/1/2019	RELEASE TOOL FOR HEAD AIR BAG RETAINING CLIP	Electrical	<a href="#">View</a>
SI B12 31 18	12/1/2018	ACTRON ACCUMULATED MISFIRE COUNTER	Electrical	<a href="#">View</a>
SI B04 15 18	12/1/2018	ACTRON ACCUMULATED MISFIRE COUNTER	Electrical	<a href="#">View</a>
SI B08 04 18	11/1/2018	TAKATA AIR BAG RECALL ? TOWING OF CUSTOMER VEHICLES	Electrical	<a href="#">View</a>
SI B61 14 18	10/1/2018	DELIVERY STOP: NEGATIVE BATTERY CABLE	Electrical	<a href="#">View</a>

SI B61 16 18	10/1/2018	DELIVERY STOP & RECALL 18V-732: REPLACE BDC MODULE	Electrical	<a href="#">View</a>
SI B12 22 18	7/1/2018	DELIVERY STOP/RECALL 18V-465: B570 DIESEL ENGINE - REPLACE THE CRANKSHAFT SENSORS	Electrical	<a href="#">View</a>
SI B09 01 18	5/1/2018	IRAP CONTROL UNIT RECOVERY	Electrical	<a href="#">View</a>
SI B01 01 18	5/1/2018	FRONT PASSENGER SEAT OCCUPANCY (OC3) MAT FOR SRS: LIMITED WARRANTY EXTENSION TO	Electrical	<a href="#">View</a>
SI B06 04 17	4/1/2017	Service Roundtable: April Show	Electrical	<a href="#">View</a>
SI B06 04 17	4/1/2017	Service Roundtable: April Show	Electrical	<a href="#">View</a>
SI B08 02 17	3/1/2017	TAKATA PARTS ALLOCATION PLAN GUIDE TO ALLOCATION AND CUSTOMER COMMUNICATION	Electrical	<a href="#">View</a>
SI B06 03 17	2/1/2017	Service Roundtable: February Show	Electrical	<a href="#">View</a>
SI B06 02 17	1/1/2017	Service Roundtable: January Show	Electrical	<a href="#">View</a>
SI B06 01 17	1/1/2017	Service Roundtable: 2016 Topics	Electrical	<a href="#">View</a>
SI B08 01 17	1/1/2017	TAKATA STATUS VIDEO SERIES	Electrical	<a href="#">View</a>
SI B12 15 16	8/1/2016	VOLUNTARY EMISSIONS RECALL CAMPAIGN 16E-A04: DME - OBD	Electrical	<a href="#">View</a>
SI B13 02 16	8/1/2016	DDE FAULT CODE 290900 AFTER PROGRAMMING	Electrical	<a href="#">View</a>
SI B12 17 16	8/1/2016	M2 - DRIVETRAIN MALFUNCTION CCM IS DISPLAYED	Electrical	<a href="#">View</a>
SI B61 15 16	7/1/2016	CCM "CHARGING NO LONGER POSSIBLE" DURING OR AFTER TRANSPORT MODE	Electrical	<a href="#">View</a>
SI B66 14 16	7/1/2016	"Parking Assistant" Operation is Jerky	Electrical	<a href="#">View</a>
SI B01 21 16	7/1/2016	REMOTE KEY READ AND SERVICE CONSULTATION	Electrical	<a href="#">View</a>
SI B04 15 16	6/1/2016	132 PIN BREAK OUT BOX - REPAIR KIT	Electrical	<a href="#">View</a>

SI B07 01 16	5/1/2016	Integrated Measurement Interface Box - IMIB R2 V6	Electrical	<a href="#">View</a>
SI B65 09 16	3/1/2016	Radio / Navigation / Head Unit Identification	Electrical	<a href="#">View</a>
SI B65 02 16	2/1/2016	Audio System Speaker Testing	Electrical	<a href="#">View</a>
SI B06 09 15	9/1/2015	Service Roundtable: September 2015 Show	Electrical	<a href="#">View</a>
SI B00 06 15	9/1/2015	SMS/Text Messaging for PuMA/ TeileClearing Cases	Electrical	<a href="#">View</a>
SI B06 08 15	8/1/2015	Service Roundtable: August 2015 Show	Electrical	<a href="#">View</a>
SI B06 07 15	7/1/2015	Service Roundtable: July 2015 Show	Electrical	<a href="#">View</a>
SI B01 16 15	7/1/2015	An "Add Engine Oil" Check Control Message Display	Electrical	<a href="#">View</a>
SI B09 02 15	7/1/2015	"The Headunit has an Invalid IP address" Message Appears at Start of ISTA/P	Electrical	<a href="#">View</a>
SI B07 02 15	7/1/2015	ISTA 3.50 Information	Electrical	<a href="#">View</a>
SI B00 05 15	6/1/2015	BMW Group Technical Support and "New" PuMA Hotline	Electrical	<a href="#">View</a>
SI B06 06 15	6/1/2015	Service Roundtable: June 2015 Show	Electrical	<a href="#">View</a>
SI B06 05 15	5/1/2015	Service Roundtable: May 2015 Show	Electrical	<a href="#">View</a>
SI B51 01 15	3/1/2015	Harman Kardon Surround Sound System Noise	Electrical	<a href="#">View</a>
SI B07 03 14	2/1/2015	Diagnosing Stored Fault Codes to Help Avoid Repeat Repair Visits	Electrical	<a href="#">View</a>
SI B12 08 15	1/1/2015	N62TU: ISTA Service Function for DME "RAM Backup"	Electrical	<a href="#">View</a>
SI B04 20 14	10/1/2014	Deutronic Battery Charger Check	Electrical	<a href="#">View</a>
SI B12 18 14	9/1/2014	Engine Misfire Due to Failed Ignition Coil	Electrical	<a href="#">View</a>

SI B65 08 14	9/1/2014	Recall Campaign 13V-564: Replace Front Passenger Air Bag Seat Occupancy Sensor	Electrical	<a href="#">View</a>
SI B61 17 14	9/1/2014	Intelligent Battery Sensor Diagnosis Hints	Electrical	<a href="#">View</a>
SI B84 02 14	7/1/2014	ConnectedDrive/BMW Assist System Diagnosis Information	Electrical	<a href="#">View</a>
SI B06 05 14	5/1/2014	Service Roundtable: May 2014 Show	Electrical	<a href="#">View</a>
SI B61 03 14	4/1/2014	Check Control Messages Related to Battery Charge During Cold Ambient Temperature	Electrical	<a href="#">View</a>
SI B06 04 14	4/1/2014	Service Roundtable: April 2014 Show	Electrical	<a href="#">View</a>
SI B65 05 14	4/1/2014	Traffic Information Is Inoperative	Electrical	<a href="#">View</a>
SI B34 01 14	4/1/2014	Vibration When Braking: Diagnosing and Repairing	Electrical	<a href="#">View</a>
SI B61 05 14	3/1/2014	Battery State of Charge Reference Chart	Electrical	<a href="#">View</a>
SI B06 03 14	3/1/2014	Service Roundtable: March 2014 Show	Electrical	<a href="#">View</a>
SI B06 02 14	2/1/2014	Service Roundtable: February 2014 Show	Electrical	<a href="#">View</a>
SI B65 25 13	1/1/2014	ConnectedDrive/BMW ASSIST Features Are Inoperative	Electrical	<a href="#">View</a>
SI B63 04 14	1/1/2014	Delay in Automatic Driving Light Switching On/Off	Electrical	<a href="#">View</a>
SI B01 08 13	12/1/2013	Exide Replacement Batteries	Electrical	<a href="#">View</a>
SI B01 03 13	9/1/2013	Vehicle Software Programming: Technician Time Control for Claim Submissions	Electrical	<a href="#">View</a>
SI B06 09 13	9/1/2013	Service Roundtable: September 2013 Show	Electrical	<a href="#">View</a>
SI B06 05 13	5/1/2013	Service Roundtable: May 2013 Show	Electrical	<a href="#">View</a>
SI B11 03 13	5/1/2013	Engine Oil Consumption	Electrical	<a href="#">View</a>

SI B61 09 13	5/1/2013	Battery Replacements	Electrical	<a href="#">View</a>
SI B06 04 13	4/1/2013	Service Roundtable: April 2013 Show	Electrical	<a href="#">View</a>
SI B06 03 13	3/1/2013	Service Roundtable: March 2013 Show	Electrical	<a href="#">View</a>
SI B06 02 13	2/1/2013	Service Roundtable: February 2013 Show	Electrical	<a href="#">View</a>
SI B06 01 13	1/1/2013	Service Roundtable: January 2013 Show	Electrical	<a href="#">View</a>
SI B06 12 12	12/1/2012	Service Roundtable: December 2012 Show	Electrical	<a href="#">View</a>
SI B09 02 12	12/1/2012	Part Swapping for Diagnostic or Programming Purposes Only (E Series Vehicles)	Electrical	<a href="#">View</a>
SI B06 11 12	11/1/2012	Service Roundtable: November 2012 Show	Electrical	<a href="#">View</a>
SI B12 17 12	11/1/2012	N52T/N55 with 8HP45: Delay in Engine Response	Electrical	<a href="#">View</a>
SI B06 10 12	10/1/2012	Service Roundtable: October 2012 Show	Electrical	<a href="#">View</a>
SI B06 09 12	9/1/2012	Service Roundtable: September 2012 Show	Electrical	<a href="#">View</a>
SI B06 08 12	8/1/2012	Service Roundtable: August 2012 Show	Electrical	<a href="#">View</a>
SI B06 07 12	7/1/2012	Service Roundtable: July 2012 Show	Electrical	<a href="#">View</a>
SI B65 09 12	7/1/2012	CIC: Replacement Part Has a Permanent Fault Code Stored in SDARS	Electrical	<a href="#">View</a>
SI B61 22 12	7/1/2012	Replacement Procedure for 90AH Absorbed Glass Matt Battery	Electrical	<a href="#">View</a>
SI B04 08 12	6/1/2012	DSC Connector Release Tool	Electrical	<a href="#">View</a>
SI B06 06 12	6/1/2012	Service Roundtable: June 2012 Show	Electrical	<a href="#">View</a>
SI B06 05 12	5/1/2012	Service Roundtable: May 2012 Show	Electrical	<a href="#">View</a>

SI B65 06 12	5/1/2012	Audio and Battery Failures Caused by Aftermarket USB Adapter Cables	Electrical	<a href="#">View</a>
SI B84 02 12	5/1/2012	CDMA Telematics Control Unit (TCU) Replacement Procedure	Electrical	<a href="#">View</a>
SI B61 15 12	4/1/2012	Updated Battery Registration Procedure	Electrical	<a href="#">View</a>
SI B61 14 12	4/1/2012	Recall Campaign 12V-126: Check the Battery Cable Connection	Electrical	<a href="#">View</a>
SI B62 06 12	4/1/2012	Maximum Permissible Speedometer Deviations	Electrical	<a href="#">View</a>
SI B06 04 12	4/1/2012	Service Roundtable: April 2012 Show	Electrical	<a href="#">View</a>
SI B06 03 12	3/1/2012	Service Roundtable: March 2012 Show	Electrical	<a href="#">View</a>
SI B06 02 12	2/1/2012	Service Roundtable: February 2012 Show	Electrical	<a href="#">View</a>
SI B61 06 12	2/1/2012	The Airbag Warning Lamp Is Illuminated and SZL Fault Codes Are Stored	Electrical	<a href="#">View</a>
SI B12 02 12	2/1/2012	N54, N73: Various Drivability Complaints & Service Engine Soon Lamp Illuminated	Electrical	<a href="#">View</a>
SI B06 01 12	1/1/2012	Service Roundtable: January 2012 Show	Electrical	<a href="#">View</a>
SI B06 12 11	12/1/2011	Service Roundtable: December 2011 Show	Electrical	<a href="#">View</a>
SI B06 11 11	11/1/2011	Service Roundtable: November 2011 Show	Electrical	<a href="#">View</a>
SI B06 10 11	10/1/2011	Service Roundtable: October 2011 Show	Electrical	<a href="#">View</a>
SI B06 09 11	9/1/2011	Service Roundtable: September 2011 Show	Electrical	<a href="#">View</a>
SI B06 08 11	8/1/2011	Service Roundtable: August 2011 Show	Electrical	<a href="#">View</a>
SI B01 06 11	8/1/2011	New BMW Vehicles - Environmental Paint Finish Damage	Electrical	<a href="#">View</a>
SI B66 02 11	8/1/2011	Remote Control and Comfort Access Is Inoperative	Electrical	<a href="#">View</a>

SI B11 07 11	7/1/2011	Turbocharger Failure: Oil Supply Line Blockage	Electrical	<a href="#">View</a>
SI B06 07 11	7/1/2011	Service Roundtable: July 2011 Show	Electrical	<a href="#">View</a>
SI B12 15 11	7/1/2011	NG6 Engine: DME FC29DA Crankshaft Sensor, Segment Adaptation	Electrical	<a href="#">View</a>
SI B03 01 11	6/1/2011	Technician Recruitment and Training	Electrical	<a href="#">View</a>
SI B06 06 11	6/1/2011	Service Roundtable: June 2011 Show	Electrical	<a href="#">View</a>
SI B12 13 11	6/1/2011	DME Fault Entry: Ambient Temperature Sensor, Plausibility	Electrical	<a href="#">View</a>
SI B06 05 11	5/1/2011	Service Roundtable: May 2011 Show	Electrical	<a href="#">View</a>
SI B12 20 10	5/1/2011	Svc Eng Soon Lamp or Check Gas Cap Is Illuminated: FC 2A15 or 2A16 DMTL Leakage	Electrical	<a href="#">View</a>
SI B84 02 11	5/1/2011	Diagnosis of Communication Systems	Electrical	<a href="#">View</a>
SI B06 04 11	4/1/2011	Service Roundtable: April 2011 Show	Electrical	<a href="#">View</a>
SI B63 03 11	4/1/2011	Headlight Wiring Deteriorated	Electrical	<a href="#">View</a>
SI B06 03 11	3/1/2011	Service Roundtable: March 2011 Show	Electrical	<a href="#">View</a>
SI B06 02 11	2/1/2011	Service Roundtable: February 2011 Show	Electrical	<a href="#">View</a>
SI B06 01 11	1/1/2011	Service Roundtable: January 2011 Show	Electrical	<a href="#">View</a>
SI B06 12 10	12/1/2010	Service Roundtable: December 2010 Show	Electrical	<a href="#">View</a>
SI B06 11 10	11/1/2010	Service Roundtable: November 2010 Show	Electrical	<a href="#">View</a>
SI B06 10 10	10/1/2010	Service Roundtable: October 2010 Show	Electrical	<a href="#">View</a>
SI B09 06 10	9/1/2010	Service Roundtable: September 2010 Show	Electrical	<a href="#">View</a>



SI B06 09 10	9/1/2010	Service Roundtable - September 2010	Electrical	<a href="#">View</a>
SI B06 08 10	8/1/2010	Service Roundtable: August 2010 Show	Electrical	<a href="#">View</a>
SI B06 07 10	7/1/2010	Service Roundtable: July 2010 Show	Electrical	<a href="#">View</a>
SI B12 09 10	5/1/2010	E72 Hybrid CAN Errors	Electrical	<a href="#">View</a>
SI B06 05 10	5/1/2010	Service Roundtable: May 2010 Show	Electrical	<a href="#">View</a>
SI B06 04 10	4/1/2010	Service Roundtable: April 2010 Show	Electrical	<a href="#">View</a>
SI B63 04 10	4/1/2010	Daytime Running Lamp Bulb Failure	Electrical	<a href="#">View</a>
SI B06 03 10	3/1/2010	Service Roundtable - March 2010	Electrical	<a href="#">View</a>
SI B00 13 09	2/1/2010	BMW Product Content Changes	Electrical	<a href="#">View</a>
SI B06 02 10	2/1/2010	Service Roundtable: February 2010 Show	Electrical	<a href="#">View</a>
SI B07 06 09	2/1/2010	Integrated Measurement Interface Box - IMIB	Electrical	<a href="#">View</a>
SI B65 40 09	2/1/2010	CIC Navigation: European Road Map Is Displayed	Electrical	<a href="#">View</a>
SI B65 01 10	2/1/2010	CCC - "Please Insert Navigation DVD" Appears on CD	Electrical	<a href="#">View</a>
SI B62 02 10	2/1/2010	Time and Date Lost When Vehicle Sleeps	Electrical	<a href="#">View</a>
SI B06 01 10	1/1/2010	Service Roundtable: January 2010 Show	Electrical	<a href="#">View</a>
SI B66 10 09	1/1/2010	Radio Remote Control Is Inoperative	Electrical	<a href="#">View</a>
SI B09 05 09	1/1/2010	Enabling Code Information	Electrical	<a href="#">View</a>
SI B09 04 09	1/1/2010	Loading/Activation of Enabling Codes with ISTA/P	Electrical	<a href="#">View</a>

SI B65 38 09	1/1/2010	CIC Navigation Road Map Update	Electrical	<a href="#">View</a>
SI B06 12 09	12/1/2009	Service Roundtable: December 2009 Show	Electrical	<a href="#">View</a>
SI B06 11 09	11/1/2009	Service Roundtable: November 2009 Show	Electrical	<a href="#">View</a>
SI B12 26 09	10/1/2009	N62TU: EDK Throttle Potentiometer Faults - Diagnosis	Electrical	<a href="#">View</a>
SI B12 25 09	10/1/2009	TeileClearing for N54 Engine Drivability Concerns	Electrical	<a href="#">View</a>
SI B06 10 09	10/1/2009	Service Roundtable: October 2009 Show	Electrical	<a href="#">View</a>
SI B65 30 09	10/1/2009	Navigation System Is Inoperative	Electrical	<a href="#">View</a>
SI B06 09 09	9/1/2009	Service Roundtable: September 2009 Show	Electrical	<a href="#">View</a>
SI B04 30 09	9/1/2009	ICOM Extension Cable	Electrical	<a href="#">View</a>
SI B63 08 09	9/1/2009	Replace Both Halogen Low-beam Headlamp Bulbs	Electrical	<a href="#">View</a>
SI B63 07 09	7/1/2009	Lights Do Not Switch Off Automatically	Electrical	<a href="#">View</a>
SI B62 03 09	7/1/2009	Outside Temperature Display Is Incorrect	Electrical	<a href="#">View</a>
SI B65 09 09	7/1/2009	The CIC Has Various Malfunctions After a Repair	Electrical	<a href="#">View</a>
SI B61 11 09	6/1/2009	Battery Charging and Testing Procedure	Electrical	<a href="#">View</a>
SI B65 21 09	6/1/2009	Artist and Song Title are Not Displayed	Electrical	<a href="#">View</a>
SI B63 02 09	5/1/2009	Interior Lights Inoperative, FC A411	Electrical	<a href="#">View</a>
SI B65 04 09	5/1/2009	Shopping Cart Icons Displayed Permanently	Electrical	<a href="#">View</a>
SI B65 10 09	5/1/2009	Vehicle Position Is Missing or Incorrect On the Navigation Map	Electrical	<a href="#">View</a>

SI B65 11 09	5/1/2009	Satellite Radio: Channel List may Be Empty or Channels Are Missing	Electrical	<a href="#">View</a>
SI B61 07 09	5/1/2009	One-Touch Windows Inoperative After General Module Replacement	Electrical	<a href="#">View</a>
SI B65 15 09	5/1/2009	DWA Siren Too Quiet When Locking and Unlocking	Electrical	<a href="#">View</a>

## EMISSION CONTROL (55 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
SI B12 31 18	12/1/2018	ACTRON ACCUMULATED MISFIRE COUNTER	Emission Control	<a href="#">View</a>
SI B06 04 17	4/1/2017	Service Roundtable: April Show	Emission Control	<a href="#">View</a>
SI B06 03 17	2/1/2017	Service Roundtable: February Show	Emission Control	<a href="#">View</a>
SI B06 01 17	1/1/2017	Service Roundtable: 2016 Topics	Emission Control	<a href="#">View</a>
SI B12 15 16	8/1/2016	VOLUNTARY EMISSIONS RECALL CAMPAIGN 16E-A04: DME - OBD	Emission Control	<a href="#">View</a>
SI B07 01 16	5/1/2016	Integrated Measurement Interface Box - IMIB R2 V6	Emission Control	<a href="#">View</a>
SI B07 01 14	5/1/2014	ISTA Expert Mode Diagnosis Enhanced for DME/DDE	Emission Control	<a href="#">View</a>
SI B01 03 13	9/1/2013	Vehicle Software Programming: Technician Time Control for Claim Submissions	Emission Control	<a href="#">View</a>
SI B06 09 13	9/1/2013	Service Roundtable: September 2013 Show	Emission Control	<a href="#">View</a>
SI B06 05 13	5/1/2013	Service Roundtable: May 2013 Show	Emission Control	<a href="#">View</a>
SI B04 06 13	5/1/2013	Spare Parts Ordering: DEF Extraction/Fill Unit & Eng Coolant Vacuum Charger Sys	Emission Control	<a href="#">View</a>
SI B06 04 13	4/1/2013	Service Roundtable: April 2013 Show	Emission Control	<a href="#">View</a>
SI B06 12 12	12/1/2012	Service Roundtable: December 2012 Show	Emission Control	<a href="#">View</a>

SI B12 17 12	11/1/2012	N52T/N55 with 8HP45: Delay in Engine Response	Emission Control	<a href="#">View</a>
SI B06 08 12	8/1/2012	Service Roundtable: August 2012 Show	Emission Control	<a href="#">View</a>
SI B06 07 12	7/1/2012	Service Roundtable: July 2012 Show	Emission Control	<a href="#">View</a>
SI B06 04 12	4/1/2012	Service Roundtable: April 2012 Show	Emission Control	<a href="#">View</a>
SI B06 01 12	1/1/2012	Service Roundtable: January 2012 Show	Emission Control	<a href="#">View</a>
SI B06 12 11	12/1/2011	Service Roundtable: December 2011 Show	Emission Control	<a href="#">View</a>
SI B06 11 11	11/1/2011	Service Roundtable: November 2011 Show	Emission Control	<a href="#">View</a>
SI B12 23 11	10/1/2011	N54, N54T - Pre-Catalyst Oxygen Sensor Dynamic Faults Stored	Emission Control	<a href="#">View</a>
SI B06 10 11	10/1/2011	Service Roundtable: October 2011 Show	Emission Control	<a href="#">View</a>
SI B06 09 11	9/1/2011	Service Roundtable: September 2011 Show	Emission Control	<a href="#">View</a>
SI B06 08 11	8/1/2011	Service Roundtable: August 2011 Show	Emission Control	<a href="#">View</a>
SI B06 07 11	7/1/2011	Service Roundtable: July 2011 Show	Emission Control	<a href="#">View</a>
SI B12 15 11	7/1/2011	NG6 Engine: DME FC29DA Crankshaft Sensor, Segment Adaptation	Emission Control	<a href="#">View</a>
SI B06 06 11	6/1/2011	Service Roundtable: June 2011 Show	Emission Control	<a href="#">View</a>
SI B12 13 11	6/1/2011	DME Fault Entry: Ambient Temperature Sensor, Plausibility	Emission Control	<a href="#">View</a>
SI B12 10 11	5/1/2011	N54/N54T - DME Knock Sensor Signal Faults Are Stored	Emission Control	<a href="#">View</a>
SI B06 05 11	5/1/2011	Service Roundtable: May 2011 Show	Emission Control	<a href="#">View</a>
SI B12 20 10	5/1/2011	Svc Eng Soon Lamp or Check Gas Cap Is Illuminated: FC 2A15 or 2A16 DMTL Leakage	Emission Control	<a href="#">View</a>

SI B01 02 11	4/1/2011	Emissions Warranty Coverage	Emission Control	<a href="#">View</a>
SI B06 04 11	4/1/2011	Service Roundtable: April 2011 Show	Emission Control	<a href="#">View</a>
SI B13 14 10	4/1/2011	Emission Recall 10E-A02: N54 Inspection and Replacement of Injectors	Emission Control	<a href="#">View</a>
SI B06 03 11	3/1/2011	Service Roundtable: March 2011 Show	Emission Control	<a href="#">View</a>
SI B06 02 11	2/1/2011	Service Roundtable: February 2011 Show	Emission Control	<a href="#">View</a>
SI B84 01 11	2/1/2011	Service Action: BMW ASSIST Vehicles Are Not Correctly Provisioned	Emission Control	<a href="#">View</a>
SI B13 13 10	2/1/2011	Emissions Recall 10E-A02: N54 High-Pressure Fuel Pump (HDP)	Emission Control	<a href="#">View</a>
SI B06 01 11	1/1/2011	Service Roundtable: January 2011 Show	Emission Control	<a href="#">View</a>
SI B06 12 10	12/1/2010	Service Roundtable: December 2010 Show	Emission Control	<a href="#">View</a>
SI B06 11 10	11/1/2010	Service Roundtable: November 2010 Show	Emission Control	<a href="#">View</a>
SI B09 06 10	9/1/2010	Service Roundtable: September 2010 Show	Emission Control	<a href="#">View</a>
SI B13 09 10	8/1/2010	Service Action: N54 Program Control Units (DME for HDP)	Emission Control	<a href="#">View</a>
SI B12 11 10	6/1/2010	N54, N54T, N55 - Diagnosis for HDP High-pressure Faults	Emission Control	<a href="#">View</a>
SI B12 02 10	3/1/2010	N51 or N52K Important Information when Programming the DME	Emission Control	<a href="#">View</a>
SI B06 02 10	2/1/2010	Service Roundtable: February 2010 Show	Emission Control	<a href="#">View</a>
SI B06 12 09	12/1/2009	Service Roundtable: December 2009 Show	Emission Control	<a href="#">View</a>
SI B06 11 09	11/1/2009	Service Roundtable: November 2009 Show	Emission Control	<a href="#">View</a>
SI B07 05 09	11/1/2009	ISTA/D Fault Code "S0001" Entries Still Present After Quick Delete	Emission Control	<a href="#">View</a>

SI B07 04 09	11/1/2009	ISTA Test Plan Priority Error	Emission Control	<a href="#">View</a>
SI B12 25 09	10/1/2009	TeileClearing for N54 Engine Drivability Concerns	Emission Control	<a href="#">View</a>
SI B06 09 09	9/1/2009	Service Roundtable: September 2009 Show	Emission Control	<a href="#">View</a>
SI B12 23 09	9/1/2009	Service Action: Program Control Units - DME (OBD)	Emission Control	<a href="#">View</a>
SI B04 15 09	5/1/2009	Test Cable Modification	Emission Control	<a href="#">View</a>
SI B24 03 09	4/1/2009	550i and 650i with N62TU and 6HP26-Various Drivability Complaints	Emission Control	<a href="#">View</a>

## EXHAUST (14 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
SI B18 01 16	2/1/2016	Correct Installation of W20 Catalytic Converter	Exhaust	<a href="#">View</a>
SI B07 01 14	5/1/2014	ISTA Expert Mode Diagnosis Enhanced for DME/DDE	Exhaust	<a href="#">View</a>
SI B06 05 14	5/1/2014	Service Roundtable: May 2014 Show	Exhaust	<a href="#">View</a>
SI B06 12 12	12/1/2012	Service Roundtable: December 2012 Show	Exhaust	<a href="#">View</a>
SI B06 11 12	11/1/2012	Service Roundtable: November 2012 Show	Exhaust	<a href="#">View</a>
SI B06 10 12	10/1/2012	Service Roundtable: October 2012 Show	Exhaust	<a href="#">View</a>
SI B06 09 12	9/1/2012	Service Roundtable: September 2012 Show	Exhaust	<a href="#">View</a>
SI B18 01 12	9/1/2012	Rear Muffler Exhaust Flap Diagnosis	Exhaust	<a href="#">View</a>
SI B06 08 12	8/1/2012	Service Roundtable: August 2012 Show	Exhaust	<a href="#">View</a>
SI B06 12 11	12/1/2011	Service Roundtable: December 2011 Show	Exhaust	<a href="#">View</a>

SI B06 08 11	8/1/2011	Service Roundtable: August 2011 Show	Exhaust	<a href="#">View</a>
SI B06 07 11	7/1/2011	Service Roundtable: July 2011 Show	Exhaust	<a href="#">View</a>
SI B06 03 10	3/1/2010	Service Roundtable - March 2010	Exhaust	<a href="#">View</a>
SI B06 12 09	12/1/2009	Service Roundtable: December 2009 Show	Exhaust	<a href="#">View</a>

## FUEL & SPARK (71 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
SI B06 04 17	4/1/2017	Service Roundtable: April Show	Fuel & Spark	<a href="#">View</a>
SI B13 02 16	8/1/2016	DDE FAULT CODE 290900 AFTER PROGRAMMING	Fuel & Spark	<a href="#">View</a>
SI B13 08 14	10/1/2014	Fuel System Failures	Fuel & Spark	<a href="#">View</a>
SI B07 01 14	5/1/2014	ISTA Expert Mode Diagnosis Enhanced for DME/DDE	Fuel & Spark	<a href="#">View</a>
SI B06 04 14	4/1/2014	Service Roundtable: April 2014 Show	Fuel & Spark	<a href="#">View</a>
SI B06 03 14	3/1/2014	Service Roundtable: March 2014 Show	Fuel & Spark	<a href="#">View</a>
SI B01 02 13	9/1/2013	BMW NA Replacement Parts on Backorder, Caused by New ATLAS Release	Fuel & Spark	<a href="#">View</a>
SI B06 09 13	9/1/2013	Service Roundtable: September 2013 Show	Fuel & Spark	<a href="#">View</a>
SI B06 05 13	5/1/2013	Service Roundtable: May 2013 Show	Fuel & Spark	<a href="#">View</a>
SI B06 04 13	4/1/2013	Service Roundtable: April 2013 Show	Fuel & Spark	<a href="#">View</a>
SI B13 02 13	3/1/2013	N54 Engine: Fuel Pressure Control Test Plan Error	Fuel & Spark	<a href="#">View</a>
SI B06 03 13	3/1/2013	Service Roundtable: March 2013 Show	Fuel & Spark	<a href="#">View</a>

SI B06 02 13	2/1/2013	Service Roundtable: February 2013 Show	Fuel & Spark	<a href="#">View</a>
SI B06 01 13	1/1/2013	Service Roundtable: January 2013 Show	Fuel & Spark	<a href="#">View</a>
SI B06 12 12	12/1/2012	Service Roundtable: December 2012 Show	Fuel & Spark	<a href="#">View</a>
SI B06 11 12	11/1/2012	Service Roundtable: November 2012 Show	Fuel & Spark	<a href="#">View</a>
SI B06 10 12	10/1/2012	Service Roundtable: October 2012 Show	Fuel & Spark	<a href="#">View</a>
SI B06 09 12	9/1/2012	Service Roundtable: September 2012 Show	Fuel & Spark	<a href="#">View</a>
SI B06 08 12	8/1/2012	Service Roundtable: August 2012 Show	Fuel & Spark	<a href="#">View</a>
SI B06 07 12	7/1/2012	Service Roundtable: July 2012 Show	Fuel & Spark	<a href="#">View</a>
SI B01 02 12	7/1/2012	N54 Engine Turbo Charger (Wastegates Only)- Proposed Warranty Ext. Settlement	Fuel & Spark	<a href="#">View</a>
SI B06 06 12	6/1/2012	Service Roundtable: June 2012 Show	Fuel & Spark	<a href="#">View</a>
SI B06 04 12	4/1/2012	Service Roundtable: April 2012 Show	Fuel & Spark	<a href="#">View</a>
SI B06 03 12	3/1/2012	Service Roundtable: March 2012 Show	Fuel & Spark	<a href="#">View</a>
SI B06 02 12	2/1/2012	Service Roundtable: February 2012 Show	Fuel & Spark	<a href="#">View</a>
SI B16 04 12	2/1/2012	Fuel Tank Access Cover Locking Ring Torque Specification Missing from ISTA/D	Fuel & Spark	<a href="#">View</a>
SI B06 12 11	12/1/2011	Service Roundtable: December 2011 Show	Fuel & Spark	<a href="#">View</a>
SI B06 11 11	11/1/2011	Service Roundtable: November 2011 Show	Fuel & Spark	<a href="#">View</a>
SI B06 10 11	10/1/2011	Service Roundtable: October 2011 Show	Fuel & Spark	<a href="#">View</a>
SI B06 08 11	8/1/2011	Service Roundtable: August 2011 Show	Fuel & Spark	<a href="#">View</a>



SI B11 07 11	7/1/2011	Turbocharger Failure: Oil Supply Line Blockage	Fuel & Spark	<a href="#">View</a>
SI B06 07 11	7/1/2011	Service Roundtable: July 2011 Show	Fuel & Spark	<a href="#">View</a>
SI B06 06 11	6/1/2011	Service Roundtable: June 2011 Show	Fuel & Spark	<a href="#">View</a>
SI B13 01 11	6/1/2011	TeileClearing for the Tank Ventilation Valve (Purge Valve)	Fuel & Spark	<a href="#">View</a>
SI B13 02 11	6/1/2011	High-pressure Direct Injection Fuel System Repairs	Fuel & Spark	<a href="#">View</a>
SI B06 05 11	5/1/2011	Service Roundtable: May 2011 Show	Fuel & Spark	<a href="#">View</a>
SI B13 05 10	4/1/2011	Testing Fuel Composition	Fuel & Spark	<a href="#">View</a>
SI B06 04 11	4/1/2011	Service Roundtable: April 2011 Show	Fuel & Spark	<a href="#">View</a>
SI B16 11 10	4/1/2011	Fuel Cap Tether Broken or Lost	Fuel & Spark	<a href="#">View</a>
SI B13 14 10	4/1/2011	Emission Recall 10E-A02: N54 Inspection and Replacement of Injectors	Fuel & Spark	<a href="#">View</a>
SI B06 03 11	3/1/2011	Service Roundtable: March 2011 Show	Fuel & Spark	<a href="#">View</a>
SI B13 13 10	2/1/2011	Emissions Recall 10E-A02: N54 High-Pressure Fuel Pump (HDP)	Fuel & Spark	<a href="#">View</a>
SI B06 12 10	12/1/2010	Service Roundtable: December 2010 Show	Fuel & Spark	<a href="#">View</a>
SI B06 11 10	11/1/2010	Service Roundtable: November 2010 Show	Fuel & Spark	<a href="#">View</a>
SI B06 10 10	10/1/2010	Service Roundtable: October 2010 Show	Fuel & Spark	<a href="#">View</a>
SI B09 06 10	9/1/2010	Service Roundtable: September 2010 Show	Fuel & Spark	<a href="#">View</a>
SI B04 15 10	9/1/2010	Turbocharger Diagnostic Tool Adapter	Fuel & Spark	<a href="#">View</a>
SI B06 09 10	9/1/2010	Service Roundtable - September 2010	Fuel & Spark	<a href="#">View</a>

SI B11 04 10	9/1/2010	Measuring and Adjusting Turbocharger Wastegate Using IMIB	Fuel & Spark	<a href="#">View</a>
SI B12 19 10	8/1/2010	Service Engine Soon Lamp Illuminated: FC 2A17 DMTL System Error	Fuel & Spark	<a href="#">View</a>
SI B12 11 10	6/1/2010	N54, N54T, N55 - Diagnosis for HDP High-pressure Faults	Fuel & Spark	<a href="#">View</a>
SI B06 05 10	5/1/2010	Service Roundtable: May 2010 Show	Fuel & Spark	<a href="#">View</a>
SI B13 02 10	4/1/2010	Gasoline and Diesel Fuel Quality Detection with ISTA D	Fuel & Spark	<a href="#">View</a>
SI B06 04 10	4/1/2010	Service Roundtable: April 2010 Show	Fuel & Spark	<a href="#">View</a>
SI B12 06 10	4/1/2010	N54 - Misfire Faults, Diagnosis with ISTA D	Fuel & Spark	<a href="#">View</a>
SI B06 03 10	3/1/2010	Service Roundtable - March 2010	Fuel & Spark	<a href="#">View</a>
SI B06 01 10	1/1/2010	Service Roundtable: January 2010 Show	Fuel & Spark	<a href="#">View</a>
SI B06 12 09	12/1/2009	Service Roundtable: December 2009 Show	Fuel & Spark	<a href="#">View</a>
SI B16 02 09	12/1/2009	Fuel Level Sensor Repairs	Fuel & Spark	<a href="#">View</a>
SI B06 11 09	11/1/2009	Service Roundtable: November 2009 Show	Fuel & Spark	<a href="#">View</a>
SI B12 26 09	10/1/2009	N62TU: EDK Throttle Potentiometer Faults - Diagnosis	Fuel & Spark	<a href="#">View</a>
SI B12 25 09	10/1/2009	TeileClearing for N54 Engine Drivability Concerns	Fuel & Spark	<a href="#">View</a>
SI B06 10 09	10/1/2009	Service Roundtable: October 2009 Show	Fuel & Spark	<a href="#">View</a>
SI B13 08 09	10/1/2009	TeileClearing for N54 Fuel System	Fuel & Spark	<a href="#">View</a>
SI B06 09 09	9/1/2009	Service Roundtable: September 2009 Show	Fuel & Spark	<a href="#">View</a>
SI B13 06 09	6/1/2009	Fuel Injection and Induction System Cleaning- Customer Information Brochure	Fuel & Spark	<a href="#">View</a>

SI B32 05 09	6/1/2009	Replacement of Electric Steering Lock (ELV)	Fuel & Spark	<a href="#">View</a>
SI B13 07 09	6/1/2009	N54 - Diagnosis for "Long Crank" Complaint	Fuel & Spark	<a href="#">View</a>
SI B04 16 09	5/1/2009	Fuel Line Plugs	Fuel & Spark	<a href="#">View</a>
SI B13 05 09	4/1/2009	N54-Diagnosis for FC 2AAF	Fuel & Spark	<a href="#">View</a>
SI B13 03 09	4/1/2009	N54-Special Ltd. High Pressure Pump Emissions Warranty of 10 Years/120,000 Miles	Fuel & Spark	<a href="#">View</a>

## HVAC (33 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
SI B06 01 17	1/1/2017	Service Roundtable: 2016 Topics	HVAC	<a href="#">View</a>
SI B06 05 14	5/1/2014	Service Roundtable: May 2014 Show	HVAC	<a href="#">View</a>
SI B06 02 14	2/1/2014	Service Roundtable: February 2014 Show	HVAC	<a href="#">View</a>
SI B06 09 13	9/1/2013	Service Roundtable: September 2013 Show	HVAC	<a href="#">View</a>
SI B06 12 12	12/1/2012	Service Roundtable: December 2012 Show	HVAC	<a href="#">View</a>
SI B06 11 12	11/1/2012	Service Roundtable: November 2012 Show	HVAC	<a href="#">View</a>
SI B06 09 12	9/1/2012	Service Roundtable: September 2012 Show	HVAC	<a href="#">View</a>
SI B06 08 12	8/1/2012	Service Roundtable: August 2012 Show	HVAC	<a href="#">View</a>
SI B06 06 12	6/1/2012	Service Roundtable: June 2012 Show	HVAC	<a href="#">View</a>
SI B06 05 12	5/1/2012	Service Roundtable: May 2012 Show	HVAC	<a href="#">View</a>
SI B06 04 12	4/1/2012	Service Roundtable: April 2012 Show	HVAC	<a href="#">View</a>

SI B06 11 11	11/1/2011	Service Roundtable: November 2011 Show	HVAC	<a href="#">View</a>
SI B06 10 11	10/1/2011	Service Roundtable: October 2011 Show	HVAC	<a href="#">View</a>
SI B06 08 11	8/1/2011	Service Roundtable: August 2011 Show	HVAC	<a href="#">View</a>
SI B06 06 11	6/1/2011	Service Roundtable: June 2011 Show	HVAC	<a href="#">View</a>
SI B06 05 11	5/1/2011	Service Roundtable: May 2011 Show	HVAC	<a href="#">View</a>
SI B06 04 11	4/1/2011	Service Roundtable: April 2011 Show	HVAC	<a href="#">View</a>
SI B64 04 11	3/1/2011	Air Intensity Fluctuates in IHKA Auto Mode Program	HVAC	<a href="#">View</a>
SI B64 14 10	1/1/2011	IHKA Control Panel Button Caps Are Broken	HVAC	<a href="#">View</a>
SI B06 12 10	12/1/2010	Service Roundtable: December 2010 Show	HVAC	<a href="#">View</a>
SI B06 10 10	10/1/2010	Service Roundtable: October 2010 Show	HVAC	<a href="#">View</a>
SI B64 09 10	9/1/2010	Refrigerant and Compressor Oil Reuse	HVAC	<a href="#">View</a>
SI B09 06 10	9/1/2010	Service Roundtable: September 2010 Show	HVAC	<a href="#">View</a>
SI B06 09 10	9/1/2010	Service Roundtable - September 2010	HVAC	<a href="#">View</a>
SI B06 05 10	5/1/2010	Service Roundtable: May 2010 Show	HVAC	<a href="#">View</a>
SI B06 04 10	4/1/2010	Service Roundtable: April 2010 Show	HVAC	<a href="#">View</a>
SI B64 01 10	3/1/2010	Service Action: Condensate Drain Hose Check	HVAC	<a href="#">View</a>
SI B06 03 10	3/1/2010	Service Roundtable - March 2010	HVAC	<a href="#">View</a>
SI B06 02 10	2/1/2010	Service Roundtable: February 2010 Show	HVAC	<a href="#">View</a>

SI B06 12 09	12/1/2009	Service Roundtable: December 2009 Show	HVAC	<a href="#">View</a>
SI B06 11 09	11/1/2009	Service Roundtable: November 2009 Show	HVAC	<a href="#">View</a>
SI B04 33 09	10/1/2009	O-ring Removal Tool	HVAC	<a href="#">View</a>
SI B62 03 09	7/1/2009	Outside Temperature Display Is Incorrect	HVAC	<a href="#">View</a>

## POWERTRAIN (94 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
SI B12 31 18	12/1/2018	ACTRON ACCUMULATED MISFIRE COUNTER	Powertrain	<a href="#">View</a>
SI B04 15 18	12/1/2018	ACTRON ACCUMULATED MISFIRE COUNTER	Powertrain	<a href="#">View</a>
SI B11 16 17	9/1/2018	RECALL 17V-683: POSITIVE CRANKCASE VENTILATION (PCV) VALVEHEATER	Powertrain	<a href="#">View</a>
SI B12 22 18	7/1/2018	DELIVERY STOP/RECALL 18V-465: B57O DIESEL ENGINE - REPLACE THECRANKSHAFT SENSO	Powertrain	<a href="#">View</a>
SI B04 06 18	6/1/2018	ENGINE OIL DRAIN PLUG THREAD REPAIR TOOL	Powertrain	<a href="#">View</a>
SI B11 07 18	6/1/2018	ENGINE OIL DRAIN PLUG THREAD REPAIR TOOL	Powertrain	<a href="#">View</a>
SI B04 02 18	2/1/2018	DRIVESHAFT CENTERING BUSHING TOOL	Powertrain	<a href="#">View</a>
SI B06 04 17	4/1/2017	Service Roundtable: April Show	Powertrain	<a href="#">View</a>
SI B06 03 17	2/1/2017	Service Roundtable: February Show	Powertrain	<a href="#">View</a>
SI B06 02 17	1/1/2017	Service Roundtable: January Show	Powertrain	<a href="#">View</a>
SI B06 01 17	1/1/2017	Service Roundtable: 2016 Topics	Powertrain	<a href="#">View</a>
SI B17 02 16	9/1/2016	Cooling System Contaminated with Oil	Powertrain	<a href="#">View</a>

SI B13 02 16	8/1/2016	DDE FAULT CODE 290900 AFTER PROGRAMMING	Powertrain	<a href="#">View</a>
SI B11 16 16	8/1/2016	CRANKSHAFT SEAL AND BED PLATE LIQUID SEALER	Powertrain	<a href="#">View</a>
SI B11 06 16	5/1/2016	N51,N52,N52KandN52T Engines:Various Eccentric Shaft Senosr Faults stored in DME	Powertrain	<a href="#">View</a>
SI B11 09 16	5/1/2016	N63, N63TU, S63 and S63TU Engines: Oil Leak from the Rear of the Engine and Tran	Powertrain	<a href="#">View</a>
SI B27 04 15	9/1/2015	Shudder from the Driveline on Vehicles with xDrive	Powertrain	<a href="#">View</a>
SI B11 12 15	8/1/2015	Repeat Repairs for Damaged Vacuum Hoses In Turbo Charged Vehicles	Powertrain	<a href="#">View</a>
SI B01 09 15	7/1/2015	BMW Engine Oil: New Repair Order Invoicing Procedure	Powertrain	<a href="#">View</a>
SI B11 09 15	5/1/2015	Engine Replacement: Filling Engine with Engine Oil Before First Start	Powertrain	<a href="#">View</a>
SI B01 11 15	4/1/2015	Engine Crankcase Oil Pans: Stripped or Crossed Threaded Drain Plugs	Powertrain	<a href="#">View</a>
SI B11 01 15	1/1/2015	BMW Engine Oil Part Number Transition	Powertrain	<a href="#">View</a>
SI B11 18 14	10/1/2014	Engine Oil Residue Found Near Oil Filler Cap	Powertrain	<a href="#">View</a>
SI B12 18 14	9/1/2014	Engine Misfire Due to Failed Ignition Coil	Powertrain	<a href="#">View</a>
SI B01 10 14	9/1/2014	Eng Camshaft Adjustment Units:Limited Warranty Ext to 10 Years No Mileage Limit	Powertrain	<a href="#">View</a>
SI B01 04 14	7/1/2014	External Engine Oil Leaks and Repairs	Powertrain	<a href="#">View</a>
SI B11 04 14	6/1/2014	Recall: Check VANOS Adjustment Unit	Powertrain	<a href="#">View</a>
SI B07 01 14	5/1/2014	ISTA Expert Mode Diagnosis Enhanced for DME/DDE	Powertrain	<a href="#">View</a>
SI B06 04 14	4/1/2014	Service Roundtable: April 2014 Show	Powertrain	<a href="#">View</a>
SI B31 02 14	4/1/2014	Front Differential Replacement Assemblies: Non- prefilled from Factory	Powertrain	<a href="#">View</a>

SI B06 02 14	2/1/2014	Service Roundtable: February 2014 Show	Powertrain	<a href="#">View</a>
SI B06 09 13	9/1/2013	Service Roundtable: September 2013 Show	Powertrain	<a href="#">View</a>
SI B06 05 13	5/1/2013	Service Roundtable: May 2013 Show	Powertrain	<a href="#">View</a>
SI B11 03 13	5/1/2013	Engine Oil Consumption	Powertrain	<a href="#">View</a>
SI B06 04 13	4/1/2013	Service Roundtable: April 2013 Show	Powertrain	<a href="#">View</a>
SI B11 02 13	3/1/2013	CPO Inspection Guidelines: Engines Requiring a TSE PuMA Case	Powertrain	<a href="#">View</a>
SI B06 03 13	3/1/2013	Service Roundtable: March 2013 Show	Powertrain	<a href="#">View</a>
SI B06 02 13	2/1/2013	Service Roundtable: February 2013 Show	Powertrain	<a href="#">View</a>
SI B06 01 13	1/1/2013	Service Roundtable: January 2013 Show	Powertrain	<a href="#">View</a>
SI B06 12 12	12/1/2012	Service Roundtable: December 2012 Show	Powertrain	<a href="#">View</a>
SI B06 11 12	11/1/2012	Service Roundtable: November 2012 Show	Powertrain	<a href="#">View</a>
SI B12 17 12	11/1/2012	N52T/N55 with 8HP45: Delay in Engine Response	Powertrain	<a href="#">View</a>
SI B24 07 12	11/1/2012	Hybrid Automatic Transmission: Fluid Maintenance Service Interval	Powertrain	<a href="#">View</a>
SI B04 01 12	10/1/2012	Checking Engine Oil Pressure	Powertrain	<a href="#">View</a>
SI B31 01 12	10/1/2012	Clicking Noise from Front Axle	Powertrain	<a href="#">View</a>
SI B06 10 12	10/1/2012	Service Roundtable: October 2012 Show	Powertrain	<a href="#">View</a>
SI B06 09 12	9/1/2012	Service Roundtable: September 2012 Show	Powertrain	<a href="#">View</a>
SI B06 08 12	8/1/2012	Service Roundtable: August 2012 Show	Powertrain	<a href="#">View</a>

SI B06 07 12	7/1/2012	Service Roundtable: July 2012 Show	Powertrain	<a href="#">View</a>
SI B24 04 12	6/1/2012	ZF Automatic Transmission Oil Leaks, Diagnosis and Scope of Repairs	Powertrain	<a href="#">View</a>
SI B24 05 12	6/1/2012	ZF Technical Support via PuMA Cases	Powertrain	<a href="#">View</a>
SI B06 06 12	6/1/2012	Service Roundtable: June 2012 Show	Powertrain	<a href="#">View</a>
SI B06 05 12	5/1/2012	Service Roundtable: May 2012 Show	Powertrain	<a href="#">View</a>
SI B35 01 12	4/1/2012	Repairs to Clutch Pedal Assembly	Powertrain	<a href="#">View</a>
SI B06 04 12	4/1/2012	Service Roundtable: April 2012 Show	Powertrain	<a href="#">View</a>
SI B06 03 12	3/1/2012	Service Roundtable: March 2012 Show	Powertrain	<a href="#">View</a>
SI B12 02 12	2/1/2012	N54, N73: Various Drivability Complaints &Service Engine Soon Lamp Illuminated	Powertrain	<a href="#">View</a>
SI B11 05 11	12/1/2011	Engine Removal and Installation Tips	Powertrain	<a href="#">View</a>
SI B06 12 11	12/1/2011	Service Roundtable: December 2011 Show	Powertrain	<a href="#">View</a>
SI B24 05 11	12/1/2011	Transmission Failures Due to Incorrect Installation	Powertrain	<a href="#">View</a>
SI B06 11 11	11/1/2011	Service Roundtable: November 2011 Show	Powertrain	<a href="#">View</a>
SI B06 10 11	10/1/2011	Service Roundtable: October 2011 Show	Powertrain	<a href="#">View</a>
SI B01 04 11	9/1/2011	WPRC Parts Return Procedure - Shipping Fluid Filled Parts	Powertrain	<a href="#">View</a>
SI B06 09 11	9/1/2011	Service Roundtable: September 2011 Show	Powertrain	<a href="#">View</a>
SI B06 08 11	8/1/2011	Service Roundtable: August 2011 Show	Powertrain	<a href="#">View</a>
SI B11 07 11	7/1/2011	Turbocharger Failure: Oil Supply Line Blockage	Powertrain	<a href="#">View</a>



SI B06 07 11	7/1/2011	Service Roundtable: July 2011 Show	Powertrain	<a href="#">View</a>
SI B06 06 11	6/1/2011	Service Roundtable: June 2011 Show	Powertrain	<a href="#">View</a>
SI B06 05 11	5/1/2011	Service Roundtable: May 2011 Show	Powertrain	<a href="#">View</a>
SI B06 04 11	4/1/2011	Service Roundtable: April 2011 Show	Powertrain	<a href="#">View</a>
SI B06 02 11	2/1/2011	Service Roundtable: February 2011 Show	Powertrain	<a href="#">View</a>
SI B06 01 11	1/1/2011	Service Roundtable: January 2011 Show	Powertrain	<a href="#">View</a>
SI B06 12 10	12/1/2010	Service Roundtable: December 2010 Show	Powertrain	<a href="#">View</a>
SI B21 01 10	11/1/2010	Dual Mass Flywheel - Diagnosis and Inspection	Powertrain	<a href="#">View</a>
SI B06 11 10	11/1/2010	Service Roundtable: November 2010 Show	Powertrain	<a href="#">View</a>
SI B06 10 10	10/1/2010	Service Roundtable: October 2010 Show	Powertrain	<a href="#">View</a>
SI B00 06 10	9/1/2010	Replacement Components Requiring 1,200 Mile Service	Powertrain	<a href="#">View</a>
SI B09 06 10	9/1/2010	Service Roundtable: September 2010 Show	Powertrain	<a href="#">View</a>
SI B01 04 10	8/1/2010	BMW Maint. Program Annual Low-mileage & Customer Pay Addtl Engine Oil Changes	Powertrain	<a href="#">View</a>
SI B04 13 10	6/1/2010	Hydraulic Wheel Bearing and Output Shaft Tool	Powertrain	<a href="#">View</a>
SI B06 05 10	5/1/2010	Service Roundtable: May 2010 Show	Powertrain	<a href="#">View</a>
SI B01 03 10	5/1/2010	DCSnet Enhancement - Service Contract Claims	Powertrain	<a href="#">View</a>
SI B06 04 10	4/1/2010	Service Roundtable: April 2010 Show	Powertrain	<a href="#">View</a>
SI B06 03 10	3/1/2010	Service Roundtable - March 2010	Powertrain	<a href="#">View</a>

SI B06 12 09	12/1/2009	Service Roundtable: December 2009 Show	Powertrain	<a href="#">View</a>
SI B06 11 09	11/1/2009	Service Roundtable: November 2009 Show	Powertrain	<a href="#">View</a>
SI B12 25 09	10/1/2009	TeileClearing for N54 Engine Drivability Concerns	Powertrain	<a href="#">View</a>
SI B06 10 09	10/1/2009	Service Roundtable: October 2009 Show	Powertrain	<a href="#">View</a>
SI B06 09 09	9/1/2009	Service Roundtable: September 2009 Show	Powertrain	<a href="#">View</a>
SI B11 08 09	9/1/2009	Engine Oil Leak	Powertrain	<a href="#">View</a>
SI B11 06 09	7/1/2009	NG6 Crankshaft Seal and Bed Plate Sealer	Powertrain	<a href="#">View</a>
SI B04 13 09	4/1/2009	New Engine Support Part Numbers	Powertrain	<a href="#">View</a>
SI B24 03 09	4/1/2009	550i and 650i with N62TU and 6HP26-Various Drivability Complaints	Powertrain	<a href="#">View</a>
SI B33 01 07	10/1/2007	E60 M5 Howling Noise from Rear Axle Areas	Powertrain	<a href="#">View</a>

## RECALL (33 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
SI B08 04 18	11/1/2018	TAKATA AIR BAG RECALL ? TOWING OF CUSTOMER VEHICLES	Recall	<a href="#">View</a>
SI B61 14 18	10/1/2018	DELIVERY STOP: NEGATIVE BATTERY CABLE	Recall	<a href="#">View</a>
SI B61 16 18	10/1/2018	DELIVERY STOP &RECALL 18V-732: REPLACE BDC MODULE	Recall	<a href="#">View</a>
SI B11 16 17	9/1/2018	RECALL 17V-683: POSITIVE CRANKCASE VENTILATION (PCV) VALVEHEATER	Recall	<a href="#">View</a>
SI B12 22 18	7/1/2018	DELIVERY STOP/RECALL 18V-465: B57O DIESEL ENGINE - REPLACE THECRANKSHAFT SENSO	Recall	<a href="#">View</a>
SI B06 04 17	4/1/2017	Service Roundtable: April Show	Recall	<a href="#">View</a>

SI B06 04 17	4/1/2017	Service Roundtable: April Show	Recall	<a href="#">View</a>
SI B08 02 17	3/1/2017	TAKATA PARTS ALLOCATION PLAN GUIDE TO ALLOCATION AND CUSTOMER COMMUNICATION	Recall	<a href="#">View</a>
SI B08 03 17	2/1/2017	Vehicle Campaign Status	Recall	<a href="#">View</a>
SI B06 03 17	2/1/2017	Service Roundtable: February Show	Recall	<a href="#">View</a>
SI B06 02 17	1/1/2017	Service Roundtable: January Show	Recall	<a href="#">View</a>
SI B06 01 17	1/1/2017	Service Roundtable: 2016 Topics	Recall	<a href="#">View</a>
SI B08 01 17	1/1/2017	TAKATA STATUS VIDEO SERIES	Recall	<a href="#">View</a>
SI B01 29 16	12/1/2016	BMW RECALL/SERVICE ACTION REPAIRS – ALTERNATIVE MOBILITY SOLUTIONS (AMS)	Recall	<a href="#">View</a>
SI B08 04 16	11/1/2016	RECALL CAMPAIGN: CUSTOMER NOTIFICATION	Recall	<a href="#">View</a>
SI B12 15 16	8/1/2016	VOLUNTARY EMISSIONS RECALL CAMPAIGN 16E-A04: DME - OBD	Recall	<a href="#">View</a>
SI B01 09 14	9/1/2014	Front Passenger Air Bag OC3 Mat: Limited Warranty Extension to 15 Years	Recall	<a href="#">View</a>
SI B65 10 14	6/1/2014	Recall 13V-564: Front Passenger Air Bag Seat Occupancy Sensor Mat for Sport Seat	Recall	<a href="#">View</a>
SI B11 04 14	6/1/2014	Recall: Check VANOS Adjustment Unit	Recall	<a href="#">View</a>
SI B65 07 14	6/1/2014	Recall 13V-564:E60, E61,E65,E66 Front Passenger Airbag Seat Occupancy Sensor Mat	Recall	<a href="#">View</a>
SI B06 02 14	2/1/2014	Service Roundtable: February 2014 Show	Recall	<a href="#">View</a>
SI B63 06 13	11/1/2013	Recall Campaign 13V-407: Replace Rear Bulb Carriers (Slide Panel)	Recall	<a href="#">View</a>
SI B06 09 13	9/1/2013	Service Roundtable: September 2013 Show	Recall	<a href="#">View</a>
SI B61 14 12	4/1/2012	Recall Campaign 12V-126: Check the Battery Cable Connection	Recall	<a href="#">View</a>

SI B34 04 10	4/1/2011	Recall Campaign 10V-446: Inspect Brake Booster Vacuum Supply Line	Recall	<a href="#">View</a>
SI B13 14 10	4/1/2011	Emission Recall 10E-A02: N54 Inspection and Replacement of Injectors	Recall	<a href="#">View</a>
SI B13 13 10	2/1/2011	Emissions Recall 10E-A02: N54 High-Pressure Fuel Pump (HDP)	Recall	<a href="#">View</a>
SI B06 12 10	12/1/2010	Service Roundtable: December 2010 Show	Recall	<a href="#">View</a>
SI B06 11 10	11/1/2010	Service Roundtable: November 2010 Show	Recall	<a href="#">View</a>
SI B06 10 10	10/1/2010	Service Roundtable: October 2010 Show	Recall	<a href="#">View</a>
SI B09 06 10	9/1/2010	Service Roundtable: September 2010 Show	Recall	<a href="#">View</a>
SI B06 09 10	9/1/2010	Service Roundtable - September 2010	Recall	<a href="#">View</a>
SI B06 09 09	9/1/2009	Service Roundtable: September 2009 Show	Recall	<a href="#">View</a>

## STEERING &SUSPENSION (38 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
SI B06 02 17	1/1/2017	Service Roundtable: January Show	Steering &Suspension	<a href="#">View</a>
SI B32 07 16	8/1/2016	NO HEATING IN ALCANTARA STEERING WHEEL	Steering &Suspension	<a href="#">View</a>
SI B04 07 14	5/1/2014	ATEQ VT-55 Tire Pressure Monitoring System Diagnostic Tool	Steering &Suspension	<a href="#">View</a>
SI B06 03 14	3/1/2014	Service Roundtable: March 2014 Show	Steering &Suspension	<a href="#">View</a>
SI B06 02 14	2/1/2014	Service Roundtable: February 2014 Show	Steering &Suspension	<a href="#">View</a>
SI B06 09 13	9/1/2013	Service Roundtable: September 2013 Show	Steering &Suspension	<a href="#">View</a>

SI B06 04 13	4/1/2013	Service Roundtable: April 2013 Show	Steering & Suspension	<a href="#">View</a>
SI B06 03 13	3/1/2013	Service Roundtable: March 2013 Show	Steering & Suspension	<a href="#">View</a>
SI B06 02 13	2/1/2013	Service Roundtable: February 2013 Show	Steering & Suspension	<a href="#">View</a>
SI B06 01 13	1/1/2013	Service Roundtable: January 2013 Show	Steering & Suspension	<a href="#">View</a>
SI B06 12 12	12/1/2012	Service Roundtable: December 2012 Show	Steering & Suspension	<a href="#">View</a>
SI B06 11 12	11/1/2012	Service Roundtable: November 2012 Show	Steering & Suspension	<a href="#">View</a>
SI B06 09 12	9/1/2012	Service Roundtable: September 2012 Show	Steering & Suspension	<a href="#">View</a>
SI B06 08 12	8/1/2012	Service Roundtable: August 2012 Show	Steering & Suspension	<a href="#">View</a>
SI B06 07 12	7/1/2012	Service Roundtable: July 2012 Show	Steering & Suspension	<a href="#">View</a>
SI B00 06 12	7/1/2012	Workshop Efficiency Guidelines	Steering & Suspension	<a href="#">View</a>
SI B01 02 12	7/1/2012	N54 Engine Turbo Charger (Wastegates Only)- Proposed Warranty Ext. Settlement	Steering & Suspension	<a href="#">View</a>
SI B06 06 12	6/1/2012	Service Roundtable: June 2012 Show	Steering & Suspension	<a href="#">View</a>
SI B06 05 12	5/1/2012	Service Roundtable: May 2012 Show	Steering & Suspension	<a href="#">View</a>
SI B06 04 12	4/1/2012	Service Roundtable: April 2012 Show	Steering & Suspension	<a href="#">View</a>
SI B06 12 11	12/1/2011	Service Roundtable: December 2011 Show	Steering & Suspension	<a href="#">View</a>
SI B06 11 11	11/1/2011	Service Roundtable: November 2011 Show	Steering & Suspension	<a href="#">View</a>

SI B06 10 11	10/1/2011	Service Roundtable: October 2011 Show	Steering & Suspension	<a href="#">View</a>
SI B01 04 11	9/1/2011	WPRC Parts Return Procedure - Shipping Fluid Filled Parts	Steering & Suspension	<a href="#">View</a>
SI B06 09 11	9/1/2011	Service Roundtable: September 2011 Show	Steering & Suspension	<a href="#">View</a>
SI B06 08 11	8/1/2011	Service Roundtable: August 2011 Show	Steering & Suspension	<a href="#">View</a>
SI B07 02 11	7/1/2011	Recommended Diagnostic Procedures	Steering & Suspension	<a href="#">View</a>
SI B06 06 11	6/1/2011	Service Roundtable: June 2011 Show	Steering & Suspension	<a href="#">View</a>
SI B06 05 11	5/1/2011	Service Roundtable: May 2011 Show	Steering & Suspension	<a href="#">View</a>
SI B32 05 11	5/1/2011	Steering Wheel Leather Cover Is Peeling	Steering & Suspension	<a href="#">View</a>
SI B06 04 11	4/1/2011	Service Roundtable: April 2011 Show	Steering & Suspension	<a href="#">View</a>
SI B06 03 11	3/1/2011	Service Roundtable: March 2011 Show	Steering & Suspension	<a href="#">View</a>
SI B36 01 10	11/1/2010	New Style Tire Valves	Steering & Suspension	<a href="#">View</a>
SI B06 12 09	12/1/2009	Service Roundtable: December 2009 Show	Steering & Suspension	<a href="#">View</a>
SI B06 11 09	11/1/2009	Service Roundtable: November 2009 Show	Steering & Suspension	<a href="#">View</a>
SI B06 10 09	10/1/2009	Service Roundtable: October 2009 Show	Steering & Suspension	<a href="#">View</a>
SI B04 24 09	8/1/2009	KDS II Wheel Alignment System	Steering & Suspension	<a href="#">View</a>
SI B36 02 09	6/1/2009	Retrofit Spare Tire and Jack Kit	Steering & Suspension	<a href="#">View</a>

## TOOLS & HARDWARE (212 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
SI B04 02 19	2/1/2019	RELEASE TOOL FOR HEAD AIR BAG RETAINING CLIP	Tools & Hardware	<a href="#">View</a>
SI B06 01 19	2/1/2019	Service Roundtable: February 2019	Tools & Hardware	<a href="#">View</a>
SI B04 15 18	12/1/2018	ACTRON ACCUMULATED MISFIRE COUNTER	Tools & Hardware	<a href="#">View</a>
SI B04 05 18	10/1/2018	NEW ENGINE TOOLS - B48TU1	Tools & Hardware	<a href="#">View</a>
SI B01 25 18	8/1/2018	MAINTENANCE REFRESH UPDATE: NEW SYSTEM ENHANCEMENTS FOR STANDARD MAINTENANCE	Tools & Hardware	<a href="#">View</a>
SI B00 04 18	7/1/2018	2018 TECHNICIAN SURVEY FROM CARLISLE	Tools & Hardware	<a href="#">View</a>
SI B06 06 18	7/1/2018	Service Roundtable: June Show	Tools & Hardware	<a href="#">View</a>
SI B04 06 18	6/1/2018	ENGINE OIL DRAIN PLUG THREAD REPAIR TOOL	Tools & Hardware	<a href="#">View</a>
SI B01 20 18	6/1/2018	2018 MODEL YEAR G01 (X3) VEHICLES WERE SHIPPED WITH 2019 MODEL YEAR WARRANTY/MA	Tools & Hardware	<a href="#">View</a>
SI B11 07 18	6/1/2018	ENGINE OIL DRAIN PLUG THREAD REPAIR TOOL	Tools & Hardware	<a href="#">View</a>
SI B06 03 18	3/1/2018	Service Roundtable: March Show	Tools & Hardware	<a href="#">View</a>
SI B04 02 18	2/1/2018	DRIVESHAFT CENTERING BUSHING TOOL	Tools & Hardware	<a href="#">View</a>
SI B04 04 18	2/1/2018	TIRE VALVE TORQUE WRENCH	Tools & Hardware	<a href="#">View</a>
SI B04 10 17	11/1/2017	BRAKE ROTOR GAUGE KIT	Tools & Hardware	<a href="#">View</a>
SI B06 04 17	4/1/2017	Service Roundtable: April Show	Tools & Hardware	<a href="#">View</a>
SI B08 04 17	3/1/2017	VIN LIST FOR DELIVERY STOPS	Tools & Hardware	<a href="#">View</a>

SI B10 02 17	3/1/2017	LAUNCH OF TECHNICAL REFERENCE INFORMATION DOCUMENTS	Tools &Hardware	<a href="#">View</a>
SI B08 03 17	2/1/2017	Vehicle Campaign Status	Tools &Hardware	<a href="#">View</a>
SI B06 03 17	2/1/2017	Service Roundtable: February Show	Tools &Hardware	<a href="#">View</a>
SI B10 01 17	1/1/2017	TERMINATION OF WEBISTA AND WEBKSD APPLICATIONS	Tools &Hardware	<a href="#">View</a>
SI B04 03 17	1/1/2017	SPECIAL TOOL PRICING - REDUCTION	Tools &Hardware	<a href="#">View</a>
SI B06 01 17	1/1/2017	Service Roundtable: 2016 Topics	Tools &Hardware	<a href="#">View</a>
SI B01 29 16	12/1/2016	BMW RECALL/SERVICE ACTION REPAIRS – ALTERNATIVE MOBILITY SOLUTIONS (AMS)	Tools &Hardware	<a href="#">View</a>
SI B04 26 16	11/1/2016	On-Car Brake Lathe	Tools &Hardware	<a href="#">View</a>
SI B01 25 16	11/1/2016	DCSNET REPAIR ORDER/CLAIM DISABLED VEHICLE: TOW/EMERGENCY SERVICE INDICATOR ...	Tools &Hardware	<a href="#">View</a>
SI B01 22 16	11/1/2016	Dangerous Goods (DG) Part Return Program	Tools &Hardware	<a href="#">View</a>
SI B01 26 16	10/1/2016	ADMINISTRATIVE PAYMENT - ELIGIBILITY FOR VALID AND APPROVED TEILECLEARING CASES	Tools &Hardware	<a href="#">View</a>
SI B00 09 16	10/1/2016	2016 Technician Survey From Carlisle	Tools &Hardware	<a href="#">View</a>
SI B06 09 16	9/1/2016	Service Roundtable: September Show	Tools &Hardware	<a href="#">View</a>
SI B06 07 16	8/1/2016	Service Roundtable: July Show	Tools &Hardware	<a href="#">View</a>
SI B06 08 16	8/1/2016	Service Roundtable: August Show	Tools &Hardware	<a href="#">View</a>
SI B51 21 16	8/1/2016	WIND NOISE FROM KIDNEY GRILL	Tools &Hardware	<a href="#">View</a>
SI B10 01 16	7/1/2016	Deactivated Service Information Bulletin List	Tools &Hardware	<a href="#">View</a>
SI B04 19 16	7/1/2016	New Crimping Die Jaws	Tools &Hardware	<a href="#">View</a>



SI B04 15 16	6/1/2016	132 PIN BREAK OUT BOX - REPAIR KIT	Tools &Hardware	<a href="#">View</a>
SI B06 06 16	6/1/2016	Service Roundtable: June Show	Tools &Hardware	<a href="#">View</a>
SI B04 13 16	5/1/2016	Stripped Locking Wheel Bolts	Tools &Hardware	<a href="#">View</a>
SI B06 05 16	5/1/2016	Service Roundtable: May Show	Tools &Hardware	<a href="#">View</a>
SI B06 04 16	4/1/2016	Service Roundtable: April Show	Tools &Hardware	<a href="#">View</a>
SI B04 10 16	4/1/2016	Antenna Test Cables	Tools &Hardware	<a href="#">View</a>
SI B09 02 16	4/1/2016	IRAP Next	Tools &Hardware	<a href="#">View</a>
SI B00 05 16	4/1/2016	Submitting PuMA/TeileClearing Cases via PuMA App on Android Devices	Tools &Hardware	<a href="#">View</a>
SI B06 03 16	3/1/2016	Service Roundtable: March 2016 Show	Tools &Hardware	<a href="#">View</a>
SI B06 02 16	2/1/2016	Service Roundtable: February Show	Tools &Hardware	<a href="#">View</a>
SI B06 01 16	1/1/2016	Service Roundtable: January Show	Tools &Hardware	<a href="#">View</a>
SI B06 12 15	12/1/2015	Service Roundtable: December 2015 Show	Tools &Hardware	<a href="#">View</a>
SI B06 11 15	11/1/2015	Service Roundtable: November 2015 Show	Tools &Hardware	<a href="#">View</a>
SI B06 10 15	10/1/2015	Service Roundtable: October 2015 Show	Tools &Hardware	<a href="#">View</a>
SI B10 04 15	8/1/2015	Advanced Information on TIS	Tools &Hardware	<a href="#">View</a>
SI B04 19 15	8/1/2015	The New BMW Equipment Program Website	Tools &Hardware	<a href="#">View</a>
SI B10 03 15	7/1/2015	Google Search Now Available in TIS	Tools &Hardware	<a href="#">View</a>
SI B11 09 15	5/1/2015	Engine Replacement: Filling Engine with Engine Oil Before First Start	Tools &Hardware	<a href="#">View</a>

SI B00 09 14	4/1/2015	2014 Technician Survey from Carlisle	Tools &Hardware	<a href="#">View</a>
SI B10 01 15	4/1/2015	Deactivated Service Information Bulletin List	Tools &Hardware	<a href="#">View</a>
SI B06 04 15	4/1/2015	Service Roundtable: April 2015 Show	Tools &Hardware	<a href="#">View</a>
SI B06 03 15	3/1/2015	Service Roundtable: March 2015 Show	Tools &Hardware	<a href="#">View</a>
SI B07 01 15	3/1/2015	Best Practices for Using ISTA with AIR	Tools &Hardware	<a href="#">View</a>
SI B51 01 15	3/1/2015	Harman Kardon Surround Sound System Noise	Tools &Hardware	<a href="#">View</a>
SI B01 07 15	2/1/2015	Add-On Policy: Expediting Customer Interaction &Increasing Workshop Efficiency	Tools &Hardware	<a href="#">View</a>
SI B06 12 14	1/1/2015	Service Roundtable: December 2014 Show	Tools &Hardware	<a href="#">View</a>
SI B06 01 15	1/1/2015	Service Roundtable: January 2015 Show	Tools &Hardware	<a href="#">View</a>
SI B11 01 15	1/1/2015	BMW Engine Oil Part Number Transition	Tools &Hardware	<a href="#">View</a>
SI B04 22 14	12/1/2014	Transport Mode Switching Device: TMSD	Tools &Hardware	<a href="#">View</a>
SI B07 04 14	12/1/2014	ISPI Next: AIR - Aftersales Information Research	Tools &Hardware	<a href="#">View</a>
SI B01 22 14	11/1/2014	Interior Trim/Components: Wear vs. Defect	Tools &Hardware	<a href="#">View</a>
SI B00 10 14	11/1/2014	Customer Assistance Process	Tools &Hardware	<a href="#">View</a>
SI B06 11 14	11/1/2014	Service Roundtable: November 2014 Show	Tools &Hardware	<a href="#">View</a>
SI B11 19 14	10/1/2014	Valve Guide to Valve Stem Wear Specification	Tools &Hardware	<a href="#">View</a>
SI B04 20 14	10/1/2014	Deutronic Battery Charger Check	Tools &Hardware	<a href="#">View</a>
SI B06 10 14	10/1/2014	Service Roundtable: October 2014 Show	Tools &Hardware	<a href="#">View</a>

SI B00 08 14	10/1/2014	US Dealer Meeting: September 2014	Tools &Hardware	<a href="#">View</a>
SI B06 09 14	9/1/2014	Service Roundtable: September 2014 Show	Tools &Hardware	<a href="#">View</a>
SI B04 12 14	8/1/2014	Glass Removal Tool	Tools &Hardware	<a href="#">View</a>
SI B04 13 14	8/1/2014	Range Extender (REx) and Basic Tools	Tools &Hardware	<a href="#">View</a>
SI B06 08 14	8/1/2014	Service Roundtable: August 2014 Show	Tools &Hardware	<a href="#">View</a>
SI B06 07 14	7/1/2014	Service Roundtable: July 2014 Show	Tools &Hardware	<a href="#">View</a>
SI B04 08 14	6/1/2014	Electronic Torque/Angle Wrench	Tools &Hardware	<a href="#">View</a>
SI B01 05 14	6/1/2014	BMW Product Quality Analysis: Special Parts Return Requests	Tools &Hardware	<a href="#">View</a>
SI B06 06 14	6/1/2014	Service Roundtable: June 2014 Show	Tools &Hardware	<a href="#">View</a>
SI B04 02 14	5/1/2014	Test Cable Storage Cabinet	Tools &Hardware	<a href="#">View</a>
SI B04 07 14	5/1/2014	ATEQ VT-55 Tire Pressure Monitoring System Diagnostic Tool	Tools &Hardware	<a href="#">View</a>
SI B06 05 14	5/1/2014	Service Roundtable: May 2014 Show	Tools &Hardware	<a href="#">View</a>
SI B06 04 14	4/1/2014	Service Roundtable: April 2014 Show	Tools &Hardware	<a href="#">View</a>
SI B00 05 14	3/1/2014	Service Quality Toolbox	Tools &Hardware	<a href="#">View</a>
SI B06 03 14	3/1/2014	Service Roundtable: March 2014 Show	Tools &Hardware	<a href="#">View</a>
SI B06 02 14	2/1/2014	Service Roundtable: February 2014 Show	Tools &Hardware	<a href="#">View</a>
SI B51 04 14	1/1/2014	BMW Group ColorSystem Document	Tools &Hardware	<a href="#">View</a>
SI B06 01 14	1/1/2014	Service Roundtable: January 2014 Show	Tools &Hardware	<a href="#">View</a>

SI B06 12 13	12/1/2013	Service Roundtable: December 2013 Show	Tools &Hardware	<a href="#">View</a>
SI B06 11 13	11/1/2013	Service Roundtable: November 2013 Show	Tools &Hardware	<a href="#">View</a>
SI B04 14 13	10/1/2013	Selective Catalytic Reduction (SCR) Test Cable	Tools &Hardware	<a href="#">View</a>
SI B06 10 13	10/1/2013	Service Roundtable: October 2013 Show	Tools &Hardware	<a href="#">View</a>
SI B01 02 13	9/1/2013	BMW NA Replacement Parts on Backorder, Caused by New ATLAS Release	Tools &Hardware	<a href="#">View</a>
SI B06 08 13	8/1/2013	Service Roundtable: August 2013 Show	Tools &Hardware	<a href="#">View</a>
SI B06 07 13	7/1/2013	Service Roundtable: July 2013 Show	Tools &Hardware	<a href="#">View</a>
SI B06 06 13	6/1/2013	Service Roundtable: June 2013 Show	Tools &Hardware	<a href="#">View</a>
SI B04 06 13	5/1/2013	Spare Parts Ordering: DEF Extraction/Fill Unit &Eng Coolant Vacuum Charger Sys	Tools &Hardware	<a href="#">View</a>
SI B07 01 13	4/1/2013	Diagnosis Process Regarding DiagCodes	Tools &Hardware	<a href="#">View</a>
SI B04 05 13	3/1/2013	Test Kit for Electrical Contacts	Tools &Hardware	<a href="#">View</a>
SI B06 12 12	12/1/2012	Service Roundtable: December 2012 Show	Tools &Hardware	<a href="#">View</a>
SI B04 28 12	11/1/2012	Special Tool Direct Shipment Availability	Tools &Hardware	<a href="#">View</a>
SI B04 01 12	10/1/2012	Checking Engine Oil Pressure	Tools &Hardware	<a href="#">View</a>
SI B06 10 12	10/1/2012	Service Roundtable: October 2012 Show	Tools &Hardware	<a href="#">View</a>
SI B04 21 12	9/1/2012	Crimping Pliers for Wire End Ferrules	Tools &Hardware	<a href="#">View</a>
SI B04 16 12	9/1/2012	Special Tools for Efficient Workshop	Tools &Hardware	<a href="#">View</a>
SI B06 08 12	8/1/2012	Service Roundtable: August 2012 Show	Tools &Hardware	<a href="#">View</a>

SI B04 18 12	8/1/2012	Wire Pull Handle with Suction Cup for Windshield Removal	Tools &Hardware	<a href="#">View</a>
SI B06 07 12	7/1/2012	Service Roundtable: July 2012 Show	Tools &Hardware	<a href="#">View</a>
SI B04 07 12	7/1/2012	Workshop Efficiency Mobile Toolbox	Tools &Hardware	<a href="#">View</a>
SI B00 06 12	7/1/2012	Workshop Efficiency Guidelines	Tools &Hardware	<a href="#">View</a>
SI B04 08 12	6/1/2012	DSC Connector Release Tool	Tools &Hardware	<a href="#">View</a>
SI B10 01 12	5/1/2012	BMW TIS Website Changes	Tools &Hardware	<a href="#">View</a>
SI B04 06 12	4/1/2012	Special Tool Stocking Inquiry: BMW AG	Tools &Hardware	<a href="#">View</a>
SI B04 05 12	4/1/2012	Special Tool Automatic Tool Shipment: Satellite Locations	Tools &Hardware	<a href="#">View</a>
SI B06 04 12	4/1/2012	Service Roundtable: April 2012 Show	Tools &Hardware	<a href="#">View</a>
SI B04 03 12	4/1/2012	Workshop Engine Crane	Tools &Hardware	<a href="#">View</a>
SI B04 04 12	4/1/2012	Special Tool Storage Cabinets	Tools &Hardware	<a href="#">View</a>
SI B04 02 12	3/1/2012	Special Tool Part Number Changes	Tools &Hardware	<a href="#">View</a>
SI B00 01 12	2/1/2012	Audit Process: BMW Warranty, CPO and Maintenance-2012 Updates	Tools &Hardware	<a href="#">View</a>
SI B06 01 12	1/1/2012	Service Roundtable: January 2012 Show	Tools &Hardware	<a href="#">View</a>
SI B01 07 11	12/1/2011	BMW Document Retention	Tools &Hardware	<a href="#">View</a>
SI B04 31 11	12/1/2011	Magnetic Test Card for Wheel Speed Sensors Incremental Ring	Tools &Hardware	<a href="#">View</a>
SI B04 30 11	12/1/2011	TKR Spare Parts Ordering	Tools &Hardware	<a href="#">View</a>
SI B06 12 11	12/1/2011	Service Roundtable: December 2011 Show	Tools &Hardware	<a href="#">View</a>

SI B06 11 11	11/1/2011	Service Roundtable: November 2011 Show	Tools &Hardware	<a href="#">View</a>
SI B03 02 11	11/1/2011	Continuing Education, BMW Associate Degree at BCC	Tools &Hardware	<a href="#">View</a>
SI B06 09 11	9/1/2011	Service Roundtable: September 2011 Show	Tools &Hardware	<a href="#">View</a>
SI B04 16 11	8/1/2011	Punch Rivet Insert Aid Tool	Tools &Hardware	<a href="#">View</a>
SI B04 12 11	8/1/2011	BMW Group Carbon Blaster	Tools &Hardware	<a href="#">View</a>
SI B04 17 11	8/1/2011	Engine Cross-Member and Support Adapters	Tools &Hardware	<a href="#">View</a>
SI B01 06 11	8/1/2011	New BMW Vehicles - Environmental Paint Finish Damage	Tools &Hardware	<a href="#">View</a>
SI B07 02 11	7/1/2011	Recommended Diagnostic Procedures	Tools &Hardware	<a href="#">View</a>
SI B03 01 11	6/1/2011	Technician Recruitment and Training	Tools &Hardware	<a href="#">View</a>
SI B07 03 11	6/1/2011	Updated Diagnosis Process in Regards to DIAGCODES	Tools &Hardware	<a href="#">View</a>
SI B04 09 11	5/1/2011	Fuel Pressure Test Lines	Tools &Hardware	<a href="#">View</a>
SI B06 05 11	5/1/2011	Service Roundtable: May 2011 Show	Tools &Hardware	<a href="#">View</a>
SI B04 06 11	5/1/2011	Coaxial Cable Repair Tool	Tools &Hardware	<a href="#">View</a>
SI B04 11 11	5/1/2011	Spare Punch Rivet Tool Tips	Tools &Hardware	<a href="#">View</a>
SI B84 02 11	5/1/2011	Diagnosis of Communication Systems	Tools &Hardware	<a href="#">View</a>
SI B04 23 10	4/1/2011	Approved Battery Charger/Power Supplies	Tools &Hardware	<a href="#">View</a>
SI B04 04 11	4/1/2011	Fuel Composition Tester	Tools &Hardware	<a href="#">View</a>
SI B06 04 11	4/1/2011	Service Roundtable: April 2011 Show	Tools &Hardware	<a href="#">View</a>

SI B04 08 11	4/1/2011	Threaded Spindle Set	Tools &Hardware	<a href="#">View</a>
SI B04 07 11	4/1/2011	Hose Pinch Pliers	Tools &Hardware	<a href="#">View</a>
SI B00 05 11	3/1/2011	BMW Group Technical Support and PuMA	Tools &Hardware	<a href="#">View</a>
SI B06 03 11	3/1/2011	Service Roundtable: March 2011 Show	Tools &Hardware	<a href="#">View</a>
SI B06 02 11	2/1/2011	Service Roundtable: February 2011 Show	Tools &Hardware	<a href="#">View</a>
SI B01 01 11	2/1/2011	BMW Warranties Documentation Site	Tools &Hardware	<a href="#">View</a>
SI B00 02 11	2/1/2011	PuMA-Standardized Fault Catalog (VFC) Enhancement	Tools &Hardware	<a href="#">View</a>
SI B04 02 11	1/1/2011	Mobile Lifting Table	Tools &Hardware	<a href="#">View</a>
SI B04 30 10	1/1/2011	DMC Injector Scan Tool	Tools &Hardware	<a href="#">View</a>
SI B06 01 11	1/1/2011	Service Roundtable: January 2011 Show	Tools &Hardware	<a href="#">View</a>
SI B06 12 10	12/1/2010	Service Roundtable: December 2010 Show	Tools &Hardware	<a href="#">View</a>
SI B07 04 10	12/1/2010	ISTA - Collecting and Saving Abbreviated Operations Reports	Tools &Hardware	<a href="#">View</a>
SI B07 05 10	12/1/2010	Text Search for Test Modules in ISTA	Tools &Hardware	<a href="#">View</a>
SI B04 27 10	11/1/2010	Test Cable Modification	Tools &Hardware	<a href="#">View</a>
SI B04 25 10	10/1/2010	Leak Testing Equipment Survey	Tools &Hardware	<a href="#">View</a>
SI B06 10 10	10/1/2010	Service Roundtable: October 2010 Show	Tools &Hardware	<a href="#">View</a>
SI B09 06 10	9/1/2010	Service Roundtable: September 2010 Show	Tools &Hardware	<a href="#">View</a>
SI B04 15 10	9/1/2010	Turbocharger Diagnostic Tool Adapter	Tools &Hardware	<a href="#">View</a>

SI B07 03 10	8/1/2010	Non-electric Diagnosis	Tools &Hardware	<a href="#">View</a>
SI B13 10 10	8/1/2010	N54 - Enhancement to HDP Replacement Procedure	Tools &Hardware	<a href="#">View</a>
SI B04 22 10	7/1/2010	Engine Harness Removal Tool	Tools &Hardware	<a href="#">View</a>
SI B04 20 10	6/1/2010	Adapters for Flushing the Transmission Oil Cooler and Lines	Tools &Hardware	<a href="#">View</a>
SI B04 13 10	6/1/2010	Hydraulic Wheel Bearing and Output Shaft Tool	Tools &Hardware	<a href="#">View</a>
SI B01 01 10	5/1/2010	Claim Entry for Repairs That Require "Diagcodes"	Tools &Hardware	<a href="#">View</a>
SI B01 03 10	5/1/2010	DCSnet Enhancement - Service Contract Claims	Tools &Hardware	<a href="#">View</a>
SI B01 03 10	5/1/2010	DCSnet Enhancement - Service Contract Claims	Tools &Hardware	<a href="#">View</a>
SI B01 02 10	5/1/2010	Claims Administration Group Contact Information	Tools &Hardware	<a href="#">View</a>
SI B07 02 10	4/1/2010	ISTA FASTA Data Not Available	Tools &Hardware	<a href="#">View</a>
SI B07 01 10	4/1/2010	ISTA PC Client	Tools &Hardware	<a href="#">View</a>
SI B04 07 10	3/1/2010	Pressure Adapter	Tools &Hardware	<a href="#">View</a>
SI B04 11 10	3/1/2010	Universal Hydraulic Jack - Important Information	Tools &Hardware	<a href="#">View</a>
SI B17 01 10	3/1/2010	Proper Evacuation and/or Filling of Cooling System after Repairs	Tools &Hardware	<a href="#">View</a>
SI B06 03 10	3/1/2010	Service Roundtable - March 2010	Tools &Hardware	<a href="#">View</a>
SI B07 06 09	2/1/2010	Integrated Measurement Interface Box - IMIB	Tools &Hardware	<a href="#">View</a>
SI B04 04 10	1/1/2010	Power Port Release Tool	Tools &Hardware	<a href="#">View</a>
SI B04 03 10	1/1/2010	Torque Wrench	Tools &Hardware	<a href="#">View</a>



SI B06 12 09	12/1/2009	Service Roundtable: December 2009 Show	Tools &Hardware	<a href="#">View</a>
SI B06 11 09	11/1/2009	Service Roundtable: November 2009 Show	Tools &Hardware	<a href="#">View</a>
SI B04 35 09	11/1/2009	Integrated Measurement Interface Box - IMIB	Tools &Hardware	<a href="#">View</a>
SI B04 34 09	11/1/2009	Third Generation (3G) Components for Purchase	Tools &Hardware	<a href="#">View</a>
SI B04 27 09	10/1/2009	Brake Rotor Puller	Tools &Hardware	<a href="#">View</a>
SI B04 33 09	10/1/2009	O-ring Removal Tool	Tools &Hardware	<a href="#">View</a>
SI B04 30 09	9/1/2009	ICOM Extension Cable	Tools &Hardware	<a href="#">View</a>
SI B04 28 09	9/1/2009	Crimping Plier Jaws	Tools &Hardware	<a href="#">View</a>
SI B51 29 09	9/1/2009	1-Hour Windshield Urethane	Tools &Hardware	<a href="#">View</a>
SI B01 04 09	8/1/2009	BMW Aftersales Mobility Program (AMP) - Shuttle Service	Tools &Hardware	<a href="#">View</a>
SI B01 03 09	8/1/2009	BMW Aftersales Mobility Program (AMP) - Two NEW Retail Types	Tools &Hardware	<a href="#">View</a>
SI B04 24 09	8/1/2009	KDS II Wheel Alignment System	Tools &Hardware	<a href="#">View</a>
SI B06 08 09	8/1/2009	Service Roundtable - August 2009 Show	Tools &Hardware	<a href="#">View</a>
SI B06 07 09	7/1/2009	Service Roundtable: July 2009 Show	Tools &Hardware	<a href="#">View</a>
SI B07 02 09	7/1/2009	Activating ISTA in Offline Mode when ISIS Is Not Available	Tools &Hardware	<a href="#">View</a>
SI B01 02 09	7/1/2009	Warranty Parts Return Center Enhancements&ProcessChanges-Effective July 1, 2009	Tools &Hardware	<a href="#">View</a>
SI B04 22 09	7/1/2009	BMW Special Tool Information Access	Tools &Hardware	<a href="#">View</a>
SI B04 21 09	6/1/2009	Approved Battery Charger/Power Supplies	Tools &Hardware	<a href="#">View</a>

SI B00 06 09	6/1/2009	Replacement of PuMA QC Infos with "Info Only" PuMA Cases	Tools &Hardware	<a href="#">View</a>
SI B06 06 09	6/1/2009	Service Roundtable: June 2009 Show	Tools &Hardware	<a href="#">View</a>
SI B04 26 09	6/1/2009	BMW Special Tools Online Catalog - ASAP	Tools &Hardware	<a href="#">View</a>
SI B61 11 09	6/1/2009	Battery Charging and Testing Procedure	Tools &Hardware	<a href="#">View</a>
SI B00 05 09	6/1/2009	CBS Service Maintenance Substitute Checklists	Tools &Hardware	<a href="#">View</a>
SI B04 15 09	5/1/2009	Test Cable Modification	Tools &Hardware	<a href="#">View</a>
SI B04 08 09	5/1/2009	Special Tool Board Update	Tools &Hardware	<a href="#">View</a>
SI B04 16 09	5/1/2009	Fuel Line Plugs	Tools &Hardware	<a href="#">View</a>
SI B06 05 09	5/1/2009	Service Roundtable: May 2009 Show	Tools &Hardware	<a href="#">View</a>
SI B04 25 09	4/1/2009	Hand-held Riveting Tool	Tools &Hardware	<a href="#">View</a>
SI B01 01 09	4/1/2009	Updated Training Tutorials for Maintenance Program Upgrades Now Available on ICP	Tools &Hardware	<a href="#">View</a>
SI B04 09 09	4/1/2009	New Special Blades for Drawing Knife Set 652 010	Tools &Hardware	<a href="#">View</a>
SI B04 13 09	4/1/2009	New Engine Support Part Numbers	Tools &Hardware	<a href="#">View</a>
SI B04 12 09	4/1/2009	Universal Seat Adapter	Tools &Hardware	<a href="#">View</a>
SI B07 01 09	4/1/2009	DIS V57 Release Notes	Tools &Hardware	<a href="#">View</a>
SI B06 04 09	4/1/2009	Service Roundtable: April 2009 Show	Tools &Hardware	<a href="#">View</a>

## WIPER AND WASHER (17 TOTAL)

OEM#s	Issue Date	TSB Description	Type	View
-------	------------	-----------------	------	------

SI B06 04 13	4/1/2013	Service Roundtable: April 2013 Show	Wiper and Washer	<a href="#">View</a>
SI B06 03 13	3/1/2013	Service Roundtable: March 2013 Show	Wiper and Washer	<a href="#">View</a>
SI B06 01 13	1/1/2013	Service Roundtable: January 2013 Show	Wiper and Washer	<a href="#">View</a>
SI B06 12 12	12/1/2012	Service Roundtable: December 2012 Show	Wiper and Washer	<a href="#">View</a>
SI B06 11 12	11/1/2012	Service Roundtable: November 2012 Show	Wiper and Washer	<a href="#">View</a>
SI B06 09 12	9/1/2012	Service Roundtable: September 2012 Show	Wiper and Washer	<a href="#">View</a>
SI B06 08 12	8/1/2012	Service Roundtable: August 2012 Show	Wiper and Washer	<a href="#">View</a>
SI B06 06 12	6/1/2012	Service Roundtable: June 2012 Show	Wiper and Washer	<a href="#">View</a>
SI B06 04 12	4/1/2012	Service Roundtable: April 2012 Show	Wiper and Washer	<a href="#">View</a>
SI B06 12 11	12/1/2011	Service Roundtable: December 2011 Show	Wiper and Washer	<a href="#">View</a>
SI B06 09 11	9/1/2011	Service Roundtable: September 2011 Show	Wiper and Washer	<a href="#">View</a>
SI B06 11 10	11/1/2010	Service Roundtable: November 2010 Show	Wiper and Washer	<a href="#">View</a>
SI B06 05 10	5/1/2010	Service Roundtable: May 2010 Show	Wiper and Washer	<a href="#">View</a>
SI B06 03 10	3/1/2010	Service Roundtable - March 2010	Wiper and Washer	<a href="#">View</a>
SI B06 01 10	1/1/2010	Service Roundtable: January 2010 Show	Wiper and Washer	<a href="#">View</a>
SI B06 12 09	12/1/2009	Service Roundtable: December 2009 Show	Wiper and Washer	<a href="#">View</a>
SI B06 11 09	11/1/2009	Service Roundtable: November 2009 Show	Wiper and Washer	<a href="#">View</a>

# Vehicle Title History

Title history requires a VIN#, rerun your report using your vehicle's VIN# for Vehicle Title Report

Ran on July 28, 2021 @ 7:45 PM | [Contact us](#)

Copyright 2021 CarMD Corp